

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BENQUET				
Total	80,104	75,600	2,628	609
Concrete/Brick/Stone	26,881	24,137	2,494	120
Wood	5,711	5,085	12	6
Half Concrete/Brick/Stone and Half Wood	14,487	13,987	99	376
Galvanized Iron/Aluminum	29,806	29,623	17	96
Bamboo/Sawali/Cogon/Nipa	742	545	-	2
Asbestos	1	1	-	-
Glass	3	2	1	-
Makeshift/Salvaged/Improvised Materials	103	80	-	-
Others/Not Reported	2,369	2,139	5	9
No Walls	1	1	-	-
ATOK				
Total	3,804	3,715	3	16
Concrete/Brick/Stone	341	335	3	2
Wood	529	495	-	2
Half Concrete/Brick/Stone and Half Wood	869	862	-	7
Galvanized Iron/Aluminum	1,814	1,805	-	3
Bamboo/Sawali/Cogon/Nipa	11	1	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	239	216	-	2
No Walls	-	-	-	-
BAKUN				
Total	2,450	2,393	3	8
Concrete/Brick/Stone	233	220	3	3
Wood	235	206	-	-
Half Concrete/Brick/Stone and Half Wood	233	230	-	3
Galvanized Iron/Aluminum	1,338	1,333	-	2
Bamboo/Sawali/Cogon/Nipa	4	3	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	407	401	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BOKOD				
Total	2,622	2,536	3	15
Concrete/Brick/Stone	161	152	2	6
Wood	446	406	1	-
Half Concrete/Brick/Stone and Half Wood	271	263	-	7
Galvanized Iron/Aluminum	1,581	1,575	-	2
Bamboo/Sawali/Cogon/Nipa	2	-	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	2	-	-
Others/Not Reported	159	138	-	-
No Walls	-	-	-	-
BUGUIAS				
Total	7,435	7,256	48	37
Concrete/Brick/Stone	2,081	2,024	47	5
Wood	393	339	-	1
Half Concrete/Brick/Stone and Half Wood	1,501	1,492	1	5
Galvanized Iron/Aluminum	3,387	3,356	-	26
Bamboo/Sawali/Cogon/Nipa	20	14	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	53	31	-	-
No Walls	-	-	-	-
ITOGON				
Total	10,337	9,920	73	263
Concrete/Brick/Stone	3,012	2,923	56	20
Wood	284	266	-	-
Half Concrete/Brick/Stone and Half Wood	2,977	2,760	13	202
Galvanized Iron/Aluminum	3,804	3,760	1	35
Bamboo/Sawali/Cogon/Nipa	102	89	-	1
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	15	12	-	-
Others/Not Reported	142	109	3	5
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
KABAYAN				
Total	2,415	2,284	5	3
Concrete/Brick/Stone	96	90	4	2
Wood	575	461	-	-
Half Concrete/Brick/Stone and Half Wood	98	96	1	1
Galvanized Iron/Aluminum	1,463	1,460	-	-
Bamboo/Sawali/Cogon/Nipa	2	-	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	3	-	-
Others/Not Reported	178	174	-	-
No Walls	-	-	-	-
KAPANGAN				
Total	3,785	3,669	13	20
Concrete/Brick/Stone	580	564	12	4
Wood	230	197	-	-
Half Concrete/Brick/Stone and Half Wood	750	731	1	14
Galvanized Iron/Aluminum	1,943	1,939	-	2
Bamboo/Sawali/Cogon/Nipa	109	76	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	3	-	-
Others/Not Reported	169	158	-	-
No Walls	1	1	-	-
KIBUNGAN				
Total	3,423	3,165	6	11
Concrete/Brick/Stone	353	348	4	1
Wood	639	450	-	3
Half Concrete/Brick/Stone and Half Wood	606	603	1	1
Galvanized Iron/Aluminum	1,725	1,717	1	6
Bamboo/Sawali/Cogon/Nipa	48	18	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	2	-	-
Others/Not Reported	43	27	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
LA TRINIDAD (Capital)				
Total	22,758	20,210	2,315	90
Concrete/Brick/Stone	13,625	11,280	2,219	58
Wood	385	347	11	-
Half Concrete/Brick/Stone and Half Wood	3,435	3,335	70	25
Galvanized Iron/Aluminum	4,727	4,699	13	6
Bamboo/Sawali/Cogon/Nipa	19	13	-	-
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	28	22	-	-
Others/Not Reported	538	513	2	1
No Walls	-	-	-	-
MANKAYAN				
Total	7,257	7,017	44	111
Concrete/Brick/Stone	1,304	1,253	37	6
Wood	852	824	-	-
Half Concrete/Brick/Stone and Half Wood	1,904	1,795	6	100
Galvanized Iron/Aluminum	2,909	2,894	1	4
Bamboo/Sawali/Cogon/Nipa	21	12	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	25	21	-	-
Others/Not Reported	242	218	-	1
No Walls	-	-	-	-
SABLAN				
Total	2,245	2,212	11	6
Concrete/Brick/Stone	802	789	10	3
Wood	63	62	-	-
Half Concrete/Brick/Stone and Half Wood	228	226	1	1
Galvanized Iron/Aluminum	1,042	1,040	-	2
Bamboo/Sawali/Cogon/Nipa	104	91	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	2	-	-
Others/Not Reported	4	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

TUBA

Total	8,453	8,182	85	22
Concrete/Brick/Stone	3,514	3,401	80	8
Wood	906	884	-	-
Half Concrete/Brick/Stone and Half Wood	1,078	1,065	3	6
Galvanized Iron/Aluminum	2,576	2,553	1	8
Bamboo/Sawali/Cogon/Nipa	233	175	-	-
Asbestos	1	1	-	-
Glass	1	-	1	-
Makeshift/Salvaged/Improvised Materials	13	12	-	-
Others/Not Reported	131	91	-	-
No Walls	-	-	-	-

TUBLAY

Total	3,120	3,041	19	7
Concrete/Brick/Stone	779	758	17	2
Wood	174	148	-	-
Half Concrete/Brick/Stone and Half Wood	537	529	2	4
Galvanized Iron/Aluminum	1,497	1,492	-	-
Bamboo/Sawali/Cogon/Nipa	67	53	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	64	61	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BENGUET					
Total	79	789	14	92	293
Concrete/Brick/Stone	20	1	-	71	38
Wood	38	555	1	5	9
Half Concrete/Brick/Stone and Half Wood	4	5	-	2	14
Galvanized Iron/Aluminum	10	32	-	1	27
Bamboo/Sawali/Cogon/Nipa	5	183	1	4	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	10	12	1	-
Others/Not Reported	2	3	-	8	203
No Walls	-	-	-	-	-
ATOK					
Total	6	43	-	2	19
Concrete/Brick/Stone	-	-	-	1	-
Wood	4	28	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	1	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	10	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	-	-	1	19
No Walls	-	-	-	-	-
BAKUN					
Total	-	33	-	9	4
Concrete/Brick/Stone	-	-	-	7	-
Wood	-	29	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	2	4
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BOKOD					
Total	2	42	-	4	20
Concrete/Brick/Stone	1	-	-	-	-
Wood	-	37	-	2	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	1	2	-	1	-
Bamboo/Sawali/Cogon/Nipa	-	2	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	1	19
No Walls	-	-	-	-	-
BUGUIAS					
Total	3	58	-	1	32
Concrete/Brick/Stone	1	-	-	1	3
Wood	1	51	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	3
Galvanized Iron/Aluminum	-	2	-	-	3
Bamboo/Sawali/Cogon/Nipa	1	5	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	22
No Walls	-	-	-	-	-
ITOGON					
Total	7	28	3	4	39
Concrete/Brick/Stone	3	-	-	4	6
Wood	2	15	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	2
Galvanized Iron/Aluminum	2	1	-	-	5
Bamboo/Sawali/Cogon/Nipa	-	12	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	3	-	-
Others/Not Reported	-	-	-	-	25
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
KABAYAN					
Total	2	116	-	-	5
Concrete/Brick/Stone	-	-	-	-	-
Wood	2	111	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	1
Bamboo/Sawali/Cogon/Nipa	-	2	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	3
No Walls	-	-	-	-	-
KAPANGAN					
Total	2	66	1	2	12
Concrete/Brick/Stone	-	-	-	-	-
Wood	2	31	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	1	2
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	32	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	1	10
No Walls	-	-	-	-	-
KIBUNGAN					
Total	2	213	-	8	18
Concrete/Brick/Stone	-	-	-	-	-
Wood	1	182	-	3	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	23	-	4	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	-	1	-
Others/Not Reported	-	-	-	-	16
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LA TRINIDAD (Capital)					
Total	49	12	6	45	31
Concrete/Brick/Stone	15	1	-	43	9
Wood	23	2	1	-	1
Half Concrete/Brick/Stone and Half Wood	4	-	-	1	-
Galvanized Iron/Aluminum	6	2	-	-	1
Bamboo/Sawali/Cogon/Nipa	-	6	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	5	-	-
Others/Not Reported	1	-	-	1	20
No Walls	-	-	-	-	-
MANKAYAN					
Total	-	41	2	2	40
Concrete/Brick/Stone	-	-	-	2	6
Wood	-	25	-	-	3
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	2
Galvanized Iron/Aluminum	-	3	-	-	7
Bamboo/Sawali/Cogon/Nipa	-	9	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	2	-	-
Others/Not Reported	-	1	-	-	22
No Walls	-	-	-	-	-
SABLAN					
Total	1	13	-	-	2
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	12	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TUBA					
Total	5	79	-	13	67
Concrete/Brick/Stone	-	-	-	11	14
Wood	3	17	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	4
Galvanized Iron/Aluminum	-	5	-	-	9
Bamboo/Sawali/Cogon/Nipa	2	56	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	2	38
No Walls	-	-	-	-	-
TUBLAY					
Total	-	45	2	2	4
Concrete/Brick/Stone	-	-	-	2	-
Wood	-	26	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	2	-	-	-
Galvanized Iron/Aluminum	-	4	-	-	1
Bamboo/Sawali/Cogon/Nipa	-	13	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	-	-	-	3
No Walls	-	-	-	-	-