

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
DAVAO DEL SUR				
Total	179,568	105,463	404	2,700
Concrete/Brick/Stone	25,428	24,552	302	154
Wood	31,917	27,064	24	198
Half Concrete/Brick/Stone and Half Wood	25,878	22,860	59	1,332
Galvanized Iron/Aluminum	677	420	3	110
Bamboo/Sawali/Cogon/Nipa	94,052	29,916	-	891
Asbestos	86	72	-	1
Glass	9	6	2	-
Makeshift/Salvaged/Improvised Materials	380	174	-	3
Others/Not Reported	1,141	399	14	11
No Walls	-	-	-	-
BANSALAN				
Total	12,035	10,416	140	323
Concrete/Brick/Stone	2,509	2,373	121	12
Wood	3,379	3,089	1	16
Half Concrete/Brick/Stone and Half Wood	2,690	2,426	14	246
Galvanized Iron/Aluminum	109	97	1	6
Bamboo/Sawali/Cogon/Nipa	3,204	2,369	-	42
Asbestos	2	1	-	-
Glass	1	-	1	-
Makeshift/Salvaged/Improvised Materials	27	4	-	1
Others/Not Reported	114	57	2	-
No Walls	-	-	-	-
CITY OF DIGOS (Capital)				
Total	31,914	27,349	144	418
Concrete/Brick/Stone	9,280	9,081	113	59
Wood	7,675	6,857	5	26
Half Concrete/Brick/Stone and Half Wood	6,375	5,966	21	248
Galvanized Iron/Aluminum	100	60	1	19
Bamboo/Sawali/Cogon/Nipa	8,218	5,222	-	64
Asbestos	5	3	-	-
Glass	5	5	-	-
Makeshift/Salvaged/Improvised Materials	111	76	-	-
Others/Not Reported	145	79	4	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
HAGONOY				
Total	10,627	7,805	1	49
Concrete/Brick/Stone	1,697	1,684	1	1
Wood	2,407	2,120	-	6
Half Concrete/Brick/Stone and Half Wood	1,779	1,709	-	22
Galvanized Iron/Aluminum	21	16	-	-
Bamboo/Sawali/Cogon/Nipa	4,672	2,261	-	19
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	13	2	-	-
Others/Not Reported	38	13	-	1
No Walls	-	-	-	-
JOSE ABAD SANTOS (TRINIDAD)				
Total	13,427	631	17	113
Concrete/Brick/Stone	477	268	4	9
Wood	544	127	-	4
Half Concrete/Brick/Stone and Half Wood	622	188	9	76
Galvanized Iron/Aluminum	27	2	-	6
Bamboo/Sawali/Cogon/Nipa	11,665	45	-	16
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	92	1	4	2
No Walls	-	-	-	-
KIBLAWAN				
Total	9,186	4,763	3	51
Concrete/Brick/Stone	270	267	1	-
Wood	2,294	1,925	1	20
Half Concrete/Brick/Stone and Half Wood	706	681	1	17
Galvanized Iron/Aluminum	61	15	-	2
Bamboo/Sawali/Cogon/Nipa	5,810	1,866	-	11
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	25	3	-	1
Others/Not Reported	19	6	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MAGSAYSAY				
Total	10,505	7,791	9	105
Concrete/Brick/Stone	1,458	1,433	2	22
Wood	2,314	2,169	6	27
Half Concrete/Brick/Stone and Half Wood	1,668	1,623	-	21
Galvanized Iron/Aluminum	18	17	-	-
Bamboo/Sawali/Cogon/Nipa	4,937	2,506	-	34
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	76	35	-	1
Others/Not Reported	33	7	1	-
No Walls	-	-	-	-
MALALAG				
Total	7,389	4,844	4	27
Concrete/Brick/Stone	894	873	3	-
Wood	1,131	1,030	-	6
Half Concrete/Brick/Stone and Half Wood	767	745	1	9
Galvanized Iron/Aluminum	10	9	-	-
Bamboo/Sawali/Cogon/Nipa	4,549	2,173	-	12
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	15	1	-	-
Others/Not Reported	22	12	-	-
No Walls	-	-	-	-
MALITA				
Total	22,385	4,946	33	920
Concrete/Brick/Stone	1,318	1,203	29	32
Wood	1,800	931	2	30
Half Concrete/Brick/Stone and Half Wood	2,549	1,574	1	461
Galvanized Iron/Aluminum	75	18	-	29
Bamboo/Sawali/Cogon/Nipa	16,474	1,169	-	366
Asbestos	1	1	-	-
Glass	2	1	1	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	163	49	-	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MATANAO				
Total	10,875	7,852	6	54
Concrete/Brick/Stone	1,572	1,559	5	1
Wood	1,702	1,552	1	10
Half Concrete/Brick/Stone and Half Wood	1,844	1,810	-	12
Galvanized Iron/Aluminum	23	20	-	1
Bamboo/Sawali/Cogon/Nipa	5,609	2,860	-	30
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	78	37	-	-
Others/Not Reported	47	14	-	-
No Walls	-	-	-	-
PADADA				
Total	5,567	4,346	13	35
Concrete/Brick/Stone	949	931	7	3
Wood	1,770	1,516	1	6
Half Concrete/Brick/Stone and Half Wood	1,305	1,236	5	19
Galvanized Iron/Aluminum	15	12	-	-
Bamboo/Sawali/Cogon/Nipa	1,383	594	-	7
Asbestos	53	51	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	2	-	-
Others/Not Reported	86	4	-	-
No Walls	-	-	-	-
SANTA CRUZ				
Total	16,767	13,601	15	196
Concrete/Brick/Stone	3,249	3,217	4	6
Wood	3,874	3,367	5	30
Half Concrete/Brick/Stone and Half Wood	2,646	2,528	4	63
Galvanized Iron/Aluminum	153	117	1	32
Bamboo/Sawali/Cogon/Nipa	6,644	4,262	-	64
Asbestos	17	9	-	1
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	19	10	-	-
Others/Not Reported	164	91	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SANTA MARIA				
Total	10,701	4,222	13	49
Concrete/Brick/Stone	611	594	11	4
Wood	1,262	997	-	8
Half Concrete/Brick/Stone and Half Wood	1,009	896	-	13
Galvanized Iron/Aluminum	21	14	-	2
Bamboo/Sawali/Cogon/Nipa	7,630	1,659	-	20
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	159	55	2	2
No Walls	-	-	-	-
SULOP				
Total	6,585	4,507	2	14
Concrete/Brick/Stone	554	550	-	-
Wood	1,257	1,186	1	-
Half Concrete/Brick/Stone and Half Wood	879	839	1	8
Galvanized Iron/Aluminum	19	14	-	1
Bamboo/Sawali/Cogon/Nipa	3,853	1,909	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	2	-	-
Others/Not Reported	20	7	-	-
No Walls	-	-	-	-
SARANGANI				
Total	4,208	1,663	3	291
Concrete/Brick/Stone	329	327	-	1
Wood	82	63	1	5
Half Concrete/Brick/Stone and Half Wood	542	428	2	93
Galvanized Iron/Aluminum	18	6	-	11
Bamboo/Sawali/Cogon/Nipa	3,218	835	-	179
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	19	4	-	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

DON MARCELINO

Total	7,397	727	1	55
Concrete/Brick/Stone	261	192	1	4
Wood	426	135	-	4
Half Concrete/Brick/Stone and Half Wood	497	211	-	24
Galvanized Iron/Aluminum	7	3	-	1
Bamboo/Sawali/Cogon/Nipa	6,186	186	-	22
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	20	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
DAVAO DEL SUR					
Total	1,750	67,733	224	676	618
Concrete/Brick/Stone	19	377	2	2	20
Wood	741	3,833	18	10	29
Half Concrete/Brick/Stone and Half Wood	83	1,514	7	4	19
Galvanized Iron/Aluminum	63	80	1	-	-
Bamboo/Sawali/Cogon/Nipa	827	61,528	104	641	145
Asbestos	2	-	-	8	3
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	1	112	90	-	-
Others/Not Reported	14	289	2	10	402
No Walls	-	-	-	-	-
BANSALAN					
Total	285	746	26	38	61
Concrete/Brick/Stone	2	-	-	-	1
Wood	252	19	-	-	2
Half Concrete/Brick/Stone and Half Wood	3	1	-	-	-
Galvanized Iron/Aluminum	2	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	26	721	6	33	7
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	20	-	-
Others/Not Reported	-	-	-	4	51
No Walls	-	-	-	-	-
CITY OF DIGOS (Capital)					
Total	464	3,394	65	1	79
Concrete/Brick/Stone	5	11	-	-	11
Wood	259	511	13	1	3
Half Concrete/Brick/Stone and Half Wood	34	97	2	-	7
Galvanized Iron/Aluminum	7	13	-	-	-
Bamboo/Sawali/Cogon/Nipa	155	2,733	33	-	11
Asbestos	2	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	19	16	-	-
Others/Not Reported	2	10	1	-	47
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
HAGONOY					
Total	17	2,727	9	1	18
Concrete/Brick/Stone	1	9	-	1	-
Wood	3	277	-	-	1
Half Concrete/Brick/Stone and Half Wood	2	46	-	-	-
Galvanized Iron/Aluminum	1	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	2,375	6	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	3	-	-
Others/Not Reported	-	8	-	-	16
No Walls	-	-	-	-	-
JOSE ABAD SANTOS (TRINIDAD)					
Total	171	12,419	1	1	74
Concrete/Brick/Stone	5	190	-	-	1
Wood	42	367	-	-	4
Half Concrete/Brick/Stone and Half Wood	4	342	-	1	2
Galvanized Iron/Aluminum	7	11	1	-	-
Bamboo/Sawali/Cogon/Nipa	104	11,486	-	-	14
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	9	23	-	-	53
No Walls	-	-	-	-	-
KIBLAWAN					
Total	97	4,217	28	21	6
Concrete/Brick/Stone	2	-	-	-	-
Wood	28	318	1	1	-
Half Concrete/Brick/Stone and Half Wood	-	6	1	-	-
Galvanized Iron/Aluminum	34	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	33	3,873	6	20	1
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	20	-	-
Others/Not Reported	-	9	-	-	4
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAGSAYSAY					
Total	34	2,364	7	165	30
Concrete/Brick/Stone	-	-	-	-	1
Wood	6	103	-	1	2
Half Concrete/Brick/Stone and Half Wood	2	19	2	-	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	24	2,195	3	164	11
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	37	2	-	-
Others/Not Reported	1	9	-	-	15
No Walls	-	-	-	-	-
MALALAG					
Total	19	2,458	6	18	13
Concrete/Brick/Stone	-	17	-	-	1
Wood	4	91	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	11	-	1	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	2,327	-	17	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	6	-	-
Others/Not Reported	-	3	-	-	7
No Walls	-	-	-	-	-
MALITA					
Total	423	15,667	3	302	91
Concrete/Brick/Stone	1	52	-	-	1
Wood	78	751	1	1	6
Half Concrete/Brick/Stone and Half Wood	31	480	1	-	1
Galvanized Iron/Aluminum	5	23	-	-	-
Bamboo/Sawali/Cogon/Nipa	307	14,295	-	298	39
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	1	64	-	3	44
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MATANAO					
Total	47	2,802	70	11	33
Concrete/Brick/Stone	1	5	-	-	1
Wood	14	122	2	-	1
Half Concrete/Brick/Stone and Half Wood	1	19	1	-	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	31	2,626	47	11	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	22	19	-	-
Others/Not Reported	-	6	1	-	26
No Walls	-	-	-	-	-
PADADA					
Total	24	1,121	-	-	28
Concrete/Brick/Stone	2	6	-	-	-
Wood	12	234	-	-	1
Half Concrete/Brick/Stone and Half Wood	1	44	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	772	-	-	1
Asbestos	-	-	-	-	2
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	-	58	-	-	24
No Walls	-	-	-	-	-
SANTA CRUZ					
Total	50	2,710	5	104	86
Concrete/Brick/Stone	-	21	-	-	1
Wood	23	437	1	6	5
Half Concrete/Brick/Stone and Half Wood	1	43	-	1	6
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	26	2,182	2	86	22
Asbestos	-	-	-	7	-
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	-	7	2	-	-
Others/Not Reported	-	17	-	3	52
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SANTA MARIA					
Total	37	6,338	1	1	40
Concrete/Brick/Stone	-	1	-	-	1
Wood	7	248	-	-	2
Half Concrete/Brick/Stone and Half Wood	1	99	-	-	-
Galvanized Iron/Aluminum	4	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	25	5,922	-	1	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	66	-	-	34
No Walls	-	-	-	-	-
SULOP					
Total	50	1,996	2	2	12
Concrete/Brick/Stone	-	2	2	-	-
Wood	9	61	-	-	-
Half Concrete/Brick/Stone and Half Wood	3	28	-	-	-
Galvanized Iron/Aluminum	3	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	35	1,901	-	2	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	2	-	-	11
No Walls	-	-	-	-	-
SARANGANI					
Total	14	2,229	-	-	8
Concrete/Brick/Stone	-	1	-	-	-
Wood	1	12	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	19	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	2,189	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	7	-	-	5
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

DON MARCELINO

Total	18	6,545	1	11	39
Concrete/Brick/Stone	-	62	-	1	1
Wood	3	282	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	260	-	1	1
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	5,931	1	9	22
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	7	-	-	13
No Walls	-	-	-	-	-