

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ZAMBOANGA DEL NORTE				
Total	182,887	86,307	202	3,301
Concrete/Brick/Stone	23,940	22,761	118	201
Wood	64,602	33,787	32	981
Half Concrete/Brick/Stone and Half Wood	17,922	14,199	32	1,576
Galvanized Iron/Aluminum	653	274	9	68
Bamboo/Sawali/Cogon/Nipa	74,438	14,883	-	468
Asbestos	35	31	-	-
Glass	7	3	-	2
Makeshift/Salvaged/Improvised Materials	476	145	-	1
Others/Not Reported	802	220	11	4
No Walls	12	4	-	-
DAPITAN CITY				
Total	15,284	9,029	47	433
Concrete/Brick/Stone	2,417	2,331	19	30
Wood	6,611	4,122	7	178
Half Concrete/Brick/Stone and Half Wood	1,775	1,419	18	193
Galvanized Iron/Aluminum	30	10	1	9
Bamboo/Sawali/Cogon/Nipa	4,373	1,123	-	22
Asbestos	3	3	-	-
Glass	1	-	-	1
Makeshift/Salvaged/Improvised Materials	31	8	-	-
Others/Not Reported	42	13	2	-
No Walls	1	-	-	-
DIPOLOG CITY (Capital)				
Total	23,114	15,784	50	265
Concrete/Brick/Stone	6,551	6,344	49	15
Wood	8,640	5,472	1	125
Half Concrete/Brick/Stone and Half Wood	3,089	2,755	-	103
Galvanized Iron/Aluminum	67	54	-	4
Bamboo/Sawali/Cogon/Nipa	4,478	1,019	-	16
Asbestos	3	2	-	-
Glass	4	2	-	1
Makeshift/Salvaged/Improvised Materials	123	66	-	-
Others/Not Reported	159	70	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
KATIPUNAN				
Total	8,511	3,025	6	189
Concrete/Brick/Stone	984	887	4	7
Wood	1,457	641	-	48
Half Concrete/Brick/Stone and Half Wood	726	536	-	51
Galvanized Iron/Aluminum	100	10	2	7
Bamboo/Sawali/Cogon/Nipa	5,225	944	-	76
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	6	-	-
Others/Not Reported	9	-	-	-
No Walls	-	-	-	-
LA LIBERTAD				
Total	1,739	1,106	4	147
Concrete/Brick/Stone	153	148	2	3
Wood	689	528	1	31
Half Concrete/Brick/Stone and Half Wood	346	266	-	73
Galvanized Iron/Aluminum	7	3	-	3
Bamboo/Sawali/Cogon/Nipa	524	153	-	37
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	20	8	1	-
No Walls	-	-	-	-
LABASON				
Total	7,849	3,051	7	54
Concrete/Brick/Stone	1,121	1,050	1	4
Wood	3,100	1,197	1	15
Half Concrete/Brick/Stone and Half Wood	973	698	2	31
Galvanized Iron/Aluminum	6	3	3	-
Bamboo/Sawali/Cogon/Nipa	2,603	94	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	2	-	-
Others/Not Reported	35	5	-	-
No Walls	5	2	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
LILOY				
Total	7,839	4,097	7	42
Concrete/Brick/Stone	1,344	1,180	4	7
Wood	2,495	1,468	2	6
Half Concrete/Brick/Stone and Half Wood	1,215	975	-	21
Galvanized Iron/Aluminum	31	25	-	1
Bamboo/Sawali/Cogon/Nipa	2,738	444	-	7
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	15	5	1	-
No Walls	-	-	-	-
MANUKAN				
Total	6,400	2,906	1	35
Concrete/Brick/Stone	1,026	926	-	3
Wood	1,051	465	-	10
Half Concrete/Brick/Stone and Half Wood	574	424	-	9
Galvanized Iron/Aluminum	18	12	-	2
Bamboo/Sawali/Cogon/Nipa	3,701	1,070	-	11
Asbestos	1	1	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	4	1	-	-
Others/Not Reported	24	6	1	-
No Walls	-	-	-	-
MUTIA				
Total	2,277	1,778	2	22
Concrete/Brick/Stone	225	220	1	2
Wood	1,382	1,186	-	2
Half Concrete/Brick/Stone and Half Wood	250	228	-	16
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	397	132	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	13	8	-	1
Others/Not Reported	10	4	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
PIÑAN (NEW PIÑAN)				
Total	3,772	2,453	-	7
Concrete/Brick/Stone	624	619	-	-
Wood	1,196	1,021	-	-
Half Concrete/Brick/Stone and Half Wood	281	271	-	2
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	1,643	525	-	5
Asbestos	9	9	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	3	-	-
Others/Not Reported	13	2	-	-
No Walls	-	-	-	-
POLANCO				
Total	7,810	4,605	5	369
Concrete/Brick/Stone	1,503	1,449	3	33
Wood	1,922	1,397	-	107
Half Concrete/Brick/Stone and Half Wood	885	708	1	123
Galvanized Iron/Aluminum	17	14	-	2
Bamboo/Sawali/Cogon/Nipa	3,385	994	-	103
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	48	25	-	-
Others/Not Reported	47	18	1	1
No Walls	3	-	-	-
PRES. MANUEL A. ROXAS				
Total	6,762	2,698	10	52
Concrete/Brick/Stone	685	619	8	5
Wood	829	545	2	2
Half Concrete/Brick/Stone and Half Wood	462	351	-	23
Galvanized Iron/Aluminum	7	5	-	1
Bamboo/Sawali/Cogon/Nipa	4,690	1,166	-	21
Asbestos	1	-	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	28	3	-	-
Others/Not Reported	59	9	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
RIZAL				
Total	3,158	1,919	2	41
Concrete/Brick/Stone	541	533	1	2
Wood	1,479	913	1	16
Half Concrete/Brick/Stone and Half Wood	362	317	-	20
Galvanized Iron/Aluminum	4	1	-	2
Bamboo/Sawali/Cogon/Nipa	762	150	-	1
Asbestos	3	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	7	2	-	-
No Walls	-	-	-	-
SALUG				
Total	5,845	2,742	10	283
Concrete/Brick/Stone	520	485	5	7
Wood	1,532	1,078	2	14
Half Concrete/Brick/Stone and Half Wood	844	482	3	254
Galvanized Iron/Aluminum	119	6	-	1
Bamboo/Sawali/Cogon/Nipa	2,790	689	-	7
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	28	-	-	-
Others/Not Reported	11	1	-	-
No Walls	-	-	-	-
SERGIO OSMEÑA SR.				
Total	5,584	3,768	2	7
Concrete/Brick/Stone	371	370	1	-
Wood	2,115	1,861	1	6
Half Concrete/Brick/Stone and Half Wood	379	375	-	-
Galvanized Iron/Aluminum	4	3	-	-
Bamboo/Sawali/Cogon/Nipa	2,706	1,156	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	2	-	-
Others/Not Reported	7	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SIAYAN				
Total	6,644	1,294	1	9
Concrete/Brick/Stone	154	154	-	-
Wood	1,118	541	1	5
Half Concrete/Brick/Stone and Half Wood	152	146	-	3
Galvanized Iron/Aluminum	29	5	-	-
Bamboo/Sawali/Cogon/Nipa	5,168	447	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	23	1	-	-
No Walls	-	-	-	-
SIBUCO				
Total	5,184	1,097	5	259
Concrete/Brick/Stone	269	256	2	3
Wood	2,313	537	1	15
Half Concrete/Brick/Stone and Half Wood	564	273	1	227
Galvanized Iron/Aluminum	18	-	1	7
Bamboo/Sawali/Cogon/Nipa	1,995	28	-	7
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	25	3	-	-
No Walls	-	-	-	-
SIBUTAD				
Total	3,651	1,783	2	70
Concrete/Brick/Stone	402	387	2	4
Wood	1,454	816	-	17
Half Concrete/Brick/Stone and Half Wood	436	350	-	23
Galvanized Iron/Aluminum	38	30	-	6
Bamboo/Sawali/Cogon/Nipa	1,299	196	-	20
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	3	-	-
Others/Not Reported	13	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SINDANGAN				
Total	17,587	9,137	15	364
Concrete/Brick/Stone	2,487	2,402	2	40
Wood	4,446	2,978	8	165
Half Concrete/Brick/Stone and Half Wood	1,487	1,268	1	106
Galvanized Iron/Aluminum	37	15	-	4
Bamboo/Sawali/Cogon/Nipa	8,998	2,423	-	49
Asbestos	3	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	16	7	-	-
Others/Not Reported	111	41	4	-
No Walls	2	1	-	-
SIOCON				
Total	7,889	1,569	4	154
Concrete/Brick/Stone	658	597	2	15
Wood	5,333	715	1	47
Half Concrete/Brick/Stone and Half Wood	385	211	1	83
Galvanized Iron/Aluminum	42	30	-	7
Bamboo/Sawali/Cogon/Nipa	1,450	15	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	21	1	-	-
No Walls	-	-	-	-
SIRAWAI				
Total	4,946	565	2	124
Concrete/Brick/Stone	69	66	-	1
Wood	2,064	261	2	47
Half Concrete/Brick/Stone and Half Wood	327	227	-	47
Galvanized Iron/Aluminum	17	7	-	7
Bamboo/Sawali/Cogon/Nipa	2,391	4	-	22
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	62	-	-	-
Others/Not Reported	16	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
TAMPILISAN				
Total	4,559	2,680	3	12
Concrete/Brick/Stone	503	500	1	-
Wood	1,601	1,315	1	1
Half Concrete/Brick/Stone and Half Wood	472	458	-	4
Galvanized Iron/Aluminum	8	7	1	-
Bamboo/Sawali/Cogon/Nipa	1,955	388	-	7
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	4	-	-
Others/Not Reported	10	7	-	-
No Walls	1	1	-	-
JOSE DALMAN (PONOT)				
Total	5,094	1,766	1	151
Concrete/Brick/Stone	157	152	-	3
Wood	1,413	739	-	78
Half Concrete/Brick/Stone and Half Wood	393	324	-	53
Galvanized Iron/Aluminum	9	3	1	2
Bamboo/Sawali/Cogon/Nipa	3,118	547	-	15
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	3	-	-	-
No Walls	-	-	-	-
GUTALAC				
Total	6,052	1,567	5	26
Concrete/Brick/Stone	387	343	3	3
Wood	2,674	786	-	10
Half Concrete/Brick/Stone and Half Wood	539	359	2	9
Galvanized Iron/Aluminum	6	1	-	-
Bamboo/Sawali/Cogon/Nipa	2,353	76	-	4
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	54	-	-	-
Others/Not Reported	38	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BALIGUIAN				
Total	3,711	357	6	119
Concrete/Brick/Stone	75	58	5	7
Wood	3,031	169	-	26
Half Concrete/Brick/Stone and Half Wood	275	126	1	81
Galvanized Iron/Aluminum	4	-	-	2
Bamboo/Sawali/Cogon/Nipa	303	2	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	23	2	-	2
No Walls	-	-	-	-
GODOD				
Total	3,259	1,842	1	8
Concrete/Brick/Stone	77	72	1	2
Wood	1,546	1,213	-	1
Half Concrete/Brick/Stone and Half Wood	121	114	-	5
Galvanized Iron/Aluminum	19	19	-	-
Bamboo/Sawali/Cogon/Nipa	1,447	405	-	-
Asbestos	8	8	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	14	7	-	-
Others/Not Reported	27	4	-	-
No Walls	-	-	-	-
BACUNGAN (LEON T. POSTIGO)				
Total	4,223	1,916	2	57
Concrete/Brick/Stone	384	365	1	5
Wood	1,289	819	-	9
Half Concrete/Brick/Stone and Half Wood	294	238	1	16
Galvanized Iron/Aluminum	8	6	-	1
Bamboo/Sawali/Cogon/Nipa	2,213	476	-	26
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	13	-	-	-
Others/Not Reported	22	12	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

KALAWIT

Total	4,144	1,773	2	2
Concrete/Brick/Stone	253	248	1	-
Wood	1,822	1,004	-	-
Half Concrete/Brick/Stone and Half Wood	316	300	1	-
Galvanized Iron/Aluminum	5	2	-	-
Bamboo/Sawali/Cogon/Nipa	1,733	217	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	12	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ZAMBOANGA DEL NORTE					
Total	1,660	90,329	223	470	395
Concrete/Brick/Stone	24	750	5	63	18
Wood	548	29,038	60	123	33
Half Concrete/Brick/Stone and Half Wood	73	1,994	21	15	12
Galvanized Iron/Aluminum	190	88	-	24	-
Bamboo/Sawali/Cogon/Nipa	815	57,945	69	192	66
Asbestos	1	-	-	3	-
Glass	-	-	-	1	1
Makeshift/Salvaged/Improvised Materials	5	255	67	3	-
Others/Not Reported	4	251	1	46	265
No Walls	-	8	-	-	-
DAPITAN CITY					
Total	97	5,599	15	36	28
Concrete/Brick/Stone	-	27	-	8	2
Wood	33	2,253	4	8	6
Half Concrete/Brick/Stone and Half Wood	4	133	3	2	3
Galvanized Iron/Aluminum	6	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	54	3,158	4	10	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	18	4	1	-
Others/Not Reported	-	5	-	7	15
No Walls	-	1	-	-	-
DIPOLOG CITY (Capital)					
Total	56	6,797	15	96	51
Concrete/Brick/Stone	4	90	3	37	9
Wood	29	2,972	3	35	3
Half Concrete/Brick/Stone and Half Wood	6	220	1	3	1
Galvanized Iron/Aluminum	1	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	3,409	-	13	5
Asbestos	-	-	-	1	-
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	-	49	8	-	-
Others/Not Reported	-	49	-	6	33
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
KATIPUNAN					
Total	340	4,881	2	51	17
Concrete/Brick/Stone	-	85	-	-	1
Wood	75	692	1	-	-
Half Concrete/Brick/Stone and Half Wood	12	123	-	3	1
Galvanized Iron/Aluminum	53	4	-	24	-
Bamboo/Sawali/Cogon/Nipa	200	3,972	-	24	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	-	3	-	-	6
No Walls	-	-	-	-	-
LA LIBERTAD					
Total	4	465	-	8	5
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	125	-	4	-
Half Concrete/Brick/Stone and Half Wood	-	7	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	325	-	2	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	7	-	2	2
No Walls	-	-	-	-	-
LABASON					
Total	31	4,668	6	19	13
Concrete/Brick/Stone	-	66	-	-	-
Wood	14	1,859	2	11	1
Half Concrete/Brick/Stone and Half Wood	1	239	2	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	2,479	-	7	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	2	-	-
Others/Not Reported	-	20	-	1	9
No Walls	-	3	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
LILOY					
Total	113	3,564	-	1	15
Concrete/Brick/Stone	-	153	-	-	-
Wood	74	943	-	-	2
Half Concrete/Brick/Stone and Half Wood	3	213	-	1	2
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	36	2,248	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	1	-	-	8
No Walls	-	-	-	-	-
MANUKAN					
Total	132	3,311	-	7	8
Concrete/Brick/Stone	2	87	-	7	1
Wood	14	561	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	141	-	-	-
Galvanized Iron/Aluminum	2	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	114	2,506	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	11	-	-	6
No Walls	-	-	-	-	-
MUTIA					
Total	15	448	5	-	7
Concrete/Brick/Stone	-	2	-	-	-
Wood	8	186	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	5	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	255	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	4	-	-
Others/Not Reported	-	-	-	-	5
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PIÑAN (NEW PIÑAN)					
Total	3	1,298	-	1	10
Concrete/Brick/Stone	-	4	-	1	-
Wood	-	175	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	8	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	1,110	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	10
No Walls	-	-	-	-	-
POLANCO					
Total	6	2,786	20	3	16
Concrete/Brick/Stone	-	14	2	1	1
Wood	3	412	3	-	-
Half Concrete/Brick/Stone and Half Wood	-	51	2	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	2,274	6	1	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	7	-	-
Others/Not Reported	-	15	-	1	11
No Walls	-	3	-	-	-
PRES. MANUEL A. ROXAS					
Total	36	3,906	9	16	35
Concrete/Brick/Stone	1	50	-	2	-
Wood	13	264	-	3	-
Half Concrete/Brick/Stone and Half Wood	1	85	-	-	2
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	21	3,468	3	3	8
Asbestos	-	-	-	1	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	19	6	-	-
Others/Not Reported	-	19	-	7	24
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
RIZAL					
Total	7	1,184	-	-	5
Concrete/Brick/Stone	-	5	-	-	-
Wood	3	546	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	25	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	607	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	5
No Walls	-	-	-	-	-
SALUG					
Total	152	2,639	10	-	9
Concrete/Brick/Stone	-	23	-	-	-
Wood	20	417	-	-	1
Half Concrete/Brick/Stone and Half Wood	6	98	1	-	-
Galvanized Iron/Aluminum	109	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	2,071	5	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	24	4	-	-
Others/Not Reported	-	3	-	-	7
No Walls	-	-	-	-	-
SERGIO OSMEÑA SR.					
Total	36	1,751	2	12	6
Concrete/Brick/Stone	-	-	-	-	-
Wood	15	223	1	7	1
Half Concrete/Brick/Stone and Half Wood	-	4	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	21	1,522	1	5	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	5
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SIAYAN					
Total	34	5,282	1	1	22
Concrete/Brick/Stone	-	-	-	-	-
Wood	7	564	-	-	-
Half Concrete/Brick/Stone and Half Wood	3	-	-	-	-
Galvanized Iron/Aluminum	13	11	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	4,700	1	1	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	7	-	-	14
No Walls	-	-	-	-	-
SIBUCO					
Total	57	3,742	-	2	22
Concrete/Brick/Stone	-	8	-	-	-
Wood	19	1,739	-	2	-
Half Concrete/Brick/Stone and Half Wood	3	60	-	-	-
Galvanized Iron/Aluminum	2	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	32	1,925	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	2	-	-	19
No Walls	-	-	-	-	-
SIBUTAD					
Total	89	1,675	14	6	12
Concrete/Brick/Stone	1	8	-	-	-
Wood	2	606	8	4	1
Half Concrete/Brick/Stone and Half Wood	15	48	-	-	-
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	70	1,006	4	2	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	2	-	-
Others/Not Reported	-	2	-	-	10
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SINDANGAN					
Total	56	7,730	76	184	25
Concrete/Brick/Stone	13	23	-	5	2
Wood	11	1,209	29	44	2
Half Concrete/Brick/Stone and Half Wood	4	94	9	5	-
Galvanized Iron/Aluminum	1	17	-	-	-
Bamboo/Sawali/Cogon/Nipa	26	6,353	36	106	5
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	4	2	2	-
Others/Not Reported	-	29	-	21	16
No Walls	-	1	-	-	-
SIOCON					
Total	61	6,073	-	3	25
Concrete/Brick/Stone	2	39	-	2	1
Wood	38	4,520	-	1	11
Half Concrete/Brick/Stone and Half Wood	6	83	-	-	1
Galvanized Iron/Aluminum	1	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	1,415	-	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	12	-	-	8
No Walls	-	-	-	-	-
SIRAWAI					
Total	109	4,099	36	2	9
Concrete/Brick/Stone	-	2	-	-	-
Wood	25	1,723	4	2	-
Half Concrete/Brick/Stone and Half Wood	3	47	3	-	-
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	80	2,280	5	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	38	24	-	-
Others/Not Reported	-	7	-	-	9
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/ Others	Not Reported
TAMPILISAN					
Total	7	1,854	3	-	-
Concrete/Brick/Stone	-	2	-	-	-
Wood	4	278	2	-	-
Half Concrete/Brick/Stone and Half Wood	-	10	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	1,557	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	1	-	-
Others/Not Reported	-	3	-	-	-
No Walls	-	-	-	-	-
JOSE DALMAN (PONOT)					
Total	15	3,156	1	-	4
Concrete/Brick/Stone	-	2	-	-	-
Wood	5	591	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	16	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	2,543	1	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	2
No Walls	-	-	-	-	-
GUTALAC					
Total	28	4,419	1	4	2
Concrete/Brick/Stone	1	37	-	-	-
Wood	14	1,863	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	169	-	-	-
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	2,258	1	2	-
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	54	-	-	-
Others/Not Reported	-	33	-	1	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BALIGUIAN					
Total	31	3,193	-	-	5
Concrete/Brick/Stone	-	5	-	-	-
Wood	23	2,813	-	-	-
Half Concrete/Brick/Stone and Half Wood	3	64	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	297	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	2	12	-	-	5
No Walls	-	-	-	-	-
GODOD					
Total	113	1,259	4	9	23
Concrete/Brick/Stone	-	1	-	-	1
Wood	84	245	1	1	1
Half Concrete/Brick/Stone and Half Wood	-	1	-	1	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	27	1,006	1	7	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	4	1	-	-
Others/Not Reported	-	2	1	-	20
No Walls	-	-	-	-	-
BACUNGAN (LEON T. POSTIGO)					
Total	25	2,204	3	9	7
Concrete/Brick/Stone	-	13	-	-	-
Wood	12	446	2	-	1
Half Concrete/Brick/Stone and Half Wood	3	36	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,693	-	9	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	10	1	-	-
Others/Not Reported	-	5	-	-	5
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
KALAWIT					
Total	7	2,346	-	-	14
Concrete/Brick/Stone	-	4	-	-	-
Wood	3	813	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	14	-	-	1
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	1,508	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	1	-	-	9
No Walls	-	-	-	-	-