

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
BILIRAN				
Total	31,866	19,547	55	1,603
Concrete/Brick/Stone	9,292	8,917	42	75
Wood	9,701	5,619	7	361
Half Concrete/Brick/Stone and Half Wood	5,334	3,769	4	962
Galvanized Iron/Aluminum	90	57	-	16
Bamboo/Sawali/Cogon/Nipa	7,108	1,131	-	174
Asbestos	2	2	-	-
Glass	3	3	-	-
Makeshift/Salvaged/Improvised Materials	84	10	-	8
Others/Not Reported	251	39	2	7
No Walls	1	-	-	-
ALMERIA				
Total	3,309	2,521	8	13
Concrete/Brick/Stone	1,121	1,084	7	6
Wood	1,357	999	1	4
Half Concrete/Brick/Stone and Half Wood	395	366	-	3
Galvanized Iron/Aluminum	3	2	-	-
Bamboo/Sawali/Cogon/Nipa	402	61	-	-
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	8	1	-	-
Others/Not Reported	22	7	-	-
No Walls	-	-	-	-
BILIRAN				
Total	3,124	1,797	6	344
Concrete/Brick/Stone	765	738	3	13
Wood	874	562	3	52
Half Concrete/Brick/Stone and Half Wood	585	302	-	222
Galvanized Iron/Aluminum	7	5	-	1
Bamboo/Sawali/Cogon/Nipa	842	183	-	52
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	3	-	1
Others/Not Reported	44	3	-	3
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
CABUCGAYAN				
Total	3,954	1,949	-	429
Concrete/Brick/Stone	870	839	-	5
Wood	615	368	-	107
Half Concrete/Brick/Stone and Half Wood	792	447	-	271
Galvanized Iron/Aluminum	34	23	-	6
Bamboo/Sawali/Cogon/Nipa	1,613	270	-	39
Asbestos	-	-	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	27	-	-	1
No Walls	1	-	-	-
CAIBIRAN				
Total	3,989	2,314	6	403
Concrete/Brick/Stone	1,129	1,075	2	35
Wood	1,357	763	2	99
Half Concrete/Brick/Stone and Half Wood	655	392	-	215
Galvanized Iron/Aluminum	15	6	-	5
Bamboo/Sawali/Cogon/Nipa	802	75	-	46
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	1	-	2
Others/Not Reported	21	2	2	1
No Walls	-	-	-	-
CULABA				
Total	2,324	1,314	1	91
Concrete/Brick/Stone	609	582	1	4
Wood	821	365	-	18
Half Concrete/Brick/Stone and Half Wood	444	314	-	60
Galvanized Iron/Aluminum	5	5	-	-
Bamboo/Sawali/Cogon/Nipa	400	47	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	28	1	-	5
Others/Not Reported	17	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
KAWAYAN				
Total	4,181	2,859	8	71
Concrete/Brick/Stone	1,355	1,310	8	1
Wood	1,333	803	-	27
Half Concrete/Brick/Stone and Half Wood	780	660	-	40
Galvanized Iron/Aluminum	11	7	-	2
Bamboo/Sawali/Cogon/Nipa	688	77	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	1	-	-
Others/Not Reported	7	1	-	-
No Walls	-	-	-	-
MARIPIPI				
Total	1,546	800	7	9
Concrete/Brick/Stone	416	384	7	4
Wood	549	200	-	1
Half Concrete/Brick/Stone and Half Wood	214	180	-	1
Galvanized Iron/Aluminum	4	2	-	-
Bamboo/Sawali/Cogon/Nipa	295	15	-	1
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	67	18	-	2
No Walls	-	-	-	-
NAVAL (Capital)				
Total	9,439	5,993	19	243
Concrete/Brick/Stone	3,027	2,905	14	7
Wood	2,795	1,559	1	53
Half Concrete/Brick/Stone and Half Wood	1,469	1,108	4	150
Galvanized Iron/Aluminum	11	7	-	2
Bamboo/Sawali/Cogon/Nipa	2,066	403	-	31
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	25	3	-	-
Others/Not Reported	46	8	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>BILIRAN</b>					
Total	175	10,169	41	112	164
Concrete/Brick/Stone	9	234	1	8	6
Wood	72	3,591	6	33	12
Half Concrete/Brick/Stone and Half Wood	42	533	3	8	13
Galvanized Iron/Aluminum	3	14	-	-	-
Bamboo/Sawali/Cogon/Nipa	47	5,684	10	44	18
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	44	21	-	-
Others/Not Reported	1	68	-	19	115
No Walls	-	1	-	-	-
<b>ALMERIA</b>					
Total	6	699	3	51	8
Concrete/Brick/Stone	-	24	-	-	-
Wood	2	334	-	14	3
Half Concrete/Brick/Stone and Half Wood	3	23	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	309	2	28	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	1	-	-
Others/Not Reported	-	2	-	9	4
No Walls	-	-	-	-	-
<b>BILIRAN</b>					
Total	7	916	1	2	51
Concrete/Brick/Stone	-	9	-	-	2
Wood	5	249	-	-	3
Half Concrete/Brick/Stone and Half Wood	-	50	-	1	10
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	602	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	4	-	1	33
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CABUCGAYAN</b>					
Total	39	1,513	-	-	24
Concrete/Brick/Stone	2	24	-	-	-
Wood	4	136	-	-	-
Half Concrete/Brick/Stone and Half Wood	16	58	-	-	-
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	1,284	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	5	-	-	21
No Walls	-	1	-	-	-
<b>CAIBIRAN</b>					
Total	15	1,222	2	14	13
Concrete/Brick/Stone	1	16	-	-	-
Wood	8	475	1	9	-
Half Concrete/Brick/Stone and Half Wood	2	46	-	-	-
Galvanized Iron/Aluminum	2	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	673	-	3	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	1	-	-
Others/Not Reported	-	4	-	2	10
No Walls	-	-	-	-	-
<b>CULABA</b>					
Total	7	876	15	2	18
Concrete/Brick/Stone	-	22	-	-	-
Wood	2	433	-	2	1
Half Concrete/Brick/Stone and Half Wood	2	66	2	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	344	2	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	11	11	-	-
Others/Not Reported	-	-	-	-	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>KAWAYAN</b>					
Total	17	1,199	5	14	8
Concrete/Brick/Stone	-	33	-	3	-
Wood	11	487	1	3	1
Half Concrete/Brick/Stone and Half Wood	2	72	-	5	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	601	1	3	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	3	-	-
Others/Not Reported	-	1	-	-	5
No Walls	-	-	-	-	-
<b>MARIPIPI</b>					
Total	3	715	-	3	9
Concrete/Brick/Stone	-	18	-	1	2
Wood	-	348	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	31	-	-	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	277	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	39	-	2	6
No Walls	-	-	-	-	-
<b>NAVAL (Capital)</b>					
Total	81	3,029	15	26	33
Concrete/Brick/Stone	6	88	1	4	2
Wood	40	1,129	4	5	4
Half Concrete/Brick/Stone and Half Wood	16	187	1	2	1
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	1,594	5	10	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	17	4	-	-
Others/Not Reported	1	13	-	5	19
No Walls	-	-	-	-	-