

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

COMPOSTELLA VALLEY

Total	132,715	106,815	265	2,963
Concrete/Brick/Stone	17,452	17,148	136	52
Wood	61,551	50,508	77	1,403
Half Concrete/Brick/Stone and Half Wood	19,497	18,030	35	905
Galvanized Iron/Aluminum	875	400	2	47
Bamboo/Sawali/Cogon/Nipa	30,927	19,754	-	526
Asbestos	92	86	-	1
Glass	6	5	-	-
Makeshift/Salvaged/Improvised Materials	693	231	-	11
Others/Not Reported	1,622	653	15	18
No Walls	-	-	-	-

COMPOSTELA

Total	14,493	12,692	27	40
Concrete/Brick/Stone	2,650	2,634	8	2
Wood	6,013	5,114	12	16
Half Concrete/Brick/Stone and Half Wood	2,233	2,200	3	11
Galvanized Iron/Aluminum	45	35	-	3
Bamboo/Sawali/Cogon/Nipa	3,300	2,588	-	7
Asbestos	72	72	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	18	11	-	-
Others/Not Reported	162	38	4	1
No Walls	-	-	-	-

LAAK (SAN VICENTE)

Total	13,768	8,986	20	1,084
Concrete/Brick/Stone	482	438	6	27
Wood	9,134	6,440	10	735
Half Concrete/Brick/Stone and Half Wood	648	565	1	71
Galvanized Iron/Aluminum	31	5	-	13
Bamboo/Sawali/Cogon/Nipa	3,375	1,506	-	232
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	9	-	1
Others/Not Reported	81	23	3	5
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
MABINI (DOÑA ALICIA)				
Total	7,338	5,298	25	52
Concrete/Brick/Stone	1,028	989	19	2
Wood	3,299	2,225	1	15
Half Concrete/Brick/Stone and Half Wood	1,283	1,194	5	31
Galvanized Iron/Aluminum	27	15	-	1
Bamboo/Sawali/Cogon/Nipa	1,531	781	-	2
Asbestos	1	1	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	7	4	-	-
Others/Not Reported	161	89	-	1
No Walls	-	-	-	-
MACO				
Total	14,189	11,424	66	358
Concrete/Brick/Stone	2,055	1,965	58	3
Wood	5,561	4,770	3	56
Half Concrete/Brick/Stone and Half Wood	2,380	2,098	5	192
Galvanized Iron/Aluminum	62	30	-	1
Bamboo/Sawali/Cogon/Nipa	3,881	2,426	-	100
Asbestos	3	-	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	50	42	-	1
Others/Not Reported	197	93	-	4
No Walls	-	-	-	-
MARAGUSAN (SAN MARIANO)				
Total	10,293	9,209	4	78
Concrete/Brick/Stone	1,479	1,470	2	1
Wood	5,027	4,525	2	56
Half Concrete/Brick/Stone and Half Wood	1,836	1,809	-	19
Galvanized Iron/Aluminum	7	6	-	-
Bamboo/Sawali/Cogon/Nipa	1,557	1,371	-	1
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	286	7	-	-
Others/Not Reported	100	20	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
MAWAB				
Total	7,404	7,005	1	36
Concrete/Brick/Stone	1,471	1,463	-	3
Wood	2,387	2,340	-	7
Half Concrete/Brick/Stone and Half Wood	1,354	1,330	-	18
Galvanized Iron/Aluminum	36	35	-	-
Bamboo/Sawali/Cogon/Nipa	2,024	1,771	-	6
Asbestos	6	6	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	123	59	1	2
No Walls	-	-	-	-
MONKAYO				
Total	19,757	15,702	28	376
Concrete/Brick/Stone	2,112	2,100	7	4
Wood	11,039	9,456	15	91
Half Concrete/Brick/Stone and Half Wood	2,220	1,937	4	227
Galvanized Iron/Aluminum	100	82	1	10
Bamboo/Sawali/Cogon/Nipa	3,800	1,857	-	43
Asbestos	2	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	154	93	-	-
Others/Not Reported	330	177	1	1
No Walls	-	-	-	-
MONTEVISTA				
Total	7,444	6,458	7	12
Concrete/Brick/Stone	861	857	1	1
Wood	3,458	3,156	4	5
Half Concrete/Brick/Stone and Half Wood	913	900	-	1
Galvanized Iron/Aluminum	9	8	-	-
Bamboo/Sawali/Cogon/Nipa	2,136	1,526	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	65	11	2	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
NABUNTURAN (Capital)				
Total	14,498	13,718	30	70
Concrete/Brick/Stone	2,929	2,902	16	3
Wood	4,018	3,901	2	17
Half Concrete/Brick/Stone and Half Wood	3,126	3,074	8	37
Galvanized Iron/Aluminum	146	143	-	2
Bamboo/Sawali/Cogon/Nipa	4,067	3,566	-	9
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	18	13	-	-
Others/Not Reported	189	114	4	2
No Walls	-	-	-	-
NEW BATAAN				
Total	8,750	7,022	10	722
Concrete/Brick/Stone	722	714	1	6
Wood	4,858	4,007	5	367
Half Concrete/Brick/Stone and Half Wood	1,657	1,404	4	242
Galvanized Iron/Aluminum	31	21	-	7
Bamboo/Sawali/Cogon/Nipa	1,340	859	-	91
Asbestos	-	-	-	-
Glass	5	5	-	-
Makeshift/Salvaged/Improvised Materials	15	-	-	9
Others/Not Reported	122	12	-	-
No Walls	-	-	-	-
PANTUKAN				
Total	14,781	9,301	47	135
Concrete/Brick/Stone	1,663	1,616	18	-
Wood	6,757	4,574	23	38
Half Concrete/Brick/Stone and Half Wood	1,847	1,519	5	56
Galvanized Iron/Aluminum	381	20	1	10
Bamboo/Sawali/Cogon/Nipa	3,916	1,503	-	30
Asbestos	2	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	123	51	-	-
Others/Not Reported	92	17	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
COMPOSTELLA VALLEY					
Total	6,117	14,390	963	283	919
Concrete/Brick/Stone	21	45	24	8	18
Wood	4,295	4,717	369	104	78
Half Concrete/Brick/Stone and Half Wood	177	274	55	2	19
Galvanized Iron/Aluminum	402	21	2	-	1
Bamboo/Sawali/Cogon/Nipa	1,193	9,152	117	135	50
Asbestos	3	-	-	2	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	4	44	394	7	2
Others/Not Reported	22	137	2	25	750
No Walls	-	-	-	-	-
COMPOSTELA					
Total	293	1,298	8	8	127
Concrete/Brick/Stone	1	5	-	-	-
Wood	244	612	1	6	8
Half Concrete/Brick/Stone and Half Wood	2	16	-	-	1
Galvanized Iron/Aluminum	4	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	42	654	2	1	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	5	-	-
Others/Not Reported	-	6	-	1	112
No Walls	-	-	-	-	-
LAAK (SAN VICENTE)					
Total	1,626	1,986	7	8	51
Concrete/Brick/Stone	8	1	1	-	1
Wood	1,307	630	1	4	7
Half Concrete/Brick/Stone and Half Wood	10	1	-	-	-
Galvanized Iron/Aluminum	9	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	284	1,345	1	3	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	2	4	-	-
Others/Not Reported	7	3	-	1	39
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MABINI (DOÑA ALICIA)					
Total	841	1,068	5	2	47
Concrete/Brick/Stone	2	9	1	2	4
Wood	721	332	-	-	5
Half Concrete/Brick/Stone and Half Wood	28	24	-	-	1
Galvanized Iron/Aluminum	11	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	76	669	1	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	1	2	-	-
Others/Not Reported	3	33	1	-	34
No Walls	-	-	-	-	-
MACO					
Total	590	1,273	317	53	108
Concrete/Brick/Stone	4	3	19	-	3
Wood	270	202	208	45	7
Half Concrete/Brick/Stone and Half Wood	14	17	52	-	2
Galvanized Iron/Aluminum	31	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	266	1,043	32	7	7
Asbestos	2	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	5	-	-
Others/Not Reported	3	6	1	1	89
No Walls	-	-	-	-	-
MARAGUSAN (SAN MARIANO)					
Total	495	55	334	17	101
Concrete/Brick/Stone	-	-	2	-	4
Wood	410	13	13	3	5
Half Concrete/Brick/Stone and Half Wood	5	-	1	-	2
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	79	41	40	13	12
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	278	-	1
Others/Not Reported	-	1	-	1	77
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAWAB					
Total	13	288	-	1	60
Concrete/Brick/Stone	1	1	-	1	2
Wood	3	35	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	2	-	-	4
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	238	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	9	-	-	52
No Walls	-	-	-	-	-
MONKAYO					
Total	410	2,875	188	61	117
Concrete/Brick/Stone	-	1	-	-	-
Wood	321	972	118	37	29
Half Concrete/Brick/Stone and Half Wood	7	39	2	-	4
Galvanized Iron/Aluminum	1	4	2	-	-
Bamboo/Sawali/Cogon/Nipa	81	1,782	28	3	6
Asbestos	-	-	-	2	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	15	38	7	1
Others/Not Reported	-	62	-	12	77
No Walls	-	-	-	-	-
MONTEVISTA					
Total	353	553	4	12	45
Concrete/Brick/Stone	-	-	-	2	-
Wood	187	101	1	2	2
Half Concrete/Brick/Stone and Half Wood	5	7	-	-	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	157	441	1	4	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	3	4	-	4	41
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
NABUNTURAN (Capital)					
Total	60	514	19	22	65
Concrete/Brick/Stone	3	1	-	3	1
Wood	23	64	8	1	2
Half Concrete/Brick/Stone and Half Wood	1	4	-	1	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	28	437	6	13	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	5	-	-
Others/Not Reported	5	7	-	4	53
No Walls	-	-	-	-	-
NEW BATAAN					
Total	534	234	8	98	122
Concrete/Brick/Stone	-	-	-	-	1
Wood	417	48	1	6	7
Half Concrete/Brick/Stone and Half Wood	2	1	-	-	4
Galvanized Iron/Aluminum	3	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	108	185	4	91	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	-	3	-	-
Others/Not Reported	1	-	-	1	108
No Walls	-	-	-	-	-
PANTUKAN					
Total	902	4,246	73	1	76
Concrete/Brick/Stone	2	24	1	-	2
Wood	392	1,708	18	-	4
Half Concrete/Brick/Stone and Half Wood	103	163	-	1	-
Galvanized Iron/Aluminum	341	8	-	-	1
Bamboo/Sawali/Cogon/Nipa	63	2,317	2	-	1
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	20	52	-	-
Others/Not Reported	-	6	-	-	68
No Walls	-	-	-	-	-