

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|-------------------------|--|
| | | Galvanized Iron/Aluminum | Tile Concrete/Clay Tile | Half Galvanized Iron and Half Concrete |
| COTABATO (North Cotabato) | | | | |
| Total | 236,269 | 167,971 | 411 | 6,986 |
| Concrete/Brick/Stone | 36,384 | 35,790 | 200 | 221 |
| Wood | 58,508 | 48,450 | 108 | 1,205 |
| Half Concrete/Brick/Stone and Half Wood | 35,650 | 31,802 | 74 | 3,129 |
| Galvanized Iron/Aluminum | 1,089 | 626 | 6 | 187 |
| Bamboo/Sawali/Cogon/Nipa | 101,918 | 50,172 | - | 2,179 |
| Asbestos | 67 | 30 | - | 4 |
| Glass | 11 | 5 | 1 | 1 |
| Makeshift/Salvaged/Improvised Materials | 781 | 336 | - | 9 |
| Others/Not Reported | 1,859 | 758 | 22 | 51 |
| No Walls | 2 | 2 | - | - |
| ALAMADA | | | | |
| Total | 10,592 | 7,482 | 46 | 149 |
| Concrete/Brick/Stone | 690 | 651 | 27 | 7 |
| Wood | 4,584 | 3,913 | 15 | 22 |
| Half Concrete/Brick/Stone and Half Wood | 1,227 | 1,110 | - | 98 |
| Galvanized Iron/Aluminum | 21 | 12 | - | 6 |
| Bamboo/Sawali/Cogon/Nipa | 3,925 | 1,725 | - | 15 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 97 | 46 | - | 1 |
| Others/Not Reported | 48 | 25 | 4 | - |
| No Walls | - | - | - | - |
| CARMEN | | | | |
| Total | 14,263 | 7,887 | 39 | 543 |
| Concrete/Brick/Stone | 995 | 934 | 25 | 30 |
| Wood | 4,131 | 2,872 | 2 | 94 |
| Half Concrete/Brick/Stone and Half Wood | 1,327 | 1,146 | 7 | 129 |
| Galvanized Iron/Aluminum | 76 | 32 | 1 | 16 |
| Bamboo/Sawali/Cogon/Nipa | 7,624 | 2,887 | - | 273 |
| Asbestos | 35 | 8 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 6 | 1 | - | - |
| Others/Not Reported | 69 | 7 | 4 | 1 |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| KABACAN | | | | |
| Total | 15,599 | 9,474 | 37 | 850 |
| Concrete/Brick/Stone | 3,898 | 3,837 | 8 | 14 |
| Wood | 1,990 | 1,569 | 6 | 84 |
| Half Concrete/Brick/Stone and Half Wood | 2,734 | 2,196 | 20 | 436 |
| Galvanized Iron/Aluminum | 156 | 64 | 1 | 43 |
| Bamboo/Sawali/Cogon/Nipa | 6,666 | 1,800 | - | 272 |
| Asbestos | 3 | 1 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 8 | 1 | - | 1 |
| Others/Not Reported | 144 | 6 | 2 | - |
| No Walls | - | - | - | - |
| CITY OF KIDAPAWAN (Capital) | | | | |
| Total | 26,093 | 23,981 | 19 | 614 |
| Concrete/Brick/Stone | 7,598 | 7,534 | 13 | 25 |
| Wood | 5,892 | 5,537 | 1 | 86 |
| Half Concrete/Brick/Stone and Half Wood | 5,232 | 4,809 | 5 | 392 |
| Galvanized Iron/Aluminum | 42 | 29 | - | 8 |
| Bamboo/Sawali/Cogon/Nipa | 7,057 | 5,988 | - | 101 |
| Asbestos | 3 | 2 | - | 1 |
| Glass | 3 | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 122 | 23 | - | - |
| Others/Not Reported | 144 | 59 | - | 1 |
| No Walls | - | - | - | - |
| LIBUNGAN | | | | |
| Total | 9,384 | 7,412 | 4 | 119 |
| Concrete/Brick/Stone | 1,557 | 1,549 | 2 | 6 |
| Wood | 2,233 | 1,988 | 2 | 14 |
| Half Concrete/Brick/Stone and Half Wood | 1,598 | 1,547 | - | 40 |
| Galvanized Iron/Aluminum | 23 | 18 | - | 2 |
| Bamboo/Sawali/Cogon/Nipa | 3,936 | 2,296 | - | 57 |
| Asbestos | 1 | 1 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 17 | 4 | - | - |
| Others/Not Reported | 19 | 9 | - | - |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| MAGPET | | | | |
| Total | 9,485 | 7,739 | 4 | 33 |
| Concrete/Brick/Stone | 975 | 972 | 1 | - |
| Wood | 3,813 | 3,590 | 2 | 10 |
| Half Concrete/Brick/Stone and Half Wood | 969 | 953 | 1 | 12 |
| Galvanized Iron/Aluminum | 12 | 11 | - | - |
| Bamboo/Sawali/Cogon/Nipa | 3,559 | 2,078 | - | 11 |
| Asbestos | - | - | - | - |
| Glass | 1 | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 132 | 120 | - | - |
| Others/Not Reported | 24 | 15 | - | - |
| No Walls | - | - | - | - |
| MAKILALA | | | | |
| Total | 15,187 | 14,442 | 11 | 15 |
| Concrete/Brick/Stone | 2,704 | 2,693 | 7 | 1 |
| Wood | 3,261 | 3,218 | 2 | 2 |
| Half Concrete/Brick/Stone and Half Wood | 3,131 | 3,115 | - | 4 |
| Galvanized Iron/Aluminum | 47 | 47 | - | - |
| Bamboo/Sawali/Cogon/Nipa | 5,905 | 5,281 | - | 8 |
| Asbestos | 2 | 2 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 11 | 6 | - | - |
| Others/Not Reported | 125 | 79 | 2 | - |
| No Walls | 1 | 1 | - | - |
| MATALAM | | | | |
| Total | 14,244 | 10,517 | 21 | 776 |
| Concrete/Brick/Stone | 2,337 | 2,306 | 18 | 7 |
| Wood | 3,335 | 2,973 | 1 | 110 |
| Half Concrete/Brick/Stone and Half Wood | 2,147 | 1,746 | 2 | 380 |
| Galvanized Iron/Aluminum | 50 | 28 | - | 18 |
| Bamboo/Sawali/Cogon/Nipa | 6,090 | 3,279 | - | 260 |
| Asbestos | 2 | 2 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 145 | 64 | - | - |
| Others/Not Reported | 137 | 118 | - | 1 |
| No Walls | 1 | 1 | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|-------------------------|--|
| | | Galvanized Iron/Aluminum | Tile Concrete/Clay Tile | Half Galvanized Iron and Half Concrete |
| MIDSAYAP | | | | |
| Total | 26,502 | 17,870 | 89 | 1,184 |
| Concrete/Brick/Stone | 4,660 | 4,587 | 20 | 25 |
| Wood | 5,997 | 4,188 | 61 | 395 |
| Half Concrete/Brick/Stone and Half Wood | 4,699 | 4,195 | 2 | 361 |
| Galvanized Iron/Aluminum | 149 | 125 | 2 | 14 |
| Bamboo/Sawali/Cogon/Nipa | 10,769 | 4,684 | - | 384 |
| Asbestos | 3 | 1 | - | 1 |
| Glass | 4 | 2 | 1 | 1 |
| Makeshift/Salvaged/Improvised Materials | 76 | 24 | - | - |
| Others/Not Reported | 145 | 64 | 3 | 3 |
| No Walls | - | - | - | - |
| M'LANG | | | | |
| Total | 18,245 | 12,763 | 37 | 670 |
| Concrete/Brick/Stone | 3,035 | 2,947 | 25 | 47 |
| Wood | 2,748 | 1,850 | 3 | 70 |
| Half Concrete/Brick/Stone and Half Wood | 3,499 | 2,980 | 8 | 399 |
| Galvanized Iron/Aluminum | 91 | 49 | - | 15 |
| Bamboo/Sawali/Cogon/Nipa | 8,765 | 4,920 | - | 138 |
| Asbestos | 7 | 3 | - | 1 |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 11 | 7 | - | - |
| Others/Not Reported | 89 | 7 | 1 | - |
| No Walls | - | - | - | - |
| PIGKAWAYAN | | | | |
| Total | 12,526 | 8,508 | 32 | 625 |
| Concrete/Brick/Stone | 2,064 | 2,023 | 20 | 10 |
| Wood | 3,123 | 2,528 | 3 | 102 |
| Half Concrete/Brick/Stone and Half Wood | 2,146 | 1,714 | 7 | 374 |
| Galvanized Iron/Aluminum | 114 | 95 | - | 8 |
| Bamboo/Sawali/Cogon/Nipa | 4,977 | 2,136 | - | 131 |
| Asbestos | 1 | 1 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 65 | 3 | - | - |
| Others/Not Reported | 36 | 8 | 2 | - |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| PIKIT | | | | |
| Total | 18,964 | 8,416 | 41 | 556 |
| Concrete/Brick/Stone | 1,166 | 1,096 | 22 | 31 |
| Wood | 3,828 | 2,685 | 1 | 92 |
| Half Concrete/Brick/Stone and Half Wood | 2,116 | 1,739 | 16 | 286 |
| Galvanized Iron/Aluminum | 107 | 25 | - | 15 |
| Bamboo/Sawali/Cogon/Nipa | 11,205 | 2,643 | - | 79 |
| Asbestos | 3 | 2 | - | 1 |
| Glass | 2 | 2 | - | - |
| Makeshift/Salvaged/Improvised Materials | 52 | 15 | - | 7 |
| Others/Not Reported | 485 | 209 | 2 | 45 |
| No Walls | - | - | - | - |
| PRESIDENT ROXAS | | | | |
| Total | 9,217 | 6,774 | 6 | 17 |
| Concrete/Brick/Stone | 983 | 979 | 2 | 1 |
| Wood | 2,697 | 2,329 | 3 | 1 |
| Half Concrete/Brick/Stone and Half Wood | 1,261 | 1,252 | 1 | 5 |
| Galvanized Iron/Aluminum | 13 | 12 | - | - |
| Bamboo/Sawali/Cogon/Nipa | 4,225 | 2,186 | - | 10 |
| Asbestos | 5 | 5 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 5 | 2 | - | - |
| Others/Not Reported | 28 | 9 | - | - |
| No Walls | - | - | - | - |
| TULUNAN | | | | |
| Total | 9,954 | 6,837 | 7 | 52 |
| Concrete/Brick/Stone | 1,715 | 1,700 | 3 | 4 |
| Wood | 760 | 702 | 2 | 2 |
| Half Concrete/Brick/Stone and Half Wood | 1,075 | 1,020 | 2 | 34 |
| Galvanized Iron/Aluminum | 42 | 30 | - | 3 |
| Bamboo/Sawali/Cogon/Nipa | 6,086 | 3,270 | - | 9 |
| Asbestos | 1 | 1 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 5 | 4 | - | - |
| Others/Not Reported | 270 | 110 | - | - |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|-------------------------|--|
| | | Galvanized Iron/Aluminum | Tile Concrete/Clay Tile | Half Galvanized Iron and Half Concrete |
| ANTIPAS | | | | |
| Total | 4,948 | 3,460 | 6 | 375 |
| Concrete/Brick/Stone | 677 | 661 | 3 | 11 |
| Wood | 1,598 | 1,228 | 2 | 96 |
| Half Concrete/Brick/Stone and Half Wood | 871 | 698 | 1 | 161 |
| Galvanized Iron/Aluminum | 9 | 7 | - | 1 |
| Bamboo/Sawali/Cogon/Nipa | 1,775 | 861 | - | 106 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 1 | 1 | - | - |
| Others/Not Reported | 17 | 4 | - | - |
| No Walls | - | - | - | - |
| BANISILAN | | | | |
| Total | 7,203 | 5,658 | 8 | 44 |
| Concrete/Brick/Stone | 413 | 408 | 4 | - |
| Wood | 4,619 | 3,934 | 1 | 14 |
| Half Concrete/Brick/Stone and Half Wood | 654 | 637 | 1 | 12 |
| Galvanized Iron/Aluminum | 89 | 23 | 2 | 13 |
| Bamboo/Sawali/Cogon/Nipa | 1,398 | 643 | - | 5 |
| Asbestos | - | - | - | - |
| Glass | 1 | 1 | - | - |
| Makeshift/Salvaged/Improvised Materials | 6 | 4 | - | - |
| Others/Not Reported | 23 | 8 | - | - |
| No Walls | - | - | - | - |
| ALEOSAN | | | | |
| Total | 6,296 | 3,961 | 4 | 339 |
| Concrete/Brick/Stone | 503 | 503 | - | - |
| Wood | 888 | 819 | 1 | 4 |
| Half Concrete/Brick/Stone and Half Wood | 461 | 452 | 1 | 1 |
| Galvanized Iron/Aluminum | 34 | 9 | - | 25 |
| Bamboo/Sawali/Cogon/Nipa | 4,401 | 2,177 | - | 309 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | - | - | - |
| Others/Not Reported | 9 | 1 | 2 | - |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |

ARAKAN

| | | | | |
|---|-------|-------|---|----|
| Total | 7,567 | 4,790 | - | 25 |
| Concrete/Brick/Stone | 414 | 410 | - | 2 |
| Wood | 3,011 | 2,527 | - | 7 |
| Half Concrete/Brick/Stone and Half Wood | 503 | 493 | - | 5 |
| Galvanized Iron/Aluminum | 14 | 10 | - | - |
| Bamboo/Sawali/Cogon/Nipa | 3,555 | 1,318 | - | 11 |
| Asbestos | 1 | 1 | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 22 | 11 | - | - |
| Others/Not Reported | 47 | 20 | - | - |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| COTABATO (North Cotabato) | | | | | |
| Total | 3,904 | 54,611 | 680 | 619 | 1,087 |
| Concrete/Brick/Stone | 28 | 31 | 5 | 40 | 69 |
| Wood | 927 | 7,484 | 110 | 92 | 132 |
| Half Concrete/Brick/Stone and Half Wood | 149 | 328 | 9 | 61 | 98 |
| Galvanized Iron/Aluminum | 183 | 79 | 4 | 1 | 3 |
| Bamboo/Sawali/Cogon/Nipa | 2,569 | 45,998 | 324 | 408 | 268 |
| Asbestos | 31 | - | - | 2 | - |
| Glass | - | - | - | - | 4 |
| Makeshift/Salvaged/Improvised Materials | 5 | 200 | 226 | 1 | 4 |
| Others/Not Reported | 12 | 491 | 2 | 14 | 509 |
| No Walls | - | - | - | - | - |
| ALAMADA | | | | | |
| Total | 255 | 2,516 | 7 | 5 | 132 |
| Concrete/Brick/Stone | 1 | - | - | - | 4 |
| Wood | 20 | 578 | 2 | 1 | 33 |
| Half Concrete/Brick/Stone and Half Wood | 2 | 6 | - | - | 11 |
| Galvanized Iron/Aluminum | 3 | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 229 | 1,879 | 1 | 3 | 73 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 46 | 4 | - | - |
| Others/Not Reported | - | 7 | - | 1 | 11 |
| No Walls | - | - | - | - | - |
| CARMEN | | | | | |
| Total | 831 | 4,915 | 6 | 1 | 41 |
| Concrete/Brick/Stone | 2 | 2 | 2 | - | - |
| Wood | 152 | 1,007 | 2 | 1 | 1 |
| Half Concrete/Brick/Stone and Half Wood | 14 | 28 | 1 | - | 2 |
| Galvanized Iron/Aluminum | 21 | 6 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 614 | 3,841 | 1 | - | 8 |
| Asbestos | 27 | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 1 | 4 | - | - | - |
| Others/Not Reported | - | 27 | - | - | 30 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| KABACAN | | | | | |
| Total | 300 | 4,698 | 5 | 100 | 135 |
| Concrete/Brick/Stone | 3 | 4 | - | 31 | 1 |
| Wood | 68 | 242 | 4 | 17 | - |
| Half Concrete/Brick/Stone and Half Wood | 7 | 25 | - | 49 | 1 |
| Galvanized Iron/Aluminum | 20 | 28 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 200 | 4,383 | 1 | 1 | 9 |
| Asbestos | 2 | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 6 | - | - | - |
| Others/Not Reported | - | 10 | - | 2 | 124 |
| No Walls | - | - | - | - | - |
| CITY OF KIDAPAWAN (Capital) | | | | | |
| Total | 233 | 814 | 231 | 40 | 161 |
| Concrete/Brick/Stone | - | - | - | 1 | 25 |
| Wood | 186 | 46 | 16 | 5 | 15 |
| Half Concrete/Brick/Stone and Half Wood | 2 | 4 | 8 | - | 12 |
| Galvanized Iron/Aluminum | 1 | 1 | 3 | - | - |
| Bamboo/Sawali/Cogon/Nipa | 42 | 757 | 113 | 33 | 23 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | 3 |
| Makeshift/Salvaged/Improvised Materials | 2 | 5 | 91 | - | 1 |
| Others/Not Reported | - | 1 | - | 1 | 82 |
| No Walls | - | - | - | - | - |
| LIBUNGAN | | | | | |
| Total | 19 | 1,784 | 5 | 28 | 13 |
| Concrete/Brick/Stone | - | - | - | - | - |
| Wood | 5 | 212 | - | 10 | 2 |
| Half Concrete/Brick/Stone and Half Wood | 1 | 8 | - | 2 | - |
| Galvanized Iron/Aluminum | 2 | 1 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 11 | 1,552 | 2 | 16 | 2 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 10 | 3 | - | - |
| Others/Not Reported | - | 1 | - | - | 9 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| MAGPET | | | | | |
| Total | 162 | 1,073 | 257 | 174 | 43 |
| Concrete/Brick/Stone | 1 | - | - | - | 1 |
| Wood | 41 | 82 | 75 | 8 | 5 |
| Half Concrete/Brick/Stone and Half Wood | - | 3 | - | - | - |
| Galvanized Iron/Aluminum | - | 1 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 120 | 985 | 170 | 165 | 30 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | 1 |
| Makeshift/Salvaged/Improvised Materials | - | 1 | 11 | - | - |
| Others/Not Reported | - | 1 | 1 | 1 | 6 |
| No Walls | - | - | - | - | - |
| MAKILALA | | | | | |
| Total | 14 | 509 | 15 | 116 | 65 |
| Concrete/Brick/Stone | - | - | 1 | - | 2 |
| Wood | 7 | 19 | 1 | 5 | 7 |
| Half Concrete/Brick/Stone and Half Wood | - | 2 | - | - | 10 |
| Galvanized Iron/Aluminum | - | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 7 | 472 | 11 | 111 | 15 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 1 | 2 | - | 2 |
| Others/Not Reported | - | 15 | - | - | 29 |
| No Walls | - | - | - | - | - |
| MATALAM | | | | | |
| Total | 71 | 2,780 | 26 | 27 | 26 |
| Concrete/Brick/Stone | 1 | 1 | - | - | 4 |
| Wood | 50 | 188 | - | 10 | 3 |
| Half Concrete/Brick/Stone and Half Wood | 1 | 10 | - | 4 | 4 |
| Galvanized Iron/Aluminum | - | 4 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 19 | 2,513 | 2 | 12 | 5 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 57 | 23 | - | 1 |
| Others/Not Reported | - | 7 | 1 | 1 | 9 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| MIDSAYAP | | | | | |
| Total | 90 | 7,101 | 32 | 18 | 118 |
| Concrete/Brick/Stone | 2 | 4 | - | - | 22 |
| Wood | 22 | 1,298 | 6 | 1 | 26 |
| Half Concrete/Brick/Stone and Half Wood | 4 | 124 | - | - | 13 |
| Galvanized Iron/Aluminum | 3 | 4 | 1 | - | - |
| Bamboo/Sawali/Cogon/Nipa | 58 | 5,603 | 13 | 14 | 13 |
| Asbestos | 1 | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 39 | 12 | 1 | - |
| Others/Not Reported | - | 29 | - | 2 | 44 |
| No Walls | - | - | - | - | - |
| M'LANG | | | | | |
| Total | 644 | 4,040 | 5 | 5 | 81 |
| Concrete/Brick/Stone | 6 | 7 | - | 2 | 1 |
| Wood | 9 | 814 | 2 | - | - |
| Half Concrete/Brick/Stone and Half Wood | 57 | 54 | - | - | 1 |
| Galvanized Iron/Aluminum | 21 | 6 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 549 | 3,152 | 1 | 1 | 4 |
| Asbestos | 1 | - | - | 2 | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 1 | 1 | 2 | - | - |
| Others/Not Reported | - | 6 | - | - | 75 |
| No Walls | - | - | - | - | - |
| PIGKAWAYAN | | | | | |
| Total | 99 | 3,145 | 60 | 6 | 51 |
| Concrete/Brick/Stone | 2 | 2 | 2 | 5 | - |
| Wood | 31 | 454 | - | 1 | 4 |
| Half Concrete/Brick/Stone and Half Wood | 2 | 17 | - | - | 32 |
| Galvanized Iron/Aluminum | 6 | 5 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 52 | 2,653 | - | - | 5 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 1 | 3 | 58 | - | - |
| Others/Not Reported | 5 | 11 | - | - | 10 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| PIKIT | | | | | |
| Total | 493 | 9,344 | 18 | 30 | 66 |
| Concrete/Brick/Stone | 7 | 8 | - | - | 2 |
| Wood | 17 | 1,019 | - | 1 | 13 |
| Half Concrete/Brick/Stone and Half Wood | 46 | 24 | - | - | 5 |
| Galvanized Iron/Aluminum | 56 | 10 | - | - | 1 |
| Bamboo/Sawali/Cogon/Nipa | 364 | 8,071 | - | 25 | 23 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 12 | 18 | - | - |
| Others/Not Reported | 3 | 200 | - | 4 | 22 |
| No Walls | - | - | - | - | - |
| PRESIDENT ROXAS | | | | | |
| Total | 100 | 2,302 | 4 | 2 | 12 |
| Concrete/Brick/Stone | 1 | - | - | - | - |
| Wood | 1 | 362 | - | - | 1 |
| Half Concrete/Brick/Stone and Half Wood | - | 3 | - | - | - |
| Galvanized Iron/Aluminum | - | 1 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 97 | 1,926 | 3 | 2 | 1 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 2 | 1 | - | - |
| Others/Not Reported | 1 | 8 | - | - | 10 |
| No Walls | - | - | - | - | - |
| TULUNAN | | | | | |
| Total | 60 | 2,938 | 2 | 4 | 54 |
| Concrete/Brick/Stone | - | 2 | - | - | 6 |
| Wood | 29 | 22 | - | - | 3 |
| Half Concrete/Brick/Stone and Half Wood | 1 | 11 | - | - | 7 |
| Galvanized Iron/Aluminum | - | 6 | - | 1 | 2 |
| Bamboo/Sawali/Cogon/Nipa | 29 | 2,749 | 1 | 3 | 25 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | - | 1 | - | - |
| Others/Not Reported | 1 | 148 | - | - | 11 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| ANTIPAS | | | | | |
| Total | 292 | 800 | - | 3 | 12 |
| Concrete/Brick/Stone | 2 | - | - | - | - |
| Wood | 215 | 57 | - | - | - |
| Half Concrete/Brick/Stone and Half Wood | 8 | 3 | - | - | - |
| Galvanized Iron/Aluminum | - | 1 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 67 | 739 | - | 2 | - |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | - | - | - | - |
| Others/Not Reported | - | - | - | 1 | 12 |
| No Walls | - | - | - | - | - |
| BANISILAN | | | | | |
| Total | 157 | 1,319 | - | 4 | 13 |
| Concrete/Brick/Stone | - | - | - | - | 1 |
| Wood | 49 | 621 | - | - | - |
| Half Concrete/Brick/Stone and Half Wood | 4 | - | - | - | - |
| Galvanized Iron/Aluminum | 46 | 5 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 58 | 688 | - | 3 | 1 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 2 | - | - | - |
| Others/Not Reported | - | 3 | - | 1 | 11 |
| No Walls | - | - | - | - | - |
| ALEOSAN | | | | | |
| Total | 40 | 1,886 | - | 51 | 15 |
| Concrete/Brick/Stone | - | - | - | - | - |
| Wood | - | 33 | - | 31 | - |
| Half Concrete/Brick/Stone and Half Wood | - | 1 | - | 6 | - |
| Galvanized Iron/Aluminum | - | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 38 | 1,851 | - | 14 | 12 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | - | - | - | - |
| Others/Not Reported | 2 | 1 | - | - | 3 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| ARAKAN | | | | | |
| Total | 44 | 2,647 | 7 | 5 | 49 |
| Concrete/Brick/Stone | - | 1 | - | 1 | - |
| Wood | 25 | 430 | 2 | 1 | 19 |
| Half Concrete/Brick/Stone and Half Wood | - | 5 | - | - | - |
| Galvanized Iron/Aluminum | 4 | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 15 | 2,184 | 5 | 3 | 19 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 11 | - | - | - |
| Others/Not Reported | - | 16 | - | - | 11 |
| No Walls | - | - | - | - | - |