

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>DAVAO ORIENTAL</b>				
Total	98,786	47,206	66	1,853
Concrete/Brick/Stone	11,023	10,462	29	147
Wood	27,118	12,873	22	415
Half Concrete/Brick/Stone and Half Wood	11,662	9,343	8	818
Galvanized Iron/Aluminum	300	175	3	51
Bamboo/Sawali/Cogon/Nipa	47,665	13,910	-	418
Asbestos	19	15	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	238	76	-	1
Others/Not Reported	759	350	4	3
No Walls	-	-	-	-
<b>BAGANGA</b>				
Total	9,317	2,943	3	177
Concrete/Brick/Stone	703	642	1	12
Wood	5,180	1,278	1	71
Half Concrete/Brick/Stone and Half Wood	1,264	894	1	83
Galvanized Iron/Aluminum	28	22	-	1
Bamboo/Sawali/Cogon/Nipa	2,113	101	-	10
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	26	6	-	-
No Walls	-	-	-	-
<b>BANAYBANAY</b>				
Total	7,443	4,047	-	317
Concrete/Brick/Stone	1,226	1,152	-	32
Wood	1,357	979	-	48
Half Concrete/Brick/Stone and Half Wood	1,139	875	-	126
Galvanized Iron/Aluminum	24	15	-	1
Bamboo/Sawali/Cogon/Nipa	3,481	930	-	108
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	147	58	-	-
Others/Not Reported	69	38	-	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>BOSTON</b>				
Total	2,162	790	-	10
Concrete/Brick/Stone	122	113	-	-
Wood	1,586	531	-	9
Half Concrete/Brick/Stone and Half Wood	186	136	-	1
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	259	7	-	-
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	7	2	-	-
No Walls	-	-	-	-
<b>CARAGA</b>				
Total	7,021	1,398	12	296
Concrete/Brick/Stone	398	269	3	25
Wood	2,371	826	7	60
Half Concrete/Brick/Stone and Half Wood	501	194	1	161
Galvanized Iron/Aluminum	45	1	1	31
Bamboo/Sawali/Cogon/Nipa	3,665	101	-	17
Asbestos	1	-	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	4	-	-	1
Others/Not Reported	34	5	-	1
No Walls	-	-	-	-
<b>CATEEL</b>				
Total	6,871	910	11	134
Concrete/Brick/Stone	294	225	7	29
Wood	4,691	402	-	43
Half Concrete/Brick/Stone and Half Wood	458	254	1	54
Galvanized Iron/Aluminum	32	21	1	2
Bamboo/Sawali/Cogon/Nipa	1,332	6	-	6
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	62	2	2	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>GOVERNOR GENEROSO</b>				
Total	9,586	5,333	3	138
Concrete/Brick/Stone	1,467	1,424	1	7
Wood	1,401	1,054	1	11
Half Concrete/Brick/Stone and Half Wood	1,484	1,289	-	85
Galvanized Iron/Aluminum	38	30	-	3
Bamboo/Sawali/Cogon/Nipa	5,148	1,524	-	32
Asbestos	5	4	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	-	-	-
Others/Not Reported	36	8	1	-
No Walls	-	-	-	-
<b>LUPON</b>				
Total	12,106	7,140	6	300
Concrete/Brick/Stone	1,547	1,491	5	9
Wood	2,487	2,024	1	62
Half Concrete/Brick/Stone and Half Wood	2,099	1,706	-	135
Galvanized Iron/Aluminum	25	17	-	1
Bamboo/Sawali/Cogon/Nipa	5,882	1,871	-	93
Asbestos	2	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	1	-	-
Others/Not Reported	58	29	-	-
No Walls	-	-	-	-
<b>MANAY</b>				
Total	7,835	1,652	3	206
Concrete/Brick/Stone	239	218	1	3
Wood	1,460	386	2	80
Half Concrete/Brick/Stone and Half Wood	886	609	-	91
Galvanized Iron/Aluminum	15	10	-	1
Bamboo/Sawali/Cogon/Nipa	5,157	421	-	31
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	23	2	-	-
Others/Not Reported	55	6	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>CITY OF MATI (Capital)</b>				
Total	25,069	16,704	21	228
Concrete/Brick/Stone	3,817	3,742	10	25
Wood	4,589	3,836	6	26
Half Concrete/Brick/Stone and Half Wood	2,408	2,231	4	73
Galvanized Iron/Aluminum	66	47	1	3
Bamboo/Sawali/Cogon/Nipa	13,903	6,697	-	101
Asbestos	10	9	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	39	13	-	-
Others/Not Reported	237	129	-	-
No Walls	-	-	-	-
<b>SAN ISIDRO</b>				
Total	6,648	4,518	3	5
Concrete/Brick/Stone	955	948	-	-
Wood	1,229	1,110	2	-
Half Concrete/Brick/Stone and Half Wood	857	821	-	1
Galvanized Iron/Aluminum	11	8	-	-
Bamboo/Sawali/Cogon/Nipa	3,438	1,510	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	2	-	-
Others/Not Reported	152	119	1	-
No Walls	-	-	-	-
<b>TARRAGONA</b>				
Total	4,728	1,771	4	42
Concrete/Brick/Stone	255	238	1	5
Wood	767	447	2	5
Half Concrete/Brick/Stone and Half Wood	380	334	1	8
Galvanized Iron/Aluminum	16	4	-	8
Bamboo/Sawali/Cogon/Nipa	3,287	742	-	16
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	23	6	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>DAVAO ORIENTAL</b>					
Total	2,439	46,288	89	580	265
Concrete/Brick/Stone	20	337	-	22	6
Wood	1,297	12,361	11	121	18
Half Concrete/Brick/Stone and Half Wood	48	1,388	3	51	3
Galvanized Iron/Aluminum	19	52	-	-	-
Bamboo/Sawali/Cogon/Nipa	1,041	31,806	48	339	103
Asbestos	2	-	-	2	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	133	26	-	1
Others/Not Reported	11	211	1	45	134
No Walls	-	-	-	-	-
<b>BAGANGA</b>					
Total	396	5,789	-	-	9
Concrete/Brick/Stone	-	48	-	-	-
Wood	326	3,502	-	-	2
Half Concrete/Brick/Stone and Half Wood	5	281	-	-	-
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	63	1,939	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	2	11	-	-	7
No Walls	-	-	-	-	-
<b>BANAYBANAY</b>					
Total	14	3,041	12	3	9
Concrete/Brick/Stone	-	42	-	-	-
Wood	4	324	1	1	-
Half Concrete/Brick/Stone and Half Wood	-	136	1	-	1
Galvanized Iron/Aluminum	1	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	2,425	8	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	88	1	-	-
Others/Not Reported	-	19	1	1	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>BOSTON</b>					
Total	87	1,271	1	-	3
Concrete/Brick/Stone	-	9	-	-	-
Wood	82	964	-	-	-
Half Concrete/Brick/Stone and Half Wood	3	46	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	250	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	2	-	-	3
No Walls	-	-	-	-	-
<b>CARAGA</b>					
Total	734	4,564	4	5	8
Concrete/Brick/Stone	2	98	-	1	-
Wood	205	1,272	-	1	-
Half Concrete/Brick/Stone and Half Wood	7	135	1	2	-
Galvanized Iron/Aluminum	9	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	510	3,036	-	-	1
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	3	-	-
Others/Not Reported	-	20	-	1	7
No Walls	-	-	-	-	-
<b>CATEEL</b>					
Total	534	5,234	2	17	29
Concrete/Brick/Stone	-	29	-	4	-
Wood	485	3,749	-	6	6
Half Concrete/Brick/Stone and Half Wood	14	130	-	5	-
Galvanized Iron/Aluminum	2	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	32	1,287	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	1	33	-	2	22
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>GOVERNOR GENEROSO</b>					
Total	115	3,960	2	9	26
Concrete/Brick/Stone	3	30	-	1	1
Wood	37	297	-	-	1
Half Concrete/Brick/Stone and Half Wood	2	103	-	5	-
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	71	3,507	2	3	9
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	6	-	-	-
Others/Not Reported	-	12	-	-	15
No Walls	-	-	-	-	-
<b>LUPON</b>					
Total	289	4,243	4	54	70
Concrete/Brick/Stone	-	39	-	3	-
Wood	58	325	2	14	1
Half Concrete/Brick/Stone and Half Wood	4	241	-	12	1
Galvanized Iron/Aluminum	2	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	222	3,624	-	24	48
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	2	-	-
Others/Not Reported	3	6	-	-	20
No Walls	-	-	-	-	-
<b>MANAY</b>					
Total	53	5,774	21	88	38
Concrete/Brick/Stone	-	5	-	12	-
Wood	23	924	3	42	-
Half Concrete/Brick/Stone and Half Wood	10	151	-	25	-
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	19	4,648	11	3	24
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	7	-	1
Others/Not Reported	-	30	-	6	13
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CITY OF MATI (Capital)</b>					
Total	139	7,484	42	391	60
Concrete/Brick/Stone	15	19	-	1	5
Wood	51	601	5	57	7
Half Concrete/Brick/Stone and Half Wood	3	93	1	2	1
Galvanized Iron/Aluminum	2	13	-	-	-
Bamboo/Sawali/Cogon/Nipa	63	6,701	26	299	16
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	10	-	-
Others/Not Reported	5	41	-	31	31
No Walls	-	-	-	-	-
<b>SAN ISIDRO</b>					
Total	25	2,076	1	12	8
Concrete/Brick/Stone	-	7	-	-	-
Wood	9	107	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	35	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	1,897	1	8	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	-	23	-	4	5
No Walls	-	-	-	-	-
<b>TARRAGONA</b>					
Total	53	2,852	-	1	5
Concrete/Brick/Stone	-	11	-	-	-
Wood	17	296	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	37	-	-	-
Galvanized Iron/Aluminum	2	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	34	2,492	-	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	14	-	-	3
No Walls	-	-	-	-	-