

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## EASTERN SAMAR

Total	83,714	44,588	278	2,716
Concrete/Brick/Stone	18,302	17,516	210	185
Wood	20,760	13,578	11	487
Half Concrete/Brick/Stone and Half Wood	10,575	8,012	44	1,563
Galvanized Iron/Aluminum	1,215	596	7	172
Bamboo/Sawali/Cogon/Nipa	32,096	4,635	-	293
Asbestos	31	29	-	-
Glass	2	1	-	-
Makeshift/Salvaged/Improvised Materials	351	83	-	7
Others/Not Reported	381	138	6	9
No Walls	1	-	-	-

## ARTECHE

Total	2,958	1,050	2	32
Concrete/Brick/Stone	425	389	2	5
Wood	588	370	-	8
Half Concrete/Brick/Stone and Half Wood	212	170	-	12
Galvanized Iron/Aluminum	29	17	-	2
Bamboo/Sawali/Cogon/Nipa	1,688	103	-	5
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	-	-	-
Others/Not Reported	10	-	-	-
No Walls	-	-	-	-

## BALANGIGA

Total	2,594	1,569	1	1
Concrete/Brick/Stone	674	670	1	-
Wood	418	336	-	-
Half Concrete/Brick/Stone and Half Wood	286	275	-	-
Galvanized Iron/Aluminum	11	5	-	-
Bamboo/Sawali/Cogon/Nipa	1,192	275	-	1
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	-	-	-
Others/Not Reported	8	7	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## BALANGKAYAN

Total	1,778	1,298	4	12
Concrete/Brick/Stone	396	391	3	-
Wood	187	174	-	-
Half Concrete/Brick/Stone and Half Wood	339	330	-	6
Galvanized Iron/Aluminum	13	12	-	-
Bamboo/Sawali/Cogon/Nipa	833	386	-	6
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	8	5	1	-
No Walls	-	-	-	-

## CITY OF BORONGAN (Capital)

Total	12,504	8,453	27	148
Concrete/Brick/Stone	3,879	3,763	24	9
Wood	3,757	2,595	2	35
Half Concrete/Brick/Stone and Half Wood	1,642	1,387	1	67
Galvanized Iron/Aluminum	164	108	-	1
Bamboo/Sawali/Cogon/Nipa	2,864	511	-	35
Asbestos	-	-	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	104	39	-	-
Others/Not Reported	93	50	-	1
No Walls	-	-	-	-

## CAN-AVID

Total	3,658	1,957	1	47
Concrete/Brick/Stone	736	702	-	5
Wood	1,354	753	1	7
Half Concrete/Brick/Stone and Half Wood	507	407	-	31
Galvanized Iron/Aluminum	10	5	-	-
Bamboo/Sawali/Cogon/Nipa	1,032	88	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	1	-	-
Others/Not Reported	13	1	-	-
No Walls	1	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## DOLORES

Total	7,229	3,572	19	263
Concrete/Brick/Stone	1,064	1,026	11	7
Wood	2,892	1,760	-	162
Half Concrete/Brick/Stone and Half Wood	634	509	5	70
Galvanized Iron/Aluminum	107	35	3	12
Bamboo/Sawali/Cogon/Nipa	2,512	238	-	12
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	1	-	-
Others/Not Reported	9	1	-	-
No Walls	-	-	-	-

## GENERAL MACARTHUR

Total	2,207	915	2	21
Concrete/Brick/Stone	347	336	2	2
Wood	380	277	-	4
Half Concrete/Brick/Stone and Half Wood	158	138	-	13
Galvanized Iron/Aluminum	45	32	-	-
Bamboo/Sawali/Cogon/Nipa	1,266	126	-	2
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	3	-	-	-
No Walls	-	-	-	-

## GIPORLOS

Total	2,300	1,237	-	5
Concrete/Brick/Stone	541	534	-	2
Wood	583	383	-	1
Half Concrete/Brick/Stone and Half Wood	179	170	-	1
Galvanized Iron/Aluminum	9	7	-	-
Bamboo/Sawali/Cogon/Nipa	977	140	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	8	2	-	-
Others/Not Reported	3	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## GUIUAN

Total	9,065	4,576	56	1,149
Concrete/Brick/Stone	2,160	2,044	26	78
Wood	1,892	1,177	1	93
Half Concrete/Brick/Stone and Half Wood	1,697	786	27	789
Galvanized Iron/Aluminum	283	76	1	117
Bamboo/Sawali/Cogon/Nipa	2,932	478	-	69
Asbestos	2	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	67	8	-	3
Others/Not Reported	32	6	1	-
No Walls	-	-	-	-

## HERNANI

Total	1,576	677	4	6
Concrete/Brick/Stone	296	285	4	1
Wood	127	86	-	2
Half Concrete/Brick/Stone and Half Wood	216	205	-	1
Galvanized Iron/Aluminum	7	3	-	-
Bamboo/Sawali/Cogon/Nipa	898	81	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	30	17	-	-
No Walls	-	-	-	-

## JIPAPAD

Total	1,304	672	2	-
Concrete/Brick/Stone	5	5	-	-
Wood	569	479	2	-
Half Concrete/Brick/Stone and Half Wood	153	149	-	-
Galvanized Iron/Aluminum	4	2	-	-
Bamboo/Sawali/Cogon/Nipa	560	34	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	12	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
LAWAAN				
Total	2,220	1,467	1	8
Concrete/Brick/Stone	686	679	1	3
Wood	452	345	-	-
Half Concrete/Brick/Stone and Half Wood	215	204	-	3
Galvanized Iron/Aluminum	9	8	-	-
Bamboo/Sawali/Cogon/Nipa	822	212	-	2
Asbestos	11	11	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	6	-	-
Others/Not Reported	8	2	-	-
No Walls	-	-	-	-
LLORENTE				
Total	3,914	2,073	32	84
Concrete/Brick/Stone	629	577	30	11
Wood	525	417	1	7
Half Concrete/Brick/Stone and Half Wood	722	656	1	22
Galvanized Iron/Aluminum	36	25	-	4
Bamboo/Sawali/Cogon/Nipa	1,960	381	-	37
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	11	2	-	-
Others/Not Reported	30	14	-	3
No Walls	-	-	-	-
MASLOG				
Total	850	568	-	2
Concrete/Brick/Stone	18	18	-	-
Wood	411	397	-	-
Half Concrete/Brick/Stone and Half Wood	85	85	-	-
Galvanized Iron/Aluminum	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	333	67	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	-	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## MAYDOLONG

Total	2,626	1,769	16	27
Concrete/Brick/Stone	784	739	16	9
Wood	516	455	-	5
Half Concrete/Brick/Stone and Half Wood	273	250	-	2
Galvanized Iron/Aluminum	17	15	-	-
Bamboo/Sawali/Cogon/Nipa	1,026	306	-	11
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	2	-	-
Others/Not Reported	5	2	-	-
No Walls	-	-	-	-

## MERCEDES

Total	1,050	690	-	1
Concrete/Brick/Stone	414	412	-	-
Wood	196	157	-	1
Half Concrete/Brick/Stone and Half Wood	57	50	-	-
Galvanized Iron/Aluminum	19	14	-	-
Bamboo/Sawali/Cogon/Nipa	363	57	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	1	-	-	-
No Walls	-	-	-	-

## ORAS

Total	6,627	2,673	26	250
Concrete/Brick/Stone	1,001	927	12	17
Wood	1,629	1,001	3	41
Half Concrete/Brick/Stone and Half Wood	693	444	9	159
Galvanized Iron/Aluminum	193	87	2	11
Bamboo/Sawali/Cogon/Nipa	3,000	192	-	18
Asbestos	5	4	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	89	14	-	4
Others/Not Reported	17	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## QUINAPONDAN

Total	2,436	1,161	-	7
Concrete/Brick/Stone	486	479	-	1
Wood	265	195	-	-
Half Concrete/Brick/Stone and Half Wood	161	152	-	2
Galvanized Iron/Aluminum	48	39	-	-
Bamboo/Sawali/Cogon/Nipa	1,467	294	-	4
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	-	-	-
Others/Not Reported	3	-	-	-
No Walls	-	-	-	-

## SALCEDO

Total	3,848	1,792	11	207
Concrete/Brick/Stone	822	793	11	3
Wood	710	346	-	61
Half Concrete/Brick/Stone and Half Wood	547	390	-	109
Galvanized Iron/Aluminum	53	31	-	5
Bamboo/Sawali/Cogon/Nipa	1,693	225	-	25
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	1	-	-
Others/Not Reported	14	4	-	4
No Walls	-	-	-	-

## SAN JULIAN

Total	2,884	1,759	2	79
Concrete/Brick/Stone	628	617	-	-
Wood	705	527	-	13
Half Concrete/Brick/Stone and Half Wood	451	393	-	37
Galvanized Iron/Aluminum	30	16	1	3
Bamboo/Sawali/Cogon/Nipa	1,058	200	-	26
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	12	6	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## SAN POLICARPO

Total	2,677	822	3	134
Concrete/Brick/Stone	433	384	2	18
Wood	689	203	-	36
Half Concrete/Brick/Stone and Half Wood	348	165	1	77
Galvanized Iron/Aluminum	33	18	-	-
Bamboo/Sawali/Cogon/Nipa	1,165	51	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	8	-	-	-
No Walls	-	-	-	-

## SULAT

Total	3,938	1,971	7	197
Concrete/Brick/Stone	969	931	5	8
Wood	873	551	-	8
Half Concrete/Brick/Stone and Half Wood	586	340	-	151
Galvanized Iron/Aluminum	31	11	-	7
Bamboo/Sawali/Cogon/Nipa	1,430	120	-	22
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	5	-	-
Others/Not Reported	44	13	2	1
No Walls	-	-	-	-

## TAFT

Total	3,471	1,867	62	36
Concrete/Brick/Stone	909	815	60	6
Wood	1,042	594	1	3
Half Concrete/Brick/Stone and Half Wood	414	357	-	11
Galvanized Iron/Aluminum	62	29	-	10
Bamboo/Sawali/Cogon/Nipa	1,025	70	-	6
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	18	2	1	-
No Walls	-	-	-	-



Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>EASTERN SAMAR</b>					
Total	952	34,827	93	104	156
Concrete/Brick/Stone	21	342	-	20	8
Wood	451	6,191	11	22	9
Half Concrete/Brick/Stone and Half Wood	80	855	4	15	2
Galvanized Iron/Aluminum	62	375	2	-	1
Bamboo/Sawali/Cogon/Nipa	335	26,770	17	30	16
Asbestos	1	-	-	1	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	2	200	58	1	-
Others/Not Reported	-	93	1	15	119
No Walls	-	1	-	-	-
<b>ARTECHE</b>					
Total	19	1,843	3	-	9
Concrete/Brick/Stone	2	27	-	-	-
Wood	8	201	-	-	1
Half Concrete/Brick/Stone and Half Wood	1	29	-	-	-
Galvanized Iron/Aluminum	-	9	1	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,570	2	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	-	-	-
Others/Not Reported	-	2	-	-	8
No Walls	-	-	-	-	-
<b>BALANGIGA</b>					
Total	1	1,016	5	1	-
Concrete/Brick/Stone	-	3	-	-	-
Wood	-	81	1	-	-
Half Concrete/Brick/Stone and Half Wood	-	11	-	-	-
Galvanized Iron/Aluminum	-	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	912	2	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	2	-	-
Others/Not Reported	-	1	-	-	-
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>BALANGKAYAN</b>					
Total	1	460	-	-	3
Concrete/Brick/Stone	-	2	-	-	-
Wood	1	12	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	3	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	440	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
<b>CITY OF BORONGAN (Capital)</b>					
Total	56	3,744	17	37	22
Concrete/Brick/Stone	10	63	-	7	3
Wood	25	1,086	4	9	1
Half Concrete/Brick/Stone and Half Wood	7	169	3	8	-
Galvanized Iron/Aluminum	-	54	1	-	-
Bamboo/Sawali/Cogon/Nipa	13	2,291	3	8	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	1	57	6	1	-
Others/Not Reported	-	24	-	4	14
No Walls	-	-	-	-	-
<b>CAN-AVID</b>					
Total	84	1,557	-	10	2
Concrete/Brick/Stone	2	24	-	3	-
Wood	74	517	-	2	-
Half Concrete/Brick/Stone and Half Wood	5	62	-	2	-
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	933	-	3	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	-	11	-	-	1
No Walls	-	1	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>DOLORES</b>					
Total	13	3,348	3	-	11
Concrete/Brick/Stone	-	19	-	-	1
Wood	5	963	-	-	2
Half Concrete/Brick/Stone and Half Wood	1	48	-	-	1
Galvanized Iron/Aluminum	-	56	-	-	1
Bamboo/Sawali/Cogon/Nipa	7	2,253	2	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	1	-	-
Others/Not Reported	-	2	-	-	6
No Walls	-	-	-	-	-
<b>GENERAL MACARTHUR</b>					
Total	1	1,265	2	-	1
Concrete/Brick/Stone	-	7	-	-	-
Wood	-	99	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	7	-	-	-
Galvanized Iron/Aluminum	-	13	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	1,137	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	2	-	-	1
No Walls	-	-	-	-	-
<b>GIPORLOS</b>					
Total	-	1,052	3	-	3
Concrete/Brick/Stone	-	4	-	-	1
Wood	-	199	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	8	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	835	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	2	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
GUIUAN					
Total	327	2,908	14	7	28
Concrete/Brick/Stone	-	9	-	1	2
Wood	83	535	-	2	1
Half Concrete/Brick/Stone and Half Wood	31	64	-	-	-
Galvanized Iron/Aluminum	52	37	-	-	-
Bamboo/Sawali/Cogon/Nipa	161	2,215	3	3	3
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	45	11	-	-
Others/Not Reported	-	3	-	-	22
No Walls	-	-	-	-	-
HERNANI					
Total	6	867	-	16	-
Concrete/Brick/Stone	-	5	-	1	-
Wood	2	35	-	2	-
Half Concrete/Brick/Stone and Half Wood	-	8	-	2	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	807	-	4	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	6	-	7	-
No Walls	-	-	-	-	-
JIPAPAD					
Total	3	613	-	3	11
Concrete/Brick/Stone	-	-	-	-	-
Wood	1	86	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	4	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	520	-	3	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	-	9
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>LAWAAN</b>					
Total	8	728	4	3	1
Concrete/Brick/Stone	1	2	-	-	-
Wood	4	102	1	-	-
Half Concrete/Brick/Stone and Half Wood	-	8	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	605	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	7	3	-	-
Others/Not Reported	-	3	-	2	1
No Walls	-	-	-	-	-
<b>LLORENTE</b>					
Total	16	1,690	4	6	9
Concrete/Brick/Stone	-	11	-	-	-
Wood	4	95	-	1	-
Half Concrete/Brick/Stone and Half Wood	3	39	-	1	-
Galvanized Iron/Aluminum	-	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	1,530	-	3	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	4	-	-
Others/Not Reported	-	3	-	1	9
No Walls	-	-	-	-	-
<b>MASLOG</b>					
Total	2	277	1	-	-
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	14	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	262	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAYDOLONG					
Total	3	803	4	-	4
Concrete/Brick/Stone	-	20	-	-	-
Wood	-	55	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	21	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	704	2	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	2	-	-
Others/Not Reported	-	-	-	-	3
No Walls	-	-	-	-	-
MERCEDES					
Total	4	354	1	-	-
Concrete/Brick/Stone	-	2	-	-	-
Wood	1	37	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	6	-	-	-
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	304	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	1	-	-
No Walls	-	-	-	-	-
ORAS					
Total	48	3,594	26	-	10
Concrete/Brick/Stone	-	45	-	-	-
Wood	13	565	5	-	1
Half Concrete/Brick/Stone and Half Wood	5	75	1	-	-
Galvanized Iron/Aluminum	4	89	-	-	-
Bamboo/Sawali/Cogon/Nipa	25	2,763	1	-	1
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	52	19	-	-
Others/Not Reported	-	5	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
QUINAPONDAN					
Total	8	1,256	3	-	1
Concrete/Brick/Stone	-	6	-	-	-
Wood	-	70	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	7	-	-	-
Galvanized Iron/Aluminum	-	9	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,161	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	3	-	-
Others/Not Reported	-	2	-	-	1
No Walls	-	-	-	-	-
SALCEDO					
Total	83	1,747	1	3	4
Concrete/Brick/Stone	-	13	-	2	-
Wood	14	288	-	1	-
Half Concrete/Brick/Stone and Half Wood	7	41	-	-	-
Galvanized Iron/Aluminum	-	17	-	-	-
Bamboo/Sawali/Cogon/Nipa	62	1,380	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	1	-	-
Others/Not Reported	-	3	-	-	3
No Walls	-	-	-	-	-
SAN JULIAN					
Total	1	1,038	1	2	2
Concrete/Brick/Stone	-	11	-	-	-
Wood	-	164	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	20	-	1	-
Galvanized Iron/Aluminum	-	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	830	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	3	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN POLICARPO					
Total	236	1,474	-	-	8
Concrete/Brick/Stone	3	26	-	-	-
Wood	208	242	-	-	-
Half Concrete/Brick/Stone and Half Wood	18	86	-	-	1
Galvanized Iron/Aluminum	4	11	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	1,107	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	2	-	-	6
No Walls	-	-	-	-	-
SULAT					
Total	19	1,719	-	15	10
Concrete/Brick/Stone	2	18	-	5	-
Wood	3	307	-	4	-
Half Concrete/Brick/Stone and Half Wood	1	93	-	1	-
Galvanized Iron/Aluminum	2	11	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	1,271	-	4	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	19	-	1	8
No Walls	-	-	-	-	-
TAFT					
Total	13	1,474	1	1	17
Concrete/Brick/Stone	1	25	-	1	1
Wood	5	438	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	46	-	-	-
Galvanized Iron/Aluminum	-	23	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	940	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	2	-	-	13
No Walls	-	-	-	-	-