

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

GUIMARAS

Total	32,031	22,809	26	1,493
Concrete/Brick/Stone	6,456	6,343	15	70
Wood	2,543	2,179	1	44
Half Concrete/Brick/Stone and Half Wood	7,013	5,857	3	875
Galvanized Iron/Aluminum	204	137	1	47
Bamboo/Sawali/Cogon/Nipa	15,612	8,189	-	454
Asbestos	2	2	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	66	34	-	2
Others/Not Reported	134	67	6	1
No Walls	-	-	-	-

BUENAVISTA

Total	9,649	6,932	7	369
Concrete/Brick/Stone	2,584	2,558	3	10
Wood	796	629	1	11
Half Concrete/Brick/Stone and Half Wood	2,162	1,820	2	259
Galvanized Iron/Aluminum	43	33	-	8
Bamboo/Sawali/Cogon/Nipa	3,974	1,833	-	81
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	21	14	-	-
Others/Not Reported	67	43	1	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

JORDAN (Capital)

Total	6,495	5,358	5	44
Concrete/Brick/Stone	1,358	1,346	5	4
Wood	1,189	1,079	-	4
Half Concrete/Brick/Stone and Half Wood	1,367	1,313	-	10
Galvanized Iron/Aluminum	52	25	-	19
Bamboo/Sawali/Cogon/Nipa	2,505	1,584	-	7
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	18	10	-	-
Others/Not Reported	6	1	-	-
No Walls	-	-	-	-

NUEVA VALENCIA

Total	7,534	4,755	10	679
Concrete/Brick/Stone	1,280	1,219	6	52
Wood	314	246	-	27
Half Concrete/Brick/Stone and Half Wood	1,834	1,401	1	338
Galvanized Iron/Aluminum	34	23	1	8
Bamboo/Sawali/Cogon/Nipa	4,012	1,843	-	253
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	22	9	-	-
Others/Not Reported	37	13	2	1
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SAN LORENZO

Total	4,645	3,125	4	389
Concrete/Brick/Stone	683	676	1	3
Wood	164	151	-	1
Half Concrete/Brick/Stone and Half Wood	1,132	825	-	263
Galvanized Iron/Aluminum	37	22	-	11
Bamboo/Sawali/Cogon/Nipa	2,603	1,442	-	109
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	1	-	2
Others/Not Reported	21	8	3	-
No Walls	-	-	-	-

SIBUNAG

Total	3,708	2,639	-	12
Concrete/Brick/Stone	551	544	-	1
Wood	80	74	-	1
Half Concrete/Brick/Stone and Half Wood	518	498	-	5
Galvanized Iron/Aluminum	38	34	-	1
Bamboo/Sawali/Cogon/Nipa	2,518	1,487	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	3	2	-	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

GUIMARAS

Total	191	7,080	19	294	119
Concrete/Brick/Stone	-	19	1	6	2
Wood	94	214	-	6	5
Half Concrete/Brick/Stone and Half Wood	20	240	2	14	2
Galvanized Iron/Aluminum	8	11	-	-	-
Bamboo/Sawali/Cogon/Nipa	69	6,562	10	261	67
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	24	6	-	-
Others/Not Reported	-	10	-	7	43
No Walls	-	-	-	-	-

BUENAVISTA

Total	132	1,827	9	289	84
Concrete/Brick/Stone	-	6	1	5	1
Wood	87	57	-	6	5
Half Concrete/Brick/Stone and Half Wood	17	47	2	14	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	28	1,704	6	257	65
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	-	-	-
Others/Not Reported	-	4	-	7	12
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

JORDAN (Capital)

Total	24	1,058	2	-	4
Concrete/Brick/Stone	-	3	-	-	-
Wood	4	102	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	44	-	-	-
Galvanized Iron/Aluminum	7	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	13	899	2	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	-	-	-
Others/Not Reported	-	1	-	-	4
No Walls	-	-	-	-	-

NUEVA VALENCIA

Total	10	2,056	6	-	18
Concrete/Brick/Stone	-	3	-	-	-
Wood	2	39	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	93	-	-	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,906	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	5	-	-
Others/Not Reported	-	5	-	-	16
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

SAN LORENZO

Total	18	1,092	2	5	10
Concrete/Brick/Stone	-	2	-	1	-
Wood	-	12	-	-	-
Half Concrete/Brick/Stone and Half Wood	3	41	-	-	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	1,032	1	4	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	-	-	-	10
No Walls	-	-	-	-	-

SIBUNAG

Total	7	1,047	-	-	3
Concrete/Brick/Stone	-	5	-	-	1
Wood	1	4	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	15	-	-	-
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	1,021	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-