

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
IFUGAO				
Total	36,032	31,308	98	360
Concrete/Brick/Stone	6,511	6,378	80	23
Wood	17,859	15,246	5	65
Half Concrete/Brick/Stone and Half Wood	4,973	4,710	11	204
Galvanized Iron/Aluminum	3,788	3,750	1	15
Bamboo/Sawali/Cogon/Nipa	2,571	1,011	0	50
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	62	36	0	1
Others/Not Reported	268	177	1	2
No Walls	0	0	0	0
BANAUE				
Total	4,028	3,383	26	11
Concrete/Brick/Stone	497	451	25	6
Wood	1,732	1,191	0	2
Half Concrete/Brick/Stone and Half Wood	469	465	1	2
Galvanized Iron/Aluminum	1,142	1,139	0	0
Bamboo/Sawali/Cogon/Nipa	59	23	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	18	15	0	0
Others/Not Reported	111	99	0	1
No Walls	0	0	0	0
HUNGDUAN				
Total	1,795	1,712	21	3
Concrete/Brick/Stone	108	87	20	1
Wood	1,236	1,193	0	0
Half Concrete/Brick/Stone and Half Wood	186	183	1	2
Galvanized Iron/Aluminum	234	234	0	0
Bamboo/Sawali/Cogon/Nipa	12	4	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0
Others/Not Reported	19	11	0	0
No Walls	0	0	0	0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
KIANGAN				
Total	3,011	2,943	6	4
Concrete/Brick/Stone	373	368	2	2
Wood	1,749	1,720	2	1
Half Concrete/Brick/Stone and Half Wood	577	575	2	0
Galvanized Iron/Aluminum	149	149	0	0
Bamboo/Sawali/Cogon/Nipa	145	124	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	4	3	0	1
Others/Not Reported	14	4	0	0
No Walls	0	0	0	0
LAGAWE (Capital)				
Total	3,429	3,283	11	17
Concrete/Brick/Stone	687	674	5	6
Wood	1,502	1,404	1	1
Half Concrete/Brick/Stone and Half Wood	1,026	1,011	5	10
Galvanized Iron/Aluminum	97	97	0	0
Bamboo/Sawali/Cogon/Nipa	92	76	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	11	9	0	0
Others/Not Reported	14	12	0	0
No Walls	0	0	0	0
LAMUT				
Total	4,559	4,195	3	99
Concrete/Brick/Stone	1,632	1,627	3	1
Wood	1,452	1,329	0	51
Half Concrete/Brick/Stone and Half Wood	894	849	0	39
Galvanized Iron/Aluminum	59	50	0	2
Bamboo/Sawali/Cogon/Nipa	489	326	0	6
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	16	3	0	0
Others/Not Reported	17	11	0	0
No Walls	0	0	0	0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MAYOYAO				
Total	3,376	2,711	4	7
Concrete/Brick/Stone	125	119	3	2
Wood	2,241	1,623	1	0
Half Concrete/Brick/Stone and Half Wood	111	109	0	2
Galvanized Iron/Aluminum	860	856	0	3
Bamboo/Sawali/Cogon/Nipa	21	2	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0
Others/Not Reported	18	2	0	0
No Walls	0	0	0	0
ALFONSO LISTA (POTIA)				
Total	5,445	3,923	3	210
Concrete/Brick/Stone	2,470	2,459	1	3
Wood	439	344	0	4
Half Concrete/Brick/Stone and Half Wood	900	712	1	148
Galvanized Iron/Aluminum	88	73	0	10
Bamboo/Sawali/Cogon/Nipa	1,524	329	0	44
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	7	2	0	0
Others/Not Reported	17	4	1	1
No Walls	0	0	0	0
AGUINALDO				
Total	3,728	3,147	20	2
Concrete/Brick/Stone	202	182	18	1
Wood	2,768	2,322	1	0
Half Concrete/Brick/Stone and Half Wood	220	219	0	1
Galvanized Iron/Aluminum	355	351	1	0
Bamboo/Sawali/Cogon/Nipa	154	55	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0
Others/Not Reported	29	18	0	0
No Walls	0	0	0	0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
HINGYON				
Total	2,085	2,055	3	1
Concrete/Brick/Stone	310	305	3	1
Wood	1,083	1,061	0	0
Half Concrete/Brick/Stone and Half Wood	196	196	0	0
Galvanized Iron/Aluminum	431	430	0	0
Bamboo/Sawali/Cogon/Nipa	52	51	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	3	3	0	0
Others/Not Reported	10	9	0	0
No Walls	0	0	0	0
TINOC				
Total	2,175	1,862	1	5
Concrete/Brick/Stone	40	40	0	0
Wood	1,610	1,304	0	5
Half Concrete/Brick/Stone and Half Wood	160	157	1	0
Galvanized Iron/Aluminum	361	360	0	0
Bamboo/Sawali/Cogon/Nipa	0	0	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	3	1	0	0
Others/Not Reported	1	0	0	0
No Walls	0	0	0	0
ASIPULO				
Total	2,401	2,094	0	1
Concrete/Brick/Stone	67	66	0	0
Wood	2,047	1,755	0	1
Half Concrete/Brick/Stone and Half Wood	234	234	0	0
Galvanized Iron/Aluminum	12	11	0	0
Bamboo/Sawali/Cogon/Nipa	23	21	0	0
Asbestos	0	0	0	0
Glass	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0
Others/Not Reported	18	7	0	0
No Walls	0	0	0	0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
IFUGAO					
Total	38	4,018	17	81	112
Concrete/Brick/Stone	1	8	1	13	7
Wood	31	2,424	2	63	23
Half Concrete/Brick/Stone and Half Wood	2	41	0	4	1
Galvanized Iron/Aluminum	1	18	0	0	3
Bamboo/Sawali/Cogon/Nipa	3	1,504	1	1	1
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	12	13	0	0
Others/Not Reported	0	11	0	0	77
No Walls	0	0	0	0	0
BANAUE					
Total	4	571	2	16	15
Concrete/Brick/Stone	0	1	0	11	3
Wood	4	528	1	4	2
Half Concrete/Brick/Stone and Half Wood	0	0	0	1	0
Galvanized Iron/Aluminum	0	3	0	0	0
Bamboo/Sawali/Cogon/Nipa	0	36	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	2	1	0	0
Others/Not Reported	0	1	0	0	10
No Walls	0	0	0	0	0
HUNGDUAN					
Total	1	49	0	0	9
Concrete/Brick/Stone	0	0	0	0	0
Wood	1	40	0	0	2
Half Concrete/Brick/Stone and Half Wood	0	0	0	0	0
Galvanized Iron/Aluminum	0	0	0	0	0
Bamboo/Sawali/Cogon/Nipa	0	8	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0	0
Others/Not Reported	0	1	0	0	7
No Walls	0	0	0	0	0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
KIANGAN					
Total	0	39	1	0	18
Concrete/Brick/Stone	0	0	1	0	0
Wood	0	18	0	0	8
Half Concrete/Brick/Stone and Half Wood	0	0	0	0	0
Galvanized Iron/Aluminum	0	0	0	0	0
Bamboo/Sawali/Cogon/Nipa	0	21	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0	0
Others/Not Reported	0	0	0	0	10
No Walls	0	0	0	0	0
LAGAWE (Capital)					
Total	2	111	1	2	2
Concrete/Brick/Stone	0	0	0	2	0
Wood	2	94	0	0	0
Half Concrete/Brick/Stone and Half Wood	0	0	0	0	0
Galvanized Iron/Aluminum	0	0	0	0	0
Bamboo/Sawali/Cogon/Nipa	0	16	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	1	1	0	0
Others/Not Reported	0	0	0	0	2
No Walls	0	0	0	0	0
LAMUT					
Total	7	238	10	0	7
Concrete/Brick/Stone	0	0	0	0	1
Wood	3	69	0	0	0
Half Concrete/Brick/Stone and Half Wood	1	5	0	0	0
Galvanized Iron/Aluminum	1	6	0	0	0
Bamboo/Sawali/Cogon/Nipa	2	154	1	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	4	9	0	0
Others/Not Reported	0	0	0	0	6
No Walls	0	0	0	0	0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAYOYAO					
Total	10	622	0	0	22
Concrete/Brick/Stone	1	0	0	0	0
Wood	9	603	0	0	5
Half Concrete/Brick/Stone and Half Wood	0	0	0	0	0
Galvanized Iron/Aluminum	0	0	0	0	1
Bamboo/Sawali/Cogon/Nipa	0	19	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0	0
Others/Not Reported	0	0	0	0	16
No Walls	0	0	0	0	0
ALFONSO LISTA (POTIA)					
Total	2	1,293	0	3	11
Concrete/Brick/Stone	0	6	0	0	1
Wood	0	91	0	0	0
Half Concrete/Brick/Stone and Half Wood	1	35	0	2	1
Galvanized Iron/Aluminum	0	5	0	0	0
Bamboo/Sawali/Cogon/Nipa	1	1,148	0	1	1
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	5	0	0	0
Others/Not Reported	0	3	0	0	8
No Walls	0	0	0	0	0
AGUINALDO					
Total	5	546	0	0	8
Concrete/Brick/Stone	0	1	0	0	0
Wood	5	438	0	0	2
Half Concrete/Brick/Stone and Half Wood	0	0	0	0	0
Galvanized Iron/Aluminum	0	2	0	0	1
Bamboo/Sawali/Cogon/Nipa	0	99	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0	0
Others/Not Reported	0	6	0	0	5
No Walls	0	0	0	0	0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
HINGYON					
Total	0	21	0	0	5
Concrete/Brick/Stone	0	0	0	0	1
Wood	0	20	0	0	2
Half Concrete/Brick/Stone and Half Wood	0	0	0	0	0
Galvanized Iron/Aluminum	0	0	0	0	1
Bamboo/Sawali/Cogon/Nipa	0	1	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0	0
Others/Not Reported	0	0	0	0	1
No Walls	0	0	0	0	0
TINOC					
Total	2	240	3	60	2
Concrete/Brick/Stone	0	0	0	0	0
Wood	2	238	1	59	1
Half Concrete/Brick/Stone and Half Wood	0	1	0	1	0
Galvanized Iron/Aluminum	0	1	0	0	0
Bamboo/Sawali/Cogon/Nipa	0	0	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	2	0	0
Others/Not Reported	0	0	0	0	1
No Walls	0	0	0	0	0
ASIPULO					
Total	5	288	0	0	13
Concrete/Brick/Stone	0	0	0	0	1
Wood	5	285	0	0	1
Half Concrete/Brick/Stone and Half Wood	0	0	0	0	0
Galvanized Iron/Aluminum	0	1	0	0	0
Bamboo/Sawali/Cogon/Nipa	0	2	0	0	0
Asbestos	0	0	0	0	0
Glass	0	0	0	0	0
Makeshift/Salvaged/Improvised Materials	0	0	0	0	0
Others/Not Reported	0	0	0	0	11
No Walls	0	0	0	0	0