

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>ILOCOS SUR</b>				
Total	131,204	121,799	273	3,649
Concrete/Brick/Stone	76,875	76,017	205	382
Wood	7,309	6,772	18	118
Half Concrete/Brick/Stone and Half Wood	26,751	23,766	29	2,627
Galvanized Iron/Aluminum	1,662	1,481	12	120
Bamboo/Sawali/Cogon/Nipa	17,805	13,280	-	385
Asbestos	18	11	-	2
Glass	13	9	1	2
Makeshift/Salvaged/Improvised Materials	156	125	-	1
Others/Not Reported	614	337	8	12
No Walls	1	1	-	-
<b>ALILEM</b>				
Total	1,250	1,195	2	2
Concrete/Brick/Stone	639	632	2	1
Wood	236	226	-	-
Half Concrete/Brick/Stone and Half Wood	248	248	-	-
Galvanized Iron/Aluminum	19	19	-	-
Bamboo/Sawali/Cogon/Nipa	106	69	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	1	-	1
No Walls	-	-	-	-
<b>BANAYOYO</b>				
Total	1,560	1,532	4	5
Concrete/Brick/Stone	852	844	3	5
Wood	107	106	-	-
Half Concrete/Brick/Stone and Half Wood	218	217	1	-
Galvanized Iron/Aluminum	29	28	-	-
Bamboo/Sawali/Cogon/Nipa	347	333	-	-
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	2	-	-
Others/Not Reported	4	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>BANTAY</b>				
Total	6,818	6,615	8	98
Concrete/Brick/Stone	5,000	4,988	5	5
Wood	209	196	-	1
Half Concrete/Brick/Stone and Half Wood	1,143	1,064	2	72
Galvanized Iron/Aluminum	48	44	-	4
Bamboo/Sawali/Cogon/Nipa	394	311	-	16
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	3	-	-
Others/Not Reported	18	8	1	-
No Walls	-	-	-	-
<b>BURGOS</b>				
Total	2,426	2,383	1	4
Concrete/Brick/Stone	1,224	1,220	1	3
Wood	149	148	-	-
Half Concrete/Brick/Stone and Half Wood	533	532	-	1
Galvanized Iron/Aluminum	19	19	-	-
Bamboo/Sawali/Cogon/Nipa	499	462	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	2	-	-
No Walls	-	-	-	-
<b>CABUGAO</b>				
Total	6,805	6,528	5	18
Concrete/Brick/Stone	4,501	4,482	3	1
Wood	100	91	1	1
Half Concrete/Brick/Stone and Half Wood	988	966	-	10
Galvanized Iron/Aluminum	17	16	-	-
Bamboo/Sawali/Cogon/Nipa	1,171	962	-	6
Asbestos	-	-	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	25	8	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>CITY OF CANDON</b>				
Total	11,885	11,687	26	39
Concrete/Brick/Stone	6,748	6,720	16	6
Wood	891	860	4	9
Half Concrete/Brick/Stone and Half Wood	2,580	2,554	5	19
Galvanized Iron/Aluminum	90	87	-	1
Bamboo/Sawali/Cogon/Nipa	1,529	1,435	-	3
Asbestos	-	-	-	-
Glass	3	2	1	-
Makeshift/Salvaged/Improvised Materials	19	19	-	-
Others/Not Reported	25	10	-	1
No Walls	-	-	-	-
<b>CAOAYAN</b>				
Total	3,861	3,715	-	7
Concrete/Brick/Stone	2,658	2,645	-	4
Wood	194	184	-	-
Half Concrete/Brick/Stone and Half Wood	594	588	-	3
Galvanized Iron/Aluminum	7	6	-	-
Bamboo/Sawali/Cogon/Nipa	397	285	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	4	-	-
Others/Not Reported	6	3	-	-
No Walls	-	-	-	-
<b>CERVANTES</b>				
Total	2,950	2,660	9	41
Concrete/Brick/Stone	1,216	1,191	9	4
Wood	377	339	-	6
Half Concrete/Brick/Stone and Half Wood	566	542	-	20
Galvanized Iron/Aluminum	361	354	-	6
Bamboo/Sawali/Cogon/Nipa	372	195	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	25	22	-	-
Others/Not Reported	33	17	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>GALIMUYOD</b>				
Total	1,997	1,892	1	35
Concrete/Brick/Stone	898	897	1	-
Wood	156	155	-	-
Half Concrete/Brick/Stone and Half Wood	464	430	-	33
Galvanized Iron/Aluminum	13	13	-	-
Bamboo/Sawali/Cogon/Nipa	438	382	-	1
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	13	10	-	-
Others/Not Reported	14	4	-	1
No Walls	-	-	-	-
<b>GREGORIO DEL PILAR (CONCEPCION)</b>				
Total	810	788	-	2
Concrete/Brick/Stone	115	111	-	1
Wood	163	159	-	-
Half Concrete/Brick/Stone and Half Wood	317	315	-	1
Galvanized Iron/Aluminum	51	51	-	-
Bamboo/Sawali/Cogon/Nipa	33	27	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	130	124	-	-
No Walls	-	-	-	-
<b>LIDLIDDA</b>				
Total	844	842	-	1
Concrete/Brick/Stone	479	479	-	-
Wood	186	185	-	1
Half Concrete/Brick/Stone and Half Wood	144	144	-	-
Galvanized Iron/Aluminum	10	10	-	-
Bamboo/Sawali/Cogon/Nipa	25	24	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	-	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>MAGSINGAL</b>				
Total	5,836	5,074	11	178
Concrete/Brick/Stone	3,265	3,198	11	18
Wood	89	68	-	-
Half Concrete/Brick/Stone and Half Wood	1,208	1,031	-	134
Galvanized Iron/Aluminum	50	37	-	8
Bamboo/Sawali/Cogon/Nipa	1,186	720	-	18
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	3	-	-
Others/Not Reported	35	17	-	-
No Walls	-	-	-	-
<b>NAGBUKEL</b>				
Total	980	966	-	3
Concrete/Brick/Stone	386	385	-	-
Wood	38	38	-	-
Half Concrete/Brick/Stone and Half Wood	354	351	-	2
Galvanized Iron/Aluminum	1	1	-	-
Bamboo/Sawali/Cogon/Nipa	200	191	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	1	-	-	-
No Walls	-	-	-	-
<b>NARVACAN</b>				
Total	8,699	8,481	4	48
Concrete/Brick/Stone	5,009	4,992	3	11
Wood	238	231	1	3
Half Concrete/Brick/Stone and Half Wood	2,181	2,150	-	29
Galvanized Iron/Aluminum	30	29	-	-
Bamboo/Sawali/Cogon/Nipa	1,211	1,057	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	3	-	-
Others/Not Reported	26	19	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>QUIRINO (ANGKAKI)</b>				
Total	1,520	1,417	13	5
Concrete/Brick/Stone	489	474	13	2
Wood	90	90	-	-
Half Concrete/Brick/Stone and Half Wood	443	440	-	1
Galvanized Iron/Aluminum	169	166	-	-
Bamboo/Sawali/Cogon/Nipa	321	243	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	8	4	-	-
No Walls	-	-	-	-
<b>SALCEDO (BAUGEN)</b>				
Total	2,283	2,187	8	14
Concrete/Brick/Stone	1,113	1,106	4	-
Wood	329	321	2	2
Half Concrete/Brick/Stone and Half Wood	307	295	1	10
Galvanized Iron/Aluminum	39	37	-	1
Bamboo/Sawali/Cogon/Nipa	477	417	-	1
Asbestos	7	7	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	11	4	1	-
No Walls	-	-	-	-
<b>SAN EMILIO</b>				
Total	1,386	1,379	2	1
Concrete/Brick/Stone	265	262	2	-
Wood	553	552	-	1
Half Concrete/Brick/Stone and Half Wood	324	324	-	-
Galvanized Iron/Aluminum	128	128	-	-
Bamboo/Sawali/Cogon/Nipa	114	111	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>SAN ESTEBAN</b>				
Total	1,695	1,572	-	65
Concrete/Brick/Stone	999	990	-	1
Wood	64	62	-	2
Half Concrete/Brick/Stone and Half Wood	371	334	-	37
Galvanized Iron/Aluminum	7	6	-	1
Bamboo/Sawali/Cogon/Nipa	240	176	-	22
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	14	4	-	2
No Walls	-	-	-	-
<b>SAN ILDEFONSO</b>				
Total	1,410	1,327	-	8
Concrete/Brick/Stone	1,150	1,143	-	1
Wood	23	16	-	-
Half Concrete/Brick/Stone and Half Wood	84	73	-	5
Galvanized Iron/Aluminum	1	1	-	-
Bamboo/Sawali/Cogon/Nipa	147	90	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	5	4	-	-
No Walls	-	-	-	-
<b>SAN JUAN (LAPOG)</b>				
Total	5,047	4,628	2	220
Concrete/Brick/Stone	3,073	3,063	1	2
Wood	204	175	-	4
Half Concrete/Brick/Stone and Half Wood	1,017	828	-	186
Galvanized Iron/Aluminum	30	19	-	3
Bamboo/Sawali/Cogon/Nipa	693	534	-	24
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	4	-	-
Others/Not Reported	24	4	1	1
No Walls	1	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>SAN VICENTE</b>				
Total	2,473	2,378	1	52
Concrete/Brick/Stone	1,554	1,544	-	8
Wood	42	40	-	1
Half Concrete/Brick/Stone and Half Wood	731	693	1	33
Galvanized Iron/Aluminum	7	7	-	-
Bamboo/Sawali/Cogon/Nipa	134	92	-	9
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	5	2	-	1
No Walls	-	-	-	-
<b>SANTA</b>				
Total	2,944	2,635	1	191
Concrete/Brick/Stone	1,958	1,927	1	27
Wood	60	58	-	-
Half Concrete/Brick/Stone and Half Wood	641	483	-	150
Galvanized Iron/Aluminum	18	12	-	3
Bamboo/Sawali/Cogon/Nipa	263	153	-	11
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	4	2	-	-
No Walls	-	-	-	-
<b>SANTA CATALINA</b>				
Total	2,606	2,509	-	39
Concrete/Brick/Stone	2,331	2,325	-	1
Wood	44	23	-	3
Half Concrete/Brick/Stone and Half Wood	120	83	-	34
Galvanized Iron/Aluminum	7	7	-	-
Bamboo/Sawali/Cogon/Nipa	102	70	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	1	-	-
No Walls	-	-	-	-



Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>SANTA CRUZ</b>				
Total	7,531	6,358	23	310
Concrete/Brick/Stone	3,723	3,546	16	89
Wood	672	510	4	41
Half Concrete/Brick/Stone and Half Wood	1,464	1,214	1	125
Galvanized Iron/Aluminum	65	54	1	7
Bamboo/Sawali/Cogon/Nipa	1,543	998	-	43
Asbestos	5	1	-	2
Glass	7	4	-	2
Makeshift/Salvaged/Improvised Materials	35	27	-	-
Others/Not Reported	17	4	1	1
No Walls	-	-	-	-
<b>SANTA LUCIA</b>				
Total	5,096	3,720	21	949
Concrete/Brick/Stone	2,195	2,078	10	104
Wood	228	178	2	28
Half Concrete/Brick/Stone and Half Wood	1,726	976	9	736
Galvanized Iron/Aluminum	121	85	-	33
Bamboo/Sawali/Cogon/Nipa	783	397	-	47
Asbestos	2	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	41	6	-	1
No Walls	-	-	-	-
<b>SANTA MARIA</b>				
Total	5,928	5,658	22	146
Concrete/Brick/Stone	3,662	3,602	22	37
Wood	189	181	-	-
Half Concrete/Brick/Stone and Half Wood	1,198	1,068	-	91
Galvanized Iron/Aluminum	32	29	-	3
Bamboo/Sawali/Cogon/Nipa	836	773	-	15
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	9	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>SANTIAGO</b>				
Total	3,751	3,402	9	212
Concrete/Brick/Stone	2,137	2,118	5	12
Wood	279	271	-	3
Half Concrete/Brick/Stone and Half Wood	784	634	-	143
Galvanized Iron/Aluminum	30	23	3	3
Bamboo/Sawali/Cogon/Nipa	513	352	-	50
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	7	3	1	1
No Walls	-	-	-	-
<b>SANTO DOMINGO</b>				
Total	5,497	5,177	9	44
Concrete/Brick/Stone	3,383	3,358	5	7
Wood	67	62	2	-
Half Concrete/Brick/Stone and Half Wood	1,343	1,298	2	28
Galvanized Iron/Aluminum	29	25	-	2
Bamboo/Sawali/Cogon/Nipa	641	412	-	7
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	32	21	-	-
No Walls	-	-	-	-
<b>SIGAY</b>				
Total	445	442	-	-
Concrete/Brick/Stone	70	70	-	-
Wood	231	230	-	-
Half Concrete/Brick/Stone and Half Wood	104	104	-	-
Galvanized Iron/Aluminum	18	18	-	-
Bamboo/Sawali/Cogon/Nipa	7	6	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	15	14	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>SINAIT</b>				
Total	5,489	4,848	13	227
Concrete/Brick/Stone	3,293	3,264	9	8
Wood	49	45	-	-
Half Concrete/Brick/Stone and Half Wood	1,124	931	2	175
Galvanized Iron/Aluminum	38	13	1	17
Bamboo/Sawali/Cogon/Nipa	959	580	-	27
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	4	-	-
Others/Not Reported	20	11	1	-
No Walls	-	-	-	-
<b>SUGPON</b>				
Total	738	662	1	11
Concrete/Brick/Stone	190	180	1	8
Wood	252	237	-	-
Half Concrete/Brick/Stone and Half Wood	175	172	-	3
Galvanized Iron/Aluminum	15	15	-	-
Bamboo/Sawali/Cogon/Nipa	98	56	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	8	2	-	-
No Walls	-	-	-	-
<b>SUYO</b>				
Total	2,217	1,344	22	572
Concrete/Brick/Stone	376	345	19	10
Wood	247	227	-	2
Half Concrete/Brick/Stone and Half Wood	1,126	634	2	477
Galvanized Iron/Aluminum	53	21	-	27
Bamboo/Sawali/Cogon/Nipa	403	116	-	55
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	12	1	1	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
<b>TAGUDIN</b>				
Total	7,244	6,937	5	17
Concrete/Brick/Stone	4,484	4,457	4	-
Wood	181	175	1	-
Half Concrete/Brick/Stone and Half Wood	1,265	1,249	-	9
Galvanized Iron/Aluminum	78	78	-	-
Bamboo/Sawali/Cogon/Nipa	1,194	948	-	8
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	6	-	-
Others/Not Reported	35	24	-	-
No Walls	-	-	-	-
<b>CITY OF VIGAN (Capital)</b>				
Total	9,183	8,861	50	85
Concrete/Brick/Stone	7,440	7,381	39	6
Wood	372	333	1	10
Half Concrete/Brick/Stone and Half Wood	866	801	3	60
Galvanized Iron/Aluminum	32	23	7	1
Bamboo/Sawali/Cogon/Nipa	429	303	-	7
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	22	14	-	1
Others/Not Reported	22	6	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>ILOCOS SUR</b>					
Total	630	4,425	40	66	322
Concrete/Brick/Stone	73	126	6	24	42
Wood	170	216	3	6	6
Half Concrete/Brick/Stone and Half Wood	181	128	2	3	15
Galvanized Iron/Aluminum	26	19	1	-	3
Bamboo/Sawali/Cogon/Nipa	177	3,914	9	19	21
Asbestos	2	-	-	2	1
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	12	18	-	-
Others/Not Reported	1	10	1	12	233
No Walls	-	-	-	-	-
<b>ALILEM</b>					
Total	-	47	-	1	3
Concrete/Brick/Stone	-	1	-	1	2
Wood	-	10	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	36	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-
<b>BANAYOYO</b>					
Total	-	16	-	-	3
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	14	-	-	-
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>BANTAY</b>					
Total	6	78	3	-	10
Concrete/Brick/Stone	-	1	1	-	-
Wood	3	9	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	3	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	65	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	-	-	-	9
No Walls	-	-	-	-	-
<b>BURGOS</b>					
Total	-	38	-	-	-
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	37	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-
<b>CABUGAO</b>					
Total	9	225	-	-	20
Concrete/Brick/Stone	-	12	-	-	3
Wood	5	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	9	-	-	2
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	199	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	2	-	-	14
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CITY OF CANDON</b>					
Total	14	95	4	1	19
Concrete/Brick/Stone	1	-	1	1	3
Wood	7	10	1	-	-
Half Concrete/Brick/Stone and Half Wood	1	1	-	-	-
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	83	2	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	14
No Walls	-	-	-	-	-
<b>CAOAYAN</b>					
Total	1	124	2	5	7
Concrete/Brick/Stone	-	6	2	-	1
Wood	1	9	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	1	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	106	-	4	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	-	3
No Walls	-	-	-	-	-
<b>CERVANTES</b>					
Total	17	196	-	14	13
Concrete/Brick/Stone	-	1	-	11	-
Wood	5	26	-	1	-
Half Concrete/Brick/Stone and Half Wood	1	3	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	162	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	-	-	2	13
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>GALIMUYOD</b>					
Total	-	57	2	-	10
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	55	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	2	-	-
Others/Not Reported	-	-	-	-	9
No Walls	-	-	-	-	-
<b>GREGORIO DEL PILAR (CONCEPCION)</b>					
Total	-	8	-	8	4
Concrete/Brick/Stone	-	1	-	2	-
Wood	-	1	-	3	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	5	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	3	2
No Walls	-	-	-	-	-
<b>LIDLIDDA</b>					
Total	-	1	-	-	-
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-



Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>MAGSINGAL</b>					
Total	5	542	1	3	22
Concrete/Brick/Stone	-	37	-	-	1
Wood	2	19	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	41	-	-	2
Galvanized Iron/Aluminum	-	4	-	-	1
Bamboo/Sawali/Cogon/Nipa	3	441	1	2	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	1	17
No Walls	-	-	-	-	-
<b>NAGBUKEL</b>					
Total	-	9	-	1	1
Concrete/Brick/Stone	-	-	-	1	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	8	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-
<b>NARVACAN</b>					
Total	5	152	1	1	7
Concrete/Brick/Stone	-	2	-	-	1
Wood	-	3	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	-	-	-	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	146	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	1	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>QUIRINO (ANGKAKI)</b>					
Total	-	79	-	-	6
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	1
Galvanized Iron/Aluminum	-	2	-	-	1
Bamboo/Sawali/Cogon/Nipa	-	76	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	4
No Walls	-	-	-	-	-
<b>SALCEDO (BAUGEN)</b>					
Total	1	61	-	-	12
Concrete/Brick/Stone	-	1	-	-	2
Wood	-	1	-	-	3
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	57	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-
<b>SAN EMILIO</b>					
Total	-	3	-	-	1
Concrete/Brick/Stone	-	-	-	-	1
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	3	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>SAN ESTEBAN</b>					
Total	1	40	-	-	17
Concrete/Brick/Stone	-	-	-	-	8
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	40	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	8
No Walls	-	-	-	-	-
<b>SAN ILDEFONSO</b>					
Total	5	66	-	4	-
Concrete/Brick/Stone	-	4	-	2	-
Wood	2	5	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	4	-	2	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	52	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	-
No Walls	-	-	-	-	-
<b>SAN JUAN (LAPOG)</b>					
Total	4	163	5	4	21
Concrete/Brick/Stone	-	5	-	1	1
Wood	-	23	2	-	-
Half Concrete/Brick/Stone and Half Wood	-	3	-	-	-
Galvanized Iron/Aluminum	4	3	1	-	-
Bamboo/Sawali/Cogon/Nipa	-	129	1	3	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	-	18
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>SAN VICENTE</b>					
Total	1	36	-	-	5
Concrete/Brick/Stone	-	-	-	-	2
Wood	1	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	3	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	33	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
<b>SANTA</b>					
Total	9	100	5	-	3
Concrete/Brick/Stone	-	1	1	-	1
Wood	-	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	4	3	1	-	-
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	92	3	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
<b>SANTA CATALINA</b>					
Total	17	38	-	1	2
Concrete/Brick/Stone	-	3	-	1	1
Wood	15	3	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	3	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	29	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>SANTA CRUZ</b>					
Total	373	441	3	7	16
Concrete/Brick/Stone	64	5	-	-	3
Wood	93	23	-	-	1
Half Concrete/Brick/Stone and Half Wood	118	5	-	-	1
Galvanized Iron/Aluminum	3	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	92	403	-	6	1
Asbestos	2	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	5	3	-	-
Others/Not Reported	1	-	-	1	9
No Walls	-	-	-	-	-
<b>SANTA LUCIA</b>					
Total	29	338	-	3	36
Concrete/Brick/Stone	-	-	-	-	3
Wood	13	6	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	5	-	-	-
Galvanized Iron/Aluminum	3	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	13	325	-	-	1
Asbestos	-	-	-	2	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	2	-	-	32
No Walls	-	-	-	-	-
<b>SANTA MARIA</b>					
Total	52	39	-	-	11
Concrete/Brick/Stone	-	-	-	-	1
Wood	6	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	38	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	37	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>SANTIAGO</b>					
Total	6	118	-	-	4
Concrete/Brick/Stone	1	-	-	-	1
Wood	3	1	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	7	-	-	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	110	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
<b>SANTO DOMINGO</b>					
Total	6	243	1	7	10
Concrete/Brick/Stone	-	10	-	1	2
Wood	2	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	13	-	-	1
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	216	-	3	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	2	-	3	6
No Walls	-	-	-	-	-
<b>SIGAY</b>					
Total	-	2	-	-	1
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>SINAIT</b>					
Total	14	374	3	1	9
Concrete/Brick/Stone	-	9	1	1	1
Wood	-	4	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	14	-	-	-
Galvanized Iron/Aluminum	7	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	346	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	1	-	-	7
No Walls	-	-	-	-	-
<b>SUGPON</b>					
Total	-	56	-	1	7
Concrete/Brick/Stone	-	-	-	1	-
Wood	-	14	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	42	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-
<b>SUYO</b>					
Total	39	228	1	-	11
Concrete/Brick/Stone	1	-	-	-	1
Wood	8	10	-	-	-
Half Concrete/Brick/Stone and Half Wood	11	1	1	-	-
Galvanized Iron/Aluminum	4	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	15	216	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>TAGUDIN</b>					
Total	7	258	1	4	15
Concrete/Brick/Stone	5	15	-	1	2
Wood	-	4	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	5	-	-	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	234	-	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	1	10
No Walls	-	-	-	-	-
<b>CITY OF VIGAN (Capital)</b>					
Total	9	154	8	-	16
Concrete/Brick/Stone	1	12	-	-	1
Wood	4	24	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	1	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	115	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	6	-	-
Others/Not Reported	-	-	1	-	15
No Walls	-	-	-	-	-