

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ILOILO				
Total	343,115	265,993	787	12,518
Concrete/Brick/Stone	77,808	75,577	619	921
Wood	18,143	15,179	11	572
Half Concrete/Brick/Stone and Half Wood	59,507	51,811	102	5,726
Galvanized Iron/Aluminum	2,017	1,348	20	444
Bamboo/Sawali/Cogon/Nipa	182,912	120,614	-	4,827
Asbestos	80	72	1	3
Glass	45	38	1	3
Makeshift/Salvaged/Improvised Materials	572	329	-	9
Others/Not Reported	2,030	1,025	33	13
No Walls	1	-	-	-
AJUY				
Total	9,178	5,850	31	742
Concrete/Brick/Stone	1,434	1,370	27	31
Wood	230	154	-	34
Half Concrete/Brick/Stone and Half Wood	1,794	1,415	2	289
Galvanized Iron/Aluminum	177	45	1	99
Bamboo/Sawali/Cogon/Nipa	5,497	2,857	-	289
Asbestos	3	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	4	-	-
Others/Not Reported	38	3	1	-
No Walls	-	-	-	-
ALIMODIAN				
Total	6,950	6,272	2	311
Concrete/Brick/Stone	1,500	1,493	2	4
Wood	168	149	-	6
Half Concrete/Brick/Stone and Half Wood	935	740	-	187
Galvanized Iron/Aluminum	41	34	-	7
Bamboo/Sawali/Cogon/Nipa	4,281	3,840	-	107
Asbestos	1	1	-	-
Glass	3	3	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	20	12	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ANILAO				
Total	4,690	3,796	2	2
Concrete/Brick/Stone	1,005	1,004	-	-
Wood	136	135	-	-
Half Concrete/Brick/Stone and Half Wood	680	670	1	-
Galvanized Iron/Aluminum	17	14	-	-
Bamboo/Sawali/Cogon/Nipa	2,830	1,970	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	1	-	-
Others/Not Reported	17	2	1	-
No Walls	-	-	-	-
BADIANGAN				
Total	5,158	4,043	27	504
Concrete/Brick/Stone	784	749	24	11
Wood	47	45	-	1
Half Concrete/Brick/Stone and Half Wood	869	716	3	138
Galvanized Iron/Aluminum	35	32	-	2
Bamboo/Sawali/Cogon/Nipa	3,421	2,500	-	352
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	1	-	-
No Walls	-	-	-	-
BALASAN				
Total	5,754	2,558	12	446
Concrete/Brick/Stone	1,132	1,098	8	12
Wood	423	153	-	45
Half Concrete/Brick/Stone and Half Wood	904	549	-	295
Galvanized Iron/Aluminum	63	33	4	17
Bamboo/Sawali/Cogon/Nipa	3,209	717	-	77
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	18	7	-	-
Others/Not Reported	5	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BANATE				
Total	5,905	4,421	16	233
Concrete/Brick/Stone	1,200	1,171	11	12
Wood	638	496	1	20
Half Concrete/Brick/Stone and Half Wood	1,250	1,071	3	133
Galvanized Iron/Aluminum	62	54	-	5
Bamboo/Sawali/Cogon/Nipa	2,734	1,624	-	63
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	20	4	1	-
No Walls	-	-	-	-
BAROTAC NUEVO				
Total	10,043	7,938	15	527
Concrete/Brick/Stone	3,278	3,087	11	170
Wood	718	609	-	64
Half Concrete/Brick/Stone and Half Wood	1,909	1,762	2	113
Galvanized Iron/Aluminum	40	25	-	8
Bamboo/Sawali/Cogon/Nipa	3,984	2,391	-	170
Asbestos	10	10	-	-
Glass	4	3	1	-
Makeshift/Salvaged/Improvised Materials	24	15	-	-
Others/Not Reported	76	36	1	2
No Walls	-	-	-	-
BAROTAC VIEJO				
Total	8,111	4,868	17	767
Concrete/Brick/Stone	1,291	1,216	12	58
Wood	208	183	-	-
Half Concrete/Brick/Stone and Half Wood	1,592	1,191	5	366
Galvanized Iron/Aluminum	30	23	-	3
Bamboo/Sawali/Cogon/Nipa	4,939	2,242	-	340
Asbestos	-	-	-	-
Glass	3	3	-	-
Makeshift/Salvaged/Improvised Materials	4	-	-	-
Others/Not Reported	44	10	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BATAD				
Total	3,740	1,857	5	414
Concrete/Brick/Stone	689	639	3	41
Wood	15	12	-	2
Half Concrete/Brick/Stone and Half Wood	627	387	2	219
Galvanized Iron/Aluminum	53	4	-	35
Bamboo/Sawali/Cogon/Nipa	2,332	808	-	116
Asbestos	2	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	7	-	1
Others/Not Reported	13	-	-	-
No Walls	-	-	-	-
BINGAWAN				
Total	2,639	2,407	3	4
Concrete/Brick/Stone	445	441	3	-
Wood	39	37	-	-
Half Concrete/Brick/Stone and Half Wood	317	317	-	-
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	1,828	1,607	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	7	2	-	-
No Walls	-	-	-	-
CABATUAN				
Total	10,666	9,500	29	134
Concrete/Brick/Stone	2,599	2,556	27	7
Wood	202	193	-	2
Half Concrete/Brick/Stone and Half Wood	1,435	1,359	2	65
Galvanized Iron/Aluminum	33	24	-	6
Bamboo/Sawali/Cogon/Nipa	6,248	5,270	-	52
Asbestos	1	-	-	-
Glass	10	7	-	2
Makeshift/Salvaged/Improvised Materials	3	2	-	-
Others/Not Reported	135	89	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
CALINOG				
Total	10,193	8,133	7	259
Concrete/Brick/Stone	1,866	1,856	4	2
Wood	307	299	-	3
Half Concrete/Brick/Stone and Half Wood	1,212	1,168	3	35
Galvanized Iron/Aluminum	97	67	-	28
Bamboo/Sawali/Cogon/Nipa	6,651	4,722	-	191
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	-	-	-
Others/Not Reported	56	21	-	-
No Walls	-	-	-	-
CARLES				
Total	11,510	5,335	30	755
Concrete/Brick/Stone	2,228	2,145	10	27
Wood	378	183	-	16
Half Concrete/Brick/Stone and Half Wood	1,804	1,172	9	432
Galvanized Iron/Aluminum	109	34	3	62
Bamboo/Sawali/Cogon/Nipa	6,941	1,791	-	216
Asbestos	4	4	-	-
Glass	3	1	-	1
Makeshift/Salvaged/Improvised Materials	13	4	-	-
Others/Not Reported	30	1	8	1
No Walls	-	-	-	-
CONCEPCION				
Total	7,414	2,848	9	732
Concrete/Brick/Stone	1,133	1,074	6	18
Wood	195	91	-	16
Half Concrete/Brick/Stone and Half Wood	1,477	789	2	502
Galvanized Iron/Aluminum	63	32	1	18
Bamboo/Sawali/Cogon/Nipa	4,452	831	-	178
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	22	5	-	-
Others/Not Reported	72	26	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
DINGLE				
Total	8,603	7,371	8	56
Concrete/Brick/Stone	2,551	2,521	8	13
Wood	336	317	-	-
Half Concrete/Brick/Stone and Half Wood	1,585	1,554	-	10
Galvanized Iron/Aluminum	37	35	-	-
Bamboo/Sawali/Cogon/Nipa	4,057	2,923	-	33
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	4	-	-
Others/Not Reported	27	16	-	-
No Walls	-	-	-	-
DUEÑAS				
Total	6,703	6,054	3	46
Concrete/Brick/Stone	1,603	1,588	3	8
Wood	244	236	-	1
Half Concrete/Brick/Stone and Half Wood	934	920	-	10
Galvanized Iron/Aluminum	16	15	-	-
Bamboo/Sawali/Cogon/Nipa	3,805	3,226	-	27
Asbestos	1	1	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	97	66	-	-
No Walls	-	-	-	-
DUMANGAS				
Total	13,285	10,673	66	426
Concrete/Brick/Stone	3,692	3,624	28	32
Wood	1,475	1,259	-	68
Half Concrete/Brick/Stone and Half Wood	2,381	2,189	32	114
Galvanized Iron/Aluminum	85	56	2	16
Bamboo/Sawali/Cogon/Nipa	5,568	3,497	-	195
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	10	-	1
Others/Not Reported	64	36	4	-
No Walls	1	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ESTANCIA				
Total	7,921	5,493	33	297
Concrete/Brick/Stone	1,524	1,474	22	5
Wood	462	264	-	28
Half Concrete/Brick/Stone and Half Wood	1,990	1,708	5	175
Galvanized Iron/Aluminum	46	31	-	8
Bamboo/Sawali/Cogon/Nipa	3,811	1,964	-	80
Asbestos	2	1	1	-
Glass	7	6	-	-
Makeshift/Salvaged/Improvised Materials	54	34	-	-
Others/Not Reported	25	11	5	1
No Walls	-	-	-	-
GUIMBAL				
Total	6,289	4,859	3	203
Concrete/Brick/Stone	1,959	1,939	3	3
Wood	278	230	-	10
Half Concrete/Brick/Stone and Half Wood	1,142	977	-	103
Galvanized Iron/Aluminum	10	9	-	1
Bamboo/Sawali/Cogon/Nipa	2,725	1,555	-	85
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	7	-	-
Others/Not Reported	166	142	-	1
No Walls	-	-	-	-
IGBARAS				
Total	6,088	5,700	3	27
Concrete/Brick/Stone	810	803	3	1
Wood	331	317	-	1
Half Concrete/Brick/Stone and Half Wood	931	919	-	5
Galvanized Iron/Aluminum	35	33	-	-
Bamboo/Sawali/Cogon/Nipa	3,930	3,601	-	19
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	4	-	1
Others/Not Reported	39	22	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
JANIUAY				
Total	11,323	9,476	10	79
Concrete/Brick/Stone	1,887	1,863	6	12
Wood	177	161	1	6
Half Concrete/Brick/Stone and Half Wood	1,655	1,613	1	29
Galvanized Iron/Aluminum	78	63	2	8
Bamboo/Sawali/Cogon/Nipa	7,477	5,748	-	24
Asbestos	3	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	44	24	-	-
No Walls	-	-	-	-
LAMBUNAO				
Total	12,490	11,127	11	239
Concrete/Brick/Stone	1,936	1,914	8	8
Wood	341	309	-	1
Half Concrete/Brick/Stone and Half Wood	1,744	1,714	1	23
Galvanized Iron/Aluminum	36	30	1	3
Bamboo/Sawali/Cogon/Nipa	8,392	7,133	-	204
Asbestos	3	3	-	-
Glass	11	11	-	-
Makeshift/Salvaged/Improvised Materials	3	2	-	-
Others/Not Reported	24	11	1	-
No Walls	-	-	-	-
LEGANES				
Total	5,509	4,283	3	64
Concrete/Brick/Stone	1,895	1,863	3	13
Wood	491	446	-	2
Half Concrete/Brick/Stone and Half Wood	696	631	-	17
Galvanized Iron/Aluminum	11	10	-	-
Bamboo/Sawali/Cogon/Nipa	2,324	1,287	-	27
Asbestos	9	9	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	48	28	-	2
Others/Not Reported	34	8	-	3
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
LEMERY				
Total	5,334	3,780	1	227
Concrete/Brick/Stone	685	679	1	3
Wood	50	36	-	1
Half Concrete/Brick/Stone and Half Wood	818	736	-	69
Galvanized Iron/Aluminum	41	33	-	4
Bamboo/Sawali/Cogon/Nipa	3,729	2,295	-	150
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	9	-	-	-
No Walls	-	-	-	-
LEON				
Total	9,017	8,790	5	7
Concrete/Brick/Stone	1,882	1,877	5	-
Wood	630	620	-	1
Half Concrete/Brick/Stone and Half Wood	1,260	1,253	-	6
Galvanized Iron/Aluminum	36	35	-	-
Bamboo/Sawali/Cogon/Nipa	5,177	4,993	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	5	-	-
Others/Not Reported	25	7	-	-
No Walls	-	-	-	-
MAASIN				
Total	6,036	5,531	25	61
Concrete/Brick/Stone	1,342	1,301	22	19
Wood	279	273	-	-
Half Concrete/Brick/Stone and Half Wood	868	832	3	32
Galvanized Iron/Aluminum	17	17	-	-
Bamboo/Sawali/Cogon/Nipa	3,498	3,094	-	8
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	29	13	-	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MIAGAO				
Total	11,865	9,938	34	155
Concrete/Brick/Stone	2,573	2,524	22	21
Wood	1,182	1,008	1	15
Half Concrete/Brick/Stone and Half Wood	2,646	2,490	8	69
Galvanized Iron/Aluminum	65	43	-	3
Bamboo/Sawali/Cogon/Nipa	5,252	3,789	-	46
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	42	29	-	1
Others/Not Reported	105	55	3	-
No Walls	-	-	-	-
MINA				
Total	4,004	3,387	4	58
Concrete/Brick/Stone	1,104	1,092	4	5
Wood	52	47	-	-
Half Concrete/Brick/Stone and Half Wood	674	645	-	17
Galvanized Iron/Aluminum	20	20	-	-
Bamboo/Sawali/Cogon/Nipa	2,146	1,580	-	36
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	5	2	-	-
No Walls	-	-	-	-
NEW LUCENA				
Total	4,224	3,873	2	6
Concrete/Brick/Stone	1,213	1,209	1	1
Wood	104	103	-	-
Half Concrete/Brick/Stone and Half Wood	538	534	-	3
Galvanized Iron/Aluminum	8	8	-	-
Bamboo/Sawali/Cogon/Nipa	2,342	2,014	-	2
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	16	4	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
OTON				
Total	16,009	11,596	253	831
Concrete/Brick/Stone	5,031	4,426	239	75
Wood	1,418	1,207	3	28
Half Concrete/Brick/Stone and Half Wood	3,375	2,668	8	460
Galvanized Iron/Aluminum	114	74	2	18
Bamboo/Sawali/Cogon/Nipa	5,863	3,101	-	249
Asbestos	5	4	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	36	18	-	-
Others/Not Reported	167	98	1	-
No Walls	-	-	-	-
CITY OF PASSI				
Total	14,922	12,895	21	356
Concrete/Brick/Stone	2,583	2,556	12	10
Wood	321	307	-	5
Half Concrete/Brick/Stone and Half Wood	3,092	2,982	3	87
Galvanized Iron/Aluminum	116	96	3	14
Bamboo/Sawali/Cogon/Nipa	8,625	6,821	-	239
Asbestos	3	3	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	29	18	-	1
Others/Not Reported	152	111	3	-
No Walls	-	-	-	-
PAVIA				
Total	8,211	6,940	7	511
Concrete/Brick/Stone	3,183	3,125	6	49
Wood	869	767	-	66
Half Concrete/Brick/Stone and Half Wood	1,676	1,420	1	243
Galvanized Iron/Aluminum	38	23	-	12
Bamboo/Sawali/Cogon/Nipa	2,322	1,520	-	139
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	92	71	-	2
Others/Not Reported	31	14	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
POTOTAN				
Total	13,567	11,307	5	226
Concrete/Brick/Stone	4,051	4,032	5	6
Wood	1,133	1,017	-	15
Half Concrete/Brick/Stone and Half Wood	2,396	2,223	-	122
Galvanized Iron/Aluminum	57	39	-	13
Bamboo/Sawali/Cogon/Nipa	5,869	3,970	-	69
Asbestos	2	1	-	1
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	27	16	-	-
Others/Not Reported	31	8	-	-
No Walls	-	-	-	-
SAN DIONISIO				
Total	6,472	3,113	11	523
Concrete/Brick/Stone	1,025	1,004	8	4
Wood	72	49	1	8
Half Concrete/Brick/Stone and Half Wood	1,044	639	1	334
Galvanized Iron/Aluminum	48	27	-	15
Bamboo/Sawali/Cogon/Nipa	4,261	1,392	-	160
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	1	-	-
Others/Not Reported	18	1	1	2
No Walls	-	-	-	-
SAN ENRIQUE				
Total	6,102	4,902	1	394
Concrete/Brick/Stone	1,189	1,187	-	1
Wood	186	173	-	3
Half Concrete/Brick/Stone and Half Wood	1,077	965	1	104
Galvanized Iron/Aluminum	23	19	-	4
Bamboo/Sawali/Cogon/Nipa	3,533	2,550	-	282
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	4	-	-
Others/Not Reported	83	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SAN JOAQUIN				
Total	9,461	7,322	7	268
Concrete/Brick/Stone	1,685	1,627	4	29
Wood	1,050	792	1	8
Half Concrete/Brick/Stone and Half Wood	1,643	1,470	1	102
Galvanized Iron/Aluminum	37	27	1	7
Bamboo/Sawali/Cogon/Nipa	4,961	3,350	-	122
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	1	-	-
Others/Not Reported	78	54	-	-
No Walls	-	-	-	-
SAN MIGUEL				
Total	4,905	3,928	7	326
Concrete/Brick/Stone	1,510	1,482	6	19
Wood	273	259	-	3
Half Concrete/Brick/Stone and Half Wood	793	669	1	115
Galvanized Iron/Aluminum	15	15	-	-
Bamboo/Sawali/Cogon/Nipa	2,290	1,490	-	189
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	4	-	-
Others/Not Reported	17	9	-	-
No Walls	-	-	-	-
SAN RAFAEL				
Total	2,790	2,089	1	3
Concrete/Brick/Stone	508	507	-	-
Wood	50	48	-	-
Half Concrete/Brick/Stone and Half Wood	324	315	-	1
Galvanized Iron/Aluminum	10	10	-	-
Bamboo/Sawali/Cogon/Nipa	1,882	1,203	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	4	-	-
Others/Not Reported	11	2	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SANTA BARBARA				
Total	10,632	8,803	40	552
Concrete/Brick/Stone	3,399	3,281	39	63
Wood	686	629	1	30
Half Concrete/Brick/Stone and Half Wood	1,740	1,391	-	319
Galvanized Iron/Aluminum	69	59	-	9
Bamboo/Sawali/Cogon/Nipa	4,599	3,372	-	129
Asbestos	13	12	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	7	-	-
Others/Not Reported	117	52	-	1
No Walls	-	-	-	-
SARA				
Total	9,509	7,920	4	60
Concrete/Brick/Stone	1,557	1,535	2	5
Wood	211	187	1	-
Half Concrete/Brick/Stone and Half Wood	2,202	2,143	-	27
Galvanized Iron/Aluminum	48	41	-	4
Bamboo/Sawali/Cogon/Nipa	5,462	4,008	-	24
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	2	-	-
Others/Not Reported	24	4	1	-
No Walls	-	-	-	-
TIGBAUAN				
Total	11,234	7,483	12	582
Concrete/Brick/Stone	2,922	2,732	9	120
Wood	815	520	1	56
Half Concrete/Brick/Stone and Half Wood	2,008	1,489	2	334
Galvanized Iron/Aluminum	41	26	-	11
Bamboo/Sawali/Cogon/Nipa	5,413	2,697	-	61
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	14	5	-	-
Others/Not Reported	16	9	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

TUBUNGAN

Total	4,202	4,081	1	18
Concrete/Brick/Stone	584	580	1	1
Wood	542	540	-	-
Half Concrete/Brick/Stone and Half Wood	751	747	-	2
Galvanized Iron/Aluminum	6	6	-	-
Bamboo/Sawali/Cogon/Nipa	2,281	2,172	-	15
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	37	35	-	-
No Walls	-	-	-	-

ZARRAGA

Total	4,457	3,453	1	87
Concrete/Brick/Stone	1,341	1,333	1	2
Wood	381	319	-	7
Half Concrete/Brick/Stone and Half Wood	719	669	-	20
Galvanized Iron/Aluminum	31	24	-	4
Bamboo/Sawali/Cogon/Nipa	1,971	1,099	-	54
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	4	-	-
Others/Not Reported	4	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ILOILO					
Total	3,330	57,908	264	1,321	994
Concrete/Brick/Stone	88	272	2	296	33
Wood	523	1,775	15	54	14
Half Concrete/Brick/Stone and Half Wood	424	1,296	7	109	32
Galvanized Iron/Aluminum	94	105	1	-	5
Bamboo/Sawali/Cogon/Nipa	2,190	54,235	150	731	165
Asbestos	2	-	-	2	-
Glass	2	-	-	1	-
Makeshift/Salvaged/Improvised Materials	5	128	88	11	2
Others/Not Reported	2	96	1	117	743
No Walls	-	1	-	-	-
AJUJY					
Total	148	2,353	6	4	44
Concrete/Brick/Stone	-	3	-	3	-
Wood	16	24	-	-	2
Half Concrete/Brick/Stone and Half Wood	33	53	-	-	2
Galvanized Iron/Aluminum	24	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	75	2,262	6	-	8
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	2	-	-	32
No Walls	-	-	-	-	-
ALIMODIAN					
Total	26	324	1	4	10
Concrete/Brick/Stone	1	-	-	-	-
Wood	11	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	4	4	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	318	-	4	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ANILAO					
Total	1	871	3	-	15
Concrete/Brick/Stone	-	-	-	-	1
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	9	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	854	2	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	-	-
Others/Not Reported	-	1	-	-	13
No Walls	-	-	-	-	-
BADIANGAN					
Total	3	573	3	-	5
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	9	2	-	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	562	1	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-
BALASAN					
Total	63	2,639	31	-	5
Concrete/Brick/Stone	-	13	-	-	1
Wood	31	184	9	-	1
Half Concrete/Brick/Stone and Half Wood	12	46	2	-	-
Galvanized Iron/Aluminum	2	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	2,386	9	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	11	-	-
Others/Not Reported	1	3	-	-	-
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BANATE					
Total	45	1,168	3	5	14
Concrete/Brick/Stone	-	3	-	3	-
Wood	29	92	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	39	-	2	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	1,030	3	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	14
No Walls	-	-	-	-	-
BAROTAC NUEVO					
Total	11	1,484	5	32	31
Concrete/Brick/Stone	-	8	-	1	1
Wood	1	43	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	27	-	3	2
Galvanized Iron/Aluminum	1	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	1,392	1	20	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	4	-	-
Others/Not Reported	-	3	-	7	27
No Walls	-	-	-	-	-
BAROTAC VIEJO					
Total	18	2,396	9	-	36
Concrete/Brick/Stone	-	4	-	-	1
Wood	1	24	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	29	-	-	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	2,334	5	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	4	-	-
Others/Not Reported	-	1	-	-	33
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BATAD					
Total	55	1,394	1	4	10
Concrete/Brick/Stone	-	6	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	19	-	-	-
Galvanized Iron/Aluminum	9	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	45	1,360	-	3	-
Asbestos	1	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	3	-	-	10
No Walls	-	-	-	-	-
BINGAWAN					
Total	2	217	1	1	4
Concrete/Brick/Stone	-	1	-	-	-
Wood	1	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	214	1	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	4
No Walls	-	-	-	-	-
CABATUAN					
Total	8	909	-	66	20
Concrete/Brick/Stone	-	3	-	6	-
Wood	1	6	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	7	-	-	1
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	889	-	31	2
Asbestos	1	-	-	-	-
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	1	-	28	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
CALINOG					
Total	252	1,479	1	23	39
Concrete/Brick/Stone	-	2	1	-	1
Wood	2	3	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	4	-	1	-
Galvanized Iron/Aluminum	-	1	-	-	1
Bamboo/Sawali/Cogon/Nipa	247	1,466	-	20	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	2	-	-	-
Others/Not Reported	-	1	-	2	32
No Walls	-	-	-	-	-
CARLES					
Total	179	5,184	6	2	19
Concrete/Brick/Stone	1	43	-	1	1
Wood	11	167	1	-	-
Half Concrete/Brick/Stone and Half Wood	34	156	-	-	1
Galvanized Iron/Aluminum	3	6	-	-	1
Bamboo/Sawali/Cogon/Nipa	128	4,797	3	-	6
Asbestos	-	-	-	-	-
Glass	1	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	2	-	-
Others/Not Reported	1	8	-	1	10
No Walls	-	-	-	-	-
CONCEPCION					
Total	145	3,594	12	44	30
Concrete/Brick/Stone	1	22	-	11	1
Wood	29	57	-	2	-
Half Concrete/Brick/Stone and Half Wood	4	166	1	12	1
Galvanized Iron/Aluminum	6	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	105	3,321	9	8	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	11	2	3	1
Others/Not Reported	-	11	-	8	27
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
DINGLE					
Total	5	1,134	4	15	10
Concrete/Brick/Stone	-	7	-	2	-
Wood	-	17	-	2	-
Half Concrete/Brick/Stone and Half Wood	1	18	1	1	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	1,086	1	9	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	2	-	-
Others/Not Reported	-	1	-	1	9
No Walls	-	-	-	-	-
DUEÑAS					
Total	3	561	-	2	34
Concrete/Brick/Stone	-	3	-	-	1
Wood	-	7	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	4	-	-	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	545	-	2	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	1	-	-	30
No Walls	-	-	-	-	-
DUMANGAS					
Total	47	2,012	1	37	23
Concrete/Brick/Stone	-	5	-	3	-
Wood	4	143	-	1	-
Half Concrete/Brick/Stone and Half Wood	4	33	-	8	1
Galvanized Iron/Aluminum	6	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	33	1,818	-	23	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	1	1	-
Others/Not Reported	-	3	-	1	20
No Walls	-	1	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ESTANCIA					
Total	208	1,867	15	2	6
Concrete/Brick/Stone	19	4	-	-	-
Wood	80	87	2	1	-
Half Concrete/Brick/Stone and Half Wood	36	65	-	-	1
Galvanized Iron/Aluminum	3	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	69	1,688	9	-	1
Asbestos	-	-	-	-	-
Glass	1	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	4	-	-
Others/Not Reported	-	3	-	1	4
No Walls	-	-	-	-	-
GUIMBAL					
Total	3	1,103	2	103	13
Concrete/Brick/Stone	1	12	-	1	-
Wood	1	33	-	4	-
Half Concrete/Brick/Stone and Half Wood	-	41	-	18	3
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	1,010	1	70	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	6	-	10	7
No Walls	-	-	-	-	-
IGBARAS					
Total	61	188	4	86	19
Concrete/Brick/Stone	-	-	-	3	-
Wood	-	12	-	1	-
Half Concrete/Brick/Stone and Half Wood	1	3	1	1	1
Galvanized Iron/Aluminum	2	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	58	171	-	80	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	3	1	-
Others/Not Reported	-	-	-	-	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
JANIUAY					
Total	104	1,624	2	8	20
Concrete/Brick/Stone	-	4	-	2	-
Wood	4	5	-	-	-
Half Concrete/Brick/Stone and Half Wood	4	8	-	-	-
Galvanized Iron/Aluminum	4	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	92	1,603	1	6	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	3	-	-	17
No Walls	-	-	-	-	-
LAMBUNAO					
Total	9	1,071	7	6	20
Concrete/Brick/Stone	-	-	-	6	-
Wood	1	29	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	3	-	-	3
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	1,037	7	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	-	12
No Walls	-	-	-	-	-
LEGANES					
Total	4	1,020	7	110	18
Concrete/Brick/Stone	-	7	-	9	-
Wood	-	39	1	3	-
Half Concrete/Brick/Stone and Half Wood	-	19	-	26	3
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	940	1	62	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	5	-	-
Others/Not Reported	-	1	-	10	12
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LEMERY					
Total	26	1,291	-	-	9
Concrete/Brick/Stone	-	-	-	-	2
Wood	13	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	11	-	-	-
Galvanized Iron/Aluminum	3	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,275	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	3	-	-	6
No Walls	-	-	-	-	-
LEON					
Total	8	161	19	3	24
Concrete/Brick/Stone	-	-	-	-	-
Wood	1	8	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	151	18	3	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	-	-	-	18
No Walls	-	-	-	-	-
MAASIN					
Total	40	312	10	27	30
Concrete/Brick/Stone	-	-	-	-	-
Wood	4	-	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	1	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	36	312	10	24	14
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	2	-
Others/Not Reported	-	-	-	-	14
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MIAGAO					
Total	202	1,371	28	97	40
Concrete/Brick/Stone	1	4	-	1	-
Wood	44	112	-	1	1
Half Concrete/Brick/Stone and Half Wood	15	62	-	2	-
Galvanized Iron/Aluminum	15	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	127	1,179	25	84	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	3	-	-
Others/Not Reported	-	1	-	9	37
No Walls	-	-	-	-	-
MINA					
Total	9	541	2	-	3
Concrete/Brick/Stone	-	3	-	-	-
Wood	1	4	-	-	-
Half Concrete/Brick/Stone and Half Wood	3	9	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	523	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	1	-	-	2
No Walls	-	-	-	-	-
NEW LUCENA					
Total	2	328	1	1	11
Concrete/Brick/Stone	-	1	-	1	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	324	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	1	-	-	10
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
OTON					
Total	670	2,267	16	319	57
Concrete/Brick/Stone	49	43	1	187	11
Wood	46	119	-	14	1
Half Concrete/Brick/Stone and Half Wood	145	82	-	12	-
Galvanized Iron/Aluminum	5	14	-	-	1
Bamboo/Sawali/Cogon/Nipa	425	1,989	4	88	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	10	-	-
Others/Not Reported	-	12	1	18	37
No Walls	-	-	-	-	-
CITY OF PASSI					
Total	10	1,512	6	51	71
Concrete/Brick/Stone	1	1	-	2	1
Wood	-	8	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	14	-	3	3
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,475	2	42	38
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	5	4	-	-
Others/Not Reported	-	6	-	4	28
No Walls	-	-	-	-	-
PAVIA					
Total	12	708	14	1	18
Concrete/Brick/Stone	-	1	-	-	2
Wood	4	31	-	-	1
Half Concrete/Brick/Stone and Half Wood	1	11	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	653	2	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	12	-	-
Others/Not Reported	-	2	-	-	15
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
POTOTAN					
Total	38	1,952	14	1	24
Concrete/Brick/Stone	1	6	-	-	1
Wood	6	94	1	-	-
Half Concrete/Brick/Stone and Half Wood	5	44	-	-	2
Galvanized Iron/Aluminum	2	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	24	1,795	9	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	3	-	-
Others/Not Reported	-	3	-	1	19
No Walls	-	-	-	-	-
SAN DIONISIO					
Total	122	2,678	2	-	23
Concrete/Brick/Stone	2	7	-	-	-
Wood	8	6	-	-	-
Half Concrete/Brick/Stone and Half Wood	23	47	-	-	-
Galvanized Iron/Aluminum	2	3	-	-	1
Bamboo/Sawali/Cogon/Nipa	87	2,614	-	-	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	2	-	-
Others/Not Reported	-	-	-	-	14
No Walls	-	-	-	-	-
SAN ENRIQUE					
Total	2	705	3	10	85
Concrete/Brick/Stone	-	-	-	-	1
Wood	-	8	-	2	-
Half Concrete/Brick/Stone and Half Wood	-	4	-	3	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	689	2	4	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	1	1	-
Others/Not Reported	-	-	-	-	80
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN JOAQUIN					
Total	296	1,381	2	154	31
Concrete/Brick/Stone	-	18	-	5	2
Wood	76	149	-	22	2
Half Concrete/Brick/Stone and Half Wood	2	54	-	13	1
Galvanized Iron/Aluminum	1	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	217	1,157	1	106	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	3	-
Others/Not Reported	-	2	-	5	17
No Walls	-	-	-	-	-
SAN MIGUEL					
Total	5	620	7	3	9
Concrete/Brick/Stone	-	-	-	2	1
Wood	1	9	1	-	-
Half Concrete/Brick/Stone and Half Wood	1	6	-	1	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	602	5	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	-	1	-	-	7
No Walls	-	-	-	-	-
SAN RAFAEL					
Total	14	671	1	1	10
Concrete/Brick/Stone	-	1	-	-	-
Wood	-	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	8	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	660	-	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SANTA BARBARA					
Total	18	1,128	3	33	55
Concrete/Brick/Stone	6	8	-	2	-
Wood	-	25	-	-	1
Half Concrete/Brick/Stone and Half Wood	3	27	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	1,063	3	20	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	2	-	11	51
No Walls	-	-	-	-	-
SARA					
Total	18	1,467	8	13	19
Concrete/Brick/Stone	-	3	-	12	-
Wood	2	21	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	28	-	1	1
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	1,407	7	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	-	3	-	-	16
No Walls	-	-	-	-	-
TIGBAUAN					
Total	428	2,673	4	36	16
Concrete/Brick/Stone	5	23	-	32	1
Wood	91	146	-	-	1
Half Concrete/Brick/Stone and Half Wood	84	96	-	1	2
Galvanized Iron/Aluminum	3	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	243	2,401	1	3	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	3	3	-	1
Others/Not Reported	-	3	-	-	4
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TUBUNGAN					
Total	7	69	-	15	11
Concrete/Brick/Stone	-	-	-	-	2
Wood	2	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	68	-	15	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
ZARRAGA					
Total	3	908	-	2	3
Concrete/Brick/Stone	-	3	-	1	1
Wood	1	54	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	30	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	815	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	2	-	-	2
No Walls	-	-	-	-	-