

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
LAGUNA				
Total	532,600	488,512	5,344	23,484
Concrete/Brick/Stone	302,644	294,155	3,267	2,872
Wood	60,237	54,717	284	1,649
Half Concrete/Brick/Stone and Half Wood	133,582	113,099	1,224	17,670
Galvanized Iron/Aluminum	5,335	4,071	491	599
Bamboo/Sawali/Cogon/Nipa	21,073	17,819	-	453
Asbestos	230	219	-	5
Glass	320	253	22	6
Makeshift/Salvaged/Improvised Materials	4,297	2,537	-	122
Others/Not Reported	4,869	1,637	56	108
No Walls	13	5	-	-
ALAMINOS				
Total	9,012	8,534	122	159
Concrete/Brick/Stone	5,425	5,268	99	37
Wood	906	832	-	6
Half Concrete/Brick/Stone and Half Wood	2,005	1,881	9	94
Galvanized Iron/Aluminum	78	59	7	9
Bamboo/Sawali/Cogon/Nipa	555	461	-	12
Asbestos	9	9	-	-
Glass	23	16	6	1
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	9	7	1	-
No Walls	-	-	-	-
BAY				
Total	10,639	10,215	27	201
Concrete/Brick/Stone	6,405	6,364	17	15
Wood	1,205	1,106	6	48
Half Concrete/Brick/Stone and Half Wood	2,407	2,251	4	130
Galvanized Iron/Aluminum	106	91	-	5
Bamboo/Sawali/Cogon/Nipa	334	274	-	2
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	115	104	-	-
Others/Not Reported	66	24	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BIÑAN				
Total	60,113	55,381	796	2,119
Concrete/Brick/Stone	31,218	29,801	538	455
Wood	9,036	8,255	30	241
Half Concrete/Brick/Stone and Half Wood	18,085	16,214	221	1,370
Galvanized Iron/Aluminum	368	339	4	14
Bamboo/Sawali/Cogon/Nipa	323	286	-	8
Asbestos	5	3	-	-
Glass	4	1	2	1
Makeshift/Salvaged/Improvised Materials	586	377	-	24
Others/Not Reported	487	105	1	6
No Walls	1	-	-	-
CABUYAO				
Total	47,073	40,472	151	5,359
Concrete/Brick/Stone	30,039	29,649	101	234
Wood	2,260	1,790	5	34
Half Concrete/Brick/Stone and Half Wood	13,457	8,455	41	4,909
Galvanized Iron/Aluminum	420	269	2	141
Bamboo/Sawali/Cogon/Nipa	66	36	-	9
Asbestos	2	2	-	-
Glass	59	57	1	1
Makeshift/Salvaged/Improvised Materials	233	86	-	2
Others/Not Reported	532	128	1	29
No Walls	5	-	-	-
CITY OF CALAMBA				
Total	76,449	70,170	1,046	2,829
Concrete/Brick/Stone	50,664	49,298	390	672
Wood	8,291	7,520	102	204
Half Concrete/Brick/Stone and Half Wood	13,891	11,708	113	1,811
Galvanized Iron/Aluminum	889	365	418	68
Bamboo/Sawali/Cogon/Nipa	736	569	-	38
Asbestos	4	2	-	-
Glass	176	128	11	2
Makeshift/Salvaged/Improvised Materials	569	282	-	20
Others/Not Reported	1,229	298	12	14
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
CALAUAN				
Total	11,278	10,147	261	618
Concrete/Brick/Stone	5,636	5,522	66	31
Wood	780	679	4	49
Half Concrete/Brick/Stone and Half Wood	3,572	2,881	170	502
Galvanized Iron/Aluminum	63	52	5	6
Bamboo/Sawali/Cogon/Nipa	991	899	-	26
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	85	71	-	1
Others/Not Reported	151	43	16	3
No Walls	-	-	-	-
CAVINTI				
Total	4,586	3,963	18	153
Concrete/Brick/Stone	2,028	1,994	15	5
Wood	732	630	1	15
Half Concrete/Brick/Stone and Half Wood	1,203	1,068	2	107
Galvanized Iron/Aluminum	62	41	-	17
Bamboo/Sawali/Cogon/Nipa	512	215	-	8
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	1
Others/Not Reported	42	10	-	-
No Walls	1	1	-	-
FAMY				
Total	2,920	2,795	10	14
Concrete/Brick/Stone	946	933	7	2
Wood	824	784	-	4
Half Concrete/Brick/Stone and Half Wood	726	712	3	8
Galvanized Iron/Aluminum	23	23	-	-
Bamboo/Sawali/Cogon/Nipa	373	327	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	21	15	-	-
Others/Not Reported	7	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
KALAYAAN				
Total	4,384	4,248	6	24
Concrete/Brick/Stone	1,546	1,527	4	13
Wood	1,587	1,525	-	5
Half Concrete/Brick/Stone and Half Wood	974	966	-	6
Galvanized Iron/Aluminum	13	13	-	-
Bamboo/Sawali/Cogon/Nipa	249	211	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	3	-	-
Others/Not Reported	12	3	2	-
No Walls	-	-	-	-
LILIW				
Total	7,126	6,949	2	75
Concrete/Brick/Stone	3,279	3,261	1	3
Wood	855	837	-	1
Half Concrete/Brick/Stone and Half Wood	2,030	1,957	1	66
Galvanized Iron/Aluminum	55	52	-	3
Bamboo/Sawali/Cogon/Nipa	832	786	-	2
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	25	18	-	-
Others/Not Reported	49	37	-	-
No Walls	-	-	-	-
LOS BAÑOS				
Total	21,167	18,902	134	1,277
Concrete/Brick/Stone	12,040	11,652	119	103
Wood	2,097	1,780	2	150
Half Concrete/Brick/Stone and Half Wood	5,014	4,099	7	834
Galvanized Iron/Aluminum	635	496	1	116
Bamboo/Sawali/Cogon/Nipa	910	667	-	48
Asbestos	5	5	-	-
Glass	4	2	2	-
Makeshift/Salvaged/Improvised Materials	177	114	-	9
Others/Not Reported	285	87	3	17
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
LUISIANA				
Total	4,073	3,700	134	139
Concrete/Brick/Stone	2,450	2,410	33	7
Wood	472	376	40	42
Half Concrete/Brick/Stone and Half Wood	880	741	59	77
Galvanized Iron/Aluminum	45	41	1	3
Bamboo/Sawali/Cogon/Nipa	203	119	-	10
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	5	-	-
Others/Not Reported	11	3	1	-
No Walls	-	-	-	-
LUMBAN				
Total	5,985	5,906	4	15
Concrete/Brick/Stone	2,466	2,449	3	5
Wood	642	628	-	1
Half Concrete/Brick/Stone and Half Wood	2,112	2,100	1	8
Galvanized Iron/Aluminum	122	122	-	-
Bamboo/Sawali/Cogon/Nipa	591	578	-	-
Asbestos	1	1	-	-
Glass	15	15	-	-
Makeshift/Salvaged/Improvised Materials	5	5	-	-
Others/Not Reported	31	8	-	1
No Walls	-	-	-	-
MABITAC				
Total	3,658	3,582	6	4
Concrete/Brick/Stone	1,272	1,264	6	2
Wood	823	814	-	1
Half Concrete/Brick/Stone and Half Wood	843	840	-	-
Galvanized Iron/Aluminum	29	28	-	1
Bamboo/Sawali/Cogon/Nipa	669	619	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	16	14	-	-
Others/Not Reported	6	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MAGDALENA				
Total	4,603	3,578	4	585
Concrete/Brick/Stone	1,274	1,225	-	45
Wood	261	200	-	39
Half Concrete/Brick/Stone and Half Wood	1,900	1,505	3	384
Galvanized Iron/Aluminum	53	47	-	5
Bamboo/Sawali/Cogon/Nipa	1,012	575	-	107
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	8	-	3
Others/Not Reported	91	18	1	2
No Walls	-	-	-	-
MAJAYJAY				
Total	5,028	4,233	75	303
Concrete/Brick/Stone	2,112	2,030	59	7
Wood	737	575	6	9
Half Concrete/Brick/Stone and Half Wood	1,220	912	10	284
Galvanized Iron/Aluminum	79	75	-	2
Bamboo/Sawali/Cogon/Nipa	798	606	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	36	17	-	-
Others/Not Reported	46	18	-	-
No Walls	-	-	-	-
NAGCARLAN				
Total	12,703	12,393	3	25
Concrete/Brick/Stone	6,865	6,858	1	1
Wood	833	819	-	-
Half Concrete/Brick/Stone and Half Wood	3,154	3,137	2	6
Galvanized Iron/Aluminum	62	62	-	-
Bamboo/Sawali/Cogon/Nipa	1,601	1,424	-	13
Asbestos	41	38	-	3
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	43	28	-	2
Others/Not Reported	104	27	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
PAETE				
Total	5,078	4,484	83	453
Concrete/Brick/Stone	1,398	1,242	46	109
Wood	1,343	1,208	-	115
Half Concrete/Brick/Stone and Half Wood	1,989	1,776	6	207
Galvanized Iron/Aluminum	107	34	31	19
Bamboo/Sawali/Cogon/Nipa	228	219	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	12	4	-	1
No Walls	-	-	-	-
PAGSANJAN				
Total	7,808	6,986	11	324
Concrete/Brick/Stone	3,378	3,347	3	14
Wood	814	712	1	32
Half Concrete/Brick/Stone and Half Wood	3,019	2,465	7	263
Galvanized Iron/Aluminum	67	52	-	6
Bamboo/Sawali/Cogon/Nipa	456	388	-	3
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	4	-	6
Others/Not Reported	56	17	-	-
No Walls	-	-	-	-
PAKIL				
Total	4,272	4,139	9	23
Concrete/Brick/Stone	2,038	2,028	8	-
Wood	578	565	-	-
Half Concrete/Brick/Stone and Half Wood	909	885	1	22
Galvanized Iron/Aluminum	17	17	-	-
Bamboo/Sawali/Cogon/Nipa	682	626	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	40	17	-	-
Others/Not Reported	8	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
PANGIL				
Total	4,902	4,718	24	56
Concrete/Brick/Stone	1,761	1,701	23	34
Wood	1,116	1,086	-	-
Half Concrete/Brick/Stone and Half Wood	1,249	1,225	1	21
Galvanized Iron/Aluminum	27	27	-	-
Bamboo/Sawali/Cogon/Nipa	719	660	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	14	10	-	-
Others/Not Reported	16	9	-	-
No Walls	-	-	-	-
PILA				
Total	9,285	9,156	27	18
Concrete/Brick/Stone	6,047	6,025	12	3
Wood	756	721	13	6
Half Concrete/Brick/Stone and Half Wood	1,011	1,003	1	6
Galvanized Iron/Aluminum	98	97	-	1
Bamboo/Sawali/Cogon/Nipa	1,094	1,078	-	1
Asbestos	122	120	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	62	57	-	-
Others/Not Reported	95	55	1	-
No Walls	-	-	-	-
RIZAL				
Total	3,398	3,317	14	9
Concrete/Brick/Stone	2,265	2,248	14	2
Wood	298	283	-	2
Half Concrete/Brick/Stone and Half Wood	462	457	-	5
Galvanized Iron/Aluminum	18	18	-	-
Bamboo/Sawali/Cogon/Nipa	255	244	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	87	62	-	-
Others/Not Reported	13	5	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
SAN PABLO CITY				
Total	50,546	47,808	210	1,431
Concrete/Brick/Stone	25,024	24,710	190	93
Wood	5,996	5,607	5	115
Half Concrete/Brick/Stone and Half Wood	15,285	13,999	12	1,111
Galvanized Iron/Aluminum	470	431	1	27
Bamboo/Sawali/Cogon/Nipa	2,854	2,555	-	70
Asbestos	-	-	-	-
Glass	3	2	-	-
Makeshift/Salvaged/Improvised Materials	409	290	-	13
Others/Not Reported	504	214	2	2
No Walls	1	-	-	-
SAN PEDRO				
Total	56,159	52,402	546	1,913
Concrete/Brick/Stone	37,727	36,756	430	403
Wood	6,094	5,592	28	160
Half Concrete/Brick/Stone and Half Wood	10,275	8,864	80	1,260
Galvanized Iron/Aluminum	383	331	5	39
Bamboo/Sawali/Cogon/Nipa	261	228	-	14
Asbestos	6	5	-	-
Glass	31	29	-	-
Makeshift/Salvaged/Improvised Materials	1,059	472	-	32
Others/Not Reported	321	123	3	5
No Walls	2	2	-	-
SANTA CRUZ (Capital)				
Total	21,899	21,033	84	404
Concrete/Brick/Stone	11,875	11,815	27	15
Wood	2,704	2,612	7	9
Half Concrete/Brick/Stone and Half Wood	5,506	5,057	43	345
Galvanized Iron/Aluminum	180	148	6	21
Bamboo/Sawali/Cogon/Nipa	1,367	1,207	-	12
Asbestos	-	-	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	105	99	-	-
Others/Not Reported	161	95	1	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SANTA MARIA				
Total	5,428	5,314	3	15
Concrete/Brick/Stone	2,735	2,726	3	2
Wood	780	766	-	3
Half Concrete/Brick/Stone and Half Wood	1,151	1,133	-	7
Galvanized Iron/Aluminum	41	41	-	-
Bamboo/Sawali/Cogon/Nipa	688	633	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	9	-	-
Others/Not Reported	21	6	-	-
No Walls	-	-	-	-
CITY OF SANTA ROSA				
Total	58,677	50,273	1,431	4,829
Concrete/Brick/Stone	35,618	33,069	961	536
Wood	5,397	4,502	32	349
Half Concrete/Brick/Stone and Half Wood	15,960	11,607	417	3,763
Galvanized Iron/Aluminum	394	286	10	91
Bamboo/Sawali/Cogon/Nipa	412	272	-	55
Asbestos	8	8	-	-
Glass	3	2	-	1
Makeshift/Salvaged/Improvised Materials	430	264	-	9
Others/Not Reported	455	263	11	25
No Walls	-	-	-	-
SINILOAN				
Total	7,278	6,995	95	43
Concrete/Brick/Stone	3,321	3,206	86	21
Wood	1,421	1,350	1	4
Half Concrete/Brick/Stone and Half Wood	1,492	1,465	8	15
Galvanized Iron/Aluminum	342	340	-	1
Bamboo/Sawali/Cogon/Nipa	571	521	-	1
Asbestos	14	13	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	98	91	-	-
Others/Not Reported	16	7	-	-
No Walls	3	2	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

VICTORIA

Total	7,073	6,719	8	67
Concrete/Brick/Stone	3,792	3,777	5	3
Wood	599	563	1	5
Half Concrete/Brick/Stone and Half Wood	1,801	1,736	2	49
Galvanized Iron/Aluminum	89	74	-	4
Bamboo/Sawali/Cogon/Nipa	731	536	-	6
Asbestos	4	4	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	24	11	-	-
Others/Not Reported	33	18	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LAGUNA					
Total	4,992	2,712	2,321	1,334	3,901
Concrete/Brick/Stone	603	32	99	1,138	478
Wood	2,676	461	293	30	127
Half Concrete/Brick/Stone and Half Wood	1,112	79	137	26	235
Galvanized Iron/Aluminum	132	19	10	2	11
Bamboo/Sawali/Cogon/Nipa	371	2,054	227	102	47
Asbestos	2	-	-	4	-
Glass	32	-	-	4	3
Makeshift/Salvaged/Improvised Materials	29	48	1,542	3	16
Others/Not Reported	35	18	11	25	2,979
No Walls	-	1	2	-	5
ALAMINOS					
Total	52	114	3	3	25
Concrete/Brick/Stone	5	1	-	3	12
Wood	24	40	-	-	4
Half Concrete/Brick/Stone and Half Wood	8	7	-	-	6
Galvanized Iron/Aluminum	1	1	-	-	1
Bamboo/Sawali/Cogon/Nipa	14	64	2	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	1	-	-	-
No Walls	-	-	-	-	-
BAY					
Total	71	54	10	5	56
Concrete/Brick/Stone	1	2	-	2	4
Wood	35	5	2	1	2
Half Concrete/Brick/Stone and Half Wood	11	-	-	1	10
Galvanized Iron/Aluminum	9	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	14	43	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	3	7	-	-
Others/Not Reported	-	1	-	1	39
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BIÑAN					
Total	706	39	276	352	444
Concrete/Brick/Stone	18	-	27	333	46
Wood	463	12	23	6	6
Half Concrete/Brick/Stone and Half Wood	211	1	39	10	19
Galvanized Iron/Aluminum	9	-	-	1	1
Bamboo/Sawali/Cogon/Nipa	1	23	4	-	1
Asbestos	-	-	-	2	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	182	-	-
Others/Not Reported	4	-	-	-	371
No Walls	-	-	1	-	-
CABUYAO					
Total	449	20	162	10	450
Concrete/Brick/Stone	11	-	1	8	35
Wood	413	5	4	-	9
Half Concrete/Brick/Stone and Half Wood	14	-	12	-	26
Galvanized Iron/Aluminum	3	1	1	-	3
Bamboo/Sawali/Cogon/Nipa	6	14	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	143	-	2
Others/Not Reported	2	-	-	2	370
No Walls	-	-	-	-	5
CITY OF CALAMBA					
Total	674	121	470	22	1,117
Concrete/Brick/Stone	91	6	54	12	141
Wood	273	39	121	3	29
Half Concrete/Brick/Stone and Half Wood	170	6	32	1	50
Galvanized Iron/Aluminum	33	-	3	-	2
Bamboo/Sawali/Cogon/Nipa	54	59	12	1	3
Asbestos	1	-	-	1	-
Glass	30	-	-	3	2
Makeshift/Salvaged/Improvised Materials	11	8	244	-	4
Others/Not Reported	11	3	4	1	886
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
CALAUAN					
Total	55	43	27	1	126
Concrete/Brick/Stone	1	2	1	-	13
Wood	25	9	10	-	4
Half Concrete/Brick/Stone and Half Wood	2	2	2	-	13
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	27	30	2	1	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	12	-	1
Others/Not Reported	-	-	-	-	89
No Walls	-	-	-	-	-
CAVINTI					
Total	70	333	1	1	47
Concrete/Brick/Stone	3	3	-	-	8
Wood	50	33	-	-	3
Half Concrete/Brick/Stone and Half Wood	15	7	-	-	4
Galvanized Iron/Aluminum	1	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	1	286	-	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	1	-	-	31
No Walls	-	-	-	-	-
FAMY					
Total	7	67	18	3	6
Concrete/Brick/Stone	1	1	-	2	-
Wood	3	27	6	-	-
Half Concrete/Brick/Stone and Half Wood	2	1	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	37	7	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	5	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
KALAYAAN					
Total	8	72	6	9	11
Concrete/Brick/Stone	-	-	-	1	1
Wood	7	43	2	4	1
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	28	4	3	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	1	6
No Walls	-	-	-	-	-
LILIW					
Total	11	30	25	3	31
Concrete/Brick/Stone	-	2	-	-	12
Wood	9	2	6	-	-
Half Concrete/Brick/Stone and Half Wood	2	-	1	-	3
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	26	11	3	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	7	-	-
Others/Not Reported	-	-	-	-	12
No Walls	-	-	-	-	-
LOS BAÑOS					
Total	347	167	67	9	264
Concrete/Brick/Stone	110	2	-	4	50
Wood	123	16	10	-	16
Half Concrete/Brick/Stone and Half Wood	32	11	2	2	27
Galvanized Iron/Aluminum	21	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	47	127	16	2	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	9	39	1	1
Others/Not Reported	10	1	-	-	167
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LUISIANA					
Total	5	81	3	-	11
Concrete/Brick/Stone	-	-	-	-	-
Wood	1	11	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	68	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	1	-	-	6
No Walls	-	-	-	-	-
LUMBAN					
Total	11	13	1	5	30
Concrete/Brick/Stone	-	1	-	2	6
Wood	10	1	-	1	1
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	10	1	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	1	21
No Walls	-	-	-	-	-
MABITAC					
Total	2	54	3	2	5
Concrete/Brick/Stone	-	-	-	-	-
Wood	2	4	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	2	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	47	1	2	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	1	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAGDALENA					
Total	15	338	6	1	76
Concrete/Brick/Stone	-	-	-	1	3
Wood	2	19	1	-	-
Half Concrete/Brick/Stone and Half Wood	1	5	-	-	2
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	313	4	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	1	-	-	69
No Walls	-	-	-	-	-
MAJAYJAY					
Total	189	76	65	58	29
Concrete/Brick/Stone	12	1	-	2	1
Wood	129	5	6	6	1
Half Concrete/Brick/Stone and Half Wood	6	4	2	2	-
Galvanized Iron/Aluminum	-	-	1	1	-
Bamboo/Sawali/Cogon/Nipa	42	66	35	46	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	19	-	-
Others/Not Reported	-	-	2	1	25
No Walls	-	-	-	-	-
NAGCARLAN					
Total	7	72	84	33	86
Concrete/Brick/Stone	-	-	-	1	4
Wood	2	7	1	4	-
Half Concrete/Brick/Stone and Half Wood	2	-	3	2	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	64	68	25	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	12	-	-
Others/Not Reported	-	-	-	1	76
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PAETE					
Total	29	19	2	-	8
Concrete/Brick/Stone	1	-	-	-	-
Wood	5	14	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	23	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	5	2	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	7
No Walls	-	-	-	-	-
PAGSANJAN					
Total	374	53	13	1	46
Concrete/Brick/Stone	11	-	-	-	3
Wood	56	11	2	-	-
Half Concrete/Brick/Stone and Half Wood	278	2	1	-	3
Galvanized Iron/Aluminum	5	2	2	-	-
Bamboo/Sawali/Cogon/Nipa	24	38	1	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	7	-	-
Others/Not Reported	-	-	-	-	39
No Walls	-	-	-	-	-
PAKIL					
Total	12	55	25	1	8
Concrete/Brick/Stone	1	-	-	-	1
Wood	2	9	2	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	1	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	46	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	22	-	-
Others/Not Reported	-	-	-	-	7
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PANGIL					
Total	13	73	7	2	9
Concrete/Brick/Stone	1	-	-	1	1
Wood	8	21	1	-	-
Half Concrete/Brick/Stone and Half Wood	-	2	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	47	5	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	-	-
Others/Not Reported	-	-	-	-	7
No Walls	-	-	-	-	-
PILA					
Total	14	20	3	4	43
Concrete/Brick/Stone	1	2	-	1	3
Wood	11	2	-	1	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	1	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	13	-	1	-
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	3	-	-
Others/Not Reported	-	1	-	-	38
No Walls	-	-	-	-	-
RIZAL					
Total	2	12	35	-	9
Concrete/Brick/Stone	-	-	-	-	1
Wood	2	5	6	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	7	4	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	25	-	-
Others/Not Reported	-	-	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN PABLO CITY					
Total	417	169	134	24	353
Concrete/Brick/Stone	3	2	-	-	26
Wood	213	28	8	1	19
Half Concrete/Brick/Stone and Half Wood	128	3	6	-	26
Galvanized Iron/Aluminum	8	1	1	-	1
Bamboo/Sawali/Cogon/Nipa	63	128	20	11	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	6	97	-	3
Others/Not Reported	2	1	1	12	270
No Walls	-	-	1	-	-
SAN PEDRO					
Total	398	13	607	25	255
Concrete/Brick/Stone	69	-	5	22	42
Wood	271	4	26	-	13
Half Concrete/Brick/Stone and Half Wood	41	2	17	1	10
Galvanized Iron/Aluminum	7	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	3	7	6	-	3
Asbestos	-	-	-	1	-
Glass	2	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	-	549	1	1
Others/Not Reported	1	-	4	-	185
No Walls	-	-	-	-	-
SANTA CRUZ (Capital)					
Total	136	145	11	10	76
Concrete/Brick/Stone	9	-	-	1	8
Wood	64	7	2	3	-
Half Concrete/Brick/Stone and Half Wood	48	4	-	2	7
Galvanized Iron/Aluminum	3	-	1	-	1
Bamboo/Sawali/Cogon/Nipa	11	131	3	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	-	1	5	-	-
Others/Not Reported	1	2	-	2	58
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SANTA MARIA					
Total	5	64	6	2	19
Concrete/Brick/Stone	-	-	1	-	3
Wood	2	8	1	-	-
Half Concrete/Brick/Stone and Half Wood	1	5	3	-	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	49	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	1	-
Others/Not Reported	1	-	-	1	13
No Walls	-	-	-	-	-
CITY OF SANTA ROSA					
Total	858	100	212	746	228
Concrete/Brick/Stone	250	4	9	741	48
Wood	440	20	44	-	10
Half Concrete/Brick/Stone and Half Wood	139	1	15	3	15
Galvanized Iron/Aluminum	7	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	74	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	8	1	144	-	4
Others/Not Reported	3	-	-	2	151
No Walls	-	-	-	-	-
SINILOAN					
Total	28	90	16	1	10
Concrete/Brick/Stone	4	2	1	-	1
Wood	19	43	4	-	-
Half Concrete/Brick/Stone and Half Wood	1	-	2	-	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	37	6	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	3	-	-
Others/Not Reported	-	2	-	-	7
No Walls	-	1	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
VICTORIA					
Total	27	205	23	1	23
Concrete/Brick/Stone	-	1	-	1	5
Wood	12	11	5	-	2
Half Concrete/Brick/Stone and Half Wood	-	11	-	-	3
Galvanized Iron/Aluminum	1	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	167	8	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	10	-	-
Others/Not Reported	-	2	-	-	13
No Walls	-	-	-	-	-