

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
LEYTE				
Total	362,513	226,496	1,271	16,046
Concrete/Brick/Stone	95,045	90,961	930	1,070
Wood	85,211	53,446	54	2,059
Half Concrete/Brick/Stone and Half Wood	61,875	44,697	206	10,074
Galvanized Iron/Aluminum	2,060	1,219	41	398
Bamboo/Sawali/Cogon/Nipa	112,315	34,297	-	2,369
Asbestos	78	54	1	5
Glass	42	26	5	4
Makeshift/Salvaged/Improvised Materials	1,658	528	-	29
Others/Not Reported	4,212	1,261	34	38
No Walls	17	7	-	-
ABUYOG				
Total	11,811	8,147	9	148
Concrete/Brick/Stone	3,233	3,113	6	14
Wood	4,998	3,244	1	34
Half Concrete/Brick/Stone and Half Wood	1,621	1,393	-	65
Galvanized Iron/Aluminum	46	23	-	4
Bamboo/Sawali/Cogon/Nipa	1,761	357	-	28
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	41	8	-	3
Others/Not Reported	111	9	2	-
No Walls	-	-	-	-
ALANGALANG				
Total	8,974	3,485	17	849
Concrete/Brick/Stone	1,621	1,549	10	13
Wood	2,529	850	-	101
Half Concrete/Brick/Stone and Half Wood	1,792	884	6	646
Galvanized Iron/Aluminum	94	38	-	26
Bamboo/Sawali/Cogon/Nipa	2,860	157	-	59
Asbestos	1	-	1	-
Glass	1	-	-	1
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	72	5	-	3
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ALBUERA				
Total	8,661	5,470	11	300
Concrete/Brick/Stone	2,549	2,409	10	70
Wood	920	620	-	15
Half Concrete/Brick/Stone and Half Wood	1,875	1,429	1	159
Galvanized Iron/Aluminum	26	15	-	4
Bamboo/Sawali/Cogon/Nipa	3,178	974	-	48
Asbestos	-	-	-	-
Glass	2	-	-	2
Makeshift/Salvaged/Improvised Materials	52	14	-	1
Others/Not Reported	58	9	-	1
No Walls	1	-	-	-
BABATNGON				
Total	4,810	2,009	43	384
Concrete/Brick/Stone	885	815	31	5
Wood	743	424	2	27
Half Concrete/Brick/Stone and Half Wood	869	438	8	301
Galvanized Iron/Aluminum	76	33	2	16
Bamboo/Sawali/Cogon/Nipa	2,121	257	-	32
Asbestos	1	-	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	19	6	-	-
Others/Not Reported	94	36	-	2
No Walls	2	-	-	-
BARUGO				
Total	5,549	2,613	31	712
Concrete/Brick/Stone	1,188	1,103	20	37
Wood	642	282	-	45
Half Concrete/Brick/Stone and Half Wood	1,712	1,002	10	500
Galvanized Iron/Aluminum	41	35	-	3
Bamboo/Sawali/Cogon/Nipa	1,926	188	-	125
Asbestos	1	-	-	1
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	35	2	1	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BATO				
Total	7,147	5,347	7	154
Concrete/Brick/Stone	1,584	1,539	6	15
Wood	1,324	1,134	-	13
Half Concrete/Brick/Stone and Half Wood	926	727	-	92
Galvanized Iron/Aluminum	56	50	1	2
Bamboo/Sawali/Cogon/Nipa	3,224	1,887	-	32
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	5	-	-
Others/Not Reported	21	4	-	-
No Walls	-	-	-	-
CITY OF BAYBAY				
Total	22,030	17,387	50	1,308
Concrete/Brick/Stone	6,937	6,758	41	82
Wood	3,596	3,098	2	45
Half Concrete/Brick/Stone and Half Wood	4,771	3,674	1	942
Galvanized Iron/Aluminum	52	30	3	12
Bamboo/Sawali/Cogon/Nipa	6,333	3,686	-	226
Asbestos	8	7	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	56	24	-	-
Others/Not Reported	277	110	3	1
No Walls	-	-	-	-
BURAUEN				
Total	10,105	4,588	55	549
Concrete/Brick/Stone	1,766	1,656	44	21
Wood	4,157	1,850	4	139
Half Concrete/Brick/Stone and Half Wood	1,342	844	5	316
Galvanized Iron/Aluminum	55	31	2	11
Bamboo/Sawali/Cogon/Nipa	2,655	179	-	57
Asbestos	9	9	-	-
Glass	3	2	-	1
Makeshift/Salvaged/Improvised Materials	46	5	-	1
Others/Not Reported	72	12	-	3
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
CALUBIAN				
Total	6,930	4,015	20	56
Concrete/Brick/Stone	1,025	973	15	3
Wood	1,565	1,257	1	13
Half Concrete/Brick/Stone and Half Wood	802	704	2	23
Galvanized Iron/Aluminum	33	22	-	2
Bamboo/Sawali/Cogon/Nipa	3,429	1,037	-	15
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	75	21	2	-
No Walls	-	-	-	-
CAPOOCAN				
Total	5,726	2,901	10	239
Concrete/Brick/Stone	879	835	5	4
Wood	1,754	875	-	29
Half Concrete/Brick/Stone and Half Wood	1,292	931	4	165
Galvanized Iron/Aluminum	41	17	1	14
Bamboo/Sawali/Cogon/Nipa	1,710	237	-	26
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	5	-	-	-
Others/Not Reported	44	5	-	1
No Walls	-	-	-	-
CARIGARA				
Total	9,439	4,859	20	482
Concrete/Brick/Stone	1,951	1,830	9	20
Wood	3,347	1,283	1	70
Half Concrete/Brick/Stone and Half Wood	2,112	1,532	8	322
Galvanized Iron/Aluminum	48	24	2	12
Bamboo/Sawali/Cogon/Nipa	1,768	139	-	56
Asbestos	9	8	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	41	10	-	1
Others/Not Reported	162	32	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
DAGAMI				
Total	6,153	2,662	5	217
Concrete/Brick/Stone	1,080	1,037	3	5
Wood	1,464	580	2	42
Half Concrete/Brick/Stone and Half Wood	944	677	-	143
Galvanized Iron/Aluminum	27	18	-	5
Bamboo/Sawali/Cogon/Nipa	2,590	343	-	20
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	13	-	-	-
Others/Not Reported	33	6	-	2
No Walls	1	-	-	-
DULAG				
Total	8,350	1,916	26	1,230
Concrete/Brick/Stone	1,476	1,158	18	186
Wood	1,770	202	3	184
Half Concrete/Brick/Stone and Half Wood	1,863	471	4	768
Galvanized Iron/Aluminum	34	11	-	17
Bamboo/Sawali/Cogon/Nipa	3,068	71	-	71
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	34	-	-	1
Others/Not Reported	103	3	1	3
No Walls	1	-	-	-
HILONGOS				
Total	12,120	7,998	83	322
Concrete/Brick/Stone	4,100	3,689	59	53
Wood	1,050	888	3	7
Half Concrete/Brick/Stone and Half Wood	1,575	1,190	14	167
Galvanized Iron/Aluminum	59	40	3	10
Bamboo/Sawali/Cogon/Nipa	5,207	2,167	-	84
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	32	7	-	-
Others/Not Reported	96	16	4	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
HINDANG				
Total	4,414	3,130	3	67
Concrete/Brick/Stone	1,841	1,783	3	3
Wood	262	220	-	-
Half Concrete/Brick/Stone and Half Wood	484	413	-	15
Galvanized Iron/Aluminum	29	16	-	10
Bamboo/Sawali/Cogon/Nipa	1,764	692	-	39
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	3	-	-
Others/Not Reported	28	3	-	-
No Walls	-	-	-	-
INOPACAN				
Total	4,408	3,595	4	240
Concrete/Brick/Stone	1,835	1,799	4	17
Wood	455	398	-	14
Half Concrete/Brick/Stone and Half Wood	816	634	-	149
Galvanized Iron/Aluminum	23	17	-	2
Bamboo/Sawali/Cogon/Nipa	1,218	729	-	58
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	5	-	-
Others/Not Reported	44	13	-	-
No Walls	-	-	-	-
ISABEL				
Total	9,240	6,314	68	418
Concrete/Brick/Stone	2,791	2,693	54	12
Wood	2,679	1,911	1	36
Half Concrete/Brick/Stone and Half Wood	1,494	1,090	7	283
Galvanized Iron/Aluminum	25	10	4	4
Bamboo/Sawali/Cogon/Nipa	2,087	551	-	82
Asbestos	4	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	101	45	-	-
Others/Not Reported	59	11	2	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
JARO				
Total	7,792	3,617	22	625
Concrete/Brick/Stone	1,859	1,771	19	13
Wood	1,290	591	-	49
Half Concrete/Brick/Stone and Half Wood	1,682	953	1	393
Galvanized Iron/Aluminum	39	10	-	18
Bamboo/Sawali/Cogon/Nipa	2,856	275	-	149
Asbestos	3	1	-	2
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	3	-	1
Others/Not Reported	46	13	2	-
No Walls	-	-	-	-
JAVIER (BUGHO)				
Total	4,811	2,496	18	379
Concrete/Brick/Stone	1,226	1,167	14	16
Wood	1,108	607	-	73
Half Concrete/Brick/Stone and Half Wood	884	503	2	215
Galvanized Iron/Aluminum	28	7	2	16
Bamboo/Sawali/Cogon/Nipa	1,450	160	-	58
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	110	49	-	1
No Walls	-	-	-	-
JULITA				
Total	2,728	494	73	224
Concrete/Brick/Stone	425	305	61	34
Wood	1,059	86	8	64
Half Concrete/Brick/Stone and Half Wood	307	90	4	106
Galvanized Iron/Aluminum	16	6	-	5
Bamboo/Sawali/Cogon/Nipa	909	6	-	15
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	9	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
KANANGA				
Total	9,652	6,541	20	402
Concrete/Brick/Stone	2,322	2,288	7	8
Wood	1,564	1,215	-	53
Half Concrete/Brick/Stone and Half Wood	2,161	1,755	3	284
Galvanized Iron/Aluminum	81	49	5	19
Bamboo/Sawali/Cogon/Nipa	3,420	1,194	-	37
Asbestos	2	2	-	-
Glass	12	9	2	-
Makeshift/Salvaged/Improvised Materials	12	8	-	1
Others/Not Reported	77	20	3	-
No Walls	1	1	-	-
LAPAZ				
Total	3,861	1,549	7	78
Concrete/Brick/Stone	619	583	5	13
Wood	1,270	442	1	35
Half Concrete/Brick/Stone and Half Wood	630	462	-	28
Galvanized Iron/Aluminum	10	7	1	-
Bamboo/Sawali/Cogon/Nipa	1,311	54	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	-	-	-
Others/Not Reported	17	1	-	-
No Walls	-	-	-	-
LEYTE				
Total	7,138	3,507	5	116
Concrete/Brick/Stone	697	683	5	4
Wood	957	775	-	8
Half Concrete/Brick/Stone and Half Wood	1,128	960	-	66
Galvanized Iron/Aluminum	69	54	-	7
Bamboo/Sawali/Cogon/Nipa	4,118	989	-	30
Asbestos	19	7	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	130	36	-	-
Others/Not Reported	20	3	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MACARTHUR				
Total	3,709	1,475	4	278
Concrete/Brick/Stone	998	824	4	80
Wood	744	353	-	26
Half Concrete/Brick/Stone and Half Wood	486	168	-	140
Galvanized Iron/Aluminum	7	2	-	-
Bamboo/Sawali/Cogon/Nipa	1,421	127	-	30
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	-	-	1
Others/Not Reported	45	1	-	1
No Walls	1	-	-	-
MAHAPLAG				
Total	5,507	4,238	22	278
Concrete/Brick/Stone	1,814	1,776	18	16
Wood	726	634	-	32
Half Concrete/Brick/Stone and Half Wood	997	763	3	201
Galvanized Iron/Aluminum	18	11	-	6
Bamboo/Sawali/Cogon/Nipa	1,903	1,046	-	23
Asbestos	-	-	-	-
Glass	1	-	1	-
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	46	7	-	-
No Walls	-	-	-	-
MATAG-OB				
Total	3,676	3,242	1	3
Concrete/Brick/Stone	721	720	1	-
Wood	1,045	1,028	-	-
Half Concrete/Brick/Stone and Half Wood	347	344	-	1
Galvanized Iron/Aluminum	13	11	-	-
Bamboo/Sawali/Cogon/Nipa	1,534	1,133	-	2
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	11	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MATALOM				
Total	6,687	5,581	7	31
Concrete/Brick/Stone	2,101	2,073	7	2
Wood	1,128	1,080	-	2
Half Concrete/Brick/Stone and Half Wood	571	530	-	11
Galvanized Iron/Aluminum	21	16	-	2
Bamboo/Sawali/Cogon/Nipa	2,774	1,853	-	13
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	26	19	-	1
Others/Not Reported	65	9	-	-
No Walls	-	-	-	-
MAYORGA				
Total	2,965	1,173	1	78
Concrete/Brick/Stone	683	633	1	11
Wood	1,150	301	-	28
Half Concrete/Brick/Stone and Half Wood	309	186	-	27
Galvanized Iron/Aluminum	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	772	53	-	12
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	49	-	-	-
No Walls	-	-	-	-
MERIDA				
Total	6,310	4,694	3	20
Concrete/Brick/Stone	1,362	1,347	1	-
Wood	1,658	1,412	-	6
Half Concrete/Brick/Stone and Half Wood	992	929	1	11
Galvanized Iron/Aluminum	5	2	-	-
Bamboo/Sawali/Cogon/Nipa	2,102	884	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	23	4	-	-
Others/Not Reported	168	116	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ORMOC CITY				
Total	37,731	26,902	140	1,131
Concrete/Brick/Stone	10,437	10,174	84	43
Wood	8,307	6,083	6	197
Half Concrete/Brick/Stone and Half Wood	8,310	6,982	44	641
Galvanized Iron/Aluminum	127	82	2	25
Bamboo/Sawali/Cogon/Nipa	9,862	3,388	-	215
Asbestos	5	5	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	275	91	-	6
Others/Not Reported	399	92	4	4
No Walls	7	3	-	-
PALO				
Total	11,197	6,056	55	503
Concrete/Brick/Stone	3,591	3,433	28	26
Wood	2,383	1,114	6	31
Half Concrete/Brick/Stone and Half Wood	1,879	1,151	12	379
Galvanized Iron/Aluminum	100	24	6	36
Bamboo/Sawali/Cogon/Nipa	3,069	301	-	29
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	25	7	-	-
Others/Not Reported	149	25	3	2
No Walls	1	1	-	-
PALOMPON				
Total	12,167	10,447	32	242
Concrete/Brick/Stone	3,037	2,991	30	6
Wood	3,955	3,798	-	2
Half Concrete/Brick/Stone and Half Wood	1,933	1,697	2	220
Galvanized Iron/Aluminum	23	20	-	1
Bamboo/Sawali/Cogon/Nipa	3,116	1,880	-	13
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	25	15	-	-
Others/Not Reported	75	43	-	-
No Walls	2	2	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
PASTRANA				
Total	3,235	664	8	346
Concrete/Brick/Stone	392	351	7	5
Wood	659	80	-	32
Half Concrete/Brick/Stone and Half Wood	774	217	-	259
Galvanized Iron/Aluminum	15	3	1	5
Bamboo/Sawali/Cogon/Nipa	1,318	11	-	42
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	74	1	-	3
No Walls	-	-	-	-
SAN ISIDRO				
Total	6,512	3,364	7	283
Concrete/Brick/Stone	933	904	4	18
Wood	1,001	869	-	23
Half Concrete/Brick/Stone and Half Wood	651	382	1	192
Galvanized Iron/Aluminum	45	17	2	9
Bamboo/Sawali/Cogon/Nipa	3,795	1,168	-	40
Asbestos	1	-	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	3	-	-
Others/Not Reported	76	21	-	-
No Walls	-	-	-	-
SAN MIGUEL				
Total	3,416	1,488	1	108
Concrete/Brick/Stone	464	447	1	6
Wood	856	468	-	16
Half Concrete/Brick/Stone and Half Wood	550	415	-	62
Galvanized Iron/Aluminum	14	7	-	4
Bamboo/Sawali/Cogon/Nipa	1,494	149	-	20
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	38	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SANTA FE

Total	3,178	1,456	1	158
Concrete/Brick/Stone	465	443	-	3
Wood	559	341	-	4
Half Concrete/Brick/Stone and Half Wood	596	378	1	117
Galvanized Iron/Aluminum	47	42	-	1
Bamboo/Sawali/Cogon/Nipa	1,491	250	-	33
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	18	2	-	-
No Walls	-	-	-	-

TABANGO

Total	6,663	3,596	5	661
Concrete/Brick/Stone	682	660	5	13
Wood	623	450	-	93
Half Concrete/Brick/Stone and Half Wood	929	686	-	228
Galvanized Iron/Aluminum	38	10	-	26
Bamboo/Sawali/Cogon/Nipa	4,326	1,765	-	300
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	5	1	-	-
Others/Not Reported	59	23	-	1
No Walls	-	-	-	-

TABONTABON

Total	1,987	688	3	117
Concrete/Brick/Stone	537	492	1	19
Wood	485	86	-	19
Half Concrete/Brick/Stone and Half Wood	256	94	2	70
Galvanized Iron/Aluminum	5	-	-	2
Bamboo/Sawali/Cogon/Nipa	692	16	-	7
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	11	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
TACLOBAN CITY (Capital)				
Total	41,977	32,410	261	1,174
Concrete/Brick/Stone	17,267	16,791	201	93
Wood	14,000	9,434	10	244
Half Concrete/Brick/Stone and Half Wood	5,583	4,450	41	752
Galvanized Iron/Aluminum	452	343	2	23
Bamboo/Sawali/Cogon/Nipa	3,105	710	-	53
Asbestos	6	5	-	-
Glass	12	5	2	-
Makeshift/Salvaged/Improvised Materials	479	181	-	6
Others/Not Reported	1,073	491	5	3
No Walls	-	-	-	-
TANAUAN				
Total	10,250	4,340	88	826
Concrete/Brick/Stone	2,631	2,389	75	64
Wood	2,719	846	2	163
Half Concrete/Brick/Stone and Half Wood	1,640	856	9	460
Galvanized Iron/Aluminum	55	15	2	30
Bamboo/Sawali/Cogon/Nipa	3,090	220	-	107
Asbestos	3	2	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	41	4	-	1
Others/Not Reported	70	7	-	1
No Walls	-	-	-	-
TOLOSA				
Total	3,616	2,143	1	134
Concrete/Brick/Stone	1,157	1,125	1	8
Wood	698	444	-	14
Half Concrete/Brick/Stone and Half Wood	433	325	-	49
Galvanized Iron/Aluminum	25	18	-	3
Bamboo/Sawali/Cogon/Nipa	1,266	225	-	60
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	2	2	-	-
Others/Not Reported	34	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

TUNGA

Total	1,297	858	2	58
Concrete/Brick/Stone	326	319	-	1
Wood	246	114	-	20
Half Concrete/Brick/Stone and Half Wood	397	331	1	23
Galvanized Iron/Aluminum	25	21	-	4
Bamboo/Sawali/Cogon/Nipa	226	63	-	4
Asbestos	-	-	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	69	10	-	5
Others/Not Reported	7	-	1	1
No Walls	-	-	-	-

VILLABA

Total	8,584	7,041	22	118
Concrete/Brick/Stone	1,558	1,533	12	8
Wood	1,766	1,679	1	11
Half Concrete/Brick/Stone and Half Wood	1,160	1,057	9	83
Galvanized Iron/Aluminum	16	12	-	2
Bamboo/Sawali/Cogon/Nipa	3,996	2,726	-	14
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	3	-	-
Others/Not Reported	82	31	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LEYTE					
Total	6,240	108,106	665	826	2,863
Concrete/Brick/Stone	141	1,725	33	82	103
Wood	2,765	26,475	87	155	170
Half Concrete/Brick/Stone and Half Wood	841	5,784	25	117	131
Galvanized Iron/Aluminum	91	300	4	5	2
Bamboo/Sawali/Cogon/Nipa	2,363	72,579	155	320	232
Asbestos	1	-	-	14	3
Glass	4	-	-	1	2
Makeshift/Salvaged/Improvised Materials	10	716	355	11	9
Others/Not Reported	23	519	6	120	2,211
No Walls	1	8	-	1	-
ABUYOG					
Total	166	3,225	3	13	100
Concrete/Brick/Stone	2	96	-	1	1
Wood	135	1,575	1	6	2
Half Concrete/Brick/Stone and Half Wood	6	152	-	3	2
Galvanized Iron/Aluminum	-	19	-	-	-
Bamboo/Sawali/Cogon/Nipa	23	1,346	-	2	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	28	2	-	-
Others/Not Reported	-	9	-	1	90
No Walls	-	-	-	-	-
ALANGALANG					
Total	178	4,354	3	-	88
Concrete/Brick/Stone	1	42	1	-	5
Wood	92	1,475	-	-	11
Half Concrete/Brick/Stone and Half Wood	15	239	-	-	2
Galvanized Iron/Aluminum	9	21	-	-	-
Bamboo/Sawali/Cogon/Nipa	61	2,570	1	-	12
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	6	-	-	58
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ALBUERA					
Total	22	2,766	24	14	54
Concrete/Brick/Stone	-	59	-	1	-
Wood	5	276	3	1	-
Half Concrete/Brick/Stone and Half Wood	3	270	1	5	7
Galvanized Iron/Aluminum	-	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	2,127	5	7	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	21	15	-	1
Others/Not Reported	-	5	-	-	43
No Walls	-	1	-	-	-
BABATNGON					
Total	35	2,234	3	57	45
Concrete/Brick/Stone	1	27	-	5	1
Wood	6	265	1	11	7
Half Concrete/Brick/Stone and Half Wood	6	90	-	20	6
Galvanized Iron/Aluminum	4	20	-	1	-
Bamboo/Sawali/Cogon/Nipa	18	1,785	2	14	13
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	11	-	2	-
Others/Not Reported	-	34	-	4	18
No Walls	-	2	-	-	-
BARUGO					
Total	31	2,116	8	1	37
Concrete/Brick/Stone	-	26	-	-	2
Wood	8	301	5	1	-
Half Concrete/Brick/Stone and Half Wood	8	190	-	-	2
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	1,593	1	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	2	-	-
Others/Not Reported	-	2	-	-	29
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BATO					
Total	153	1,453	9	1	23
Concrete/Brick/Stone	3	19	-	-	2
Wood	7	169	1	-	-
Half Concrete/Brick/Stone and Half Wood	61	43	1	-	2
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	82	1,214	5	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	2	-	-
Others/Not Reported	-	1	-	1	15
No Walls	-	-	-	-	-
CITY OF BAYBAY					
Total	109	2,871	33	104	168
Concrete/Brick/Stone	3	42	-	4	7
Wood	63	374	-	12	2
Half Concrete/Brick/Stone and Half Wood	18	126	1	5	4
Galvanized Iron/Aluminum	2	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	23	2,297	15	70	16
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	16	2	1
Others/Not Reported	-	14	1	11	137
No Walls	-	-	-	-	-
BURAUEN					
Total	700	4,132	17	11	53
Concrete/Brick/Stone	6	36	-	1	2
Wood	619	1,541	1	2	1
Half Concrete/Brick/Stone and Half Wood	31	143	-	2	1
Galvanized Iron/Aluminum	1	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	43	2,372	-	3	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	24	16	-	-
Others/Not Reported	-	6	-	3	48
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
CALUBIAN					
Total	14	2,735	-	79	11
Concrete/Brick/Stone	1	25	-	7	1
Wood	2	284	-	8	-
Half Concrete/Brick/Stone and Half Wood	-	71	-	1	1
Galvanized Iron/Aluminum	1	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	2,324	-	39	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	23	-	24	5
No Walls	-	-	-	-	-
CAPOOCAN					
Total	125	2,384	13	13	41
Concrete/Brick/Stone	4	28	1	1	1
Wood	68	769	7	3	3
Half Concrete/Brick/Stone and Half Wood	28	157	1	4	2
Galvanized Iron/Aluminum	4	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	21	1,418	1	4	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	3	-	-
Others/Not Reported	-	5	-	1	32
No Walls	-	-	-	-	-
CARIGARA					
Total	513	3,425	5	15	120
Concrete/Brick/Stone	23	64	-	1	4
Wood	346	1,630	2	4	11
Half Concrete/Brick/Stone and Half Wood	32	210	-	4	4
Galvanized Iron/Aluminum	5	4	-	1	-
Bamboo/Sawali/Cogon/Nipa	107	1,453	-	4	9
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	27	3	-	-
Others/Not Reported	-	37	-	1	91
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
DAGAMI					
Total	343	2,872	4	30	20
Concrete/Brick/Stone	9	23	-	1	2
Wood	38	795	1	6	-
Half Concrete/Brick/Stone and Half Wood	16	90	-	16	2
Galvanized Iron/Aluminum	2	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	278	1,942	-	7	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	10	3	-	-
Others/Not Reported	-	9	-	-	16
No Walls	-	1	-	-	-
DULAG					
Total	875	4,195	12	2	94
Concrete/Brick/Stone	5	105	-	1	3
Wood	203	1,172	1	1	4
Half Concrete/Brick/Stone and Half Wood	118	499	-	-	3
Galvanized Iron/Aluminum	-	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	544	2,373	5	-	4
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	25	6	-	-
Others/Not Reported	1	15	-	-	80
No Walls	1	-	-	-	-
HILONGOS					
Total	34	3,571	17	1	94
Concrete/Brick/Stone	-	296	1	1	1
Wood	8	141	-	-	3
Half Concrete/Brick/Stone and Half Wood	7	195	-	-	2
Galvanized Iron/Aluminum	-	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	19	2,910	8	-	19
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	8	-	1
Others/Not Reported	-	7	-	-	68
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
HINDANG					
Total	15	1,161	3	4	31
Concrete/Brick/Stone	1	49	-	-	2
Wood	-	41	1	-	-
Half Concrete/Brick/Stone and Half Wood	2	53	-	1	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	1,012	2	3	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	-	-	-	25
No Walls	-	-	-	-	-
INOPACAN					
Total	2	517	16	2	32
Concrete/Brick/Stone	-	14	-	-	1
Wood	-	42	1	-	-
Half Concrete/Brick/Stone and Half Wood	1	27	4	1	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	424	5	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	6	-	-
Others/Not Reported	-	-	-	-	31
No Walls	-	-	-	-	-
ISABEL					
Total	70	2,302	24	5	39
Concrete/Brick/Stone	3	26	-	1	2
Wood	46	680	2	2	1
Half Concrete/Brick/Stone and Half Wood	8	106	-	-	-
Galvanized Iron/Aluminum	3	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	1,430	8	-	6
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	42	14	-	-
Others/Not Reported	-	14	-	1	30
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
JARO					
Total	238	3,225	17	20	28
Concrete/Brick/Stone	8	44	-	2	2
Wood	126	515	2	2	5
Half Concrete/Brick/Stone and Half Wood	62	261	1	8	3
Galvanized Iron/Aluminum	4	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	36	2,381	6	7	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	8	-	-
Others/Not Reported	2	12	-	1	16
No Walls	-	-	-	-	-
JAVIER (BUGHO)					
Total	60	1,810	-	-	48
Concrete/Brick/Stone	2	27	-	-	-
Wood	19	409	-	-	-
Half Concrete/Brick/Stone and Half Wood	22	141	-	-	1
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	1,215	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	14	-	-	46
No Walls	-	-	-	-	-
JULITA					
Total	64	1,864	-	-	9
Concrete/Brick/Stone	-	24	-	-	1
Wood	61	837	-	-	3
Half Concrete/Brick/Stone and Half Wood	1	106	-	-	-
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	886	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	3	-	-	5
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
KANANGA					
Total	120	2,473	5	2	89
Concrete/Brick/Stone	-	14	1	-	4
Wood	47	241	-	2	6
Half Concrete/Brick/Stone and Half Wood	30	76	-	-	13
Galvanized Iron/Aluminum	3	4	1	-	-
Bamboo/Sawali/Cogon/Nipa	40	2,133	2	-	14
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	-	3	-	-	51
No Walls	-	-	-	-	-
LAPAZ					
Total	196	2,005	2	-	24
Concrete/Brick/Stone	3	13	-	-	2
Wood	171	620	-	-	1
Half Concrete/Brick/Stone and Half Wood	8	129	-	-	3
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	1,236	1	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	-	-
Others/Not Reported	-	2	-	-	14
No Walls	-	-	-	-	-
LEYTE					
Total	129	3,300	54	12	15
Concrete/Brick/Stone	-	4	-	-	1
Wood	30	141	1	-	2
Half Concrete/Brick/Stone and Half Wood	-	101	-	-	1
Galvanized Iron/Aluminum	-	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	98	2,990	7	-	4
Asbestos	-	-	-	12	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	48	46	-	-
Others/Not Reported	1	8	-	-	7
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MACARTHUR					
Total	107	1,796	-	11	38
Concrete/Brick/Stone	19	69	-	2	-
Wood	22	340	-	3	-
Half Concrete/Brick/Stone and Half Wood	51	125	-	-	2
Galvanized Iron/Aluminum	1	3	-	1	-
Bamboo/Sawali/Cogon/Nipa	14	1,245	-	5	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	-	-	-
Others/Not Reported	-	7	-	-	36
No Walls	-	1	-	-	-
MAHAPLAG					
Total	30	898	1	1	39
Concrete/Brick/Stone	-	4	-	-	-
Wood	14	46	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	27	-	-	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	817	1	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	2	-	-	37
No Walls	-	-	-	-	-
MATAG-OB					
Total	5	412	2	2	9
Concrete/Brick/Stone	-	-	-	-	-
Wood	2	15	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	394	-	2	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	-	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MATALOM					
Total	5	985	3	10	65
Concrete/Brick/Stone	-	11	-	5	3
Wood	1	43	-	-	2
Half Concrete/Brick/Stone and Half Wood	1	28	-	1	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	896	-	4	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	3	-	-
Others/Not Reported	-	1	-	-	55
No Walls	-	-	-	-	-
MAYORGA					
Total	27	1,640	-	2	44
Concrete/Brick/Stone	-	36	-	-	2
Wood	6	813	-	1	1
Half Concrete/Brick/Stone and Half Wood	6	90	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	694	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	3	5	-	-	41
No Walls	-	-	-	-	-
MERIDA					
Total	2	1,507	28	44	12
Concrete/Brick/Stone	-	14	-	-	-
Wood	-	236	-	3	1
Half Concrete/Brick/Stone and Half Wood	-	45	-	5	1
Galvanized Iron/Aluminum	-	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	2	1,167	17	25	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	10	1	-
Others/Not Reported	-	35	-	10	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ORMOC CITY					
Total	230	8,831	117	24	356
Concrete/Brick/Stone	13	94	15	4	10
Wood	83	1,899	14	4	21
Half Concrete/Brick/Stone and Half Wood	31	567	7	4	34
Galvanized Iron/Aluminum	5	12	-	-	1
Bamboo/Sawali/Cogon/Nipa	91	6,099	25	9	35
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	119	56	-	-
Others/Not Reported	4	38	-	2	255
No Walls	-	3	-	1	-
PALO					
Total	243	4,169	9	12	150
Concrete/Brick/Stone	5	86	3	5	5
Wood	152	1,066	2	2	10
Half Concrete/Brick/Stone and Half Wood	19	305	-	4	9
Galvanized Iron/Aluminum	16	18	-	-	-
Bamboo/Sawali/Cogon/Nipa	51	2,670	2	1	15
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	2	-	-
Others/Not Reported	-	8	-	-	111
No Walls	-	-	-	-	-
PALOMPON					
Total	8	1,365	8	28	37
Concrete/Brick/Stone	1	7	1	-	1
Wood	2	139	1	6	7
Half Concrete/Brick/Stone and Half Wood	-	13	-	-	1
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	1,191	3	19	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	3	-	-
Others/Not Reported	-	7	-	3	22
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PASTRANA					
Total	418	1,754	2	2	41
Concrete/Brick/Stone	2	27	-	-	-
Wood	9	536	-	2	-
Half Concrete/Brick/Stone and Half Wood	112	184	1	-	1
Galvanized Iron/Aluminum	3	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	287	977	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	5	26	-	-	39
No Walls	-	-	-	-	-
SAN ISIDRO					
Total	303	2,502	3	15	35
Concrete/Brick/Stone	1	5	-	-	1
Wood	20	85	1	-	3
Half Concrete/Brick/Stone and Half Wood	53	22	-	-	1
Galvanized Iron/Aluminum	13	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	215	2,360	1	6	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	4	1	1	-
Others/Not Reported	-	22	-	8	25
No Walls	-	-	-	-	-
SAN MIGUEL					
Total	15	1,758	1	1	44
Concrete/Brick/Stone	1	5	1	1	2
Wood	1	368	-	-	3
Half Concrete/Brick/Stone and Half Wood	3	69	-	-	1
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	1,312	-	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	1	-	-	34
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SANTA FE					
Total	36	1,508	-	-	19
Concrete/Brick/Stone	-	19	-	-	-
Wood	3	210	-	-	1
Half Concrete/Brick/Stone and Half Wood	9	90	-	-	1
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	24	1,182	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	1	-	-	15
No Walls	-	-	-	-	-
TABANGO					
Total	41	2,318	2	1	39
Concrete/Brick/Stone	-	4	-	-	-
Wood	6	71	-	-	3
Half Concrete/Brick/Stone and Half Wood	3	11	-	-	1
Galvanized Iron/Aluminum	2	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	30	2,226	1	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	-	-
Others/Not Reported	-	3	-	1	31
No Walls	-	-	-	-	-
TABONTABON					
Total	13	1,157	-	-	9
Concrete/Brick/Stone	-	25	-	-	-
Wood	5	375	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	89	-	-	1
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	662	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	3	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TACLOBAN CITY (Capital)					
Total	325	6,927	142	229	509
Concrete/Brick/Stone	15	100	8	37	22
Wood	213	3,960	23	70	46
Half Concrete/Brick/Stone and Half Wood	26	272	6	29	7
Galvanized Iron/Aluminum	3	76	2	2	1
Bamboo/Sawali/Cogon/Nipa	59	2,219	9	47	8
Asbestos	-	-	-	1	-
Glass	3	-	-	1	1
Makeshift/Salvaged/Improvised Materials	4	188	89	5	6
Others/Not Reported	2	112	5	37	418
No Walls	-	-	-	-	-
TANAUAN					
Total	209	4,695	17	5	70
Concrete/Brick/Stone	9	90	-	1	3
Wood	121	1,577	1	-	9
Half Concrete/Brick/Stone and Half Wood	38	271	-	2	4
Galvanized Iron/Aluminum	5	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	33	2,724	1	2	3
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	21	15	-	-
Others/Not Reported	3	9	-	-	50
No Walls	-	-	-	-	-
TOLOSA					
Total	15	1,277	2	11	33
Concrete/Brick/Stone	-	20	1	-	2
Wood	3	234	-	3	-
Half Concrete/Brick/Stone and Half Wood	1	55	-	2	1
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	963	1	6	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	2	-	-	29
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
TUNGA					
Total	7	319	43	-	10
Concrete/Brick/Stone	-	4	-	-	2
Wood	1	95	15	-	1
Half Concrete/Brick/Stone and Half Wood	2	36	2	-	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	146	10	-	1
Asbestos	-	-	-	-	-
Glass	1	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	38	16	-	-
Others/Not Reported	1	-	-	-	4
No Walls	-	-	-	-	-
VILLABA					
Total	9	1,298	13	42	41
Concrete/Brick/Stone	-	2	-	-	3
Wood	1	74	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	9	-	-	1
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	1,204	10	31	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	3	-	-
Others/Not Reported	-	8	-	11	32
No Walls	-	-	-	-	-