

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

LUCENA CITY

Total	47,602	40,169	499	3,618
Concrete/Brick/Stone	21,059	20,145	434	370
Wood	10,019	8,220	10	759
Half Concrete/Brick/Stone and Half Wood	12,014	9,470	53	2,245
Galvanized Iron/Aluminum	329	270	-	40
Bamboo/Sawali/Cogon/Nipa	3,124	1,588	-	173
Asbestos	34	29	-	3
Glass	3	2	-	-
Makeshift/Salvaged/Improvised Materials	443	248	-	20
Others/Not Reported	577	197	2	8
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LUCENA CITY					
Total	842	1,862	163	60	389
Concrete/Brick/Stone	76	16	1	3	14
Wood	480	505	21	7	17
Half Concrete/Brick/Stone and Half Wood	157	74	4	1	10
Galvanized Iron/Aluminum	9	8	1	-	1
Bamboo/Sawali/Cogon/Nipa	117	1,203	13	22	8
Asbestos	-	-	-	2	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	2	47	123	2	1
Others/Not Reported	1	9	-	23	337
No Walls	-	-	-	-	-