

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MAGUINDANAO				
Total	243,057	95,175	997	10,976
Concrete/Brick/Stone	11,817	10,464	221	465
Wood	94,671	49,178	370	3,437
Half Concrete/Brick/Stone and Half Wood	29,776	20,728	244	5,356
Galvanized Iron/Aluminum	2,881	1,186	78	680
Bamboo/Sawali/Cogon/Nipa	95,984	12,814	-	936
Asbestos	45	20	2	7
Glass	73	31	18	8
Makeshift/Salvaged/Improvised Materials	1,204	297	-	38
Others/Not Reported	6,494	443	63	48
No Walls	112	14	1	1
AMPATUAN				
Total	6,063	1,859	47	219
Concrete/Brick/Stone	253	222	6	10
Wood	1,274	272	4	45
Half Concrete/Brick/Stone and Half Wood	1,043	625	25	124
Galvanized Iron/Aluminum	88	55	-	9
Bamboo/Sawali/Cogon/Nipa	2,092	609	-	25
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	-	-	2
Others/Not Reported	1,308	75	12	4
No Walls	-	-	-	-
BULDON				
Total	6,043	4,519	27	181
Concrete/Brick/Stone	334	309	7	5
Wood	4,694	3,550	12	115
Half Concrete/Brick/Stone and Half Wood	498	432	5	52
Galvanized Iron/Aluminum	18	12	-	3
Bamboo/Sawali/Cogon/Nipa	459	211	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	38	5	3	3
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BULUAN				
Total	5,948	1,978	19	469
Concrete/Brick/Stone	542	502	9	19
Wood	526	227	1	28
Half Concrete/Brick/Stone and Half Wood	1,130	596	4	358
Galvanized Iron/Aluminum	65	21	5	30
Bamboo/Sawali/Cogon/Nipa	3,620	629	-	32
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	64	2	-	2
No Walls	-	-	-	-
DATU PAGLAS				
Total	6,179	1,230	5	281
Concrete/Brick/Stone	188	177	2	1
Wood	1,140	336	2	28
Half Concrete/Brick/Stone and Half Wood	701	407	1	230
Galvanized Iron/Aluminum	15	5	-	5
Bamboo/Sawali/Cogon/Nipa	4,055	303	-	17
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	51	-	-	-
Others/Not Reported	29	2	-	-
No Walls	-	-	-	-
DATU PIANG				
Total	8,984	3,747	13	94
Concrete/Brick/Stone	120	108	1	-
Wood	5,199	3,031	9	32
Half Concrete/Brick/Stone and Half Wood	513	430	1	52
Galvanized Iron/Aluminum	197	23	1	3
Bamboo/Sawali/Cogon/Nipa	2,768	132	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	95	1	-	3
Others/Not Reported	92	22	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

DATU ODIN SINSUAT (DINAIG)

Total	19,594	6,809	66	822
Concrete/Brick/Stone	2,090	1,970	9	24
Wood	6,519	2,940	22	270
Half Concrete/Brick/Stone and Half Wood	2,107	1,275	23	432
Galvanized Iron/Aluminum	152	30	2	35
Bamboo/Sawali/Cogon/Nipa	8,329	516	-	49
Asbestos	4	1	1	-
Glass	4	-	4	-
Makeshift/Salvaged/Improvised Materials	35	5	-	7
Others/Not Reported	354	72	5	5
No Walls	-	-	-	-

SHARIFF AGUAK (MAGANOY) (Capital)

Total	12,998	4,412	114	846
Concrete/Brick/Stone	685	448	11	180
Wood	4,372	1,394	71	245
Half Concrete/Brick/Stone and Half Wood	2,964	2,277	21	342
Galvanized Iron/Aluminum	215	71	4	38
Bamboo/Sawali/Cogon/Nipa	4,482	205	-	34
Asbestos	-	-	-	-
Glass	13	7	-	3
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	242	10	6	4
No Walls	25	-	1	-

MATANOG

Total	7,280	5,659	23	184
Concrete/Brick/Stone	187	171	3	4
Wood	5,052	4,041	16	115
Half Concrete/Brick/Stone and Half Wood	1,237	1,155	2	53
Galvanized Iron/Aluminum	81	62	2	7
Bamboo/Sawali/Cogon/Nipa	568	185	-	4
Asbestos	3	2	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	149	41	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
PAGALUNGAN				
Total	6,186	2,359	11	52
Concrete/Brick/Stone	380	350	6	2
Wood	2,186	829	2	6
Half Concrete/Brick/Stone and Half Wood	434	378	-	19
Galvanized Iron/Aluminum	20	9	1	4
Bamboo/Sawali/Cogon/Nipa	3,136	790	-	21
Asbestos	-	-	-	-
Glass	6	1	2	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	24	2	-	-
No Walls	-	-	-	-
PARANG				
Total	19,558	13,250	90	1,789
Concrete/Brick/Stone	1,398	1,338	14	33
Wood	11,215	8,351	31	835
Half Concrete/Brick/Stone and Half Wood	3,712	2,567	35	859
Galvanized Iron/Aluminum	472	394	6	30
Bamboo/Sawali/Cogon/Nipa	2,635	571	-	30
Asbestos	1	-	-	-
Glass	2	-	2	-
Makeshift/Salvaged/Improvised Materials	10	2	-	1
Others/Not Reported	113	27	2	1
No Walls	-	-	-	-
SULTAN KUDARAT (NULING)				
Total	23,750	11,839	167	1,269
Concrete/Brick/Stone	1,522	1,330	72	63
Wood	12,454	7,130	47	509
Half Concrete/Brick/Stone and Half Wood	3,398	2,535	20	527
Galvanized Iron/Aluminum	452	253	22	100
Bamboo/Sawali/Cogon/Nipa	5,681	568	-	40
Asbestos	15	5	1	2
Glass	17	4	2	2
Makeshift/Salvaged/Improvised Materials	54	3	-	20
Others/Not Reported	157	11	3	6
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SULTAN SA BARONGIS (LAMBAYONG)				
Total	4,234	638	2	272
Concrete/Brick/Stone	144	130	1	10
Wood	202	53	-	73
Half Concrete/Brick/Stone and Half Wood	335	179	1	126
Galvanized Iron/Aluminum	10	5	-	3
Bamboo/Sawali/Cogon/Nipa	3,454	256	-	59
Asbestos	-	-	-	-
Glass	13	13	-	-
Makeshift/Salvaged/Improvised Materials	4	-	-	-
Others/Not Reported	72	2	-	1
No Walls	-	-	-	-
KABUNTALAN (TUMBAO)				
Total	3,379	1,467	2	92
Concrete/Brick/Stone	52	46	-	5
Wood	1,461	800	1	22
Half Concrete/Brick/Stone and Half Wood	578	491	-	56
Galvanized Iron/Aluminum	37	11	-	4
Bamboo/Sawali/Cogon/Nipa	1,212	118	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	39	1	1	-
No Walls	-	-	-	-
UPI				
Total	8,665	4,972	4	74
Concrete/Brick/Stone	448	443	2	2
Wood	831	736	1	16
Half Concrete/Brick/Stone and Half Wood	752	712	-	30
Galvanized Iron/Aluminum	41	28	-	8
Bamboo/Sawali/Cogon/Nipa	5,956	2,811	-	16
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	413	212	-	2
Others/Not Reported	146	24	1	-
No Walls	78	6	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
TALAYAN				
Total	5,055	2,300	3	42
Concrete/Brick/Stone	358	192	-	3
Wood	2,629	998	2	16
Half Concrete/Brick/Stone and Half Wood	861	801	1	7
Galvanized Iron/Aluminum	12	5	-	-
Bamboo/Sawali/Cogon/Nipa	1,163	299	-	14
Asbestos	4	2	-	2
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	27	2	-	-
No Walls	-	-	-	-
SOUTH UPI				
Total	6,771	1,926	3	37
Concrete/Brick/Stone	89	85	2	1
Wood	1,698	1,211	-	6
Half Concrete/Brick/Stone and Half Wood	206	188	-	12
Galvanized Iron/Aluminum	21	4	1	-
Bamboo/Sawali/Cogon/Nipa	4,509	434	-	18
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	246	3	-	-
No Walls	-	-	-	-
BARIRA				
Total	5,578	4,998	8	21
Concrete/Brick/Stone	149	148	-	1
Wood	3,373	3,215	6	5
Half Concrete/Brick/Stone and Half Wood	1,078	1,063	1	6
Galvanized Iron/Aluminum	41	30	-	1
Bamboo/Sawali/Cogon/Nipa	862	514	-	8
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	74	27	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

GEN. S. K. PENDATUN

Total	5,916	705	6	497
Concrete/Brick/Stone	118	106	5	2
Wood	658	171	-	145
Half Concrete/Brick/Stone and Half Wood	431	117	1	294
Galvanized Iron/Aluminum	25	7	-	7
Bamboo/Sawali/Cogon/Nipa	4,279	294	-	49
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	279	2	-	-
Others/Not Reported	126	8	-	-
No Walls	-	-	-	-

MAMASAPANO

Total	5,854	1,592	27	86
Concrete/Brick/Stone	182	167	3	-
Wood	2,669	757	12	32
Half Concrete/Brick/Stone and Half Wood	316	282	-	21
Galvanized Iron/Aluminum	15	8	-	1
Bamboo/Sawali/Cogon/Nipa	2,505	378	-	32
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	166	-	12	-
No Walls	-	-	-	-

TALITAY

Total	4,683	203	34	319
Concrete/Brick/Stone	16	10	1	3
Wood	1,431	76	4	21
Half Concrete/Brick/Stone and Half Wood	417	95	23	115
Galvanized Iron/Aluminum	203	6	4	161
Bamboo/Sawali/Cogon/Nipa	2,484	15	-	17
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	129	1	2	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
PAGAGAWAN				
Total	6,612	2,896	25	217
Concrete/Brick/Stone	263	256	2	2
Wood	2,910	2,094	19	111
Half Concrete/Brick/Stone and Half Wood	306	181	3	59
Galvanized Iron/Aluminum	41	5	-	6
Bamboo/Sawali/Cogon/Nipa	2,881	282	-	39
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	131	67	-	-
Others/Not Reported	80	11	1	-
No Walls	-	-	-	-
PAGLAT				
Total	4,084	137	17	267
Concrete/Brick/Stone	40	20	6	-
Wood	112	36	2	7
Half Concrete/Brick/Stone and Half Wood	168	14	2	134
Galvanized Iron/Aluminum	82	2	-	45
Bamboo/Sawali/Cogon/Nipa	1,970	63	-	74
Asbestos	2	1	-	-
Glass	3	-	1	1
Makeshift/Salvaged/Improvised Materials	44	1	-	1
Others/Not Reported	1,663	-	6	5
No Walls	-	-	-	-
SULTAN MASTURA				
Total	4,748	3,370	2	135
Concrete/Brick/Stone	265	260	2	1
Wood	1,746	1,279	-	81
Half Concrete/Brick/Stone and Half Wood	1,778	1,710	-	44
Galvanized Iron/Aluminum	35	34	-	-
Bamboo/Sawali/Cogon/Nipa	916	86	-	9
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	1	-	-
Others/Not Reported	3	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
GUINDULUNGAN				
Total	3,535	740	12	128
Concrete/Brick/Stone	59	52	3	2
Wood	1,609	387	1	12
Half Concrete/Brick/Stone and Half Wood	421	246	7	112
Galvanized Iron/Aluminum	8	4	-	-
Bamboo/Sawali/Cogon/Nipa	1,422	51	-	2
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	15	-	1	-
No Walls	-	-	-	-
DATU SAUDI-AMPATUAN				
Total	9,992	2,818	60	356
Concrete/Brick/Stone	378	306	13	39
Wood	5,623	1,818	8	69
Half Concrete/Brick/Stone and Half Wood	1,056	578	31	136
Galvanized Iron/Aluminum	173	18	8	71
Bamboo/Sawali/Cogon/Nipa	2,641	96	-	39
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	18	-	-	1
Others/Not Reported	103	2	-	1
No Walls	-	-	-	-
DATU UNSAY				
Total	9,296	765	19	383
Concrete/Brick/Stone	27	11	5	6
Wood	3,625	596	2	240
Half Concrete/Brick/Stone and Half Wood	160	39	3	76
Galvanized Iron/Aluminum	58	7	-	16
Bamboo/Sawali/Cogon/Nipa	5,150	96	-	38
Asbestos	-	-	-	-
Glass	10	1	7	2
Makeshift/Salvaged/Improvised Materials	36	1	-	1
Others/Not Reported	225	10	2	3
No Walls	5	4	-	1

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

DATU ABDULLAH SANKI

Total	6,474	1,270	39	482
Concrete/Brick/Stone	231	169	9	5
Wood	871	263	7	38
Half Concrete/Brick/Stone and Half Wood	759	249	4	310
Galvanized Iron/Aluminum	57	24	18	4
Bamboo/Sawali/Cogon/Nipa	4,489	561	-	122
Asbestos	6	3	-	3
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	60	-	1	-
No Walls	-	-	-	-

RAJAH BUAYAN

Total	4,897	497	18	451
Concrete/Brick/Stone	86	41	7	3
Wood	1,991	120	1	36
Half Concrete/Brick/Stone and Half Wood	740	173	9	359
Galvanized Iron/Aluminum	55	7	1	14
Bamboo/Sawali/Cogon/Nipa	1,946	154	-	39
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	76	-	-	-
No Walls	1	1	-	-

DATU BLAH T. SINSUAT

Total	4,526	708	40	163
Concrete/Brick/Stone	34	25	2	3
Wood	1,295	312	38	82
Half Concrete/Brick/Stone and Half Wood	314	216	-	63
Galvanized Iron/Aluminum	15	3	-	4
Bamboo/Sawali/Cogon/Nipa	2,425	75	-	11
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	-	-	-
Others/Not Reported	432	77	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

DATU ANGGAL MIDTIMBANG

Total	4,120	1,548	5	164
Concrete/Brick/Stone	550	523	4	5
Wood	1,914	711	1	52
Half Concrete/Brick/Stone and Half Wood	353	226	-	98
Galvanized Iron/Aluminum	44	5	-	7
Bamboo/Sawali/Cogon/Nipa	1,253	83	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	6	-	-	-
No Walls	-	-	-	-

MANGUDADATU

Total	4,334	1,425	14	192
Concrete/Brick/Stone	27	20	-	5
Wood	260	227	8	5
Half Concrete/Brick/Stone and Half Wood	319	215	3	92
Galvanized Iron/Aluminum	63	26	1	26
Bamboo/Sawali/Cogon/Nipa	3,496	935	-	54
Asbestos	3	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	165	-	2	10
No Walls	-	-	-	-

PANDAG

Total	2,947	756	60	226
Concrete/Brick/Stone	356	286	14	26
Wood	1,170	330	35	76
Half Concrete/Brick/Stone and Half Wood	189	83	10	68
Galvanized Iron/Aluminum	54	5	1	34
Bamboo/Sawali/Cogon/Nipa	1,142	51	-	22
Asbestos	2	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	34	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

NORTHERN KABUNTALAN

Total	4,774	1,783	15	166
Concrete/Brick/Stone	246	243	-	-
Wood	1,962	887	5	64
Half Concrete/Brick/Stone and Half Wood	502	193	8	90
Galvanized Iron/Aluminum	16	7	1	4
Bamboo/Sawali/Cogon/Nipa	2,004	443	-	8
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	37	6	1	-
No Walls	3	3	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAGUINDANAO					
Total	12,047	118,421	645	572	4,224
Concrete/Brick/Stone	197	389	4	26	51
Wood	6,038	35,052	263	173	160
Half Concrete/Brick/Stone and Half Wood	1,076	2,074	103	31	164
Galvanized Iron/Aluminum	594	322	4	2	15
Bamboo/Sawali/Cogon/Nipa	3,635	78,013	122	163	301
Asbestos	10	-	-	5	1
Glass	10	-	-	4	2
Makeshift/Salvaged/Improvised Materials	93	622	145	2	7
Others/Not Reported	381	1,866	4	166	3,523
No Walls	13	83	-	-	-
AMPATUAN					
Total	669	2,820	-	19	430
Concrete/Brick/Stone	-	11	-	-	4
Wood	339	611	-	1	2
Half Concrete/Brick/Stone and Half Wood	58	134	-	-	77
Galvanized Iron/Aluminum	13	7	-	-	4
Bamboo/Sawali/Cogon/Nipa	212	1,236	-	5	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	47	819	-	13	338
No Walls	-	-	-	-	-
BULDON					
Total	175	1,103	2	3	33
Concrete/Brick/Stone	-	9	-	-	4
Wood	143	862	1	3	8
Half Concrete/Brick/Stone and Half Wood	3	4	-	-	2
Galvanized Iron/Aluminum	2	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	21	222	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	6	4	-	-	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BULUAN					
Total	204	3,210	-	1	67
Concrete/Brick/Stone	1	11	-	-	-
Wood	135	134	-	-	1
Half Concrete/Brick/Stone and Half Wood	28	140	-	1	3
Galvanized Iron/Aluminum	2	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	38	2,906	-	-	15
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	12	-	-	48
No Walls	-	-	-	-	-
DATU PAGLAS					
Total	103	4,539	2	5	14
Concrete/Brick/Stone	1	7	-	-	-
Wood	49	721	-	4	-
Half Concrete/Brick/Stone and Half Wood	1	62	-	-	-
Galvanized Iron/Aluminum	2	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	50	3,682	-	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	50	1	-	-
Others/Not Reported	-	14	1	-	12
No Walls	-	-	-	-	-
DATU PIANG					
Total	765	4,207	93	3	62
Concrete/Brick/Stone	1	10	-	-	-
Wood	447	1,605	66	2	7
Half Concrete/Brick/Stone and Half Wood	10	17	1	-	2
Galvanized Iron/Aluminum	155	15	-	-	-
Bamboo/Sawali/Cogon/Nipa	76	2,533	17	1	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	74	7	9	-	1
Others/Not Reported	2	20	-	-	47
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
DATU ODIN SINSUAT (DINAIG)					
Total	2,705	8,937	8	127	120
Concrete/Brick/Stone	62	10	-	10	5
Wood	1,212	2,056	5	10	4
Half Concrete/Brick/Stone and Half Wood	201	157	-	12	7
Galvanized Iron/Aluminum	68	16	-	-	1
Bamboo/Sawali/Cogon/Nipa	1,159	6,584	-	3	18
Asbestos	2	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	20	1	1	1
Others/Not Reported	1	94	2	91	84
No Walls	-	-	-	-	-
SHARIFF AGUAK (MAGANOY) (Capital)					
Total	545	6,850	-	2	229
Concrete/Brick/Stone	26	16	-	-	4
Wood	118	2,533	-	2	9
Half Concrete/Brick/Stone and Half Wood	77	240	-	-	7
Galvanized Iron/Aluminum	73	29	-	-	-
Bamboo/Sawali/Cogon/Nipa	236	3,983	-	-	24
Asbestos	-	-	-	-	-
Glass	1	-	-	-	2
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	38	-	-	183
No Walls	13	11	-	-	-
MATANOG					
Total	283	998	2	8	123
Concrete/Brick/Stone	-	8	-	1	-
Wood	238	622	1	5	14
Half Concrete/Brick/Stone and Half Wood	13	12	-	-	2
Galvanized Iron/Aluminum	7	2	-	1	-
Bamboo/Sawali/Cogon/Nipa	20	354	-	-	5
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	5	-	-	-	102
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PAGALUNGAN					
Total	66	3,682	-	-	16
Concrete/Brick/Stone	8	13	-	-	1
Wood	27	1,320	-	-	2
Half Concrete/Brick/Stone and Half Wood	6	31	-	-	-
Galvanized Iron/Aluminum	3	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	19	2,300	-	-	6
Asbestos	-	-	-	-	-
Glass	3	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	15	-	-	7
No Walls	-	-	-	-	-
PARANG					
Total	1,021	3,316	2	1	89
Concrete/Brick/Stone	4	8	-	-	1
Wood	725	1,268	2	1	2
Half Concrete/Brick/Stone and Half Wood	219	29	-	-	3
Galvanized Iron/Aluminum	30	10	-	-	2
Bamboo/Sawali/Cogon/Nipa	36	1,994	-	-	4
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	4	-	-	-
Others/Not Reported	3	3	-	-	77
No Walls	-	-	-	-	-
SULTAN KUDARAT (NULING)					
Total	957	9,295	9	93	121
Concrete/Brick/Stone	40	12	4	-	1
Wood	467	4,213	2	73	13
Half Concrete/Brick/Stone and Half Wood	190	121	-	3	2
Galvanized Iron/Aluminum	42	35	-	-	-
Bamboo/Sawali/Cogon/Nipa	195	4,862	2	2	12
Asbestos	5	-	-	2	-
Glass	6	-	-	3	-
Makeshift/Salvaged/Improvised Materials	3	26	1	1	-
Others/Not Reported	9	26	-	9	93
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SULTAN SA BARONGIS (LAMBAYONG)					
Total	2	3,254	-	-	66
Concrete/Brick/Stone	-	1	-	-	2
Wood	-	76	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	28	-	-	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	3,132	-	-	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	-	11	-	-	58
No Walls	-	-	-	-	-
KABUNTALAN (TUMBAO)					
Total	180	1,328	257	31	22
Concrete/Brick/Stone	-	1	-	-	-
Wood	142	293	178	23	2
Half Concrete/Brick/Stone and Half Wood	5	12	10	4	-
Galvanized Iron/Aluminum	20	1	1	-	-
Bamboo/Sawali/Cogon/Nipa	2	1,013	68	4	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	11	8	-	-	18
No Walls	-	-	-	-	-
UPI					
Total	55	3,413	23	1	123
Concrete/Brick/Stone	-	-	-	-	1
Wood	36	39	2	-	1
Half Concrete/Brick/Stone and Half Wood	1	9	-	-	-
Galvanized Iron/Aluminum	1	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	3,102	4	1	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	179	17	-	1
Others/Not Reported	-	8	-	-	113
No Walls	-	72	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TALAYAN					
Total	39	2,646	1	2	22
Concrete/Brick/Stone	21	140	-	1	1
Wood	6	1,607	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	50	-	1	-
Galvanized Iron/Aluminum	2	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	839	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	5	-	-	20
No Walls	-	-	-	-	-
SOUTH UPI					
Total	102	4,660	2	1	40
Concrete/Brick/Stone	-	1	-	-	-
Wood	23	455	-	1	2
Half Concrete/Brick/Stone and Half Wood	3	3	-	-	-
Galvanized Iron/Aluminum	8	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	68	3,983	2	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	209	-	-	34
No Walls	-	-	-	-	-
BARIRA					
Total	113	345	-	30	63
Concrete/Brick/Stone	-	-	-	-	-
Wood	97	48	-	-	2
Half Concrete/Brick/Stone and Half Wood	2	3	-	1	2
Galvanized Iron/Aluminum	9	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	293	-	27	15
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	2	44
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
GEN. S. K. PENDATUN					
Total	66	4,439	83	1	119
Concrete/Brick/Stone	-	-	-	-	5
Wood	3	338	-	1	-
Half Concrete/Brick/Stone and Half Wood	3	16	-	-	-
Galvanized Iron/Aluminum	7	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	46	3,876	7	-	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	192	76	-	2
Others/Not Reported	-	13	-	-	105
No Walls	-	-	-	-	-
MAMASAPANO					
Total	52	3,924	-	19	154
Concrete/Brick/Stone	-	10	-	-	2
Wood	21	1,826	-	19	2
Half Concrete/Brick/Stone and Half Wood	-	13	-	-	-
Galvanized Iron/Aluminum	3	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	28	2,064	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	7	-	-	147
No Walls	-	-	-	-	-
TALITAY					
Total	362	3,656	3	1	105
Concrete/Brick/Stone	2	-	-	-	-
Wood	50	1,275	1	-	4
Half Concrete/Brick/Stone and Half Wood	44	124	1	-	15
Galvanized Iron/Aluminum	23	8	-	-	1
Bamboo/Sawali/Cogon/Nipa	241	2,199	1	-	11
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-	-
Others/Not Reported	-	50	-	-	74
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PAGAGAWAN					
Total	116	3,146	22	154	36
Concrete/Brick/Stone	-	3	-	-	-
Wood	10	653	-	16	7
Half Concrete/Brick/Stone and Half Wood	46	17	-	-	-
Galvanized Iron/Aluminum	24	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	34	2,397	5	117	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	47	17	-	-
Others/Not Reported	2	23	-	21	22
No Walls	-	-	-	-	-
PAGLAT					
Total	451	2,028	6	14	1,164
Concrete/Brick/Stone	4	7	-	1	2
Wood	14	52	-	1	-
Half Concrete/Brick/Stone and Half Wood	10	7	1	-	-
Galvanized Iron/Aluminum	12	18	3	-	2
Bamboo/Sawali/Cogon/Nipa	162	1,658	2	1	10
Asbestos	1	-	-	-	-
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	1	40	-	-	1
Others/Not Reported	247	246	-	10	1,149
No Walls	-	-	-	-	-
SULTAN MASTURA					
Total	27	1,211	-	-	3
Concrete/Brick/Stone	-	2	-	-	-
Wood	18	368	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	22	-	-	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	815	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	-	-	-	-	3
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
GUINDULUNGAN					
Total	300	2,340	-	3	12
Concrete/Brick/Stone	1	-	-	1	-
Wood	263	945	-	1	-
Half Concrete/Brick/Stone and Half Wood	8	48	-	-	-
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	27	1,339	-	-	3
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	5	-	-	9
No Walls	-	-	-	-	-
DATU SAUDI-AMPATUAN					
Total	442	6,113	107	5	91
Concrete/Brick/Stone	2	18	-	-	-
Wood	69	3,651	3	5	-
Half Concrete/Brick/Stone and Half Wood	22	194	89	-	6
Galvanized Iron/Aluminum	24	51	-	-	1
Bamboo/Sawali/Cogon/Nipa	323	2,169	6	-	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	7	9	-	-
Others/Not Reported	1	23	-	-	76
No Walls	-	-	-	-	-
DATU UNSAY					
Total	374	7,606	7	9	133
Concrete/Brick/Stone	1	3	-	-	1
Wood	81	2,687	-	-	19
Half Concrete/Brick/Stone and Half Wood	27	14	-	-	1
Galvanized Iron/Aluminum	27	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	232	4,753	4	-	27
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	31	2	-	1
Others/Not Reported	6	110	1	9	84
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

DATU ABDULLAH SANKI

Total	292	4,209	2	26	154
Concrete/Brick/Stone	-	20	-	11	17
Wood	189	338	-	-	36
Half Concrete/Brick/Stone and Half Wood	51	110	-	9	26
Galvanized Iron/Aluminum	2	6	-	-	3
Bamboo/Sawali/Cogon/Nipa	50	3,704	2	1	49
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	31	-	5	23
No Walls	-	-	-	-	-

RAJAH BUAYAN

Total	643	3,224	1	7	56
Concrete/Brick/Stone	18	17	-	-	-
Wood	501	1,319	-	-	14
Half Concrete/Brick/Stone and Half Wood	29	164	-	-	6
Galvanized Iron/Aluminum	2	30	-	1	-
Bamboo/Sawali/Cogon/Nipa	57	1,676	-	-	20
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	36	18	-	6	16
No Walls	-	-	-	-	-

DATU BLAH T. SINSUAT

Total	208	3,041	11	-	355
Concrete/Brick/Stone	-	4	-	-	-
Wood	104	756	1	-	2
Half Concrete/Brick/Stone and Half Wood	4	31	-	-	-
Galvanized Iron/Aluminum	1	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	98	2,231	-	-	10
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	10	-	-
Others/Not Reported	1	11	-	-	343
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

DATU ANGGAL MIDTIMBANG

Total	53	2,331	1	3	15
Concrete/Brick/Stone	3	15	-	-	-
Wood	14	1,127	1	3	5
Half Concrete/Brick/Stone and Half Wood	3	24	-	-	2
Galvanized Iron/Aluminum	20	12	-	-	-
Bamboo/Sawali/Cogon/Nipa	13	1,150	-	-	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	3	-	-	3
No Walls	-	-	-	-	-

MANGUDADATU

Total	56	2,518	1	-	128
Concrete/Brick/Stone	-	2	-	-	-
Wood	9	11	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	8	1	-	-
Galvanized Iron/Aluminum	3	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	41	2,457	-	-	9
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	3	32	-	-	118
No Walls	-	-	-	-	-

PANDAG

Total	304	1,568	-	3	30
Concrete/Brick/Stone	1	28	-	1	-
Wood	213	513	-	2	1
Half Concrete/Brick/Stone and Half Wood	6	22	-	-	-
Galvanized Iron/Aluminum	6	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	77	992	-	-	-
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	5	-	-	29
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
NORTHERN KABUNTALAN					
Total	317	2,464	-	-	29
Concrete/Brick/Stone	1	2	-	-	-
Wood	275	730	-	-	1
Half Concrete/Brick/Stone and Half Wood	3	208	-	-	-
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	37	1,515	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	3	-	-	27
No Walls	-	-	-	-	-