

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## MARINDUQUE

Total	49,725	39,454	158	1,434
Concrete/Brick/Stone	18,298	17,990	82	73
Wood	9,084	7,545	11	207
Half Concrete/Brick/Stone and Half Wood	10,942	9,588	50	828
Galvanized Iron/Aluminum	176	124	12	32
Bamboo/Sawali/Cogon/Nipa	10,784	4,004	-	291
Asbestos	8	7	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	209	95	-	3
Others/Not Reported	221	98	3	-
No Walls	2	2	-	-

## BOAC (Capital)

Total	11,153	9,101	30	267
Concrete/Brick/Stone	4,536	4,479	16	3
Wood	1,903	1,496	2	41
Half Concrete/Brick/Stone and Half Wood	2,637	2,320	3	169
Galvanized Iron/Aluminum	53	21	9	21
Bamboo/Sawali/Cogon/Nipa	1,954	745	-	33
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	13	5	-	-
Others/Not Reported	56	34	-	-
No Walls	1	1	-	-

## BUENAVISTA

Total	4,376	2,828	8	135
Concrete/Brick/Stone	1,171	1,140	8	6
Wood	592	487	-	-
Half Concrete/Brick/Stone and Half Wood	963	775	-	102
Galvanized Iron/Aluminum	13	8	-	3
Bamboo/Sawali/Cogon/Nipa	1,599	404	-	24
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	25	10	-	-
Others/Not Reported	13	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## GASAN

Total	7,350	4,804	71	629
Concrete/Brick/Stone	2,439	2,329	17	39
Wood	906	581	8	110
Half Concrete/Brick/Stone and Half Wood	1,933	1,392	43	368
Galvanized Iron/Aluminum	17	10	2	4
Bamboo/Sawali/Cogon/Nipa	1,956	470	-	106
Asbestos	1	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	46	13	-	2
Others/Not Reported	51	8	1	-
No Walls	-	-	-	-

## MOGPOG

Total	7,546	6,604	7	34
Concrete/Brick/Stone	2,990	2,950	5	6
Wood	1,623	1,404	-	8
Half Concrete/Brick/Stone and Half Wood	1,636	1,567	2	12
Galvanized Iron/Aluminum	13	11	-	1
Bamboo/Sawali/Cogon/Nipa	1,224	655	-	7
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	26	7	-	-
Others/Not Reported	29	5	-	-
No Walls	-	-	-	-

## SANTA CRUZ

Total	13,007	11,453	33	84
Concrete/Brick/Stone	5,186	5,143	28	6
Wood	3,354	2,993	1	25
Half Concrete/Brick/Stone and Half Wood	2,202	2,141	1	30
Galvanized Iron/Aluminum	48	44	1	1
Bamboo/Sawali/Cogon/Nipa	2,068	1,038	-	21
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	85	49	-	1
Others/Not Reported	62	43	2	-
No Walls	1	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## TORRIJOS

Total	6,293	4,664	9	285
Concrete/Brick/Stone	1,976	1,949	8	13
Wood	706	584	-	23
Half Concrete/Brick/Stone and Half Wood	1,571	1,393	1	147
Galvanized Iron/Aluminum	32	30	-	2
Bamboo/Sawali/Cogon/Nipa	1,983	692	-	100
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	14	11	-	-
Others/Not Reported	10	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>MARINDUQUE</b>					
Total	174	8,114	111	163	117
Concrete/Brick/Stone	27	101	2	14	9
Wood	20	1,235	9	41	16
Half Concrete/Brick/Stone and Half Wood	38	377	10	40	11
Galvanized Iron/Aluminum	3	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	86	6,279	47	58	19
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	66	43	2	-
Others/Not Reported	-	51	-	8	61
No Walls	-	-	-	-	-
<b>BOAC (Capital)</b>					
Total	23	1,634	12	58	28
Concrete/Brick/Stone	-	33	-	5	-
Wood	4	333	2	17	8
Half Concrete/Brick/Stone and Half Wood	2	120	-	20	3
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	1,136	3	14	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	7	-	-
Others/Not Reported	-	9	-	2	11
No Walls	-	-	-	-	-
<b>BUENAVISTA</b>					
Total	5	1,340	4	48	8
Concrete/Brick/Stone	-	16	-	-	1
Wood	-	99	1	4	1
Half Concrete/Brick/Stone and Half Wood	-	71	-	14	1
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	1,134	1	30	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	2	-	-
Others/Not Reported	-	6	-	-	3
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>GASAN</b>					
Total	97	1,686	35	14	14
Concrete/Brick/Stone	27	23	1	-	3
Wood	3	197	1	6	-
Half Concrete/Brick/Stone and Half Wood	30	91	7	1	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	37	1,325	14	2	2
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	18	12	1	-
Others/Not Reported	-	31	-	4	7
No Walls	-	-	-	-	-
<b>MOGPOG</b>					
Total	6	794	47	17	37
Concrete/Brick/Stone	-	20	1	5	3
Wood	2	196	3	5	5
Half Concrete/Brick/Stone and Half Wood	-	48	3	2	2
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	522	28	5	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	12	-	-
Others/Not Reported	-	1	-	-	23
No Walls	-	-	-	-	-
<b>SANTA CRUZ</b>					
Total	32	1,346	12	24	23
Concrete/Brick/Stone	-	4	-	4	1
Wood	9	314	2	8	2
Half Concrete/Brick/Stone and Half Wood	5	19	-	3	3
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	981	1	6	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	25	9	1	-
Others/Not Reported	-	2	-	2	13
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

## TORRIJOS

Total	11	1,314	1	2	7
Concrete/Brick/Stone	-	5	-	-	1
Wood	2	96	-	1	-
Half Concrete/Brick/Stone and Half Wood	1	28	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,181	-	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	-	2	-	-	4
No Walls	-	-	-	-	-