

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>MASBATE</b>				
Total	154,860	59,481	753	3,801
Concrete/Brick/Stone	26,154	23,278	602	330
Wood	36,966	15,959	16	410
Half Concrete/Brick/Stone and Half Wood	17,352	11,396	82	2,221
Galvanized Iron/Aluminum	884	359	29	273
Bamboo/Sawali/Cogon/Nipa	69,709	8,098	-	526
Asbestos	25	15	1	-
Glass	52	26	10	2
Makeshift/Salvaged/Improvised Materials	2,424	160	-	17
Others/Not Reported	1,293	190	13	22
No Walls	1	-	-	-
<b>AROROY</b>				
Total	11,739	4,440	21	274
Concrete/Brick/Stone	1,919	1,809	11	15
Wood	2,304	892	-	57
Half Concrete/Brick/Stone and Half Wood	1,721	1,243	5	148
Galvanized Iron/Aluminum	61	26	3	13
Bamboo/Sawali/Cogon/Nipa	5,496	431	-	25
Asbestos	3	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	125	12	-	14
Others/Not Reported	110	26	2	2
No Walls	-	-	-	-
<b>BALENO</b>				
Total	3,995	1,088	8	97
Concrete/Brick/Stone	737	653	5	15
Wood	861	146	-	15
Half Concrete/Brick/Stone and Half Wood	509	251	3	57
Galvanized Iron/Aluminum	5	1	-	1
Bamboo/Sawali/Cogon/Nipa	1,820	31	-	9
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	16	2	-	-
Others/Not Reported	47	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>BALUD</b>				
Total	6,214	2,019	81	329
Concrete/Brick/Stone	1,101	973	47	53
Wood	538	158	1	13
Half Concrete/Brick/Stone and Half Wood	811	502	14	175
Galvanized Iron/Aluminum	55	15	15	14
Bamboo/Sawali/Cogon/Nipa	3,629	358	-	69
Asbestos	3	-	-	-
Glass	1	-	-	1
Makeshift/Salvaged/Improvised Materials	22	7	-	-
Others/Not Reported	54	6	4	4
No Walls	-	-	-	-
<b>BATUAN</b>				
Total	2,568	532	16	19
Concrete/Brick/Stone	465	364	15	10
Wood	1,335	94	-	6
Half Concrete/Brick/Stone and Half Wood	183	65	1	3
Galvanized Iron/Aluminum	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	569	4	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	12	4	-	-
No Walls	-	-	-	-
<b>CATAINGAN</b>				
Total	9,938	5,000	38	114
Concrete/Brick/Stone	1,416	1,348	33	16
Wood	2,230	1,489	1	13
Half Concrete/Brick/Stone and Half Wood	957	807	1	67
Galvanized Iron/Aluminum	76	63	-	5
Bamboo/Sawali/Cogon/Nipa	5,138	1,250	-	13
Asbestos	3	3	-	-
Glass	16	14	2	-
Makeshift/Salvaged/Improvised Materials	38	10	-	-
Others/Not Reported	64	16	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>CAWAYAN</b>				
Total	12,632	6,010	7	131
Concrete/Brick/Stone	2,299	2,246	5	14
Wood	1,549	1,201	1	11
Half Concrete/Brick/Stone and Half Wood	982	863	1	62
Galvanized Iron/Aluminum	41	29	-	3
Bamboo/Sawali/Cogon/Nipa	7,570	1,640	-	40
Asbestos	2	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	92	14	-	-
Others/Not Reported	97	16	-	1
No Walls	-	-	-	-
<b>CLAVERIA</b>				
Total	8,051	1,781	29	124
Concrete/Brick/Stone	997	786	26	16
Wood	558	202	-	3
Half Concrete/Brick/Stone and Half Wood	1,090	516	1	93
Galvanized Iron/Aluminum	30	13	-	3
Bamboo/Sawali/Cogon/Nipa	4,952	256	-	9
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	377	6	-	-
Others/Not Reported	47	2	2	-
No Walls	-	-	-	-
<b>DIMASALANG</b>				
Total	4,629	1,720	50	104
Concrete/Brick/Stone	830	718	46	15
Wood	1,264	558	-	7
Half Concrete/Brick/Stone and Half Wood	539	328	-	63
Galvanized Iron/Aluminum	27	17	4	3
Bamboo/Sawali/Cogon/Nipa	1,873	96	-	16
Asbestos	1	-	-	-
Glass	13	-	-	-
Makeshift/Salvaged/Improvised Materials	22	1	-	-
Others/Not Reported	59	2	-	-
No Walls	1	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>ESPERANZA</b>				
Total	3,587	1,606	24	76
Concrete/Brick/Stone	759	654	24	5
Wood	497	321	-	12
Half Concrete/Brick/Stone and Half Wood	494	338	-	13
Galvanized Iron/Aluminum	20	12	-	2
Bamboo/Sawali/Cogon/Nipa	1,758	274	-	43
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	58	7	-	1
No Walls	-	-	-	-
<b>MANDAON</b>				
Total	6,748	2,270	12	78
Concrete/Brick/Stone	1,079	1,013	12	10
Wood	264	196	-	1
Half Concrete/Brick/Stone and Half Wood	793	625	-	38
Galvanized Iron/Aluminum	26	18	-	4
Bamboo/Sawali/Cogon/Nipa	4,535	403	-	25
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	2	-	-
Others/Not Reported	44	13	-	-
No Walls	-	-	-	-
<b>CITY OF MASBATE (Capital)</b>				
Total	15,854	10,940	192	437
Concrete/Brick/Stone	3,365	3,132	151	42
Wood	6,845	5,189	10	113
Half Concrete/Brick/Stone and Half Wood	2,516	2,113	29	266
Galvanized Iron/Aluminum	42	30	-	3
Bamboo/Sawali/Cogon/Nipa	2,915	433	-	12
Asbestos	6	4	1	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	83	20	-	1
Others/Not Reported	82	19	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>MILAGROS</b>				
Total	9,022	2,476	33	696
Concrete/Brick/Stone	1,082	990	30	24
Wood	942	438	-	34
Half Concrete/Brick/Stone and Half Wood	1,527	742	3	485
Galvanized Iron/Aluminum	143	17	-	59
Bamboo/Sawali/Cogon/Nipa	5,199	270	-	86
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	45	5	-	-
Others/Not Reported	83	13	-	8
No Walls	-	-	-	-
<b>MOBO</b>				
Total	6,158	2,381	28	150
Concrete/Brick/Stone	1,127	988	26	18
Wood	1,963	773	-	21
Half Concrete/Brick/Stone and Half Wood	707	452	1	91
Galvanized Iron/Aluminum	7	2	1	1
Bamboo/Sawali/Cogon/Nipa	2,212	163	-	16
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	2	-	2
Others/Not Reported	125	1	-	1
No Walls	-	-	-	-
<b>MONREAL</b>				
Total	4,338	777	31	8
Concrete/Brick/Stone	735	494	30	3
Wood	2,403	215	-	3
Half Concrete/Brick/Stone and Half Wood	149	47	-	1
Galvanized Iron/Aluminum	3	2	-	-
Bamboo/Sawali/Cogon/Nipa	560	5	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	447	10	-	-
Others/Not Reported	41	4	1	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>PALANAS</b>				
Total	5,300	1,545	47	392
Concrete/Brick/Stone	675	541	42	6
Wood	1,641	562	-	35
Half Concrete/Brick/Stone and Half Wood	670	244	2	277
Galvanized Iron/Aluminum	47	24	3	13
Bamboo/Sawali/Cogon/Nipa	2,239	170	-	60
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	27	4	-	1
No Walls	-	-	-	-
<b>PIO V. CORPUZ (LIMBUHAN)</b>				
Total	4,901	2,638	5	60
Concrete/Brick/Stone	1,104	996	5	3
Wood	1,257	777	-	15
Half Concrete/Brick/Stone and Half Wood	599	462	-	29
Galvanized Iron/Aluminum	28	22	-	2
Bamboo/Sawali/Cogon/Nipa	1,888	373	-	11
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	1	-	-
Others/Not Reported	16	7	-	-
No Walls	-	-	-	-
<b>PLACER</b>				
Total	10,327	4,166	41	289
Concrete/Brick/Stone	1,364	1,283	22	6
Wood	1,328	978	1	10
Half Concrete/Brick/Stone and Half Wood	876	599	17	110
Galvanized Iron/Aluminum	169	36	1	117
Bamboo/Sawali/Cogon/Nipa	6,430	1,237	-	44
Asbestos	5	5	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	73	14	-	-
Others/Not Reported	81	13	-	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>SAN FERNANDO</b>				
Total	4,215	1,049	15	24
Concrete/Brick/Stone	857	679	14	5
Wood	2,479	252	-	2
Half Concrete/Brick/Stone and Half Wood	253	104	-	16
Galvanized Iron/Aluminum	6	4	-	-
Bamboo/Sawali/Cogon/Nipa	547	5	-	1
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	41	-	-	-
Others/Not Reported	31	5	1	-
No Walls	-	-	-	-
<b>SAN JACINTO</b>				
Total	6,185	1,295	32	48
Concrete/Brick/Stone	1,115	851	30	10
Wood	3,493	182	-	8
Half Concrete/Brick/Stone and Half Wood	569	251	1	20
Galvanized Iron/Aluminum	16	-	-	8
Bamboo/Sawali/Cogon/Nipa	930	3	-	2
Asbestos	-	-	-	-
Glass	2	1	-	-
Makeshift/Salvaged/Improvised Materials	15	-	-	-
Others/Not Reported	45	7	1	-
No Walls	-	-	-	-
<b>SAN PASCUAL</b>				
Total	8,328	2,287	17	138
Concrete/Brick/Stone	1,457	1,238	15	31
Wood	583	337	-	4
Half Concrete/Brick/Stone and Half Wood	535	289	2	79
Galvanized Iron/Aluminum	23	12	-	1
Bamboo/Sawali/Cogon/Nipa	4,635	342	-	22
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	981	48	-	-
Others/Not Reported	113	20	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

USON

Total	10,131	3,461	26	213
Concrete/Brick/Stone	1,671	1,522	13	13
Wood	2,632	999	2	27
Half Concrete/Brick/Stone and Half Wood	872	555	1	128
Galvanized Iron/Aluminum	57	15	2	21
Bamboo/Sawali/Cogon/Nipa	4,814	354	-	23
Asbestos	-	-	-	-
Glass	18	9	8	1
Makeshift/Salvaged/Improvised Materials	10	6	-	-
Others/Not Reported	57	1	-	-
No Walls	-	-	-	-



Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
<b>MASBATE</b>					
Total	896	86,593	2,083	441	812
Concrete/Brick/Stone	17	1,802	19	49	57
Wood	409	19,625	378	55	114
Half Concrete/Brick/Stone and Half Wood	81	3,495	31	12	34
Galvanized Iron/Aluminum	71	137	5	1	9
Bamboo/Sawali/Cogon/Nipa	312	60,262	255	103	153
Asbestos	1	-	-	6	2
Glass	-	-	-	-	14
Makeshift/Salvaged/Improvised Materials	1	848	1,384	5	9
Others/Not Reported	4	423	11	210	420
No Walls	-	1	-	-	-
<b>AROROY</b>					
Total	62	6,756	83	35	68
Concrete/Brick/Stone	1	74	-	1	8
Wood	9	1,325	5	11	5
Half Concrete/Brick/Stone and Half Wood	4	303	4	5	9
Galvanized Iron/Aluminum	-	14	4	-	1
Bamboo/Sawali/Cogon/Nipa	48	4,953	10	11	18
Asbestos	-	-	-	1	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	36	59	-	4
Others/Not Reported	-	51	1	6	22
No Walls	-	-	-	-	-
<b>BALENO</b>					
Total	10	2,740	23	2	27
Concrete/Brick/Stone	-	57	3	1	3
Wood	4	687	7	-	2
Half Concrete/Brick/Stone and Half Wood	1	194	3	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	1,770	1	1	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	9	-	-
Others/Not Reported	-	24	-	-	19
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>BALUD</b>					
Total	65	3,684	11	4	21
Concrete/Brick/Stone	3	24	-	1	-
Wood	14	350	-	-	2
Half Concrete/Brick/Stone and Half Wood	4	116	-	-	-
Galvanized Iron/Aluminum	2	8	1	-	-
Bamboo/Sawali/Cogon/Nipa	40	3,148	8	-	6
Asbestos	-	-	-	3	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	2	-	-
Others/Not Reported	2	25	-	-	13
No Walls	-	-	-	-	-
<b>BATUAN</b>					
Total	8	1,975	-	-	18
Concrete/Brick/Stone	-	72	-	-	4
Wood	5	1,221	-	-	9
Half Concrete/Brick/Stone and Half Wood	1	112	-	-	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	563	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	4	-	-	4
No Walls	-	-	-	-	-
<b>CATAINGAN</b>					
Total	64	4,645	18	8	51
Concrete/Brick/Stone	1	18	-	-	-
Wood	46	677	1	-	3
Half Concrete/Brick/Stone and Half Wood	3	79	-	-	-
Galvanized Iron/Aluminum	4	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	3,849	1	5	10
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	12	16	-	-
Others/Not Reported	-	6	-	3	38
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CAWAYAN</b>					
Total	7	6,348	50	31	48
Concrete/Brick/Stone	-	31	1	-	2
Wood	2	331	-	-	3
Half Concrete/Brick/Stone and Half Wood	-	56	-	-	-
Galvanized Iron/Aluminum	-	9	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	5,857	11	2	15
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	41	37	-	-
Others/Not Reported	-	23	1	28	28
No Walls	-	-	-	-	-
<b>CLAVERIA</b>					
Total	25	5,777	272	10	33
Concrete/Brick/Stone	-	168	1	-	-
Wood	3	348	1	-	1
Half Concrete/Brick/Stone and Half Wood	1	474	5	-	-
Galvanized Iron/Aluminum	6	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	4,634	29	-	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	135	234	-	2
Others/Not Reported	-	10	2	10	21
No Walls	-	-	-	-	-
<b>DIMASALANG</b>					
Total	102	2,531	37	43	42
Concrete/Brick/Stone	-	41	-	9	1
Wood	73	603	14	4	5
Half Concrete/Brick/Stone and Half Wood	3	143	1	-	1
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	25	1,706	8	14	8
Asbestos	1	-	-	-	-
Glass	-	-	-	-	13
Makeshift/Salvaged/Improvised Materials	-	7	14	-	-
Others/Not Reported	-	27	-	16	14
No Walls	-	1	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>ESPERANZA</b>					
Total	3	1,832	1	26	19
Concrete/Brick/Stone	-	74	-	1	1
Wood	-	160	-	1	3
Half Concrete/Brick/Stone and Half Wood	-	141	-	1	1
Galvanized Iron/Aluminum	-	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	1,434	-	3	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	17	-	20	13
No Walls	-	-	-	-	-
<b>MANDAON</b>					
Total	31	4,318	8	1	30
Concrete/Brick/Stone	3	37	-	1	3
Wood	1	65	-	-	1
Half Concrete/Brick/Stone and Half Wood	7	117	5	-	1
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	19	4,080	3	-	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	-	-	-
Others/Not Reported	-	11	-	-	20
No Walls	-	-	-	-	-
<b>CITY OF MASBATE (Capital)</b>					
Total	121	4,019	58	40	47
Concrete/Brick/Stone	2	27	-	8	3
Wood	76	1,434	15	1	7
Half Concrete/Brick/Stone and Half Wood	20	84	-	1	3
Galvanized Iron/Aluminum	3	5	-	1	-
Bamboo/Sawali/Cogon/Nipa	19	2,439	3	6	3
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	21	40	-	-
Others/Not Reported	-	9	-	22	31
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>MILAGROS</b>					
Total	144	5,568	38	44	23
Concrete/Brick/Stone	2	34	1	-	1
Wood	55	405	2	5	3
Half Concrete/Brick/Stone and Half Wood	14	278	2	3	-
Galvanized Iron/Aluminum	42	24	-	-	1
Bamboo/Sawali/Cogon/Nipa	30	4,781	7	20	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	14	25	1	-
Others/Not Reported	1	32	1	15	13
No Walls	-	-	-	-	-
<b>MOBO</b>					
Total	21	3,430	7	101	40
Concrete/Brick/Stone	-	93	-	-	2
Wood	9	1,136	3	17	4
Half Concrete/Brick/Stone and Half Wood	1	162	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	1,989	-	32	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	3	1	-
Others/Not Reported	-	38	1	51	33
No Walls	-	-	-	-	-
<b>MONREAL</b>					
Total	6	2,685	797	13	21
Concrete/Brick/Stone	1	197	5	1	4
Wood	4	1,859	309	6	7
Half Concrete/Brick/Stone and Half Wood	-	94	7	-	-
Galvanized Iron/Aluminum	-	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	1	432	120	2	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	84	352	-	1
Others/Not Reported	-	19	4	4	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>PALANAS</b>					
Total	30	3,253	1	1	31
Concrete/Brick/Stone	-	85	-	-	1
Wood	23	1,014	-	1	6
Half Concrete/Brick/Stone and Half Wood	3	140	-	-	4
Galvanized Iron/Aluminum	1	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	2,001	1	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	6	-	-	16
No Walls	-	-	-	-	-
<b>PIO V. CORPUZ (LIMBUHAN)</b>					
Total	8	2,170	5	2	13
Concrete/Brick/Stone	-	99	-	1	-
Wood	4	458	-	-	3
Half Concrete/Brick/Stone and Half Wood	1	105	-	1	1
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	1,498	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	5	-	-
Others/Not Reported	-	3	-	-	6
No Walls	-	-	-	-	-
<b>PLACER</b>					
Total	38	5,678	44	13	58
Concrete/Brick/Stone	2	46	1	-	4
Wood	9	327	1	-	2
Half Concrete/Brick/Stone and Half Wood	5	145	-	-	-
Galvanized Iron/Aluminum	2	13	-	-	-
Bamboo/Sawali/Cogon/Nipa	20	5,091	16	3	19
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	33	26	-	-
Others/Not Reported	-	23	-	10	33
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
<b>SAN FERNANDO</b>					
Total	10	3,068	11	16	22
Concrete/Brick/Stone	-	148	-	8	3
Wood	9	2,199	6	3	8
Half Concrete/Brick/Stone and Half Wood	-	131	-	-	2
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	532	3	1	4
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	39	2	-	-
Others/Not Reported	-	17	-	4	4
No Walls	-	-	-	-	-
<b>SAN JACINTO</b>					
Total	22	4,674	25	18	71
Concrete/Brick/Stone	1	203	-	14	6
Wood	11	3,255	5	4	28
Half Concrete/Brick/Stone and Half Wood	2	288	1	-	6
Galvanized Iron/Aluminum	1	5	-	-	2
Bamboo/Sawali/Cogon/Nipa	7	892	13	-	13
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	9	6	-	-
Others/Not Reported	-	22	-	-	15
No Walls	-	-	-	-	-
<b>SAN PASCUAL</b>					
Total	10	5,200	593	29	54
Concrete/Brick/Stone	1	158	7	2	5
Wood	6	225	9	-	2
Half Concrete/Brick/Stone and Half Wood	-	159	3	-	3
Galvanized Iron/Aluminum	-	8	-	-	2
Bamboo/Sawali/Cogon/Nipa	3	4,233	20	3	12
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	375	553	3	2
Others/Not Reported	-	42	1	21	28
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

USON

Total	109	6,242	1	4	75
Concrete/Brick/Stone	-	116	-	1	6
Wood	46	1,546	-	2	10
Half Concrete/Brick/Stone and Half Wood	11	174	-	1	2
Galvanized Iron/Aluminum	9	8	-	-	2
Bamboo/Sawali/Cogon/Nipa	42	4,380	1	-	14
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	1	14	-	-	41
No Walls	-	-	-	-	-