

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MISAMIS ORIENTAL				
Total	151,163	115,088	278	5,560
Concrete/Brick/Stone	31,097	30,302	126	346
Wood	65,491	50,861	70	2,251
Half Concrete/Brick/Stone and Half Wood	24,560	21,232	67	2,402
Galvanized Iron/Aluminum	652	490	6	70
Bamboo/Sawali/Cogon/Nipa	28,359	11,736	-	483
Asbestos	49	48	-	-
Glass	4	3	1	-
Makeshift/Salvaged/Improvised Materials	231	91	-	2
Others/Not Reported	711	321	8	6
No Walls	9	4	-	-
ALUBIJID				
Total	5,607	3,285	4	100
Concrete/Brick/Stone	752	742	2	3
Wood	1,485	1,188	-	17
Half Concrete/Brick/Stone and Half Wood	684	483	1	70
Galvanized Iron/Aluminum	20	8	-	1
Bamboo/Sawali/Cogon/Nipa	2,649	855	-	9
Asbestos	4	4	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	4	-	-
Others/Not Reported	8	1	1	-
No Walls	-	-	-	-
BALINGASAG				
Total	11,027	7,761	26	597
Concrete/Brick/Stone	1,765	1,670	7	51
Wood	4,552	3,136	7	231
Half Concrete/Brick/Stone and Half Wood	2,667	2,272	10	273
Galvanized Iron/Aluminum	47	25	2	11
Bamboo/Sawali/Cogon/Nipa	1,928	651	-	31
Asbestos	2	2	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	62	3	-	-
No Walls	2	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BALINGOAN				
Total	1,660	1,106	2	299
Concrete/Brick/Stone	227	222	1	2
Wood	962	607	1	212
Half Concrete/Brick/Stone and Half Wood	298	214	-	81
Galvanized Iron/Aluminum	3	2	-	1
Bamboo/Sawali/Cogon/Nipa	161	57	-	3
Asbestos	3	3	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	4	-	-	-
No Walls	-	-	-	-
BINUANGAN				
Total	1,297	1,240	-	-
Concrete/Brick/Stone	198	198	-	-
Wood	777	746	-	-
Half Concrete/Brick/Stone and Half Wood	262	262	-	-
Galvanized Iron/Aluminum	2	2	-	-
Bamboo/Sawali/Cogon/Nipa	56	31	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	1	-	-
No Walls	-	-	-	-
CLAVERIA				
Total	8,596	7,876	9	37
Concrete/Brick/Stone	878	869	2	6
Wood	5,084	4,779	3	12
Half Concrete/Brick/Stone and Half Wood	911	886	4	13
Galvanized Iron/Aluminum	31	18	-	1
Bamboo/Sawali/Cogon/Nipa	1,653	1,307	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	5	-	-
Others/Not Reported	34	12	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
CITY OF EL SALVADOR				
Total	9,176	7,013	13	63
Concrete/Brick/Stone	2,505	2,464	3	4
Wood	3,631	2,709	5	9
Half Concrete/Brick/Stone and Half Wood	845	765	3	43
Galvanized Iron/Aluminum	20	15	-	4
Bamboo/Sawali/Cogon/Nipa	2,056	1,001	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	3	-	-
Others/Not Reported	102	56	2	-
No Walls	-	-	-	-
GINGOOG CITY				
Total	21,635	15,766	79	1,675
Concrete/Brick/Stone	2,831	2,711	25	69
Wood	11,947	8,893	26	864
Half Concrete/Brick/Stone and Half Wood	3,699	2,912	22	647
Galvanized Iron/Aluminum	222	170	4	23
Bamboo/Sawali/Cogon/Nipa	2,815	1,032	-	69
Asbestos	6	6	-	-
Glass	1	-	1	-
Makeshift/Salvaged/Improvised Materials	29	13	-	-
Others/Not Reported	81	27	1	3
No Walls	4	2	-	-
GITAGUM				
Total	3,071	2,312	1	16
Concrete/Brick/Stone	663	659	1	-
Wood	908	756	-	7
Half Concrete/Brick/Stone and Half Wood	432	416	-	3
Galvanized Iron/Aluminum	7	7	-	-
Bamboo/Sawali/Cogon/Nipa	1,058	473	-	6
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	2	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
INITAO				
Total	6,232	4,276	7	37
Concrete/Brick/Stone	1,092	1,064	4	5
Wood	1,486	1,211	2	5
Half Concrete/Brick/Stone and Half Wood	1,021	966	1	10
Galvanized Iron/Aluminum	7	7	-	-
Bamboo/Sawali/Cogon/Nipa	2,560	990	-	17
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	61	35	-	-
No Walls	1	1	-	-
JASAAN				
Total	9,051	7,649	15	21
Concrete/Brick/Stone	1,939	1,916	12	2
Wood	3,180	2,717	-	8
Half Concrete/Brick/Stone and Half Wood	2,330	2,277	3	9
Galvanized Iron/Aluminum	50	43	-	-
Bamboo/Sawali/Cogon/Nipa	1,519	681	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	18	8	-	-
Others/Not Reported	15	7	-	-
No Walls	-	-	-	-
KINOQUITAN				
Total	2,214	1,846	3	8
Concrete/Brick/Stone	465	463	1	-
Wood	1,256	969	1	4
Half Concrete/Brick/Stone and Half Wood	331	324	1	1
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	147	82	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	3	-	-
Others/Not Reported	5	2	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
LAGONGLONG				
Total	3,486	2,301	2	89
Concrete/Brick/Stone	934	899	1	8
Wood	1,017	730	1	20
Half Concrete/Brick/Stone and Half Wood	506	434	-	40
Galvanized Iron/Aluminum	18	14	-	2
Bamboo/Sawali/Cogon/Nipa	1,000	223	-	19
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	10	-	-	-
No Walls	-	-	-	-
LAGUINDINGAN				
Total	4,271	3,255	4	190
Concrete/Brick/Stone	943	928	1	2
Wood	1,639	1,398	1	12
Half Concrete/Brick/Stone and Half Wood	729	546	1	162
Galvanized Iron/Aluminum	10	10	-	-
Bamboo/Sawali/Cogon/Nipa	939	371	-	14
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	11	2	1	-
No Walls	-	-	-	-
LIBERTAD				
Total	2,222	1,285	2	298
Concrete/Brick/Stone	380	341	1	24
Wood	472	402	-	1
Half Concrete/Brick/Stone and Half Wood	393	264	1	119
Galvanized Iron/Aluminum	10	2	-	7
Bamboo/Sawali/Cogon/Nipa	934	251	-	147
Asbestos	4	4	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	28	20	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
LUGAIT				
Total	3,587	3,278	2	34
Concrete/Brick/Stone	667	664	2	-
Wood	1,293	1,174	-	22
Half Concrete/Brick/Stone and Half Wood	881	864	-	10
Galvanized Iron/Aluminum	12	11	-	1
Bamboo/Sawali/Cogon/Nipa	722	559	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	9	5	-	-
No Walls	-	-	-	-
MAGSAYSAY (LINUGOS)				
Total	5,504	2,609	6	226
Concrete/Brick/Stone	860	755	1	57
Wood	3,085	1,269	3	99
Half Concrete/Brick/Stone and Half Wood	566	425	1	57
Galvanized Iron/Aluminum	16	5	-	8
Bamboo/Sawali/Cogon/Nipa	939	149	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	16	-	-	-
Others/Not Reported	22	6	1	-
No Walls	-	-	-	-
MANTICAO				
Total	5,082	4,326	2	8
Concrete/Brick/Stone	1,066	1,057	1	-
Wood	1,736	1,582	-	3
Half Concrete/Brick/Stone and Half Wood	739	721	1	-
Galvanized Iron/Aluminum	14	11	-	-
Bamboo/Sawali/Cogon/Nipa	1,473	915	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	53	39	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MEDINA				
Total	5,716	3,756	54	883
Concrete/Brick/Stone	1,163	1,077	39	42
Wood	2,586	1,678	5	303
Half Concrete/Brick/Stone and Half Wood	1,318	813	9	467
Galvanized Iron/Aluminum	9	8	-	-
Bamboo/Sawali/Cogon/Nipa	619	168	-	70
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	1
Others/Not Reported	18	12	1	-
No Walls	-	-	-	-
NAAWAN				
Total	3,719	2,699	4	27
Concrete/Brick/Stone	747	726	4	-
Wood	937	800	-	4
Half Concrete/Brick/Stone and Half Wood	475	437	-	19
Galvanized Iron/Aluminum	7	6	-	-
Bamboo/Sawali/Cogon/Nipa	1,515	700	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	4	-	-
Others/Not Reported	32	26	-	-
No Walls	1	-	-	-
OPOL				
Total	10,014	8,120	20	91
Concrete/Brick/Stone	3,901	3,864	12	9
Wood	3,157	2,653	3	16
Half Concrete/Brick/Stone and Half Wood	1,202	1,120	5	45
Galvanized Iron/Aluminum	56	42	-	8
Bamboo/Sawali/Cogon/Nipa	1,629	423	-	11
Asbestos	1	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	20	4	-	-
Others/Not Reported	47	13	-	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
SALAY				
Total	4,669	3,661	4	103
Concrete/Brick/Stone	913	903	1	2
Wood	2,502	1,902	3	71
Half Concrete/Brick/Stone and Half Wood	719	656	-	26
Galvanized Iron/Aluminum	43	40	-	1
Bamboo/Sawali/Cogon/Nipa	483	155	-	3
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	4	2	-	-
No Walls	-	-	-	-
SUGBONGCOGON				
Total	1,571	1,437	-	-
Concrete/Brick/Stone	229	228	-	-
Wood	931	897	-	-
Half Concrete/Brick/Stone and Half Wood	256	256	-	-
Galvanized Iron/Aluminum	1	1	-	-
Bamboo/Sawali/Cogon/Nipa	146	53	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	2	-	-
Others/Not Reported	3	-	-	-
No Walls	-	-	-	-
TAGOLOAN				
Total	11,772	10,598	6	33
Concrete/Brick/Stone	3,293	3,272	2	-
Wood	6,390	5,587	3	27
Half Concrete/Brick/Stone and Half Wood	1,436	1,411	1	-
Galvanized Iron/Aluminum	31	30	-	-
Bamboo/Sawali/Cogon/Nipa	530	262	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	58	16	-	1
Others/Not Reported	34	20	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

TALISAYAN

Total	4,292	2,699	9	716
Concrete/Brick/Stone	680	616	1	60
Wood	2,322	1,471	4	300
Half Concrete/Brick/Stone and Half Wood	815	499	3	303
Galvanized Iron/Aluminum	5	3	-	2
Bamboo/Sawali/Cogon/Nipa	459	106	-	51
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	3	-	-
Others/Not Reported	5	-	1	-
No Walls	-	-	-	-

VILLANUEVA

Total	5,692	4,934	4	9
Concrete/Brick/Stone	2,006	1,994	2	-
Wood	2,156	1,607	2	4
Half Concrete/Brick/Stone and Half Wood	1,045	1,009	-	4
Galvanized Iron/Aluminum	8	7	-	-
Bamboo/Sawali/Cogon/Nipa	369	241	-	1
Asbestos	26	26	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	22	18	-	-
Others/Not Reported	59	31	-	-
No Walls	1	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MISAMIS ORIENTAL					
Total	1,850	27,205	195	568	419
Concrete/Brick/Stone	30	231	5	23	34
Wood	1,183	10,770	89	199	68
Half Concrete/Brick/Stone and Half Wood	204	575	4	42	34
Galvanized Iron/Aluminum	32	52	-	1	1
Bamboo/Sawali/Cogon/Nipa	396	15,367	35	285	57
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	71	60	3	2
Others/Not Reported	2	134	2	15	223
No Walls	-	5	-	-	-
ALUBIJID					
Total	388	1,816	1	8	5
Concrete/Brick/Stone	-	5	-	-	-
Wood	132	147	-	-	1
Half Concrete/Brick/Stone and Half Wood	116	14	-	-	-
Galvanized Iron/Aluminum	6	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	134	1,642	-	8	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	3	-	-	3
No Walls	-	-	-	-	-
BALINGASAG					
Total	64	2,464	6	1	108
Concrete/Brick/Stone	3	20	1	-	13
Wood	30	1,129	4	1	14
Half Concrete/Brick/Stone and Half Wood	15	86	-	-	11
Galvanized Iron/Aluminum	3	5	-	-	1
Bamboo/Sawali/Cogon/Nipa	13	1,219	1	-	13
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	3	-	-	56
No Walls	-	2	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
BALINGOAN					
Total	6	244	-	-	3
Concrete/Brick/Stone	-	2	-	-	-
Wood	5	137	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	3	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	100	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	1	-	-	3
No Walls	-	-	-	-	-
BINUANGAN					
Total	1	55	-	-	1
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	31	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	24	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-
CLAVERIA					
Total	128	494	10	17	25
Concrete/Brick/Stone	-	1	-	-	-
Wood	100	176	3	10	1
Half Concrete/Brick/Stone and Half Wood	1	6	-	-	1
Galvanized Iron/Aluminum	4	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	23	303	7	7	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	22
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
CITY OF EL SALVADOR					
Total	15	1,955	7	102	8
Concrete/Brick/Stone	1	27	3	2	1
Wood	4	899	-	5	-
Half Concrete/Brick/Stone and Half Wood	1	31	-	1	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	948	2	91	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	12	1	-	1
Others/Not Reported	-	37	1	3	3
No Walls	-	-	-	-	-
GINGOOG CITY					
Total	707	3,326	10	32	40
Concrete/Brick/Stone	12	12	-	2	-
Wood	528	1,623	2	9	2
Half Concrete/Brick/Stone and Half Wood	53	64	1	-	-
Galvanized Iron/Aluminum	14	11	-	-	-
Bamboo/Sawali/Cogon/Nipa	97	1,594	3	20	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	9	4	-	1
Others/Not Reported	1	11	-	1	37
No Walls	-	2	-	-	-
GITAGUM					
Total	3	737	-	-	2
Concrete/Brick/Stone	-	3	-	-	-
Wood	1	143	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	13	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	577	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
INITAO					
Total	22	1,787	-	69	34
Concrete/Brick/Stone	2	13	-	2	2
Wood	7	248	-	3	10
Half Concrete/Brick/Stone and Half Wood	2	34	-	-	8
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	1,470	-	64	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	20	-	-	6
No Walls	-	-	-	-	-
JASAAN					
Total	20	1,306	22	3	15
Concrete/Brick/Stone	1	4	-	2	2
Wood	5	441	6	1	2
Half Concrete/Brick/Stone and Half Wood	1	39	-	-	1
Galvanized Iron/Aluminum	1	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	810	11	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	5	-	-
Others/Not Reported	-	1	-	-	7
No Walls	-	-	-	-	-
KINOGUITAN					
Total	4	349	2	-	2
Concrete/Brick/Stone	1	-	-	-	-
Wood	3	279	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	5	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	63	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	2	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LAGONGLONG					
Total	11	1,072	-	-	11
Concrete/Brick/Stone	-	25	-	-	1
Wood	5	261	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	32	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	751	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	9
No Walls	-	-	-	-	-
LAGUINDINGAN					
Total	24	788	-	1	9
Concrete/Brick/Stone	1	10	-	1	-
Wood	2	224	-	-	2
Half Concrete/Brick/Stone and Half Wood	3	17	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	18	536	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	7
No Walls	-	-	-	-	-
LIBERTAD					
Total	4	631	-	1	1
Concrete/Brick/Stone	-	13	-	1	-
Wood	1	68	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	9	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	533	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	7	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LUGAIT					
Total	1	266	-	3	3
Concrete/Brick/Stone	-	1	-	-	-
Wood	1	95	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	7	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	161	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	1	-
Others/Not Reported	-	1	-	-	3
No Walls	-	-	-	-	-
MAGSAYSAY (LINUGOS)					
Total	53	2,481	13	106	10
Concrete/Brick/Stone	1	40	-	5	1
Wood	46	1,607	2	58	1
Half Concrete/Brick/Stone and Half Wood	1	50	1	31	-
Galvanized Iron/Aluminum	-	2	-	1	-
Bamboo/Sawali/Cogon/Nipa	5	771	-	8	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	10	-	-
Others/Not Reported	-	5	-	3	7
No Walls	-	-	-	-	-
MANTICAO					
Total	7	674	2	45	18
Concrete/Brick/Stone	-	7	-	-	1
Wood	1	141	-	5	4
Half Concrete/Brick/Stone and Half Wood	-	14	1	-	2
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	504	1	39	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	6	-	1	7
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MEDINA					
Total	235	777	2	-	9
Concrete/Brick/Stone	-	3	-	-	2
Wood	228	371	-	-	1
Half Concrete/Brick/Stone and Half Wood	2	26	-	-	1
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	374	1	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	2	-	-	3
No Walls	-	-	-	-	-
NAAWAN					
Total	18	935	1	25	10
Concrete/Brick/Stone	1	15	-	1	-
Wood	12	116	-	4	1
Half Concrete/Brick/Stone and Half Wood	-	19	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	780	1	16	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	2	-	4	-
No Walls	-	1	-	-	-
OPOL					
Total	79	1,661	15	2	26
Concrete/Brick/Stone	5	10	-	-	1
Wood	35	449	-	1	-
Half Concrete/Brick/Stone and Half Wood	7	24	-	-	1
Galvanized Iron/Aluminum	1	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	30	1,162	2	1	-
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	13	-	-
Others/Not Reported	-	8	-	-	24
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SALAY					
Total	13	863	1	16	8
Concrete/Brick/Stone	-	5	-	1	1
Wood	9	506	1	8	2
Half Concrete/Brick/Stone and Half Wood	-	32	-	3	2
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	316	-	4	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
SUGBONGCOGON					
Total	-	127	3	-	4
Concrete/Brick/Stone	-	-	-	-	1
Wood	-	31	2	-	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	92	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	1	-	-	2
No Walls	-	-	-	-	-
TAGOLOAN					
Total	13	905	72	94	51
Concrete/Brick/Stone	2	6	1	2	8
Wood	8	623	48	73	21
Half Concrete/Brick/Stone and Half Wood	-	15	-	4	5
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	235	3	13	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	20	19	2	-
Others/Not Reported	-	5	1	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TALISAYAN					
Total	29	825	4	-	10
Concrete/Brick/Stone	-	3	-	-	-
Wood	18	522	3	-	4
Half Concrete/Brick/Stone and Half Wood	2	8	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	291	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	-	-	-	4
No Walls	-	-	-	-	-
VILLANUEVA					
Total	5	667	24	43	6
Concrete/Brick/Stone	-	6	-	4	-
Wood	2	503	18	20	-
Half Concrete/Brick/Stone and Half Wood	-	27	1	3	1
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	111	2	13	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	3	-	-
Others/Not Reported	1	19	-	3	5
No Walls	-	-	-	-	-