

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>NEGROS OCCIDENTAL</b>				
Total	469,518	318,533	1,305	22,780
Concrete/Brick/Stone	85,214	81,884	875	1,139
Wood	77,799	61,301	85	2,382
Half Concrete/Brick/Stone and Half Wood	98,117	80,300	193	12,962
Galvanized Iron/Aluminum	4,672	3,039	61	792
Bamboo/Sawali/Cogon/Nipa	197,962	89,157	-	5,396
Asbestos	147	127	-	14
Glass	88	68	1	2
Makeshift/Salvaged/Improvised Materials	2,783	1,511	-	59
Others/Not Reported	2,722	1,136	90	34
No Walls	14	10	-	-
<b>BAGO CITY</b>				
Total	32,114	24,641	41	953
Concrete/Brick/Stone	6,598	6,482	31	50
Wood	3,495	3,046	2	109
Half Concrete/Brick/Stone and Half Wood	7,110	6,426	4	520
Galvanized Iron/Aluminum	220	197	-	8
Bamboo/Sawali/Cogon/Nipa	14,322	8,338	-	263
Asbestos	12	10	-	2
Glass	9	-	-	-
Makeshift/Salvaged/Improvised Materials	172	65	-	1
Others/Not Reported	176	77	4	-
No Walls	-	-	-	-
<b>BINALBAGAN</b>				
Total	12,731	8,903	28	577
Concrete/Brick/Stone	2,204	2,158	14	17
Wood	1,025	808	2	64
Half Concrete/Brick/Stone and Half Wood	3,803	3,327	10	376
Galvanized Iron/Aluminum	90	62	1	18
Bamboo/Sawali/Cogon/Nipa	5,533	2,521	-	98
Asbestos	1	1	-	-
Glass	3	3	-	-
Makeshift/Salvaged/Improvised Materials	11	4	-	2
Others/Not Reported	61	19	1	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>CADIZ CITY</b>				
Total	29,397	19,566	59	557
Concrete/Brick/Stone	5,709	5,554	31	16
Wood	7,992	5,900	6	104
Half Concrete/Brick/Stone and Half Wood	5,119	4,414	7	290
Galvanized Iron/Aluminum	268	176	13	18
Bamboo/Sawali/Cogon/Nipa	9,601	3,354	-	119
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	424	108	-	7
Others/Not Reported	284	60	2	3
No Walls	-	-	-	-
<b>CALATRAVA</b>				
Total	16,098	11,484	12	528
Concrete/Brick/Stone	1,244	1,220	5	8
Wood	5,544	4,682	5	290
Half Concrete/Brick/Stone and Half Wood	1,892	1,731	-	134
Galvanized Iron/Aluminum	107	54	1	6
Bamboo/Sawali/Cogon/Nipa	7,187	3,719	-	82
Asbestos	9	1	-	8
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	15	10	-	-
Others/Not Reported	98	66	1	-
No Walls	2	1	-	-
<b>CANDONI</b>				
Total	4,209	2,823	3	57
Concrete/Brick/Stone	349	345	2	1
Wood	478	432	1	21
Half Concrete/Brick/Stone and Half Wood	655	630	-	16
Galvanized Iron/Aluminum	15	12	-	3
Bamboo/Sawali/Cogon/Nipa	2,692	1,388	-	15
Asbestos	3	3	-	-
Glass	3	2	-	1
Makeshift/Salvaged/Improvised Materials	2	2	-	-
Others/Not Reported	11	8	-	-
No Walls	1	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>CAUAYAN</b>				
Total	18,475	5,637	52	949
Concrete/Brick/Stone	1,703	1,431	14	32
Wood	2,236	1,051	3	64
Half Concrete/Brick/Stone and Half Wood	2,482	1,332	6	383
Galvanized Iron/Aluminum	209	72	6	67
Bamboo/Sawali/Cogon/Nipa	11,743	1,747	-	398
Asbestos	3	1	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	-	-	-
Others/Not Reported	92	3	23	4
No Walls	-	-	-	-
<b>ENRIQUE B. MAGALONA (SARAVIA)</b>				
Total	11,607	8,022	29	1,219
Concrete/Brick/Stone	3,627	3,467	18	99
Wood	1,684	1,381	5	85
Half Concrete/Brick/Stone and Half Wood	2,459	1,731	3	646
Galvanized Iron/Aluminum	177	123	2	27
Bamboo/Sawali/Cogon/Nipa	3,493	1,226	-	356
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	77	44	-	3
Others/Not Reported	89	49	1	3
No Walls	-	-	-	-
<b>CITY OF ESCALANTE</b>				
Total	18,525	14,305	41	393
Concrete/Brick/Stone	3,425	3,350	19	37
Wood	4,757	4,312	8	82
Half Concrete/Brick/Stone and Half Wood	3,304	3,021	10	195
Galvanized Iron/Aluminum	133	94	2	7
Bamboo/Sawali/Cogon/Nipa	6,292	3,067	-	67
Asbestos	8	8	-	-
Glass	3	3	-	-
Makeshift/Salvaged/Improvised Materials	485	423	-	5
Others/Not Reported	115	24	2	-
No Walls	3	3	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>CITY OF HIMAMAYLAN</b>				
Total	20,239	11,896	12	1,372
Concrete/Brick/Stone	2,774	2,705	4	42
Wood	2,876	2,054	2	206
Half Concrete/Brick/Stone and Half Wood	4,054	3,104	4	732
Galvanized Iron/Aluminum	116	84	1	15
Bamboo/Sawali/Cogon/Nipa	10,352	3,934	-	373
Asbestos	3	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	29	4	-	4
Others/Not Reported	34	8	1	-
No Walls	1	-	-	-
<b>HINIGARAN</b>				
Total	16,089	6,618	40	3,277
Concrete/Brick/Stone	2,130	1,937	30	96
Wood	1,927	1,111	2	195
Half Concrete/Brick/Stone and Half Wood	4,873	2,130	5	2,416
Galvanized Iron/Aluminum	164	64	3	85
Bamboo/Sawali/Cogon/Nipa	6,918	1,357	-	480
Asbestos	2	-	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	28	13	-	-
Others/Not Reported	45	4	-	5
No Walls	-	-	-	-
<b>HINOBA-AN (ASIA)</b>				
Total	10,229	4,669	4	109
Concrete/Brick/Stone	1,488	1,361	-	4
Wood	1,732	940	1	23
Half Concrete/Brick/Stone and Half Wood	1,783	1,373	3	57
Galvanized Iron/Aluminum	28	16	-	5
Bamboo/Sawali/Cogon/Nipa	5,165	969	-	19
Asbestos	3	3	-	-
Glass	2	1	-	-
Makeshift/Salvaged/Improvised Materials	9	3	-	1
Others/Not Reported	19	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

ILOG

Total	10,789	5,034	10	193
Concrete/Brick/Stone	1,147	1,077	7	9
Wood	1,427	960	-	9
Half Concrete/Brick/Stone and Half Wood	1,670	1,388	1	100
Galvanized Iron/Aluminum	58	42	2	4
Bamboo/Sawali/Cogon/Nipa	6,389	1,544	-	71
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	19	3	-	-
Others/Not Reported	77	18	-	-
No Walls	-	-	-	-

ISABELA

Total	11,425	7,404	37	846
Concrete/Brick/Stone	1,377	1,333	25	11
Wood	1,500	970	3	29
Half Concrete/Brick/Stone and Half Wood	2,492	2,141	8	306
Galvanized Iron/Aluminum	239	53	-	164
Bamboo/Sawali/Cogon/Nipa	5,734	2,874	-	334
Asbestos	11	9	-	2
Glass	4	4	-	-
Makeshift/Salvaged/Improvised Materials	33	12	-	-
Others/Not Reported	35	8	1	-
No Walls	-	-	-	-

CITY OF KABANKALAN

Total	31,656	20,684	87	617
Concrete/Brick/Stone	2,692	2,615	25	22
Wood	3,695	3,041	9	106
Half Concrete/Brick/Stone and Half Wood	4,772	4,254	29	320
Galvanized Iron/Aluminum	182	120	7	20
Bamboo/Sawali/Cogon/Nipa	20,114	10,555	-	146
Asbestos	8	8	-	-
Glass	5	4	1	-
Makeshift/Salvaged/Improvised Materials	31	12	-	3
Others/Not Reported	157	75	16	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>LA CARLOTA CITY</b>				
Total	12,732	7,829	48	1,960
Concrete/Brick/Stone	2,804	2,676	39	53
Wood	1,049	661	2	97
Half Concrete/Brick/Stone and Half Wood	4,314	2,799	6	1,221
Galvanized Iron/Aluminum	175	46	1	46
Bamboo/Sawali/Cogon/Nipa	4,102	1,498	-	533
Asbestos	1	1	-	-
Glass	40	38	-	1
Makeshift/Salvaged/Improvised Materials	138	45	-	3
Others/Not Reported	109	65	-	6
No Walls	-	-	-	-
<b>LA CASTELLANA</b>				
Total	13,947	11,233	8	516
Concrete/Brick/Stone	1,554	1,524	1	18
Wood	1,714	1,527	3	19
Half Concrete/Brick/Stone and Half Wood	3,046	2,844	1	158
Galvanized Iron/Aluminum	262	251	2	4
Bamboo/Sawali/Cogon/Nipa	7,233	4,994	-	317
Asbestos	12	12	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	3	-	-
Others/Not Reported	118	77	1	-
No Walls	1	1	-	-
<b>MANAPLA</b>				
Total	10,359	7,472	90	356
Concrete/Brick/Stone	2,732	2,635	51	14
Wood	1,820	1,502	13	15
Half Concrete/Brick/Stone and Half Wood	2,590	2,207	15	240
Galvanized Iron/Aluminum	184	112	9	34
Bamboo/Sawali/Cogon/Nipa	2,930	970	-	51
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	37	21	-	-
Others/Not Reported	66	25	2	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>MOISES PADILLA (MAGALLON)</b>				
Total	7,524	5,694	5	173
Concrete/Brick/Stone	704	700	3	1
Wood	188	168	-	-
Half Concrete/Brick/Stone and Half Wood	1,238	1,164	-	58
Galvanized Iron/Aluminum	288	272	1	9
Bamboo/Sawali/Cogon/Nipa	5,070	3,380	-	103
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	13	-	-	1
Others/Not Reported	22	9	1	1
No Walls	-	-	-	-
<b>MURCIA</b>				
Total	14,480	12,159	4	47
Concrete/Brick/Stone	3,615	3,548	3	5
Wood	1,450	1,316	-	3
Half Concrete/Brick/Stone and Half Wood	3,238	3,155	-	18
Galvanized Iron/Aluminum	74	65	-	1
Bamboo/Sawali/Cogon/Nipa	5,987	3,998	-	20
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	31	21	-	-
Others/Not Reported	82	53	1	-
No Walls	1	1	-	-
<b>PONTEVEDRA</b>				
Total	9,854	6,946	4	582
Concrete/Brick/Stone	1,758	1,736	3	6
Wood	1,230	933	-	69
Half Concrete/Brick/Stone and Half Wood	2,209	1,801	-	335
Galvanized Iron/Aluminum	70	48	1	18
Bamboo/Sawali/Cogon/Nipa	4,445	2,381	-	146
Asbestos	5	5	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	94	31	-	8
Others/Not Reported	42	10	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>PULUPANDAN</b>				
Total	5,630	3,498	6	893
Concrete/Brick/Stone	1,479	1,340	3	117
Wood	474	297	-	56
Half Concrete/Brick/Stone and Half Wood	2,328	1,530	1	598
Galvanized Iron/Aluminum	44	24	1	14
Bamboo/Sawali/Cogon/Nipa	1,262	292	-	108
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	27	11	-	-
Others/Not Reported	16	4	1	-
No Walls	-	-	-	-
<b>SAGAY CITY</b>				
Total	27,514	16,892	63	2,782
Concrete/Brick/Stone	4,132	3,820	36	250
Wood	7,285	5,388	3	430
Half Concrete/Brick/Stone and Half Wood	5,730	3,985	20	1,557
Galvanized Iron/Aluminum	360	131	2	84
Bamboo/Sawali/Cogon/Nipa	9,825	3,533	-	454
Asbestos	4	3	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	53	17	-	4
Others/Not Reported	125	15	2	2
No Walls	-	-	-	-
<b>SAN CARLOS CITY</b>				
Total	26,046	19,021	223	924
Concrete/Brick/Stone	2,744	2,532	198	9
Wood	6,989	5,469	6	81
Half Concrete/Brick/Stone and Half Wood	4,786	4,088	15	650
Galvanized Iron/Aluminum	383	244	1	54
Bamboo/Sawali/Cogon/Nipa	10,850	6,521	-	127
Asbestos	5	5	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	104	50	-	2
Others/Not Reported	183	110	3	1
No Walls	-	-	-	-



Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>SAN ENRIQUE</b>				
Total	4,675	3,307	8	262
Concrete/Brick/Stone	977	951	3	14
Wood	843	684	2	34
Half Concrete/Brick/Stone and Half Wood	1,465	1,171	2	166
Galvanized Iron/Aluminum	19	6	-	8
Bamboo/Sawali/Cogon/Nipa	1,344	491	-	38
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	-	-	-
Others/Not Reported	21	4	1	2
No Walls	-	-	-	-
<b>SILAY CITY</b>				
Total	24,095	20,979	24	585
Concrete/Brick/Stone	7,390	7,305	11	20
Wood	3,762	3,397	3	57
Half Concrete/Brick/Stone and Half Wood	6,950	6,421	7	410
Galvanized Iron/Aluminum	247	225	-	4
Bamboo/Sawali/Cogon/Nipa	5,228	3,276	-	82
Asbestos	3	3	-	-
Glass	3	1	-	-
Makeshift/Salvaged/Improvised Materials	394	293	-	12
Others/Not Reported	118	58	3	-
No Walls	-	-	-	-
<b>CITY OF SIPALAY</b>				
Total	12,791	6,353	50	455
Concrete/Brick/Stone	1,549	1,363	37	85
Wood	1,984	1,459	1	54
Half Concrete/Brick/Stone and Half Wood	2,373	1,835	10	244
Galvanized Iron/Aluminum	48	31	1	8
Bamboo/Sawali/Cogon/Nipa	6,729	1,633	-	63
Asbestos	5	5	-	-
Glass	2	-	-	-
Makeshift/Salvaged/Improvised Materials	37	12	-	-
Others/Not Reported	64	15	1	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

CITY OF TALISAY

Total	19,479	16,894	31	675
Concrete/Brick/Stone	7,604	7,475	20	80
Wood	1,950	1,775	2	39
Half Concrete/Brick/Stone and Half Wood	4,229	3,816	3	370
Galvanized Iron/Aluminum	110	93	-	10
Bamboo/Sawali/Cogon/Nipa	5,453	3,658	-	176
Asbestos	2	2	-	-
Glass	5	4	-	-
Makeshift/Salvaged/Improvised Materials	79	63	-	-
Others/Not Reported	47	8	6	-
No Walls	-	-	-	-

CITY OF TALISAY

Total	8,433	6,259	29	291
Concrete/Brick/Stone	1,036	1,033	1	-
Wood	1,998	1,894	-	8
Half Concrete/Brick/Stone and Half Wood	1,229	1,150	11	47
Galvanized Iron/Aluminum	88	39	4	41
Bamboo/Sawali/Cogon/Nipa	3,837	2,027	-	193
Asbestos	26	25	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	163	62	-	2
Others/Not Reported	53	26	13	-
No Walls	2	2	-	-

VALLADOLID

Total	7,549	5,414	11	401
Concrete/Brick/Stone	2,382	2,334	11	8
Wood	516	440	-	9
Half Concrete/Brick/Stone and Half Wood	2,033	1,642	-	273
Galvanized Iron/Aluminum	20	13	-	3
Bamboo/Sawali/Cogon/Nipa	2,417	883	-	107
Asbestos	13	12	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	42	12	-	-
Others/Not Reported	123	78	-	1
No Walls	2	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

CITY OF VICTORIAS

Total	16,612	13,977	241	163
Concrete/Brick/Stone	5,929	5,525	227	13
Wood	2,695	2,509	-	22
Half Concrete/Brick/Stone and Half Wood	3,494	3,351	11	70
Galvanized Iron/Aluminum	274	254	-	5
Bamboo/Sawali/Cogon/Nipa	3,775	2,023	-	51
Asbestos	2	1	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	206	158	-	1
Others/Not Reported	235	154	3	1
No Walls	1	1	-	-

SALVADOR BENEDICTO

Total	4,215	2,920	5	68
Concrete/Brick/Stone	358	352	3	2
Wood	1,484	1,194	1	2
Half Concrete/Brick/Stone and Half Wood	397	339	1	56
Galvanized Iron/Aluminum	20	16	-	2
Bamboo/Sawali/Cogon/Nipa	1,940	1,006	-	6
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	9	-	-
Others/Not Reported	5	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>NEGROS OCCIDENTAL</b>					
Total	5,905	116,619	1,122	1,170	2,084
Concrete/Brick/Stone	110	783	28	252	143
Wood	3,020	10,643	43	97	228
Half Concrete/Brick/Stone and Half Wood	552	3,604	139	217	150
Galvanized Iron/Aluminum	360	327	4	76	13
Bamboo/Sawali/Cogon/Nipa	1,832	100,383	284	418	492
Asbestos	3	-	-	3	-
Glass	1	-	-	-	16
Makeshift/Salvaged/Improvised Materials	15	553	620	12	13
Others/Not Reported	12	322	4	95	1,029
No Walls	-	4	-	-	-
<b>BAGO CITY</b>					
Total	83	6,113	77	95	111
Concrete/Brick/Stone	3	18	1	7	6
Wood	42	273	6	13	4
Half Concrete/Brick/Stone and Half Wood	3	135	4	13	5
Galvanized Iron/Aluminum	1	11	-	2	1
Bamboo/Sawali/Cogon/Nipa	34	5,597	28	44	18
Asbestos	-	-	-	-	-
Glass	-	-	-	-	9
Makeshift/Salvaged/Improvised Materials	-	65	38	2	1
Others/Not Reported	-	14	-	14	67
No Walls	-	-	-	-	-
<b>BINALBAGAN</b>					
Total	95	3,041	5	3	79
Concrete/Brick/Stone	3	8	-	1	3
Wood	19	128	-	-	4
Half Concrete/Brick/Stone and Half Wood	12	68	-	-	10
Galvanized Iron/Aluminum	1	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	58	2,826	1	2	27
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	3	-	-
Others/Not Reported	2	1	1	-	35
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CADIZ CITY</b>					
Total	416	8,179	258	9	353
Concrete/Brick/Stone	3	87	5	1	12
Wood	114	1,753	8	1	106
Half Concrete/Brick/Stone and Half Wood	28	352	6	1	21
Galvanized Iron/Aluminum	20	39	-	-	2
Bamboo/Sawali/Cogon/Nipa	243	5,835	20	1	29
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	74	219	1	8
Others/Not Reported	1	39	-	4	175
No Walls	-	-	-	-	-
<b>CALATRAVA</b>					
Total	53	3,980	8	11	22
Concrete/Brick/Stone	-	9	1	-	1
Wood	3	555	1	-	8
Half Concrete/Brick/Stone and Half Wood	-	27	-	-	-
Galvanized Iron/Aluminum	34	12	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	3,356	4	8	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	2	-	-
Others/Not Reported	-	17	-	3	11
No Walls	-	1	-	-	-
<b>CANDONI</b>					
Total	21	1,297	-	3	5
Concrete/Brick/Stone	-	1	-	-	-
Wood	4	20	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	8	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	1,266	-	3	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	2	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CAUAYAN</b>					
Total	294	11,453	4	9	77
Concrete/Brick/Stone	6	214	3	-	3
Wood	14	1,094	-	4	6
Half Concrete/Brick/Stone and Half Wood	19	737	-	1	4
Galvanized Iron/Aluminum	19	44	-	-	1
Bamboo/Sawali/Cogon/Nipa	232	9,344	1	3	18
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	-	-	-
Others/Not Reported	3	13	-	1	45
No Walls	-	-	-	-	-
<b>ENRIQUE B. MAGALONA (SARAVIA)</b>					
Total	111	2,146	25	17	38
Concrete/Brick/Stone	1	36	-	3	3
Wood	22	181	2	7	1
Half Concrete/Brick/Stone and Half Wood	9	68	-	1	1
Galvanized Iron/Aluminum	11	13	-	1	-
Bamboo/Sawali/Cogon/Nipa	68	1,829	2	4	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	21	-	-
Others/Not Reported	-	10	-	1	25
No Walls	-	-	-	-	-
<b>CITY OF ESCALANTE</b>					
Total	292	3,337	39	1	117
Concrete/Brick/Stone	9	4	2	1	3
Wood	107	233	3	-	12
Half Concrete/Brick/Stone and Half Wood	47	23	-	-	8
Galvanized Iron/Aluminum	23	6	1	-	-
Bamboo/Sawali/Cogon/Nipa	102	3,036	4	-	16
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	25	29	-	-
Others/Not Reported	1	10	-	-	78
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CITY OF HIMAMAYLAN</b>					
Total	163	6,704	17	50	25
Concrete/Brick/Stone	-	19	1	1	2
Wood	50	557	-	6	1
Half Concrete/Brick/Stone and Half Wood	8	190	5	10	1
Galvanized Iron/Aluminum	12	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	93	5,913	3	30	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	8	-	-
Others/Not Reported	-	7	-	3	15
No Walls	-	1	-	-	-
<b>HINIGARAN</b>					
Total	507	5,549	7	11	80
Concrete/Brick/Stone	36	20	-	8	3
Wood	183	422	-	1	13
Half Concrete/Brick/Stone and Half Wood	105	196	-	-	21
Galvanized Iron/Aluminum	7	4	-	-	1
Bamboo/Sawali/Cogon/Nipa	175	4,890	4	-	12
Asbestos	-	-	-	2	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	12	3	-	-
Others/Not Reported	1	5	-	-	30
No Walls	-	-	-	-	-
<b>HINOBA-AN (ASIA)</b>					
Total	18	5,388	27	4	10
Concrete/Brick/Stone	-	115	8	-	-
Wood	-	764	2	2	-
Half Concrete/Brick/Stone and Half Wood	2	340	6	-	2
Galvanized Iron/Aluminum	1	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	4,146	10	2	5
Asbestos	-	-	-	-	-
Glass	1	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	1	-	-
Others/Not Reported	-	13	-	-	3
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>ILOG</b>					
Total	43	5,437	10	13	49
Concrete/Brick/Stone	4	46	-	2	2
Wood	8	447	-	-	3
Half Concrete/Brick/Stone and Half Wood	7	170	-	1	3
Galvanized Iron/Aluminum	2	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	22	4,735	2	9	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	8	-	1
Others/Not Reported	-	24	-	1	34
No Walls	-	-	-	-	-
<b>ISABELA</b>					
Total	337	2,736	13	2	50
Concrete/Brick/Stone	-	5	-	-	3
Wood	296	195	-	-	7
Half Concrete/Brick/Stone and Half Wood	5	30	-	-	2
Galvanized Iron/Aluminum	8	14	-	-	-
Bamboo/Sawali/Cogon/Nipa	28	2,475	5	2	16
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	8	-	-
Others/Not Reported	-	4	-	-	22
No Walls	-	-	-	-	-
<b>CITY OF KABANKALAN</b>					
Total	76	9,906	55	97	134
Concrete/Brick/Stone	2	15	-	3	10
Wood	24	498	2	11	4
Half Concrete/Brick/Stone and Half Wood	5	142	10	5	7
Galvanized Iron/Aluminum	6	27	-	-	2
Bamboo/Sawali/Cogon/Nipa	39	9,196	33	67	78
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	10	1	-
Others/Not Reported	-	23	-	10	33
No Walls	-	-	-	-	-



Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>LA CARLOTA CITY</b>					
Total	267	2,032	205	304	87
Concrete/Brick/Stone	-	4	4	25	3
Wood	218	59	3	9	-
Half Concrete/Brick/Stone and Half Wood	22	48	77	135	6
Galvanized Iron/Aluminum	2	8	-	72	-
Bamboo/Sawali/Cogon/Nipa	25	1,877	61	50	58
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	28	57	4	1
Others/Not Reported	-	8	3	9	18
No Walls	-	-	-	-	-
<b>LA CASTELLANA</b>					
Total	108	1,925	3	71	83
Concrete/Brick/Stone	-	3	-	1	7
Wood	84	70	-	8	3
Half Concrete/Brick/Stone and Half Wood	1	26	-	9	7
Galvanized Iron/Aluminum	2	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	21	1,813	2	42	44
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	-	-
Others/Not Reported	-	7	-	11	22
No Walls	-	-	-	-	-
<b>MANAPLA</b>					
Total	212	2,123	13	9	84
Concrete/Brick/Stone	10	10	-	-	12
Wood	45	222	1	4	18
Half Concrete/Brick/Stone and Half Wood	53	68	-	-	7
Galvanized Iron/Aluminum	21	4	-	-	4
Bamboo/Sawali/Cogon/Nipa	79	1,805	4	5	16
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	8	-	-
Others/Not Reported	4	6	-	-	27
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>MOISES PADILLA (MAGALLON)</b>					
Total	16	1,568	14	13	41
Concrete/Brick/Stone	-	-	-	-	-
Wood	5	15	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	11	-	-	4
Galvanized Iron/Aluminum	-	4	1	-	1
Bamboo/Sawali/Cogon/Nipa	10	1,535	2	13	27
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	11	-	-
Others/Not Reported	-	2	-	-	9
No Walls	-	-	-	-	-
<b>MURCIA</b>					
Total	15	2,095	7	43	110
Concrete/Brick/Stone	-	6	-	11	42
Wood	3	118	-	3	7
Half Concrete/Brick/Stone and Half Wood	-	52	-	-	13
Galvanized Iron/Aluminum	-	7	-	1	-
Bamboo/Sawali/Cogon/Nipa	12	1,901	3	26	27
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	4	-	1
Others/Not Reported	-	6	-	2	20
No Walls	-	-	-	-	-
<b>PONTEVEDRA</b>					
Total	19	2,230	50	1	22
Concrete/Brick/Stone	-	13	-	-	-
Wood	6	221	1	-	-
Half Concrete/Brick/Stone and Half Wood	2	66	4	1	-
Galvanized Iron/Aluminum	-	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	9	1,895	9	-	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	18	35	-	-
Others/Not Reported	-	15	-	-	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>PULUPANDAN</b>					
Total	34	1,162	6	21	10
Concrete/Brick/Stone	-	18	-	-	1
Wood	2	117	-	1	1
Half Concrete/Brick/Stone and Half Wood	3	185	-	9	2
Galvanized Iron/Aluminum	2	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	27	823	3	9	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	3	-	-
Others/Not Reported	-	3	-	2	6
No Walls	-	-	-	-	-
<b>SAGAY CITY</b>					
Total	798	6,806	22	7	144
Concrete/Brick/Stone	5	14	-	-	7
Wood	416	1,034	1	2	11
Half Concrete/Brick/Stone and Half Wood	60	96	1	2	9
Galvanized Iron/Aluminum	129	13	-	-	1
Bamboo/Sawali/Cogon/Nipa	187	5,619	6	2	24
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	16	14	1	-
Others/Not Reported	-	14	-	-	92
No Walls	-	-	-	-	-
<b>SAN CARLOS CITY</b>					
Total	1,134	4,623	37	13	71
Concrete/Brick/Stone	2	1	-	1	1
Wood	959	460	5	4	5
Half Concrete/Brick/Stone and Half Wood	12	20	-	-	1
Galvanized Iron/Aluminum	38	46	-	-	-
Bamboo/Sawali/Cogon/Nipa	123	4,056	15	7	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	35	17	-	-
Others/Not Reported	-	5	-	1	63
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>SAN ENRIQUE</b>					
Total	154	922	2	1	19
Concrete/Brick/Stone	2	5	-	-	2
Wood	27	94	1	1	-
Half Concrete/Brick/Stone and Half Wood	81	44	-	-	1
Galvanized Iron/Aluminum	3	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	41	772	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	1	-	-
Others/Not Reported	-	-	-	-	14
No Walls	-	-	-	-	-
<b>SILAY CITY</b>					
Total	108	2,181	69	73	76
Concrete/Brick/Stone	5	10	2	32	5
Wood	52	240	1	6	6
Half Concrete/Brick/Stone and Half Wood	15	76	4	11	6
Galvanized Iron/Aluminum	12	5	1	-	-
Bamboo/Sawali/Cogon/Nipa	22	1,810	8	23	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	2
Makeshift/Salvaged/Improvised Materials	2	33	53	-	1
Others/Not Reported	-	7	-	1	49
No Walls	-	-	-	-	-
<b>CITY OF SIPALAY</b>					
Total	166	5,671	31	26	39
Concrete/Brick/Stone	9	52	-	3	-
Wood	67	399	2	1	1
Half Concrete/Brick/Stone and Half Wood	21	259	2	1	1
Galvanized Iron/Aluminum	-	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	69	4,925	12	13	14
Asbestos	-	-	-	-	-
Glass	-	-	-	-	2
Makeshift/Salvaged/Improvised Materials	-	8	15	2	-
Others/Not Reported	-	20	-	6	21
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CITY OF TALISAY</b>					
Total	77	1,715	22	18	47
Concrete/Brick/Stone	2	14	-	10	3
Wood	28	100	3	1	2
Half Concrete/Brick/Stone and Half Wood	6	30	-	1	3
Galvanized Iron/Aluminum	2	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	39	1,553	11	6	10
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	8	8	-	-
Others/Not Reported	-	5	-	-	28
No Walls	-	-	-	-	-
<b>CITY OF TALISAY</b>					
Total	7	1,807	25	-	15
Concrete/Brick/Stone	-	1	-	-	1
Wood	2	94	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	20	1	-	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	1,605	6	-	2
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	81	18	-	-
Others/Not Reported	-	2	-	-	12
No Walls	-	-	-	-	-
<b>VALLADOLID</b>					
Total	38	1,592	14	52	27
Concrete/Brick/Stone	3	24	-	-	2
Wood	3	56	-	7	1
Half Concrete/Brick/Stone and Half Wood	20	85	1	9	3
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	1,386	3	24	3
Asbestos	1	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	20	10	-	-
Others/Not Reported	-	15	-	12	17
No Walls	-	2	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

CITY OF VICTORIAS

Total	23	1,905	57	192	54
Concrete/Brick/Stone	5	10	1	142	6
Wood	3	154	1	5	1
Half Concrete/Brick/Stone and Half Wood	4	31	18	7	2
Galvanized Iron/Aluminum	2	13	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	1,641	22	22	7
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	31	15	1	-
Others/Not Reported	-	25	-	14	38
No Walls	-	-	-	-	-

SALVADOR BENEDICTO

Total	220	996	-	1	5
Concrete/Brick/Stone	-	1	-	-	-
Wood	214	70	-	-	3
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	2	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	923	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-