

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>NEGROS ORIENTAL</b>				
Total	256,399	143,122	526	6,538
Concrete/Brick/Stone	46,256	43,144	234	632
Wood	50,047	33,393	152	1,047
Half Concrete/Brick/Stone and Half Wood	40,560	30,866	75	3,401
Galvanized Iron/Aluminum	1,324	861	19	147
Bamboo/Sawali/Cogon/Nipa	114,697	33,915	-	1,263
Asbestos	39	31	2	2
Glass	30	22	3	-
Makeshift/Salvaged/Improvised Materials	695	195	-	5
Others/Not Reported	2,729	684	41	41
No Walls	22	11	-	-
<b>AMLAN (AYUQUITAN)</b>				
Total	4,492	2,111	2	22
Concrete/Brick/Stone	1,301	1,058	-	8
Wood	1,200	557	-	3
Half Concrete/Brick/Stone and Half Wood	489	291	1	6
Galvanized Iron/Aluminum	4	1	-	1
Bamboo/Sawali/Cogon/Nipa	1,444	190	-	4
Asbestos	-	-	-	-
Glass	4	3	1	-
Makeshift/Salvaged/Improvised Materials	10	3	-	-
Others/Not Reported	40	8	-	-
No Walls	-	-	-	-
<b>AYUNGON</b>				
Total	8,924	3,412	4	193
Concrete/Brick/Stone	970	867	2	5
Wood	2,561	1,330	1	34
Half Concrete/Brick/Stone and Half Wood	901	581	-	75
Galvanized Iron/Aluminum	53	13	1	11
Bamboo/Sawali/Cogon/Nipa	4,205	563	-	59
Asbestos	1	-	-	1
Glass	2	-	-	-
Makeshift/Salvaged/Improvised Materials	74	6	-	-
Others/Not Reported	157	52	-	8
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>BACONG</b>				
Total	6,165	3,909	2	63
Concrete/Brick/Stone	2,517	2,419	2	3
Wood	378	282	-	5
Half Concrete/Brick/Stone and Half Wood	990	750	-	20
Galvanized Iron/Aluminum	13	12	-	-
Bamboo/Sawali/Cogon/Nipa	2,197	426	-	35
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	69	19	-	-
No Walls	-	-	-	-
<b>BAIS CITY</b>				
Total	15,052	10,720	11	146
Concrete/Brick/Stone	2,422	2,294	7	2
Wood	4,460	3,445	1	32
Half Concrete/Brick/Stone and Half Wood	2,555	2,240	2	84
Galvanized Iron/Aluminum	69	38	-	5
Bamboo/Sawali/Cogon/Nipa	5,442	2,671	-	22
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	30	12	-	-
Others/Not Reported	72	18	1	1
No Walls	1	1	-	-
<b>BASAY</b>				
Total	4,812	1,718	3	126
Concrete/Brick/Stone	470	400	1	3
Wood	927	361	-	16
Half Concrete/Brick/Stone and Half Wood	870	537	1	63
Galvanized Iron/Aluminum	31	17	1	6
Bamboo/Sawali/Cogon/Nipa	2,331	390	-	38
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	108	2	-	-
Others/Not Reported	75	11	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>CITY OF BAYAWAN (TULONG)</b>				
Total	21,872	13,184	11	726
Concrete/Brick/Stone	3,234	3,066	7	15
Wood	3,263	2,455	1	137
Half Concrete/Brick/Stone and Half Wood	2,203	1,594	1	398
Galvanized Iron/Aluminum	247	203	-	17
Bamboo/Sawali/Cogon/Nipa	12,681	5,768	-	155
Asbestos	10	9	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	48	15	-	-
Others/Not Reported	181	74	2	3
No Walls	5	-	-	-
<b>BINDOY (PAYABON)</b>				
Total	7,449	3,373	4	120
Concrete/Brick/Stone	671	614	1	4
Wood	1,777	1,284	-	41
Half Concrete/Brick/Stone and Half Wood	754	546	-	52
Galvanized Iron/Aluminum	23	16	-	3
Bamboo/Sawali/Cogon/Nipa	4,177	904	-	20
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	44	7	3	-
No Walls	-	-	-	-
<b>CANLAON CITY</b>				
Total	10,240	8,207	27	153
Concrete/Brick/Stone	1,764	1,732	17	7
Wood	2,577	2,491	4	28
Half Concrete/Brick/Stone and Half Wood	1,409	1,254	3	87
Galvanized Iron/Aluminum	111	76	1	10
Bamboo/Sawali/Cogon/Nipa	4,158	2,568	-	21
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	78	63	-	-
Others/Not Reported	140	20	2	-
No Walls	2	2	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>DAUIN</b>				
Total	5,282	2,574	12	45
Concrete/Brick/Stone	1,488	1,356	10	16
Wood	492	209	-	2
Half Concrete/Brick/Stone and Half Wood	807	556	1	16
Galvanized Iron/Aluminum	7	6	-	1
Bamboo/Sawali/Cogon/Nipa	2,425	440	-	10
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	63	7	1	-
No Walls	-	-	-	-
<b>DUMAGUETE CITY (Capital)</b>				
Total	23,694	17,116	174	969
Concrete/Brick/Stone	9,141	8,649	71	168
Wood	3,796	1,948	54	168
Half Concrete/Brick/Stone and Half Wood	6,877	5,359	37	534
Galvanized Iron/Aluminum	171	117	6	28
Bamboo/Sawali/Cogon/Nipa	3,460	973	-	66
Asbestos	3	2	1	-
Glass	8	4	1	-
Makeshift/Salvaged/Improvised Materials	72	13	-	-
Others/Not Reported	165	51	4	5
No Walls	1	-	-	-
<b>GUIHULNGAN</b>				
Total	19,187	9,877	11	254
Concrete/Brick/Stone	1,696	1,633	3	10
Wood	5,682	3,814	2	88
Half Concrete/Brick/Stone and Half Wood	1,937	1,654	1	84
Galvanized Iron/Aluminum	58	40	1	5
Bamboo/Sawali/Cogon/Nipa	9,307	2,505	-	48
Asbestos	7	6	-	-
Glass	7	6	1	-
Makeshift/Salvaged/Improvised Materials	81	27	-	1
Others/Not Reported	406	188	3	18
No Walls	6	4	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>JIMALALUD</b>				
Total	5,538	1,343	1	130
Concrete/Brick/Stone	467	437	-	1
Wood	496	263	-	61
Half Concrete/Brick/Stone and Half Wood	404	267	-	17
Galvanized Iron/Aluminum	15	11	1	-
Bamboo/Sawali/Cogon/Nipa	4,128	364	-	51
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	28	1	-	-
No Walls	-	-	-	-
<b>LA LIBERTAD</b>				
Total	7,983	2,771	12	204
Concrete/Brick/Stone	499	464	6	17
Wood	666	476	-	25
Half Concrete/Brick/Stone and Half Wood	818	564	-	106
Galvanized Iron/Aluminum	31	18	5	3
Bamboo/Sawali/Cogon/Nipa	5,921	1,240	-	53
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	41	6	1	-
No Walls	4	2	-	-
<b>MABINAY</b>				
Total	15,073	11,334	7	298
Concrete/Brick/Stone	1,275	1,259	6	7
Wood	5,023	4,301	1	32
Half Concrete/Brick/Stone and Half Wood	1,910	1,751	-	136
Galvanized Iron/Aluminum	76	65	-	3
Bamboo/Sawali/Cogon/Nipa	6,702	3,911	-	119
Asbestos	3	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	39	24	-	1
Others/Not Reported	45	20	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>MANJUYOD</b>				
Total	8,536	4,739	87	198
Concrete/Brick/Stone	1,264	1,207	3	7
Wood	2,006	1,266	72	127
Half Concrete/Brick/Stone and Half Wood	1,211	1,030	4	28
Galvanized Iron/Aluminum	8	7	-	-
Bamboo/Sawali/Cogon/Nipa	3,908	1,209	-	35
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	137	20	8	1
No Walls	-	-	-	-
<b>PAMPLONA</b>				
Total	7,462	4,596	16	290
Concrete/Brick/Stone	991	954	6	4
Wood	1,953	1,303	2	14
Half Concrete/Brick/Stone and Half Wood	1,605	1,392	3	108
Galvanized Iron/Aluminum	67	50	1	3
Bamboo/Sawali/Cogon/Nipa	2,707	873	-	161
Asbestos	2	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	60	9	-	-
Others/Not Reported	77	14	4	-
No Walls	-	-	-	-
<b>SAN JOSE</b>				
Total	3,706	2,245	2	15
Concrete/Brick/Stone	790	747	-	-
Wood	519	430	-	1
Half Concrete/Brick/Stone and Half Wood	681	494	1	6
Galvanized Iron/Aluminum	5	5	-	-
Bamboo/Sawali/Cogon/Nipa	1,658	558	-	8
Asbestos	1	-	1	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	51	10	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>SANTA CATALINA</b>				
Total	14,732	5,543	13	894
Concrete/Brick/Stone	1,568	1,347	11	39
Wood	2,219	1,330	-	32
Half Concrete/Brick/Stone and Half Wood	2,267	1,062	1	693
Galvanized Iron/Aluminum	61	20	1	19
Bamboo/Sawali/Cogon/Nipa	8,407	1,727	-	111
Asbestos	1	1	-	-
Glass	4	4	-	-
Makeshift/Salvaged/Improvised Materials	10	4	-	-
Others/Not Reported	194	47	-	-
No Walls	1	1	-	-
<b>SIATON</b>				
Total	14,216	5,355	29	175
Concrete/Brick/Stone	2,608	2,334	25	27
Wood	1,168	661	1	6
Half Concrete/Brick/Stone and Half Wood	1,606	1,089	3	115
Galvanized Iron/Aluminum	39	18	-	1
Bamboo/Sawali/Cogon/Nipa	8,669	1,219	-	25
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	122	32	-	1
No Walls	1	1	-	-
<b>SIBULAN</b>				
Total	10,377	5,866	51	494
Concrete/Brick/Stone	3,703	3,354	31	152
Wood	1,312	603	3	18
Half Concrete/Brick/Stone and Half Wood	1,782	1,172	6	277
Galvanized Iron/Aluminum	36	14	1	5
Bamboo/Sawali/Cogon/Nipa	3,443	708	-	41
Asbestos	-	-	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	37	3	-	-
Others/Not Reported	62	10	10	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>CITY OF TANJAY</b>				
Total	16,411	9,571	18	641
Concrete/Brick/Stone	2,901	2,589	13	115
Wood	3,749	1,963	3	120
Half Concrete/Brick/Stone and Half Wood	4,697	3,569	-	323
Galvanized Iron/Aluminum	88	65	-	13
Bamboo/Sawali/Cogon/Nipa	4,744	1,347	-	69
Asbestos	3	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	6	-	-
Others/Not Reported	217	29	2	1
No Walls	1	-	-	-
<b>TAYASAN</b>				
Total	6,968	2,354	3	37
Concrete/Brick/Stone	565	545	1	1
Wood	1,136	627	-	14
Half Concrete/Brick/Stone and Half Wood	441	342	2	9
Galvanized Iron/Aluminum	52	12	-	2
Bamboo/Sawali/Cogon/Nipa	4,550	809	-	10
Asbestos	1	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	5	-	-	1
Others/Not Reported	217	18	-	-
No Walls	-	-	-	-
<b>VALENCIA (LUZURRIAGA)</b>				
Total	5,983	4,242	3	125
Concrete/Brick/Stone	1,964	1,936	1	1
Wood	770	528	1	13
Half Concrete/Brick/Stone and Half Wood	1,281	1,073	1	76
Galvanized Iron/Aluminum	16	13	-	1
Bamboo/Sawali/Cogon/Nipa	1,903	681	-	30
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	-	-	2
Others/Not Reported	37	10	-	2
No Walls	-	-	-	-



Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

VALLEHERMOSO

Total	7,026	4,820	4	18
Concrete/Brick/Stone	751	735	-	2
Wood	1,546	1,272	2	3
Half Concrete/Brick/Stone and Half Wood	1,410	1,328	2	3
Galvanized Iron/Aluminum	24	20	-	1
Bamboo/Sawali/Cogon/Nipa	3,229	1,450	-	9
Asbestos	2	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	6	-	-
Others/Not Reported	52	8	-	-
No Walls	-	-	-	-

ZAMBOANGUITA

Total	5,219	2,142	19	202
Concrete/Brick/Stone	1,236	1,148	10	18
Wood	371	194	4	27
Half Concrete/Brick/Stone and Half Wood	655	371	5	85
Galvanized Iron/Aluminum	19	4	-	9
Bamboo/Sawali/Cogon/Nipa	2,901	421	-	63
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	37	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>NEGROS ORIENTAL</b>					
Total	2,242	99,638	366	1,936	2,031
Concrete/Brick/Stone	135	1,968	5	52	86
Wood	660	14,431	42	199	123
Half Concrete/Brick/Stone and Half Wood	356	5,661	9	108	84
Galvanized Iron/Aluminum	111	173	1	-	12
Bamboo/Sawali/Cogon/Nipa	949	76,520	153	1,496	401
Asbestos	2	-	-	2	-
Glass	2	-	-	-	3
Makeshift/Salvaged/Improvised Materials	5	331	151	1	7
Others/Not Reported	22	545	4	78	1,314
No Walls	-	9	1	-	1
<b>AMLAN (AYUQUITAN)</b>					
Total	4	2,284	-	17	52
Concrete/Brick/Stone	1	220	-	8	6
Wood	1	627	-	5	7
Half Concrete/Brick/Stone and Half Wood	-	179	-	3	9
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	1,242	-	1	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	-	-	-
Others/Not Reported	-	7	-	-	25
No Walls	-	-	-	-	-
<b>AYUNGON</b>					
Total	95	4,953	61	53	153
Concrete/Brick/Stone	2	75	-	3	16
Wood	27	1,117	20	8	24
Half Concrete/Brick/Stone and Half Wood	8	215	1	14	7
Galvanized Iron/Aluminum	18	9	-	-	1
Bamboo/Sawali/Cogon/Nipa	31	3,454	7	25	66
Asbestos	-	-	-	-	-
Glass	-	-	-	-	2
Makeshift/Salvaged/Improvised Materials	5	29	31	-	3
Others/Not Reported	4	54	2	3	34
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>BACONG</b>					
Total	11	2,088	-	58	34
Concrete/Brick/Stone	-	85	-	5	3
Wood	1	86	-	2	2
Half Concrete/Brick/Stone and Half Wood	3	212	-	4	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	1,688	-	39	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	16	-	8	26
No Walls	-	-	-	-	-
<b>BAIS CITY</b>					
Total	86	4,005	7	16	61
Concrete/Brick/Stone	-	113	-	4	2
Wood	31	947	2	-	2
Half Concrete/Brick/Stone and Half Wood	15	211	-	-	3
Galvanized Iron/Aluminum	13	13	-	-	-
Bamboo/Sawali/Cogon/Nipa	27	2,703	3	12	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	2	-	-
Others/Not Reported	-	2	-	-	50
No Walls	-	-	-	-	-
<b>BASAY</b>					
Total	50	2,811	30	1	73
Concrete/Brick/Stone	-	66	-	-	-
Wood	17	527	1	1	4
Half Concrete/Brick/Stone and Half Wood	3	262	-	-	4
Galvanized Iron/Aluminum	2	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	28	1,857	5	-	13
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	80	24	-	2
Others/Not Reported	-	14	-	-	50
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CITY OF BAYAWAN (TULONG)</b>					
Total	139	7,584	67	45	116
Concrete/Brick/Stone	12	130	-	-	4
Wood	25	634	2	1	8
Half Concrete/Brick/Stone and Half Wood	5	202	1	1	1
Galvanized Iron/Aluminum	7	18	1	-	1
Bamboo/Sawali/Cogon/Nipa	89	6,545	58	42	24
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	29	4	-	-
Others/Not Reported	1	22	-	1	78
No Walls	-	4	1	-	-
<b>BINDOY (PAYABON)</b>					
Total	20	3,750	4	94	84
Concrete/Brick/Stone	2	43	1	1	5
Wood	5	431	-	7	9
Half Concrete/Brick/Stone and Half Wood	-	149	2	1	4
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	3,109	1	82	49
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	1	13	-	3	17
No Walls	-	-	-	-	-
<b>CANLAON CITY</b>					
Total	176	1,509	26	5	137
Concrete/Brick/Stone	8	-	-	-	-
Wood	12	41	-	-	1
Half Concrete/Brick/Stone and Half Wood	50	12	1	-	2
Galvanized Iron/Aluminum	17	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	87	1,444	12	5	21
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	12	-	-
Others/Not Reported	2	2	1	-	113
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>DAUIN</b>					
Total	26	2,539	-	27	59
Concrete/Brick/Stone	2	100	-	1	3
Wood	2	276	-	1	2
Half Concrete/Brick/Stone and Half Wood	2	229	-	1	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	20	1,927	-	23	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	7	-	1	47
No Walls	-	-	-	-	-
<b>DUMAGUETE CITY (Capital)</b>					
Total	455	4,804	31	29	116
Concrete/Brick/Stone	75	162	-	4	12
Wood	164	1,440	3	11	8
Half Concrete/Brick/Stone and Half Wood	164	770	-	6	7
Galvanized Iron/Aluminum	7	13	-	-	-
Bamboo/Sawali/Cogon/Nipa	38	2,370	4	4	5
Asbestos	-	-	-	-	-
Glass	2	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	35	24	-	-
Others/Not Reported	5	14	-	4	82
No Walls	-	-	-	-	1
<b>GUIHULNGAN</b>					
Total	51	8,735	3	89	167
Concrete/Brick/Stone	-	45	-	2	3
Wood	21	1,721	1	18	17
Half Concrete/Brick/Stone and Half Wood	-	181	-	12	5
Galvanized Iron/Aluminum	-	11	-	-	1
Bamboo/Sawali/Cogon/Nipa	30	6,659	1	41	23
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	52	1	-	-
Others/Not Reported	-	64	-	15	118
No Walls	-	2	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>JIMALALUD</b>					
Total	19	4,028	1	-	16
Concrete/Brick/Stone	-	29	-	-	-
Wood	3	169	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	120	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	3,695	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	12	-	-	15
No Walls	-	-	-	-	-
<b>LA LIBERTAD</b>					
Total	51	4,908	3	-	34
Concrete/Brick/Stone	3	9	-	-	-
Wood	2	162	-	-	1
Half Concrete/Brick/Stone and Half Wood	6	141	-	-	1
Galvanized Iron/Aluminum	1	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	39	4,577	1	-	11
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	13	-	-	21
No Walls	-	2	-	-	-
<b>MABINAY</b>					
Total	41	3,268	58	24	43
Concrete/Brick/Stone	-	2	1	-	-
Wood	14	656	9	7	3
Half Concrete/Brick/Stone and Half Wood	1	19	-	1	2
Galvanized Iron/Aluminum	2	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	24	2,572	43	16	17
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	5	-	-
Others/Not Reported	-	4	-	-	21
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>MANJUYOD</b>					
Total	21	3,301	3	69	118
Concrete/Brick/Stone	2	40	-	1	4
Wood	5	526	-	4	6
Half Concrete/Brick/Stone and Half Wood	2	141	-	2	4
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	2,578	3	60	11
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	13	-	2	93
No Walls	-	-	-	-	-
<b>PAMPLONA</b>					
Total	63	2,415	26	1	55
Concrete/Brick/Stone	1	25	-	-	1
Wood	14	619	-	-	1
Half Concrete/Brick/Stone and Half Wood	6	94	1	-	1
Galvanized Iron/Aluminum	1	12	-	-	-
Bamboo/Sawali/Cogon/Nipa	40	1,629	-	1	3
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	26	25	-	-
Others/Not Reported	-	10	-	-	49
No Walls	-	-	-	-	-
<b>SAN JOSE</b>					
Total	5	1,395	-	1	43
Concrete/Brick/Stone	-	42	-	1	-
Wood	1	86	-	-	1
Half Concrete/Brick/Stone and Half Wood	1	178	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	1,086	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	3	-	-	38
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>SANTA CATALINA</b>					
Total	120	7,714	3	341	104
Concrete/Brick/Stone	5	161	-	4	1
Wood	54	789	-	11	3
Half Concrete/Brick/Stone and Half Wood	6	489	-	7	9
Galvanized Iron/Aluminum	7	14	-	-	-
Bamboo/Sawali/Cogon/Nipa	47	6,207	2	300	13
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	1	-	-
Others/Not Reported	1	49	-	19	78
No Walls	-	-	-	-	-
<b>SIATON</b>					
Total	113	7,593	7	860	84
Concrete/Brick/Stone	2	216	1	3	-
Wood	59	349	-	92	-
Half Concrete/Brick/Stone and Half Wood	3	380	1	12	3
Galvanized Iron/Aluminum	13	6	-	-	1
Bamboo/Sawali/Cogon/Nipa	34	6,626	5	735	25
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	1	-
Others/Not Reported	2	15	-	17	55
No Walls	-	-	-	-	-
<b>SIBULAN</b>					
Total	179	3,686	16	36	49
Concrete/Brick/Stone	9	145	1	4	7
Wood	41	632	3	11	1
Half Concrete/Brick/Stone and Half Wood	19	297	1	9	1
Galvanized Iron/Aluminum	5	11	-	-	-
Bamboo/Sawali/Cogon/Nipa	104	2,567	2	10	11
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	25	9	-	-
Others/Not Reported	1	9	-	2	29
No Walls	-	-	-	-	-



Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>CITY OF TANJAY</b>					
Total	134	5,775	4	49	219
Concrete/Brick/Stone	-	160	1	7	16
Wood	62	1,574	1	13	13
Half Concrete/Brick/Stone and Half Wood	43	729	-	22	11
Galvanized Iron/Aluminum	1	9	-	-	-
Bamboo/Sawali/Cogon/Nipa	28	3,281	-	7	12
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	2	-	1
Others/Not Reported	-	19	-	-	166
No Walls	-	1	-	-	-
<b>TAYASAN</b>					
Total	213	4,280	5	13	63
Concrete/Brick/Stone	-	16	-	-	2
Wood	51	438	-	1	5
Half Concrete/Brick/Stone and Half Wood	10	77	-	1	-
Galvanized Iron/Aluminum	16	14	-	-	8
Bamboo/Sawali/Cogon/Nipa	131	3,568	4	10	18
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	1
Others/Not Reported	5	165	-	-	29
No Walls	-	-	-	-	-
<b>VALENCIA (LUZURRIAGA)</b>					
Total	11	1,556	8	19	19
Concrete/Brick/Stone	-	24	-	2	-
Wood	4	223	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	125	-	5	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	1,173	1	10	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	7	-	-
Others/Not Reported	-	7	-	1	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>VALLEHERMOSO</b>					
Total	15	2,097	2	22	48
Concrete/Brick/Stone	-	12	-	2	-
Wood	4	259	-	3	3
Half Concrete/Brick/Stone and Half Wood	1	68	1	5	2
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	1,746	-	12	3
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	1	-	-
Others/Not Reported	-	4	-	-	40
No Walls	-	-	-	-	-
<b>ZAMBOANGUITA</b>					
Total	144	2,560	1	67	84
Concrete/Brick/Stone	11	48	-	-	1
Wood	40	102	-	2	2
Half Concrete/Brick/Stone and Half Wood	8	181	-	2	3
Galvanized Iron/Aluminum	1	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	84	2,217	-	61	55
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	7	1	2	23
No Walls	-	-	-	-	-