

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ORIENTAL MINDORO				
Total	154,283	93,372	1,372	11,178
Concrete/Brick/Stone	53,490	50,505	917	1,079
Wood	20,204	12,410	107	986
Half Concrete/Brick/Stone and Half Wood	30,829	20,116	250	7,447
Galvanized Iron/Aluminum	1,212	679	49	300
Bamboo/Sawali/Cogon/Nipa	44,613	8,783	-	1,292
Asbestos	46	29	-	2
Glass	69	19	4	9
Makeshift/Salvaged/Improvised Materials	1,060	188	-	21
Others/Not Reported	2,713	631	44	38
No Walls	47	12	1	4
BACO				
Total	6,914	4,551	5	314
Concrete/Brick/Stone	2,563	2,537	4	3
Wood	1,074	701	-	54
Half Concrete/Brick/Stone and Half Wood	1,085	825	1	164
Galvanized Iron/Aluminum	37	20	-	10
Bamboo/Sawali/Cogon/Nipa	1,703	350	-	81
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	312	57	-	1
Others/Not Reported	140	61	-	1
No Walls	-	-	-	-
BANSUD				
Total	7,318	4,465	11	347
Concrete/Brick/Stone	1,923	1,852	4	41
Wood	529	421	1	8
Half Concrete/Brick/Stone and Half Wood	1,672	1,403	3	182
Galvanized Iron/Aluminum	39	24	1	7
Bamboo/Sawali/Cogon/Nipa	3,087	756	-	108
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	21	1	-	-
Others/Not Reported	47	8	2	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BONGABONG				
Total	13,283	6,092	38	1,418
Concrete/Brick/Stone	3,439	3,206	19	146
Wood	1,468	688	3	177
Half Concrete/Brick/Stone and Half Wood	2,138	1,121	10	832
Galvanized Iron/Aluminum	152	71	5	61
Bamboo/Sawali/Cogon/Nipa	5,744	959	-	197
Asbestos	15	1	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	101	5	-	1
Others/Not Reported	211	40	1	2
No Walls	15	1	-	1
BULALACAO (SAN PEDRO)				
Total	5,944	1,518	6	272
Concrete/Brick/Stone	740	685	4	4
Wood	226	160	1	14
Half Concrete/Brick/Stone and Half Wood	548	240	-	199
Galvanized Iron/Aluminum	15	6	-	5
Bamboo/Sawali/Cogon/Nipa	3,808	299	-	41
Asbestos	1	1	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	13	4	-	-
Others/Not Reported	592	122	1	9
No Walls	-	-	-	-
CITY OF CALAPAN (Capital)				
Total	24,893	18,646	126	2,316
Concrete/Brick/Stone	11,550	11,051	87	296
Wood	4,526	2,897	2	306
Half Concrete/Brick/Stone and Half Wood	6,216	4,095	35	1,563
Galvanized Iron/Aluminum	141	81	1	43
Bamboo/Sawali/Cogon/Nipa	2,144	419	-	90
Asbestos	1	1	-	-
Glass	4	2	1	1
Makeshift/Salvaged/Improvised Materials	158	45	-	11
Others/Not Reported	147	50	-	6
No Walls	6	5	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
GLORIA				
Total	8,727	5,323	69	366
Concrete/Brick/Stone	2,931	2,789	42	8
Wood	1,700	862	15	30
Half Concrete/Brick/Stone and Half Wood	1,738	1,156	7	276
Galvanized Iron/Aluminum	160	126	3	19
Bamboo/Sawali/Cogon/Nipa	1,960	345	-	29
Asbestos	-	-	-	-
Glass	1	-	1	-
Makeshift/Salvaged/Improvised Materials	124	6	-	1
Others/Not Reported	109	37	1	2
No Walls	4	2	-	1
MANSALAY				
Total	8,745	2,766	25	566
Concrete/Brick/Stone	2,135	1,692	18	265
Wood	181	106	-	3
Half Concrete/Brick/Stone and Half Wood	839	409	2	247
Galvanized Iron/Aluminum	39	19	3	2
Bamboo/Sawali/Cogon/Nipa	5,477	533	-	45
Asbestos	2	-	-	-
Glass	4	-	1	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	65	6	1	4
No Walls	-	-	-	-
NAUJAN				
Total	19,286	11,647	157	1,615
Concrete/Brick/Stone	6,679	6,362	124	53
Wood	2,027	1,376	4	77
Half Concrete/Brick/Stone and Half Wood	3,919	2,290	26	1,206
Galvanized Iron/Aluminum	203	129	1	41
Bamboo/Sawali/Cogon/Nipa	5,646	1,380	-	220
Asbestos	9	8	-	1
Glass	52	13	-	7
Makeshift/Salvaged/Improvised Materials	110	26	-	3
Others/Not Reported	633	60	2	6
No Walls	8	3	-	1

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
PINAMALAYAN				
Total	16,017	10,446	81	1,357
Concrete/Brick/Stone	5,875	5,598	57	123
Wood	2,000	1,199	1	150
Half Concrete/Brick/Stone and Half Wood	4,029	2,736	10	913
Galvanized Iron/Aluminum	157	65	3	57
Bamboo/Sawali/Cogon/Nipa	3,830	811	-	109
Asbestos	3	3	-	-
Glass	2	-	1	-
Makeshift/Salvaged/Improvised Materials	23	10	-	1
Others/Not Reported	93	24	9	4
No Walls	5	-	-	-
POLA				
Total	6,999	3,025	144	808
Concrete/Brick/Stone	1,428	1,284	81	20
Wood	1,205	426	5	53
Half Concrete/Brick/Stone and Half Wood	1,796	863	52	631
Galvanized Iron/Aluminum	52	19	5	15
Bamboo/Sawali/Cogon/Nipa	2,466	425	-	86
Asbestos	2	2	-	-
Glass	3	1	-	1
Makeshift/Salvaged/Improvised Materials	8	-	-	-
Others/Not Reported	39	5	1	2
No Walls	-	-	-	-
PUERTO GALERA				
Total	6,086	4,761	58	77
Concrete/Brick/Stone	2,598	2,493	53	6
Wood	1,224	963	4	11
Half Concrete/Brick/Stone and Half Wood	1,241	1,072	1	55
Galvanized Iron/Aluminum	9	8	-	1
Bamboo/Sawali/Cogon/Nipa	871	216	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	98	2	-	1
Others/Not Reported	45	7	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ROXAS				
Total	9,499	6,903	15	168
Concrete/Brick/Stone	4,211	4,129	14	7
Wood	902	717	1	4
Half Concrete/Brick/Stone and Half Wood	1,080	922	-	83
Galvanized Iron/Aluminum	56	45	-	2
Bamboo/Sawali/Cogon/Nipa	2,804	927	-	71
Asbestos	4	4	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	20	10	-	-
Others/Not Reported	420	149	-	1
No Walls	2	-	-	-
SAN TEODORO				
Total	3,257	2,123	-	66
Concrete/Brick/Stone	1,123	1,091	-	7
Wood	669	388	-	15
Half Concrete/Brick/Stone and Half Wood	580	477	-	27
Galvanized Iron/Aluminum	7	6	-	-
Bamboo/Sawali/Cogon/Nipa	851	157	-	17
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	8	1	-	-
Others/Not Reported	16	2	-	-
No Walls	3	1	-	-
SOCORRO				
Total	7,922	5,829	18	572
Concrete/Brick/Stone	2,908	2,882	12	7
Wood	990	758	2	41
Half Concrete/Brick/Stone and Half Wood	1,696	1,282	3	334
Galvanized Iron/Aluminum	57	25	-	20
Bamboo/Sawali/Cogon/Nipa	2,107	801	-	167
Asbestos	9	9	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	55	20	-	2
Others/Not Reported	95	50	1	-
No Walls	3	-	-	1

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

VICTORIA

Total	9,393	5,277	619	916
Concrete/Brick/Stone	3,387	2,854	398	93
Wood	1,483	748	68	43
Half Concrete/Brick/Stone and Half Wood	2,252	1,225	100	735
Galvanized Iron/Aluminum	88	35	27	17
Bamboo/Sawali/Cogon/Nipa	2,115	405	-	28
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	-	-	-
Others/Not Reported	61	10	25	-
No Walls	1	-	1	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ORIENTAL MINDORO					
Total	3,876	42,102	642	338	1,403
Concrete/Brick/Stone	146	714	8	33	88
Wood	1,463	5,068	33	77	60
Half Concrete/Brick/Stone and Half Wood	533	2,339	11	49	84
Galvanized Iron/Aluminum	80	97	1	1	5
Bamboo/Sawali/Cogon/Nipa	1,604	32,694	52	70	118
Asbestos	-	-	-	13	2
Glass	35	-	-	-	2
Makeshift/Salvaged/Improvised Materials	4	302	532	6	7
Others/Not Reported	11	861	2	89	1,037
No Walls	-	27	3	-	-
BACO					
Total	23	1,781	179	5	56
Concrete/Brick/Stone	-	13	-	-	6
Wood	7	310	-	-	2
Half Concrete/Brick/Stone and Half Wood	3	88	-	-	4
Galvanized Iron/Aluminum	2	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	1,249	5	2	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	78	174	-	2
Others/Not Reported	-	38	-	3	37
No Walls	-	-	-	-	-
BANSUD					
Total	37	2,411	20	2	25
Concrete/Brick/Stone	3	22	-	-	1
Wood	3	96	-	-	-
Half Concrete/Brick/Stone and Half Wood	5	75	1	-	3
Galvanized Iron/Aluminum	1	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	20	2,199	-	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	19	-	-
Others/Not Reported	5	12	-	2	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BONGABONG					
Total	93	5,435	83	45	79
Concrete/Brick/Stone	2	59	-	2	5
Wood	16	576	4	3	1
Half Concrete/Brick/Stone and Half Wood	10	148	2	3	12
Galvanized Iron/Aluminum	10	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	55	4,502	3	3	25
Asbestos	-	-	-	13	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	19	74	1	1
Others/Not Reported	-	113	-	20	35
No Walls	-	13	-	-	-
BULALACAO (SAN PEDRO)					
Total	9	4,013	2	17	107
Concrete/Brick/Stone	1	45	-	-	1
Wood	1	50	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	99	-	1	9
Galvanized Iron/Aluminum	-	3	-	-	1
Bamboo/Sawali/Cogon/Nipa	5	3,447	-	3	13
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	2	-	-
Others/Not Reported	2	362	-	13	83
No Walls	-	-	-	-	-
CITY OF CALAPAN (Capital)					
Total	493	3,086	83	37	106
Concrete/Brick/Stone	6	89	3	7	11
Wood	297	990	14	10	10
Half Concrete/Brick/Stone and Half Wood	118	378	6	13	8
Galvanized Iron/Aluminum	2	13	-	1	-
Bamboo/Sawali/Cogon/Nipa	68	1,555	7	3	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	45	52	1	2
Others/Not Reported	-	16	-	2	73
No Walls	-	-	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
GLORIA					
Total	269	2,451	107	92	50
Concrete/Brick/Stone	5	73	-	9	5
Wood	73	677	3	36	4
Half Concrete/Brick/Stone and Half Wood	57	229	-	11	2
Galvanized Iron/Aluminum	6	4	-	-	2
Bamboo/Sawali/Cogon/Nipa	128	1,431	2	20	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	14	101	2	-
Others/Not Reported	-	22	1	14	32
No Walls	-	1	-	-	-
MANSALAY					
Total	734	4,571	2	4	77
Concrete/Brick/Stone	64	82	1	2	11
Wood	8	64	-	-	-
Half Concrete/Brick/Stone and Half Wood	60	118	-	2	1
Galvanized Iron/Aluminum	3	11	-	-	1
Bamboo/Sawali/Cogon/Nipa	594	4,277	1	-	27
Asbestos	-	-	-	-	2
Glass	3	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	2	17	-	-	35
No Walls	-	-	-	-	-
NAUJAN					
Total	310	4,885	62	6	604
Concrete/Brick/Stone	19	91	2	2	26
Wood	60	504	-	1	5
Half Concrete/Brick/Stone and Half Wood	53	324	1	1	18
Galvanized Iron/Aluminum	10	22	-	-	-
Bamboo/Sawali/Cogon/Nipa	134	3,893	1	2	16
Asbestos	-	-	-	-	-
Glass	31	-	-	-	1
Makeshift/Salvaged/Improvised Materials	1	22	57	-	1
Others/Not Reported	2	26	-	-	537
No Walls	-	3	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PINAMALAYAN					
Total	490	3,469	12	58	104
Concrete/Brick/Stone	19	66	-	1	11
Wood	86	513	3	22	26
Half Concrete/Brick/Stone and Half Wood	47	293	-	15	15
Galvanized Iron/Aluminum	20	10	1	-	1
Bamboo/Sawali/Cogon/Nipa	318	2,567	4	18	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	9	3	-	-
Others/Not Reported	-	6	1	2	47
No Walls	-	5	-	-	-
POLA					
Total	669	2,309	6	11	27
Concrete/Brick/Stone	9	32	-	-	2
Wood	503	216	-	1	1
Half Concrete/Brick/Stone and Half Wood	77	169	-	-	4
Galvanized Iron/Aluminum	10	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	69	1,879	1	-	6
Asbestos	-	-	-	-	-
Glass	1	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	5	-	1
Others/Not Reported	-	8	-	10	13
No Walls	-	-	-	-	-
PUERTO GALERA					
Total	7	1,093	34	21	35
Concrete/Brick/Stone	1	30	2	8	5
Wood	1	238	2	3	2
Half Concrete/Brick/Stone and Half Wood	2	106	1	2	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	638	10	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	75	19	1	-
Others/Not Reported	-	6	-	6	26
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ROXAS					
Total	23	2,310	2	36	42
Concrete/Brick/Stone	1	57	-	2	1
Wood	10	167	-	1	2
Half Concrete/Brick/Stone and Half Wood	1	72	-	-	2
Galvanized Iron/Aluminum	1	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	1,776	1	15	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	1	1	-
Others/Not Reported	-	220	-	17	33
No Walls	-	2	-	-	-
SAN TEODORO					
Total	1	1,050	4	-	13
Concrete/Brick/Stone	-	25	-	-	-
Wood	-	266	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	75	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	677	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	4	-	-
Others/Not Reported	-	1	-	-	13
No Walls	-	2	-	-	-
SOCORRO					
Total	92	1,320	44	2	45
Concrete/Brick/Stone	1	5	-	-	1
Wood	36	142	7	-	4
Half Concrete/Brick/Stone and Half Wood	6	69	-	-	2
Galvanized Iron/Aluminum	8	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	40	1,074	16	2	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	12	20	-	-
Others/Not Reported	-	13	-	-	31
No Walls	-	1	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
VICTORIA					
Total	626	1,918	2	2	33
Concrete/Brick/Stone	15	25	-	-	2
Wood	362	259	-	-	3
Half Concrete/Brick/Stone and Half Wood	93	96	-	1	2
Galvanized Iron/Aluminum	7	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	149	1,530	1	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	1	-	-
Others/Not Reported	-	1	-	-	25
No Walls	-	-	-	-	-