

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
QUEZON CITY				
Total	571,812	504,394	14,703	37,838
Concrete/Brick/Stone	316,394	297,297	12,247	4,521
Wood	67,176	59,906	361	2,599
Half Concrete/Brick/Stone and Half Wood	172,063	138,056	1,931	29,552
Galvanized Iron/Aluminum	6,783	5,256	101	1,022
Bamboo/Sawali/Cogon/Nipa	394	258	-	20
Asbestos	74	34	1	3
Glass	96	59	13	8
Makeshift/Salvaged/Improvised Materials	4,514	2,443	-	54
Others/Not Reported	4,287	1,069	42	57
No walls	31	16	7	2

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
QUEZON CITY					
Total	6,374	61	2,973	1,706	3,763
Concrete/Brick/Stone	796	4	86	1,077	366
Wood	3,485	11	590	117	107
Half Concrete/Brick/Stone and Half Wood	1,583	4	349	366	222
Galvanized Iron/Aluminum	358	3	18	12	13
Bamboo/Sawali/Cogon/Nipa	75	31	9	-	1
Asbestos	1	-	-	32	3
Glass	3	-	-	1	12
Makeshift/Salvaged/Improvised Materials	54	6	1,897	9	51
Others/Not Reported	17	2	22	90	2,988
No walls	2	-	2	2	-