Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	terials of the Roo	of		
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ROMBLON									_
Total	57,692	29,157	446	3,177	508	23,845	116	199	244
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls  ALCANTARA	18,055 6,334 9,483 307 22,755 3 12 347 393	16,292 3,484 5,493 132 3,540 2 10 101 103 0	372 4 60 5 0 0 1 0 4	316 171 1,960 124 582 1 1 14 8	4 86 66 9 338 0 0 2 3 0	995 2,545 1,828 36 18,190 0 141 108 2	2 3 4 0 19 0 86 1	44 29 49 0 38 0 1 38 0	30 12 23 1 48 0 0 2 128
Total	3,052	1,229	12	499	7	1,260	28	1	16
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	986 58 780 20 1,161 0 6 26 15	833 28 221 12 128 0 5 0	111 0 0 0 0 0 0 1 1 0 0	37 1 407 4 50 0 0 0 0	1 5 0 0 1 0 0 0 0	104 24 146 4 979 0 0 0 3	0 0 1 0 1 0 0 26 0	0 0 1 0 0 0 0 0	0 0 4 0 2 0 0 0 0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	terials of the Roo	of		
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BANTON									
Total	1,396	812	2	178	9	386	0	0	9
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls  CAJIDIOCAN	448 218 314 4 399 0 6 0 7	416 173 144 2 70 0 5 0 2	1 1 0 0 0 0 0 0 0 0 0	-	0 1 1 0 7 0 0 0 0	5 33 43 0 304 0 0 0	0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0	0 1 1 0 3 0 0 0 0 4
Total	4,408	2,483	17	35	25	1,819	14	0	15
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1,543 1,017 382 19 1,386 0 0 42 19	1,482 548 269 14 157 0 0 7 6	15 0 2 0 0 0 0 0 0 0	9	0 12 3 0 10 0 0 0	37 446 94 5 1,208 0 0 22 7	0 0 0 1 0 0 13 0	0 0 0 0 0 0 0 0	3 2 0 0 4 0 0 0 6

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	terials of the Ro	of		
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
CALATRAVA									
Total	1,888	857	17	50	3	864	9	75	13
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls  CONCEPCION	661 254 238 7 667 0 0 9 52	554 109 133 3 44 0 0 2 12	16 0 0 0 0 0 0 0	18 7 18 0 7 0 0 0 0	0 1 0 0 2 0 0 0 0	59 129 61 4 593 0 0 2 16	2 0 1 0 2 0 0 3 1	8 7 22 0 16 0 0 1 21 0	4 1 3 0 3 0 0 1 1 0
Total	997	607	2	52	0	331	3	0	2
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	351 130 91 2 408 0 0 13 2	340 102 65 1 97 0 0 1 1	2 0 0 0 0 0 0 0 0 0	3 3 14 1 30 0 0 1	0 0 0 0 0 0 0	6 25 12 0 280 0 0 8 0	0 0 0 0 0 0 0 3 0	0 0 0 0 0 0 0	0 0 0 0 1 0 0 0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	ruction Materials of the Roof					
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported		
CORCUERA											
Total	2,232	473	21	118	103	1,498	0	0	19		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	521 186 306 17 1,189 0 0 13	367 27 57 8 14 0 0 0	19 0 0 0 0 0 0 0 2	5 0 48 6 59 0 0 0	0 2 2 0 99 0 0 0	129 157 197 3 1,012 0 0 0	0 0 0 0 0 0 0	0 0 0 0 0 0 0	1 0 2 0 5 0 0 0 0		
LOOC											
Total	4,499	2,591	17	373	33	1,478	2	0	5		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1,763 135 754 21 1,811 0 5	1,663 100 398 8 419 0 0	15 0 2 0 0 0 0 0 0	11	0 0 0 33 0 0 0	68 24 101 2 1,274 0 0 3 6	0 0 0 0 1 0 0 1	0 0 0 0 0 0 0	2 0 1 0 1 0 0 0		

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	terials of the Ro	of		
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAGDIWANG									
Total	2,598	1,194	4	67	8	1,294	3	7	21
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls  ODIONGAN	570 975 431 9 585 0 0 3 25	344 282 0 39 0 0 0	3 0 1 0 0 0 0 0 0	6 42 9 5 0 0 0	1 2 1 0 4 0 0 0 0	34 620 100 0 537 0 0 0	0 0 0 0 0 0 0 3 0	0 1 5 0 0 0 0 0	0 2 0 0 0 0 0 0
Total	9,384	6,666	12	482	115	2,048	9	19	33
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	3,511 1,083 1,613 45 3,074 1 0 25 32	1,174 38 1,146 1 0 12	9 1 2 0 0 0 0 0 0 0	62 306 4 89 0 0	0 13 41 1 60 0 0 0	40 143 87 2 1,771 0 0 1 4	0 0 1 0 2 0 0 6 0	17 0 0 0 1 0 0 0	8 4 2 0 5 0 0 0 14

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	terials of the Ro	of		
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ROMBLON (Capital)									_
Total	7,664	4,077	197	447	24	2,806	41	38	34
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls  SAN AGUSTIN	2,389 803 1,691 39 2,454 0 0 203 85	423 1,064 26 447 0 0	188 0 8 0 0 0 0 0	19 308 5 63 0 0 6 2	1 7 5 3 5 0 0 2 1	130 347 297 5 1,909 0 92 26	0 2 0 0 11 0 0 28 0	10 5 6 0 14 0 0 0 3	6 0 3 0 5 0 0 1 19 0
Total	4,400	1,869	115	328	114	1,921	1	11	41
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1,236 223 811 75 1,977 1 0 3 74	1,092 139 442 1 177 1 0 0	67 0 43 5 0 0 0 0	189 61 48 0 0	0 16 6 3 87 0 0 0 2	46 63 125 4 1,656 0 0 2 25	0 0 0 0 0 0 0 1	5 0 3 0 2 0 0 0	2 1 3 1 7 0 0 0 27 0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	terials of the Ro	of		
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN ANDRES									
Total	2,927	1,451	9	97	22	1,342	0	5	1
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls  SAN FERNANDO	745 188 525 8 1,457 0 0 1 3	116 410 5 216 0 0 0	7 0 2 0 0 0 0 0 0	42 0 34 0 0 0	0 9 0 13 0 0 0	19 58 68 3 1,193 0 0 1	0 0 0 0 0 0 0 0	1 0 3 0 1 0 0 0	1 0 0 0 0 0 0 0
Total	4,346	2,115	14	105	32	2,029	4	31	16
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1,030 891 729 12 1,654 0 0 15 14	402 516	12 2 0 0 0 0 0 0 0 0	26	1 18 3 2 8 0 0 0 0	30 425 143 0 1,418 0 9 4	0 1 0 0 0 0 0 2 0	3 16 9 0 3 0 0 0	2 1 3 0 7 0 0 0 3

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	terials of the Ro	of		
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN JOSE									
Total	1,772	521	0	78	0	1,148	2	12	11
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls SANTA FE	517 27 134 3 1,057 0 0 1 31	1 72 0 0 0 3	0 0 0 0 0 0 0 0	7 43 0 24 0 0 1 1	0 0 0 0 0 0 0 0	109 13 58 2 958 0 0 0 6	0 0 1 0 1 0 0 0 0	0 0 0 1 0 0 0 0	1 0 0 0 1 0 0 0 0 9
Total	3,135	938	0	53	5	2,136	0	0	3
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	906 17 345 18 1,841 0 0 1 7	7 116	0 0 0 0 0 0 0 0	5 0 29 13 6 0 0 0	0 0 2 0 3 0 0 0 0	151 10 198 2 1,769 0 0 1 5	0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0	0 0 0 0 2 0 0 0

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

				Cons	truction Ma	terials of the Roo	of		
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
FERROL									
Total	1,423	769	0	1	6	646	0	0	1
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls  SANTA MARIA (IMELDA)	471 103 61 3 784 0 0 0	463 87 55 3 160 0 0	0 0 0 0 0 0 0 0	0 0 0 1 0 0 0	0 0 1 0 5 0 0 0	8 16 5 0 617 0 0 0	0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0	0 0 0 1 0 0 0
Total	1,571	505	7	214	2	839	0	0	4
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	407 26 278 5 851 0 0 0 4	285 12 115 4 89 0 0 0	7 0 0 0 0 0 0 0 0 0	95 2 68 1 48 0 0 0	0 0 1 0 1 0 0 0 0	20 12 93 0 712 0 0 2	0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0	0 0 1 0 1 0 0 0 2