

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SOUTHERN LEYTE

Total	82,281	64,329	203	1,730
Concrete/Brick/Stone	26,556	25,939	153	67
Wood	17,867	13,750	11	210
Half Concrete/Brick/Stone and Half Wood	15,164	12,968	31	1,046
Galvanized Iron/Aluminum	343	287	7	28
Bamboo/Sawali/Cogon/Nipa	21,606	11,051	-	370
Asbestos	3	3	-	-
Glass	4	3	-	-
Makeshift/Salvaged/Improvised Materials	144	73	-	2
Others/Not Reported	578	244	1	6
No Walls	16	11	-	1

ANAHAWAN

Total	1,653	1,414	-	7
Concrete/Brick/Stone	389	388	-	-
Wood	547	466	-	2
Half Concrete/Brick/Stone and Half Wood	472	460	-	3
Galvanized Iron/Aluminum	8	8	-	-
Bamboo/Sawali/Cogon/Nipa	232	92	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	4	-	-	-
No Walls	-	-	-	-

BONTOC

Total	5,769	5,077	3	15
Concrete/Brick/Stone	1,825	1,820	-	1
Wood	642	609	1	-
Half Concrete/Brick/Stone and Half Wood	914	890	-	8
Galvanized Iron/Aluminum	32	27	1	3
Bamboo/Sawali/Cogon/Nipa	2,341	1,721	-	3
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	7	-	-
Others/Not Reported	5	2	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
HINUNANGAN				
Total	6,117	5,049	65	45
Concrete/Brick/Stone	1,595	1,524	53	5
Wood	2,191	1,739	3	5
Half Concrete/Brick/Stone and Half Wood	1,572	1,492	6	31
Galvanized Iron/Aluminum	33	26	3	2
Bamboo/Sawali/Cogon/Nipa	667	227	-	2
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	4	1	-	-
Others/Not Reported	54	39	-	-
No Walls	-	-	-	-
HINUNDAYAN				
Total	2,744	1,514	4	96
Concrete/Brick/Stone	766	739	4	4
Wood	794	392	-	8
Half Concrete/Brick/Stone and Half Wood	530	358	-	77
Galvanized Iron/Aluminum	3	1	-	1
Bamboo/Sawali/Cogon/Nipa	585	23	-	6
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	62	-	-	-
No Walls	1	-	-	-
LIBAGON				
Total	2,962	2,031	4	167
Concrete/Brick/Stone	676	662	2	2
Wood	381	325	-	6
Half Concrete/Brick/Stone and Half Wood	643	517	2	96
Galvanized Iron/Aluminum	15	11	-	3
Bamboo/Sawali/Cogon/Nipa	1,235	512	-	60
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	3	-	-
Others/Not Reported	7	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
LILOAN				
Total	4,773	3,186	7	292
Concrete/Brick/Stone	1,699	1,641	6	9
Wood	980	661	-	45
Half Concrete/Brick/Stone and Half Wood	864	593	1	160
Galvanized Iron/Aluminum	6	4	-	-
Bamboo/Sawali/Cogon/Nipa	1,174	268	-	78
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	50	19	-	-
No Walls	-	-	-	-
CITY OF MAASIN (Capital)				
Total	16,912	14,297	49	280
Concrete/Brick/Stone	6,641	6,484	46	6
Wood	3,075	2,742	-	7
Half Concrete/Brick/Stone and Half Wood	2,216	1,915	3	209
Galvanized Iron/Aluminum	37	24	-	11
Bamboo/Sawali/Cogon/Nipa	4,728	3,025	-	42
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	63	40	-	-
Others/Not Reported	151	66	-	5
No Walls	-	-	-	-
MACROHON				
Total	5,360	4,475	10	43
Concrete/Brick/Stone	2,029	1,997	10	3
Wood	898	780	-	10
Half Concrete/Brick/Stone and Half Wood	1,029	943	-	5
Galvanized Iron/Aluminum	29	27	-	-
Bamboo/Sawali/Cogon/Nipa	1,355	724	-	25
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	3	-	-
Others/Not Reported	13	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

MALITBOG

Total	4,067	3,100	-	103
Concrete/Brick/Stone	1,224	1,214	-	4
Wood	358	323	-	12
Half Concrete/Brick/Stone and Half Wood	762	696	-	43
Galvanized Iron/Aluminum	8	7	-	1
Bamboo/Sawali/Cogon/Nipa	1,706	856	-	43
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	1	-	-
Others/Not Reported	5	3	-	-
No Walls	-	-	-	-

PADRE BURGOS

Total	2,065	1,690	1	9
Concrete/Brick/Stone	853	841	1	1
Wood	276	230	-	1
Half Concrete/Brick/Stone and Half Wood	374	327	-	3
Galvanized Iron/Aluminum	8	4	-	2
Bamboo/Sawali/Cogon/Nipa	529	277	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	1	-	-
Others/Not Reported	20	10	-	-
No Walls	-	-	-	-

PINTUYAN

Total	1,944	1,071	1	11
Concrete/Brick/Stone	518	488	1	2
Wood	782	276	-	7
Half Concrete/Brick/Stone and Half Wood	394	268	-	1
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	249	39	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	1	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
SAINT BERNARD				
Total	5,384	3,794	2	94
Concrete/Brick/Stone	1,533	1,510	2	2
Wood	1,443	1,125	-	26
Half Concrete/Brick/Stone and Half Wood	886	765	-	39
Galvanized Iron/Aluminum	20	20	-	-
Bamboo/Sawali/Cogon/Nipa	1,359	307	-	25
Asbestos	-	-	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	14	2	-	2
Others/Not Reported	128	65	-	-
No Walls	-	-	-	-
SAN FRANCISCO				
Total	2,663	2,036	2	26
Concrete/Brick/Stone	1,020	1,008	2	1
Wood	579	406	-	7
Half Concrete/Brick/Stone and Half Wood	534	469	-	12
Galvanized Iron/Aluminum	8	6	-	2
Bamboo/Sawali/Cogon/Nipa	506	142	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	14	4	-	-
No Walls	-	-	-	-
SAN JUAN (CABALIAN)				
Total	3,038	2,145	2	173
Concrete/Brick/Stone	683	676	1	2
Wood	917	625	1	29
Half Concrete/Brick/Stone and Half Wood	719	585	-	101
Galvanized Iron/Aluminum	62	62	-	-
Bamboo/Sawali/Cogon/Nipa	648	194	-	41
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	6	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SAN RICARDO

Total	1,899	852	41	211
Concrete/Brick/Stone	458	429	16	6
Wood	657	178	5	14
Half Concrete/Brick/Stone and Half Wood	432	205	18	179
Galvanized Iron/Aluminum	6	2	2	2
Bamboo/Sawali/Cogon/Nipa	327	33	-	9
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	1	-	-
Others/Not Reported	12	4	-	1
No Walls	-	-	-	-

SILAGO

Total	2,531	2,114	1	4
Concrete/Brick/Stone	561	556	1	-
Wood	1,280	1,048	-	3
Half Concrete/Brick/Stone and Half Wood	419	405	-	-
Galvanized Iron/Aluminum	10	1	-	1
Bamboo/Sawali/Cogon/Nipa	240	92	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	1	-	-
Others/Not Reported	17	11	-	-
No Walls	-	-	-	-

SOGOD

Total	7,939	7,357	6	51
Concrete/Brick/Stone	2,697	2,687	3	1
Wood	1,556	1,465	1	17
Half Concrete/Brick/Stone and Half Wood	1,483	1,444	1	19
Galvanized Iron/Aluminum	41	40	1	-
Bamboo/Sawali/Cogon/Nipa	2,119	1,692	-	13
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	2	-	-
Others/Not Reported	24	15	-	-
No Walls	15	11	-	1

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

TOMAS OPPUS

Total	3,200	2,589	2	21
Concrete/Brick/Stone	891	876	2	7
Wood	357	334	-	1
Half Concrete/Brick/Stone and Half Wood	551	534	-	8
Galvanized Iron/Aluminum	17	17	-	-
Bamboo/Sawali/Cogon/Nipa	1,367	816	-	5
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	10	-	-
Others/Not Reported	5	1	-	-
No Walls	-	-	-	-

LIMASAWA

Total	1,261	538	3	82
Concrete/Brick/Stone	498	399	3	11
Wood	154	26	-	10
Half Concrete/Brick/Stone and Half Wood	370	102	-	52
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	239	11	-	9
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	-	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SOUTHERN LEYTE					
Total	799	14,625	71	268	256
Concrete/Brick/Stone	5	335	1	38	18
Wood	539	3,289	13	43	12
Half Concrete/Brick/Stone and Half Wood	34	1,035	3	40	7
Galvanized Iron/Aluminum	13	7	-	-	1
Bamboo/Sawali/Cogon/Nipa	205	9,815	33	107	25
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	50	19	-	-
Others/Not Reported	3	90	2	40	192
No Walls	-	4	-	-	-
ANAHAWAN					
Total	-	226	1	1	4
Concrete/Brick/Stone	-	1	-	-	-
Wood	-	79	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	9	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	137	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	-	4
No Walls	-	-	-	-	-
BONTOC					
Total	18	618	2	30	6
Concrete/Brick/Stone	-	3	-	-	1
Wood	8	20	1	3	-
Half Concrete/Brick/Stone and Half Wood	3	13	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	7	581	-	26	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	-	-	1	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
HINUNANGAN					
Total	9	928	4	1	16
Concrete/Brick/Stone	-	11	-	-	2
Wood	3	439	1	-	1
Half Concrete/Brick/Stone and Half Wood	1	40	-	-	2
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	429	2	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	-	6	-	-	9
No Walls	-	-	-	-	-
HINUNDAYAN					
Total	4	1,062	-	1	63
Concrete/Brick/Stone	-	19	-	-	-
Wood	1	393	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	92	-	1	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	554	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	-	-	-	62
No Walls	-	1	-	-	-
LIBAGON					
Total	5	749	1	3	2
Concrete/Brick/Stone	1	9	-	-	-
Wood	2	48	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	27	-	1	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	659	1	2	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	4	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LILOAN					
Total	21	1,131	1	130	5
Concrete/Brick/Stone	-	33	-	8	2
Wood	11	234	1	27	1
Half Concrete/Brick/Stone and Half Wood	3	74	-	33	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	775	-	46	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	13	-	16	2
No Walls	-	-	-	-	-
CITY OF MAASIN (Capital)					
Total	165	1,948	29	48	96
Concrete/Brick/Stone	1	74	1	22	7
Wood	64	250	2	3	7
Half Concrete/Brick/Stone and Half Wood	7	77	-	2	3
Galvanized Iron/Aluminum	2	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	91	1,525	17	20	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	7	-	-
Others/Not Reported	-	6	2	1	71
No Walls	-	-	-	-	-
MACROHON					
Total	14	801	4	1	12
Concrete/Brick/Stone	-	18	-	1	-
Wood	11	97	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	81	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	598	3	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	-	-
Others/Not Reported	-	2	-	-	10
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MALITBOG					
Total	8	848	2	1	5
Concrete/Brick/Stone	-	4	-	-	2
Wood	2	21	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	22	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	800	-	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	2	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
PADRE BURGOS					
Total	2	340	4	14	5
Concrete/Brick/Stone	-	5	-	4	1
Wood	-	41	1	3	-
Half Concrete/Brick/Stone and Half Wood	-	41	1	2	-
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	245	2	2	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	-	3	-	3	4
No Walls	-	-	-	-	-
PINTUYAN					
Total	3	856	-	1	1
Concrete/Brick/Stone	-	27	-	-	-
Wood	3	495	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	125	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	209	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAINT BERNARD					
Total	32	1,427	8	15	12
Concrete/Brick/Stone	-	18	-	-	1
Wood	18	269	4	-	1
Half Concrete/Brick/Stone and Half Wood	2	78	1	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	1,014	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	8	2	-	-
Others/Not Reported	-	40	-	15	8
No Walls	-	-	-	-	-
SAN FRANCISCO					
Total	1	588	2	2	6
Concrete/Brick/Stone	-	9	-	-	-
Wood	-	166	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	52	1	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	357	1	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	3	-	1	6
No Walls	-	-	-	-	-
SAN JUAN (CABALIAN)					
Total	136	574	2	3	3
Concrete/Brick/Stone	-	3	-	1	-
Wood	123	136	-	2	1
Half Concrete/Brick/Stone and Half Wood	4	29	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	403	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	-	1	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN RICARDO					
Total	291	494	2	7	1
Concrete/Brick/Stone	1	5	-	1	-
Wood	262	194	-	4	-
Half Concrete/Brick/Stone and Half Wood	6	23	-	1	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	19	265	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	2	-	-
Others/Not Reported	3	3	-	1	-
No Walls	-	-	-	-	-
SILAGO					
Total	22	389	-	-	1
Concrete/Brick/Stone	-	4	-	-	-
Wood	14	215	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	14	-	-	-
Galvanized Iron/Aluminum	8	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	148	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	5	-	-	1
No Walls	-	-	-	-	-
SOGOD					
Total	24	473	7	9	12
Concrete/Brick/Stone	2	2	-	-	2
Wood	12	57	3	-	1
Half Concrete/Brick/Stone and Half Wood	1	17	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	391	3	7	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	3	-	2	4
No Walls	-	3	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

TOMAS OPPUS

Total	43	536	2	1	6
Concrete/Brick/Stone	-	5	-	1	-
Wood	5	17	-	-	-
Half Concrete/Brick/Stone and Half Wood	3	6	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	35	506	2	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	1	-	-	3
No Walls	-	-	-	-	-

LIMASAWA

Total	1	637	-	-	-
Concrete/Brick/Stone	-	85	-	-	-
Wood	-	118	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	215	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	219	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-