

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>ZAMBOANGA SIBUGAY</b>				
Total	106,221	44,790	180	2,008
Concrete/Brick/Stone	8,628	8,296	74	61
Wood	42,211	23,667	39	928
Half Concrete/Brick/Stone and Half Wood	10,352	8,622	34	678
Galvanized Iron/Aluminum	420	206	6	53
Bamboo/Sawali/Cogon/Nipa	43,705	3,868	-	278
Asbestos	6	3	-	-
Glass	4	2	-	1
Makeshift/Salvaged/Improvised Materials	305	49	-	2
Others/Not Reported	588	76	27	7
No Walls	2	1	-	-
<b>ALICIA</b>				
Total	6,648	2,056	3	120
Concrete/Brick/Stone	280	235	-	7
Wood	3,341	1,405	2	84
Half Concrete/Brick/Stone and Half Wood	295	234	1	20
Galvanized Iron/Aluminum	13	5	-	1
Bamboo/Sawali/Cogon/Nipa	2,676	174	-	7
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	42	3	-	1
No Walls	-	-	-	-
<b>BUUG</b>				
Total	6,766	4,783	3	271
Concrete/Brick/Stone	921	915	-	4
Wood	3,422	2,718	2	127
Half Concrete/Brick/Stone and Half Wood	887	760	1	115
Galvanized Iron/Aluminum	15	7	-	4
Bamboo/Sawali/Cogon/Nipa	1,463	363	-	18
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	19	9	-	1
Others/Not Reported	38	10	-	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>DIPLAHAN</b>				
Total	5,652	3,824	10	41
Concrete/Brick/Stone	685	669	9	4
Wood	3,442	2,417	-	30
Half Concrete/Brick/Stone and Half Wood	557	537	-	7
Galvanized Iron/Aluminum	6	2	-	-
Bamboo/Sawali/Cogon/Nipa	918	192	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	43	6	1	-
No Walls	-	-	-	-
<b>IMELDA</b>				
Total	4,329	2,327	3	49
Concrete/Brick/Stone	397	386	2	-
Wood	2,474	1,490	1	19
Half Concrete/Brick/Stone and Half Wood	396	355	-	21
Galvanized Iron/Aluminum	7	2	-	1
Bamboo/Sawali/Cogon/Nipa	1,009	86	-	7
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	45	7	-	1
No Walls	-	-	-	-
<b>IPIL (Capital)</b>				
Total	13,089	5,914	15	403
Concrete/Brick/Stone	1,638	1,558	4	18
Wood	4,645	2,398	2	154
Half Concrete/Brick/Stone and Half Wood	1,854	1,419	4	177
Galvanized Iron/Aluminum	113	95	3	6
Bamboo/Sawali/Cogon/Nipa	4,736	399	-	48
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	57	34	-	-
Others/Not Reported	45	11	2	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>KABASALAN</b>				
Total	7,676	2,850	63	127
Concrete/Brick/Stone	705	634	45	5
Wood	3,598	1,211	4	30
Half Concrete/Brick/Stone and Half Wood	1,129	873	13	59
Galvanized Iron/Aluminum	69	26	-	18
Bamboo/Sawali/Cogon/Nipa	1,953	101	-	13
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	165	-	-	1
Others/Not Reported	56	5	1	1
No Walls	-	-	-	-
<b>MABUHAY</b>				
Total	5,011	810	45	60
Concrete/Brick/Stone	98	94	1	1
Wood	1,082	448	20	30
Half Concrete/Brick/Stone and Half Wood	258	205	4	11
Galvanized Iron/Aluminum	56	4	-	2
Bamboo/Sawali/Cogon/Nipa	3,464	57	-	15
Asbestos	1	1	-	-
Glass	1	-	-	1
Makeshift/Salvaged/Improvised Materials	10	-	-	-
Others/Not Reported	41	1	20	-
No Walls	-	-	-	-
<b>MALANGAS</b>				
Total	5,877	3,313	8	263
Concrete/Brick/Stone	610	594	5	8
Wood	2,379	1,513	1	113
Half Concrete/Brick/Stone and Half Wood	959	818	2	92
Galvanized Iron/Aluminum	25	11	-	8
Bamboo/Sawali/Cogon/Nipa	1,874	375	-	41
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	27	1	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>NAGA</b>				
Total	6,979	3,148	3	47
Concrete/Brick/Stone	482	473	1	1
Wood	3,122	1,731	1	15
Half Concrete/Brick/Stone and Half Wood	985	805	1	19
Galvanized Iron/Aluminum	24	11	-	3
Bamboo/Sawali/Cogon/Nipa	2,341	126	-	9
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	24	2	-	-
No Walls	-	-	-	-
<b>OLUTANGA</b>				
Total	4,913	1,607	-	24
Concrete/Brick/Stone	285	284	-	-
Wood	933	705	-	5
Half Concrete/Brick/Stone and Half Wood	301	265	-	8
Galvanized Iron/Aluminum	12	3	-	-
Bamboo/Sawali/Cogon/Nipa	3,335	343	-	11
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	24	2	-	-
Others/Not Reported	23	5	-	-
No Walls	-	-	-	-
<b>PAYAO</b>				
Total	5,733	1,548	6	41
Concrete/Brick/Stone	243	224	3	2
Wood	2,244	978	1	13
Half Concrete/Brick/Stone and Half Wood	321	257	-	21
Galvanized Iron/Aluminum	15	5	2	2
Bamboo/Sawali/Cogon/Nipa	2,877	80	-	3
Asbestos	-	-	-	-
Glass	3	2	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	29	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>ROSELLER LIM</b>				
Total	6,890	2,802	2	141
Concrete/Brick/Stone	308	301	-	1
Wood	2,944	1,808	1	119
Half Concrete/Brick/Stone and Half Wood	370	342	1	5
Galvanized Iron/Aluminum	5	2	-	1
Bamboo/Sawali/Cogon/Nipa	3,228	344	-	14
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	34	4	-	1
No Walls	-	-	-	-
<b>SIAY</b>				
Total	6,631	2,506	11	91
Concrete/Brick/Stone	440	424	1	-
Wood	3,646	1,502	2	49
Half Concrete/Brick/Stone and Half Wood	478	391	4	32
Galvanized Iron/Aluminum	10	5	1	-
Bamboo/Sawali/Cogon/Nipa	2,017	178	-	10
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	1	-	-
Others/Not Reported	30	5	3	-
No Walls	-	-	-	-
<b>TALUSAN</b>				
Total	3,728	825	1	10
Concrete/Brick/Stone	104	104	-	-
Wood	687	480	1	1
Half Concrete/Brick/Stone and Half Wood	101	91	-	1
Galvanized Iron/Aluminum	10	3	-	3
Bamboo/Sawali/Cogon/Nipa	2,802	147	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	-	-	-
Others/Not Reported	13	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## TITAY

Total	8,859	4,244	5	278
Concrete/Brick/Stone	1,030	1,008	3	9
Wood	2,648	1,806	-	129
Half Concrete/Brick/Stone and Half Wood	976	839	2	71
Galvanized Iron/Aluminum	31	22	-	2
Bamboo/Sawali/Cogon/Nipa	4,143	566	-	67
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	29	3	-	-
No Walls	-	-	-	-

## TUNGAWAN

Total	7,440	2,233	2	42
Concrete/Brick/Stone	402	393	-	1
Wood	1,604	1,057	1	10
Half Concrete/Brick/Stone and Half Wood	485	431	1	19
Galvanized Iron/Aluminum	9	3	-	2
Bamboo/Sawali/Cogon/Nipa	4,869	337	-	10
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	69	11	-	-
No Walls	2	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>ZAMBOANGA SIBUGAY</b>					
Total	1,502	56,821	253	92	575
Concrete/Brick/Stone	63	117	3	2	12
Wood	492	16,882	43	66	94
Half Concrete/Brick/Stone and Half Wood	167	813	5	5	28
Galvanized Iron/Aluminum	78	75	-	-	2
Bamboo/Sawali/Cogon/Nipa	696	38,671	65	15	112
Asbestos	2	-	-	1	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	115	136	1	2
Others/Not Reported	4	147	1	2	324
No Walls	-	1	-	-	-
<b>ALICIA</b>					
Total	177	4,252	-	1	39
Concrete/Brick/Stone	30	7	-	-	1
Wood	22	1,825	-	-	3
Half Concrete/Brick/Stone and Half Wood	15	25	-	-	-
Galvanized Iron/Aluminum	4	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	104	2,379	-	1	11
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	13	-	-	24
No Walls	-	-	-	-	-
<b>BUUG</b>					
Total	10	1,614	1	20	64
Concrete/Brick/Stone	-	1	-	-	1
Wood	5	535	1	15	19
Half Concrete/Brick/Stone and Half Wood	-	7	-	-	4
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	1,056	-	4	18
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	-	1	1
Others/Not Reported	-	5	-	-	21
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>DIPLAHAN</b>					
Total	21	1,722	1	-	33
Concrete/Brick/Stone	-	3	-	-	-
Wood	19	976	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	12	-	-	1
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	723	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	4	-	-	32
No Walls	-	-	-	-	-
<b>IMELDA</b>					
Total	43	1,834	3	4	66
Concrete/Brick/Stone	-	4	2	2	1
Wood	14	935	1	1	13
Half Concrete/Brick/Stone and Half Wood	1	9	-	1	9
Galvanized Iron/Aluminum	2	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	26	884	-	-	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	37
No Walls	-	-	-	-	-
<b>IPIL (Capital)</b>					
Total	334	6,334	17	6	66
Concrete/Brick/Stone	28	27	-	-	3
Wood	135	1,949	-	3	4
Half Concrete/Brick/Stone and Half Wood	88	157	-	2	7
Galvanized Iron/Aluminum	-	8	-	-	1
Bamboo/Sawali/Cogon/Nipa	83	4,179	2	-	25
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	15	-	-
Others/Not Reported	-	6	-	-	26
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>KABASALAN</b>					
Total	314	4,105	171	2	44
Concrete/Brick/Stone	2	18	-	-	1
Wood	105	2,232	11	1	4
Half Concrete/Brick/Stone and Half Wood	20	157	5	-	2
Galvanized Iron/Aluminum	17	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	167	1,619	50	1	2
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	58	105	-	1
Others/Not Reported	2	13	-	-	34
No Walls	-	-	-	-	-
<b>MABUHAY</b>					
Total	197	3,877	1	1	20
Concrete/Brick/Stone	-	1	-	-	1
Wood	13	568	-	1	2
Half Concrete/Brick/Stone and Half Wood	6	31	-	-	1
Galvanized Iron/Aluminum	44	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	134	3,249	-	-	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	1	-	-
Others/Not Reported	-	13	-	-	7
No Walls	-	-	-	-	-
<b>MALANGAS</b>					
Total	46	2,223	-	1	23
Concrete/Brick/Stone	1	2	-	-	-
Wood	7	742	-	1	2
Half Concrete/Brick/Stone and Half Wood	17	29	-	-	1
Galvanized Iron/Aluminum	3	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	18	1,440	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	5	-	-	20
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>NAGA</b>					
Total	31	3,729	1	-	20
Concrete/Brick/Stone	-	7	-	-	-
Wood	4	1,367	-	-	4
Half Concrete/Brick/Stone and Half Wood	6	154	-	-	-
Galvanized Iron/Aluminum	-	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	21	2,176	1	-	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	14	-	-	8
No Walls	-	-	-	-	-
<b>OLUTANGA</b>					
Total	18	3,230	23	-	11
Concrete/Brick/Stone	-	1	-	-	-
Wood	4	218	1	-	-
Half Concrete/Brick/Stone and Half Wood	1	27	-	-	-
Galvanized Iron/Aluminum	1	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	2,958	9	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	10	12	-	-
Others/Not Reported	-	8	1	-	9
No Walls	-	-	-	-	-
<b>PAYAO</b>					
Total	90	4,002	29	3	14
Concrete/Brick/Stone	1	12	1	-	-
Wood	27	1,196	27	-	2
Half Concrete/Brick/Stone and Half Wood	4	36	-	2	1
Galvanized Iron/Aluminum	2	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	55	2,736	1	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	1	17	-	1	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>ROSELLER LIM</b>					
Total	20	3,857	1	43	24
Concrete/Brick/Stone	-	3	-	-	3
Wood	8	968	1	39	-
Half Concrete/Brick/Stone and Half Wood	-	22	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	2,854	-	3	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	8	-	1	20
No Walls	-	-	-	-	-
<b>SIAY</b>					
Total	83	3,874	-	1	65
Concrete/Brick/Stone	-	14	-	-	1
Wood	67	1,992	-	1	33
Half Concrete/Brick/Stone and Half Wood	-	51	-	-	-
Galvanized Iron/Aluminum	1	2	-	-	1
Bamboo/Sawali/Cogon/Nipa	15	1,800	-	-	14
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	-	-	-
Others/Not Reported	-	6	-	-	16
No Walls	-	-	-	-	-
<b>TALUSAN</b>					
Total	34	2,848	4	-	6
Concrete/Brick/Stone	-	-	-	-	-
Wood	22	183	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	9	-	-	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	2,637	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	3	-	-
Others/Not Reported	-	7	-	-	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
<b>TITAY</b>					
Total	32	4,272	1	-	27
Concrete/Brick/Stone	1	9	-	-	-
Wood	15	695	1	-	2
Half Concrete/Brick/Stone and Half Wood	-	63	-	-	1
Galvanized Iron/Aluminum	-	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	16	3,490	-	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	6	-	-	20
No Walls	-	-	-	-	-
<b>TUNGAWAN</b>					
Total	52	5,048	-	10	53
Concrete/Brick/Stone	-	8	-	-	-
Wood	25	501	-	4	6
Half Concrete/Brick/Stone and Half Wood	9	24	-	-	1
Galvanized Iron/Aluminum	3	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	4,491	-	6	10
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	22	-	-	36
No Walls	-	1	-	-	-