

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

ANGELES CITY

Total	68,631	61,480	663	3,782
Concrete/Brick/Stone	47,164	46,369	459	114
Wood	3,345	2,579	88	219
Half Concrete/Brick/Stone and Half Wood	14,825	11,250	90	3,302
Galvanized Iron/Aluminum	575	385	13	117
Bamboo/Sawali/Cogon/Nipa	604	329	-	15
Asbestos	1	1	-	-
Glass	16	5	9	-
Makeshift/Salvaged/Improvised Materials	470	255	-	3
Others/Not Reported	1,631	307	4	12
No walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ANGELES CITY					
Total	607	183	291	7	1,618
Concrete/Brick/Stone	14	1	3	-	204
Wood	382	35	19	1	22
Half Concrete/Brick/Stone and Half Wood	101	-	3	2	77
Galvanized Iron/Aluminum	49	6	-	1	4
Bamboo/Sawali/Cogon/Nipa	53	133	68	-	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	2
Makeshift/Salvaged/Improvised Materials	5	8	197	-	2
Others/Not Reported	3	-	1	3	1,301
No walls	-	-	-	-	-