

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls	Total Occupied Housing Units	Const		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

ILIGAN CITY

Total	61,341	55,293	286	2,394
Concrete/Brick/Stone	19,691	19,081	233	266
Wood	25,083	22,648	26	472
Half Concrete/Brick/Stone and Half Wood	13,874	12,126	26	1,598
Galvanized Iron/Aluminum	131	101	-	25
Bamboo/Sawali/Cogon/Nipa	2,281	1,217	-	22
Asbestos	8	7	-	1
Glass	8	8	-	-
Makeshift/Salvaged/Improvised Materials	99	59	-	8
Others/Not Reported	162	43	1	2
No Walls	4	3	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ILIGAN CITY					
Total	437	2,695	56	26	154
Concrete/Brick/Stone	76	13	7	6	9
Wood	244	1,652	14	5	22
Half Concrete/Brick/Stone and Half Wood	70	44	1	1	8
Galvanized Iron/Aluminum	1	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	46	967	13	11	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	11	21	-	-
Others/Not Reported	-	3	-	3	110
No Walls	-	1	-	-	-