

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
ILOILO CITY				
Total	81,250	72,352	497	3,609
Concrete/Brick/Stone	27,076	26,123	389	400
Wood	15,844	14,416	18	658
Half Concrete/Brick/Stone and Half Wood	23,909	21,214	68	2,214
Galvanized Iron/Aluminum	547	394	9	82
Bamboo/Sawali/Cogon/Nipa	12,435	9,355	-	233
Asbestos	36	24	-	3
Glass	12	8	1	1
Makeshift/Salvaged/Improvised Materials	956	704	-	13
Others/Not Reported	404	113	12	1
No walls	31	1	-	4

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ILOILO CITY					
Total	882	3,144	256	214	296
Concrete/Brick/Stone	52	23	6	69	14
Wood	324	354	25	37	12
Half Concrete/Brick/Stone and Half Wood	214	121	8	55	15
Galvanized Iron/Aluminum	36	20	4	2	-
Bamboo/Sawali/Cogon/Nipa	231	2,516	57	32	11
Asbestos	3	-	-	6	-
Glass	-	-	-	-	2
Makeshift/Salvaged/Improvised Materials	4	80	153	2	-
Others/Not Reported	4	22	3	7	242
No walls	14	8	-	4	-