

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

## OLONGAPO CITY

Total	49,041	45,572	321	1,831
Concrete/Brick/Stone	34,146	33,608	205	225
Wood	3,683	3,149	61	114
Half Concrete/Brick/Stone and Half Wood	9,115	7,549	50	1,425
Galvanized Iron/Aluminum	449	405	2	27
Bamboo/Sawali/Cogon/Nipa	690	346	-	26
Asbestos	2	1	1	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	752	461	-	13
Others/Not Reported	203	52	2	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

OLONGAPO CITY

Total	505	341	297	6	168
Concrete/Brick/Stone	72	11	8	4	13
Wood	318	28	13	-	-
Half Concrete/Brick/Stone and Half Wood	73	6	6	-	6
Galvanized Iron/Aluminum	12	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	25	280	11	1	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	14	257	-	2
Others/Not Reported	-	-	1	1	146
No Walls	-	-	-	-	-